



Asbestos Management Survey Report



WAIMARINO HEALTH CENTRE

Report Production

Report Prepared by: Ali Lind

Position in Company: Asbestos Project Manager

Signature: 

Date: 19/03/2018

Contents Page

Section 1

- **Report Details**
- **Introduction**
- **Survey Methodology**
- **General Recommendations for Asbestos Cement Products**
- **General Recommendation for Asbestos Insulation, Coatings or Insulating Board (AIB)**
- **Survey Summary & Recommendations**
- **Risk Assessment Methods**

Section 2

- **Identification & Photographic Register Sheets**
- **Survey Recommendations**
- **Survey Record Sheets**
- **Laboratory Certificate of Analysis**
- **Management Inspection Record**

Introduction

Further to an invitation from: **GRANT HOOD (W.D.H.B)**

AISL - Asbestos Inspection Services Limited was requested to carry out a Management Survey at -

WAIMARINO HEALTH CENTRE, RAETIHI.

There are 2 designated categories of Asbestos surveys currently available. These are listed below:

Management Survey

Standard sampling, identification and assessment survey (Sampling Survey), the purpose of which is to locate as far as reasonably Practicable the presence and extent of any suspect asbestos containing materials in the building and their condition. This is done by the collection and analysis of samples of suspect asbestos containing materials.

Refurbishment / Demolition Survey

Full access sampling and identification survey (Pre-demolition/Major Refurbishment Survey). This type of survey is used to locate and describe as far as reasonably practicable, all asbestos containing materials in the building and may involve destructive inspection as necessary to gain access to all areas, including those that may be difficult to reach. A full sampling programme is undertaken to identify possible asbestos containing materials and estimates of the volume and surface areas of asbestos containing materials made.

Access arrangements were made with aid of Mr. Grant Hood (Whanganui District Health Board) to ensure all accessible areas were surveyed during the project.

The survey was carried out on 19/03/2018 and completed 2 days thereafter.

The survey was to include for visual inspection within the above premises.

The survey was undertaken and completed by Ali Lind member of the AISL – Asbestos Inspection Services Limited survey team.

During the survey the building remained un-occupied.

Disclaimer

Every effort has been made to identify all asbestos materials so far as was reasonably practicable to do so within the scope of the survey and the attached report. Methods used to carry out the survey were agreed with the client prior to any works being commenced.

Survey techniques used involves trained and experienced surveyors using the combined approach about visual examination. and bulk sample collections where required.

It is always possible after a survey that asbestos based materials may remain in the property or area covered by that survey, this could be due to several reasons:

- Asbestos materials existing outside the scope of the survey.**
- Materials may be concealed or hidden by other items or covered surfaces i.e. paint, over boarding, concealing etc. Where this is the case then its discovery will be limited.**
- Asbestos may well be hidden as part of the structure to a building and not visible until the structure is demolished later.**
- Fragments from previous asbestos removal projects may well be present in various areas; general asbestos fragments do not form part of this survey however all good intentions are made for its discovery.**

Where an area has been formerly stripped of asbestos i.e. plant rooms, ducts etc. and new coverings added, it must be pointed out that asbestos removal techniques have improved steadily over the years since its initial introduction. Most particularly would be the Health and Safety at Work (Asbestos) Regulations 2016, that outline enforceable strategies. Asbestos removal prior to this regulation would not be of today's standard and therefore fragments may be present beneath new coverings.

This survey will detail areas accessed and all samples taken, where an area is not covered by this survey it will be due to No Access for one reason or other i.e. working technicians, delicate location or just simply no admittance. It may have been necessary for the restrictions of the surveyor's specialist to be confirmed prior to the survey.

Admittance for the survey may be restricted for many reasons outside our control such as height, deadlines to others, steady complications or confined space. Where electrical equipment is present and presumed in the way of the survey no access will be attempted until proof of its safe state is given. Our operatives have a duty of care under the Health and Safety at Work Act (2016) for both themselves and others.

Disclaimer

In the structure where asbestos has been located and not all zones have been examined, any material that is found to be suspicious and not detailed as part of the survey should be treated with caution and sampled accordingly.

Certain materials contain asbestos to variable grades and some may be less densely contaminated at certain locations (Artex for example). Where this is the case the sample taken may not be representative of the whole product throughout, therefore composite sampling is therefore encouraged.

Where a survey is carried out under the guidance of the owner of the property or his representative, then the survey will be as per his/her instructions and supervision at that time.

Asbestos Inspection Services Limited cannot accept any liability for loss, injury, damage or penalty issues due to errors or oversights contained within this report.

Asbestos Inspection Services Limited cannot be held responsible for any damage caused as part of this survey carried out on your behalf. Due to the landscape and stipulation of sampling for asbestos some danger is inevitable and will be limited to just that necessary for the taking of the sample.

General Recommendations for Asbestos Cement Products.

Work with cement products containing asbestos is covered by the Management and Removal of Asbestos (November 2016) Approved Code of Practice.

An assessment of all proposed works which may disturb any asbestos should be carried out to launch the risk existing, the appropriate precautions must be adopted to control any exposure. This should combine the succeeding over-all principles:

- **Where work on asbestos cement is inevitable, keep the materials wet during work and avoid breakage wherever possible. Acceptable PPE must be worn always.**
- **Avoid using power tools. If deemed necessary to use power tools set at the lowest possible speed, exhaust ventilation such as cowls must be fitted to power tool and utilising the “investigation technique” with high efficiency H type vacuum units.**
- **Organise the work in a single controlled location where practicable, to streamline control and supervision. Isolate working areas using warning signs and tape barriers, or in case of significant fibre levels by means of a sealed polythene work enclosure and negative pressure equipment. Air tests must also be carried out by an independent asbestos assessor.**
- **Signify respirator zones where the Control Limit is likely to be exceeded and ensure that all persons entering the zones wear appropriate RPE/PPE are trained in its use.**
- **Ensure that those persons employed in working on asbestos cement are suitably trained in the correct working practices, control methods and anticipation of risks.**
- **Keep the work area clean during the work and use methods that abate dust creation, avoid sweeping and brushing, which will make dust airborne.**
- **Dispose of asbestos cement waste safely as Asbestos Waste under the statutory consignment note procedures in accordance with the Health and Safety at Work (Asbestos) Regulations 2016.**
- **Avoid further disturbance of asbestos cement products wherever possible by relocating or re-routing facilities.**
- **Clearly identify and label any asbestos cement products.**

General Recommendations for Asbestos Insulation, Coatings or Insulating Board (AIB)

Where the materials are in safe condition and the risk of disturbance is small, they can be maintained on site. They should be identified with adequate warning signs and routinely inspected for damages. All asbestos materials should not be drilled, abraded or disturbed in any way.

All asbestos containing materials should be removed prior to any planned refurbishment or demolition works, where damage is likely to be sustained during the occupant's activities or where future decline is likely.

Work on any of these items may only be carried out by a specialist contractor licensed under the Health & Safety at Work Act 2016. The selected contractor is required to notify the WSNZ at least 5 days prior to commencement of the works, and to provide a written Method Statement as follows:

- **Full explanation of the works to be carried out and its duration.**
- **Type, quantity and location of asbestos to be removed.**
- **Anticipated exposure levels and persons affected.**
- **Enclosure construction details, layout and location, signage and ventilation.**
- **Protections to be adopted to minimize exposure to lowest possible level and to control release of asbestos fibre beyond the work area.**
- **Validation for any withdrawal from preferred methods, e.g. where wet stripping cannot be used.**
- **Type, use and decontamination of RPE/PPE**
- **Waste removal and disposal procedures**
- **Training and instruction of employees**
- **Emergency procedures on site**

Material Assessment Methods

total risk score of between 0 and 12 is calculated using four categories that are evaluated by the surveyor against given values. The criteria and the respective values are as follows:

Product Type

- 1 Asbestos reinforced composites such as plastics, resins, mastic, roofing felt, vinyl tiles, paints and decorative finishes, asbestos cement products.
- 2 Asbestos insulation board, mill boards, other low-density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.
- 3 Thermal insulation (e.g. pipe and boiler lagging), sprayed asbestos, loose asbestos, asbestos mattresses and packing.

Condition/Extent of Damage

- 0 Good condition, no visible damage.
- 1 Low damage, a few scratches or surface marks, broken edges on boards, tiles etc.
- 2 Medium damage, significant breakage of materials or several small areas where material has been damaged, revealing loose asbestos fibres.
- 3 High damage or delamination of materials, sprays and thermal insulation. Visible asbestos debris.

Surface Treatment

- 0 Composite materials containing asbestos, such as reinforced plastics, resins, vinyl tiles.
- 1 Enclosed sprays and lagging, asbestos insulation board with exposed surface painted or encapsulated, asbestos cement products.
- 2 Unsealed asbestos insulation board or encapsulated lagging and sprays.
- 3 Unsealed lagging and sprays.

Material Assessment Methods

Asbestos Type

- 1 Chrysotile (white) asbestos.
- 2 Amosite (brown) asbestos.
- 3 Crocidolite (blue) asbestos.

The algorithms shown against each situation are added together to give a total material risk score, for conciseness, the register we have prepared contains only the total risk score rather than the component scores.

The total score for each situation can be broadly classified using the following bands:

Material Risk Score

0 - 3 Very Low Risk

4 - 6 Low Risk

7 – 9 Medium Risk

10 – 12 High Risk

It is likely that high risk items will be highlighted in the report text and that some immediate action will be required.

Other items may also be measured for consideration where the decision of the surveyor recommends this would be beneficial.

Priority Assessment Formula

A priority risk score of between 0 and 12 is calculated using four categories that are evaluated by the duty holder.

Although a surveyor may have some of the information which will contribute to the risk assessment and may be part of an assessment team, the duty holder is required to make a risk assessment based on the survey findings and their detailed knowledge of the activities carried out within the premises. The criteria and the respective values are as follows:

Normal occupant activity

Assessment factor	Score	Examples of score variables
Main type of activity in area	0	Rare disturbance activity (e.g. little used store room)
	1	Low disturbance activities (e.g. office type activity)
	2	Periodic disturbance (e.g. industrial or vehicular activity which may contact ACMs)
	3	High levels of disturbance, (e.g. fire door with asbestos insulating board)
Secondary activities for area	As above	

Priority Assessment Formula

Likelihood of disturbance

Assessment factor	Score	Examples of score variables
Location	0	Outdoors
	1	Large rooms or well-ventilated areas
	2	Rooms up to 100 m ²
	3	Confined spaces
Accessibility	0	Usually inaccessible or unlikely to be disturbed
	1	Occasionally likely to be disturbed
	2	Easily disturbed
	3	Routinely disturbed
Extent/amount	0	Small amounts or items (e.g. strings, gaskets)
	1	<10 m ² or <10 m
	2	10 m ² to 50 m ² or 10 m to 50 m
	3	>50 m ² or >50 m

Human exposure potential

Assessment factor	Score	Examples of score variables
Number of occupants	0	None
	1	1 to 3
	2	4 to 10
	3	>10
Frequency of use of area	0	Infrequent
	1	Monthly
	2	Weekly
	3	Daily
Average time area is in use	0	<1 hour
	1	1 to 3 hours
	2	3 to 6 hours
	3	>6 hours

Priority Assessment Formula

Maintenance activity

Assessment factor	Score	Examples of score variables
Type of maintenance activity	0	Minor disturbance (e.g. possibility of contact when gaining access)
	1	Low disturbance (e.g. changing light bulbs in asbestos insulating board ceiling)
	2	Medium disturbance (e.g. lifting one or two asbestos insulating board ceiling tiles to access a valve)
	3	High levels of disturbance (e.g. removing many asbestos insulating board ceiling tiles to replace a valve or for re-cabling)
Frequency of maintenance activity	0	ACM unlikely to be disturbed for maintenance
	1	≤1 per year
	2	>1 per year
	3	>1 per month

The score for each variable is determined by calculating the average score of the appropriate factors.

The algorithms shown against each section are added together to give a total priority risk score, for conciseness, the register we have prepared contains only the overall risk score rather than the component scores.

Priority Risk Score

0 - 3 Very Low Risk

4 - 6 Low Risk

7 – 9 Medium Risk

10 – 12 High Risk

Overall Hazard Risk Assessment Formulae

The material and priority assessment scores provide an overall hazard risk score for each situation which can be broadly classified using the following table:

		Material Assessment			
		10-12	7-9	5-6	1-4
Priority Assessment	10-12				
	7-9				
	4-6				
	0-3				

Key		
	High Risk	Total score = 19-24
	Medium Risk	Total score = 13-18
	Low Risk	Total score = 7-12
	Very Low Risk	Total score = 1-6

Specific Locations that may contain asbestos based material's or Presumed to Contain Asbestos Containing material's.

ID: CARD NO:001

Photograph No.	
Location/Area	External-Gable Ends
Sample No.	Presumed the presence of ACM.
Laboratory Analysis Findings	Sample not taken.
Quantity	85.0m2
Current Status/Overall score	Good Condition / Very Low Risk.
Recommended Action	Sample required for repairs work.




ID: CARD NO:002

Photograph No.	
Location/Area	External-Front Entry
Sample No.	Presumed the presence of ACM.
Laboratory Analysis Findings	Sample not taken.
Quantity	16.0m2
Current Status/Overall score	Good Condition / Very Low Risk.
Recommended Action	Sample required for repairs work.




ID: CARD NO:003

Photograph No.	
Location/Area	Physiotherapy (Floor)
Sample No.	Presumed the presence of ACM.
Laboratory Analysis Findings	Sample not taken.
Quantity	33.0m2
Current Status/Overall score	Good Condition / Very Low Risk.
Recommended Action	Sample required for repairs work.




ID: CARD NO:004

Photograph No.	
Location/Area	Community Base Storage (Floor)
Sample No.	Presumed the presence of ACM.
Laboratory Analysis Findings	Sample not taken.
Quantity	7.0m2
Current Status/Overall score	Good Condition / Very Low Risk.
Recommended Action	Sample required for repairs work.




Specific Locations that may contain asbestos based material's or Presumed to Contain Asbestos Containing material's.


ID: CARD NO:005

Photograph No.		
Location/Area	W/C toilet (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	3.0.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	


ID: CARD NO:006

Photograph No.		
Location/Area	Treatment Room (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	12.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	

ID: CARD NO:007


Photograph No.		
Location/Area	Kitchen (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	8.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	

ID: CARD NO:008


Photograph No.		
Location/Area	Switch Boards	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	4.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	

Specific Locations that may contain asbestos based material's or Presumed to Contain Asbestos Containing material's.


ID: CARD NO:009

Photograph No.		
Location/Area	Community Room 1 (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	17.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	


ID: CARD NO:010

Photograph No.		
Location/Area	Community Rooms toilet (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	8.5m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	

ID: CARD NO:011


Photograph No.		
Location/Area	Community Room 2 (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	17.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	

ID: CARD NO:012


Photograph No.		
Location/Area	Maternity 3 (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	25.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	

Specific Locations that may contain asbestos based material's or Presumed to Contain Asbestos Containing material's.


ID: CARD NO:013

Photograph No.		
Location/Area	Maternity Room 3&4 bathroom (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	10.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	


ID: CARD NO:014

Photograph No.		
Location/Area	Maternity Room 4 (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	25.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	

ID: CARD NO:015


Photograph No.		
Location/Area	Maternity Room 5 (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	25.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	

ID: CARD NO:016


Photograph No.		
Location/Area	Sluice (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	2.5m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	

Specific Locations that may contain asbestos based material's or Presumed to Contain Asbestos Containing material's.


ID: CARD NO:017

Photograph No.		
Location/Area	Lounge/Day Hospital (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	1.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	


ID: CARD NO:018

Photograph No.		
Location/Area	Maternity Bathroom (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	5.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	

ID: CARD NO:019


Photograph No.		
Location/Area	Linen (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	2.5m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	

ID: CARD NO:020


Photograph No.		
Location/Area	Cleaners (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	2.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	

Specific Locations that may contain asbestos based material's or Presumed to Contain Asbestos Containing material's.


ID: CARD NO:017

Photograph No.		
Location/Area	Staff (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	2.5m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	


ID: CARD NO:018

Photograph No.		
Location/Area	Staff toilet (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	4.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	

ID: CARD NO:019


Photograph No.		
Location/Area	Radiology (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	25.5m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	

ID: CARD NO:020


Photograph No.		
Location/Area	Radiology VR (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	10.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	

Specific Locations that may contain asbestos based material's or Presumed to Contain Asbestos Containing material's.


ID: CARD NO:017

Photograph No.		
Location/Area	Radiology DR (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	2.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	


ID: CARD NO:018

Photograph No.		
Location/Area	Radiology Waiting Rm (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	4.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	

ID: CARD NO:019

Photograph No.		
Location/Area	Files (Floor)	
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	6.5m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	

ID: CARD NO:020

Photograph No.		
Location/Area		
Sample No.	Presumed the presence of ACM.	
Laboratory Analysis Findings	Sample not taken.	
Quantity	.0m2	
Current Status/Overall score	Good Condition / Very Low Risk.	
Recommended Action	Sample required for repairs work.	



Inspection Record

Enter site name

Date	Print Name	Signature	Company Name	Phone Number



Survey Record Sheet

Ref: WDHB

Site Address: Waimarino Health Centre, Raetihi

Date: 19/03/18

Survey Type:

Management Survey

ID Card No	Photo No	Location/Area Description	Sample Ref /Presumed	Quantity	Product Description	Asbestos Type	Product Type	Condition	Surface Treatment	Asbestos Type	Material Risk Score	Normal Occupant Activity	Likelihood of Disturbance	Human Exposure Potential	Maintenance Activity	Priority Risk Score	Overall Risk Score	Action
001		External-Gable End	Presumed	85.0m2	Gable lining board	Compressed board	1	0	0	1	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
002		External-Front Entry	Presumed	16.0m2	Soffit lining board	Compressed board	1	0	0	1	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
003		Internal-Physiotherapy (Floor)	Presumed	33.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
004		Internal-Community Base Storage (Floor)	Presumed	7.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
005		Internal-W/C toilet (Floor)	Presumed	3.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
006		Internal-Treatment Room (Floor)	Presumed	12.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
007		Internal-Kitchen (Floor)	Presumed	8.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
008		Internal-Switch board	Presumed	4.0m2	Suspect backing board	Compressed board	1	0	0	1	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
009		Internal-Community Room 1 (Floor)	Presumed	17.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
010		Internal-Community Room 1 (Floor)	Presumed	8.5m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.



Survey Record Sheet

Ref: WDHB

Site Address: Waimarino Health Centre, Raetihi

Date: 19/03/18

Survey Type:

Management Survey

ID Card No	Photo No	Location/Area Description	Sample Ref /Presumed	Quantity	Product Description	Asbestos Type	Product Type	Condition	Surface Treatment	Asbestos Type	Material Risk Score	Normal Occupant Activity	Likelihood of Disturbance	Human Exposure Potential	Maintenance Activity	Priority Risk Score	Overall Risk Score	Action	
011		Internal-Community Room (Floor)	Presumed	17.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
012		Internal-Maternity 3 (Floor)	Presumed	25.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
013		Internal-Maternity 3&4 Bathroom (Floor)	Presumed	10.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
014		Internal-Maternity 4 (Floor)	Presumed	25.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
015		Internal-Maternity 5 (Floor)	Presumed	25.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
016		Internal-Sluice (Floor)	Presumed	2.5m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
017		Internal-Lounge/Day Hospital (Floor)	Presumed	1.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
018		Internal-Linen (Floor)	Presumed	2.5m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
019		Internal-Cleaners (Floor)	Presumed	2.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
020		Internal-Maternity Bathroom (Floor)	Presumed	5.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.



Survey Record Sheet

Ref: WDHB


Site Address: Waimarino Health Centre, Raetihi

Date: 19/03/18

Survey Type:

Management Survey

ID Card No	Photo No	Location/Area Description	Sample Ref /Presumed	Quantity	Product Description	Asbestos Type	Product Type	Condition	Surface Treatment	Asbestos Type	Material Risk Score	Normal Occupant Activity	Likelihood of Disturbance	Human Exposure Potential	Maintenance Activity	Priority Risk Score	Overall Risk Score	Action
021		Internal-Staff (Floor)	Presumed	2.5m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
022		Internal Staff toilet (Floor)	Presumed	4.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
023		Internal-Radiology (Floor)	Presumed	25.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
024		Internal-Radiology VR (Floor)	Presumed	10.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
025		Internal-Radiology DR (Floor)	Presumed	2.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
026		Internal-Radiology Waiting Rm (Floor)	Presumed	4.0m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
027		Internal-Files (Floor)	Presumed	6.5m2	Suspect vinyl or backing	Vinyl resin	1	0	0	1	0	0	0	0	0	0	1	Sample analysis for repairs works essential before commencing proposed works activity.
028																		



DRILL HOLE PLAN

WARRANTING SUBMIT