



INTRODUCTION

This report has been prepared by the Institute of Geological and Nuclear Sciences Limited (GNS Science) by collaborative arrangement with the Department of Conservation (DoC). The work was undertaken as part of GNS Science's FRST research into the age and genesis of landslides in Fiordland. DoC contributed logistic support (helicopter and accommodation) during visits to Mintaro Hut in 2009, and provided current data on the hut site, including a report by consultant geologist Royden Thomson^{8*} on rock falls that occurred near the hut site during a M_L 6.7 earthquake on 16 October 2007.

One of the authors (G Hancox) carried out a *Baseline Geological Inspection* of Mintaro Hut on the Milford Track for DoC in April 2000³ which identified a potential rock fall hazard at the site. Earthquake-induced rock fall activity near the hut in 2007, and greater knowledge of landslides in Fiordland from GNS Science research over the last nine years, suggested that the rock fall hazard at Mintaro Hut is greater than previously thought, and should be reassessed using a qualitative risk assessment approach. The revised methodology was developed for DoC in 2008 for evaluating geological hazards and risk at DoC backcountry hut and camp sites⁵.

The need for a reassessment of landslide hazards at Mintaro Hut was supported by Ross Kerr (Programme Manager Visitor Assets, DoC Te Anau Area Office), who approved helicopter landing at the site on the Milford Track. He also arranged for assistance from the resident Hut Ranger during the visit by the authors in April 2009, and accommodation at the hut in October 2009. This report provides the results of those visits, and includes dendrochronology evidence used to determine the age of old rock fall deposits at the site, which was an essential part of the risk assessment. The report is intended to advise and assist DoC in managing Mintaro Hut and advising the public and hut users on geological hazards at the site. The format used is the *Standard DoC Form* for reporting on geological inspections of DoC hut sites.

The report describes the geology, geomorphic setting, and geological hazards at the Mintaro Hut site in the upper Clinton valley. The estimated likelihood and consequences of these hazards are then used in a *qualitative risk analysis* to assess the *risk* of each hazard to the hut and hut users. The assessed risk and management options for geological hazards at the hut site are discussed, and where necessary recommendations are made to reduce risk at the site to an acceptable level, including the option of moving the hut to a new location.

Note: References used in the report are indicated by superscript numbers and are listed in Section C11.

DISCLAIMER

This report has been prepared by the Institute of Geological and Nuclear Sciences Limited (GNS Science) in collaboration with and for use by the Department of Conservation. GNS Science accepts no responsibility for any use of, or reliance on any contents of this Report by any person or organization other than the Department of Conservation and shall not be liable to any person or organization other than the Department of Conservation, on any ground, for any loss, damage or expense arising from such use or reliance.

GEOLOGICAL INSPECTION REPORT

Page 1 of 16

A. SITE DATA


A1. SITE: Mintaro Hut	GRID REF: E 2097 478, N 5586 715	ALTITUDE: c. 620 m	BUILT: 1 Jan 1985
A2. LOCATION: Upper Clinton valley, Milford Track (Clinton Hut to Mackinnon Pass Section)			

B. GEOLOGICAL INSPECTION AND HAZARD ASSESSMENT

B1. GEOLOGICAL INSPECTION BY: G Hancox, N Perrin, 2 April; 29-30 Oct 2009	REPORT 22 July 2010
B2. PREVIOUS INSPECTIONS: G Hancox, 11 April 2000; R Thomson, 7 December 2007.	
B3. REFERENCES <u>Hancox, G.</u> , 2000: Baseline Inspection Report on Mintaro Hut. <i>GNS Hut Site Report</i> . ³ <u>Thomson, R.</u> , 2008: Seismic Impact on the Milford Track: Report on rockfall inspections 7 Dec 2007. ⁸ (see Section C11 for full list of references used in the report)	

C. REPORT**C.1. SITE DESCRIPTION****C1.1 LOCATION:**

Mintaro Hut is located at an altitude of c.620 m on the south (true right) side of the upper Clinton valley, on the Milford Track between Clinton Hut and Mackinnon Pass. The hut site is on a bush-covered knoll about 15 m above the level of the track, well above the Clinton River and Lake Mintaro (see *Location Map*).



SITE LOCATION MAP (1:50,000 – D41)

C1.2 TOPOGRAPHY:

The hut is sited on a mound of old rock fall debris overlooking Lake Mintaro, a small (c.200 m long) landslide and fan-dammed lake in the head of the Clinton valley. The site is bush-covered and is relatively flat, with abundant boulders apparent on the ground surface. About 50 m southwest of the hut the valley slope (*'Mintaro Ridge'*⁸) rises steeply (45-65°) to an elevation of c.1250 m up the glaciated rock wall of the Clinton valley. The slope below the hut falls gently c.20 m to the broad valley bottom and the partly infilled Lake Mintaro (see *site photos*).

C1.3 SITE EXPOSURE:

The site is in dense bush in the valley floor and is relatively sheltered.

C1.4 VEGETATION:

Mature Fiordland rain forest (silver beech) and sub-alpine scrub.

C1.5 FLOODING HAZARD:

Very low - hut is about 20 m above the Clinton River and Lake Mintaro.

C1.6 OTHER COMMENTS:

Several snow avalanche paths are present in the area (see *Site Map 2*)⁶.

Rock fall activity in the vicinity of Mintaro Hut (in gully c 400 m southwest of hut) was reported by DoC staff to have occurred during the 16 October 2007, M_L 6.7 earthquake. GNS Science (GeoNet) reported that the earthquake was located 60 km west of Milford Sound (approx. 50 km WNW of Mintaro Hut). The Modified Mercalli (MM) shaking intensity in the Milford Sound–Mintaro Hut area was estimated to be MM 6–7 (see *Appendix 3*). The maximum MM intensity reported was MM 7 in the Hollyford valley. Rock fall effects caused by the earthquake in the vicinity of Mintaro Hut were inspected by Royden Thomson for DoC on 7 December 2007⁸.


Note:

This report should be used with reference to the "Revised Geological Hazard and Risk Assessment Method for DoC Backcountry Hut Sites and Camp Sites". GNS Science Consultancy Report 2008/256⁵.

C2. SITE DESCRIPTION




Site Photo. Aerial view of Mintaro Hut in the upper Clinton Valley. The hut is sited at the foot of Mintaro Ridge on a mound of old rock fall debris which has dammed the Clinton River to form Lake Mintaro, which is now partly infilled. The line of the site Cross Section (NE-SW, below) is also shown.




Site Cross Section. Topographic cross section of the hut site showing Mintaro Hut in relation to the slope above and across-valley from the hut site. The slope behind the hut rises steeply from elevation 750–1150 m, with an average slope of about 60°. A potential rock fall source (PRS) is located at the top of the steepest section of the slope directly above the hut.

SITE MAP 1. Geomorphic map of hut site area



Site Map 1. Geomorphic map of Mintaro Hut site showing old and recent rock fall deposits, rock fall paths, October 2007 rock fall sources, and the possible source of a future large rock fall at the hut site. The volume of the older rock fall deposits on which the hut is located (inside the dashed red line) is about ~650,000 m³.

SITE MAP 2. Snow Avalanche Paths in the Mintaro Hut area



Site Map 2. Map showing snow avalanche paths along the Milford Track in the upper Clinton valley⁶. Avalanches may carry rock, soil and vegetation, and build debris fans (track location shown is incorrect – see Site Map 1).

C3. SITE PHOTOS




Photo 1. Aerial view of Mintaro Hut sited on old rock fall debris (yellow triangles) on the south side of the upper Clinton valley. The old rock fall deposits at the hut site include angular boulders 1–6 m across, on which ~170 year old beech trees are growing. About 100 m southwest (upstream) of the hut is an area of younger, scrub-covered rock fall debris, built up at the base of the slope by periodic rock falls down paths (YRP) on the northwest side of Mintaro Ridge. These falls did not reach the hut site. The October 2007 earthquake triggered several small rock falls near the crest the ridge (scars outlined in red). Debris from these and other recent rock falls has accumulated at the apex of the debris fan, c.400 m southwest of the hut. Rock at the top of the ridge directly above the hut is well jointed, with areas of relaxed open-jointed rock (OJ), and is a potential source of a future large rock fall at the site (PRS), particularly during a large (M7.5 or >) earthquake. The Mintaro avalanche path⁶ c.650 upstream (right) of the hut, does not affect the site.

C3. SITE PHOTOS (contd.)




Photo 2. Aerial view of Mintaro Hut site in the head of the Clinton valley, and Mackinnon Pass 1.5 km to the northwest. An area of steep, jointed rock on the northern end of Mintaro Ridge is a potential source of a large rock falls (*PRS*) that could affect Mintaro Hut in the foreseeable future (next 50 years). The hut is founded on bush covered old rock fall debris, which last fell from that (*PRS*) part of the ridge possibly c. 200 years ago.




Photo 3. Closer view of Mintaro Hut (*H*). The old, bush covered rock fall debris (*od*) includes 1-6 m boulders, which are scattered around the site. Other features to note are younger, scrub-covered, rock fall deposits (*yd*); recent (c.1990-2007) rock fall debris (*rd*), and an active rock fall path (*rp*) about 250 m downstream. The partly-infilled Lake Mintaro was formed by blockage of the Clinton River by rock fall debris and a large debris fan (*lower right*).

C3. SITE PHOTOS (contd.)




Photo 4. Aerial view of an area of well jointed rock on the ridge 400-500 m above Mintaro Hut, which was the source of rock fall debris on which the hut is built, and is the likely source of future large rock falls at the site. Scars of older wedge failures are still visible (os), as are the source-scars of the October 2007 rock falls (RS). The glaciated rock mass to the right is more massive and has few failure scars.




Photo 5. Closer view of the jointed rock on the ridge above Mintaro Hut showing scars of older failures (os), one large area of opened jointed rock (oj), and source-scars (RS) and paths (rp) of the October 2007 rock falls.

C3. SITE PHOTOS (contd.)




Photo 6. Aerial view of two prominent areas of open-jointed rock (OJ) on the ridge about 500 m above Mintaro Hut. This photo was taken in April 2000. Both of these sites survived the October 2007 earthquake, although one small (~1 m) block was dislodged from the upper site. The vertical extent of the lower site is estimated to be at least 15-20 m. The approximate locations of two of the 2007 rock fall source-scars are also shown (sites 1 and 2).




Photo 7. Close up view of the area behind Mintaro Hut (H) showing a large (6 x 4 x 3 m) boulder (b) 17 m from the hut. There are also many other 1–2 m boulders scattered around the hut site. A silver beech tree about 500 mm in diameter is growing on the boulder. Coring of a nearby beech tree 560 mm in diameter showed the tree to be c.165 years old. Assuming there was a forest regrowth time lag of c.20 years, the last large fall rock fall to reach the hut site occurred possibly 180-200 years ago.



Photo 8. Silver beech tree growing on a rock fall boulder on the Milford Track, 25 m north of Mintaro Hut. This tree is slightly smaller and younger (~83 years old, see Appendix 4) than the tree which was cored (see Photo 9).

C3. SITE PHOTOS (contd.)




Photo 9. This photo shows the 560 mm diameter silver beech tree (*t1*) behind Mintaro Hut. Coring of this tree with an incremental tree corer (*tc*) showed that it is about 165 years old. The large rock fall boulder (*b*) to the left of the cored tree has a beech tree (*t2*) of similar size and age growing on it. This indicates that the last rock fall to reach the hut site could have occurred about 180-200 years ago.



Photo 10. The tree shown here is one of a number of larger (c.1 m diameter), c.325 year old beech trees growing on older rock fall debris around the hut site. This particular tree, which is on the Milford Track about 20 from the hut, was knocked over and tilted by a 1.5 m boulder (out of picture to the left), after which it continued to grow sub-vertically. This suggests there has been a succession of large rock falls on to the Mintaro Hut site in the last few hundred years. The last large rock fall in the hut site area occurred possibly about 183 years ago, during the 1826 Fiordland earthquake (~M 8-8.5)¹.

C4. SITE GEOLOGY

Mintaro Hut is sited on a knoll of old rock fall debris derived from a very steep (45-65°) ridge (Mintaro Ridge) on the south wall of the Clinton valley, immediately behind (southwest) of the hut (see *Site Maps and Photos*). Based on the GNS 1:250,000 Geological Map 18⁹, bedrock in the Mintaro Hut site area is *granitic orthogneiss*. The rock is unweathered and very strong, but is weakly foliated, and has well developed joint sets. On the Mintaro Ridge above 900 m (elevation) the joints are steep to sub-vertical, closely spaced (about 0.5-1 m), and persistent over c.5-10 m or more. Some of the joints are open and show signs of rock mass dilation (see *Photo 6*).

The coarse rock fall debris on which the hut is built is estimated to be at least ~20 m thick, and includes angular gravel with boulders from 1 to 6 m across (*Photos 7 and 9*). The rock fall debris covers an area of c.120,000 m², and has an estimated volume of about 650,000 m³. Rock fall debris and a large debris fan formed by the stream draining the south face of Mt Balloon has blocked the Clinton River to form *Lake Mintaro*, which is now partly infilled with glacial and alluvial sediments (*Photo 3*).

The rock fall deposit which the hut is sited on is inferred to have accumulated in the Clinton valley bottom over the last 10,000-12,000 years, since the end of the last glaciation. Silver beech forest on the older rock fall deposits includes trees up to ~600 mm diameter growing on boulders near the hut. Incremental tree coring has shown that these beech trees are approximately 165-180 years old (see *Appendix 4*). This suggests that the last large fall rock fall at the site occurred at least 180-200 years ago, possibly during the ~M 8 Fiordland earthquake of 1826¹. There are also some ~1– 1.2 m diameter* (~300-400 year old) beech trees growing on older rock fall debris near the hut (*Photo 10*), which may have been deposited during the last (1717) Alpine Fault earthquake about 300 years ago^{10, 11}.

Scrub-covered rock fall debris c. 80 m southwest of the hut (*Site Map 1*) suggests there have been periodic smaller rock falls in the area which prevented establishment of beech forest, but did not reach the hut site. No rock fall trails are apparent in beech forest near the site.

* Tree diameter at breast height (standard measurement point).

C5. SITE and FOUNDATION STABILITY

The foundation material at Mintaro Hut is old, bush covered rock fall debris – angular gravel and large angular boulders of orthogneiss, which provides a stable, well drained foundation for the hut. No foundation stability or erosion problems are present at the site.

C6. GEOLOGICAL HAZARDS – Summary (for details refer to Section C8, C9, and Appendices 1, 2, and 3.

Mintaro Hut is potentially exposed to a range of geological hazards, and it has been assigned an overall geological hazard rating of *Moderate (14)*, based on the all types of geological hazards, which are listed and rated in *Appendix 1*. The foundation material (coarse angular gravel and boulders) provides a stable foundation for the hut, and because of its elevated position 20 m above the valley floor it is not exposed to erosion, flooding or debris flow hazards, for which low ratings (0 -1) are assigned. However, the hut is sited on an old rock fall deposit, below a very steep, high slope, and is directly in the rock fall hazard zone if future large rock falls occur, especially during strong earthquake, for which the maximum possible hazard ratings (5) are assigned. The all-hazard rating (*Moderate*) of the site is potentially misleading as it tends to downplay the significant hazard and risk presented by future earthquake-triggered rock falls at the site. Therefore, for the evaluation of geological hazards and risk at Mintaro Hut greater reliance is placed on the qualitative rock fall risk assessment presented in Section C8 and Appendix 2.

The 16 October 2007, M_L 6.7 earthquake (locally MM 6-7) caused small rock falls (c.1-2 m³, in total possibly 5 –10 m³) in gullies 200-400 m from the hut (see *Site Map 1 and Photo 1*). No rock falls appear to have reached the hut site in the last ~180–200 years, based on tree-ring dating. However, jointed rock on the ridge above the hut is a potential source of future large rock falls (possibly c.1000 –10,000 m³ or >) that could affect the hut, given a suitable trigger, such as a nearby ~M 7.5 or > earthquake. The estimated volume (c. 650,000 m³) of old rock fall debris suggests there have been many such earthquake-induced rock falls at this site in the last 10,000 years, and they will continue to occur in the future. Rainfall induced landslides, typically shallow slides and flows, have not affected the site in the past and, mainly because of the geomorphic features at the site, are unlikely to in the future.

Qualitative ratings of the *risk from geological hazards at Mintaro Hut (Section C8 and Appendix 2)* are assessed to range from *Very Low to High to Very High*. The hut site should be inspected by an engineering geologist when future small rock fall occur (*Priority 4*).

The major hazard at the site is from a future large rock fall (c.1000 m³ or greater, with 1–6 m boulders) triggered by an Alpine Fault earthquake (the probability of this event in the next 50 years is potentially as high as ~30%)^{7, 11}, or a large subduction zone earthquake, as occurred in 1826. Because a large rock fall at the site is likely to cause substantial damage to the hut and probably loss of life, the *risk* from such an event is considered to be *High to Very High*.

Because of the very steep, inaccessible terrain at the site, slope stabilisation or rock fall protection measures to reduce the potential risk from earthquake triggered rock falls at Mintaro Hut are likely to be impractical. It is therefore recommended that DoC give consideration to moving the hut to a lower risk location as soon as reasonably practicable [*Priority 2*].

C7. SITE MONITORING

No instrumental or survey monitoring is necessary at Mintaro Hut. However, the site is prone to periodic rock fall activity, and DoC should keep a record of future rock falls that occur at or near the hut site. Any new rock fall activity should be evaluated by an engineering geologist. The condition of the jointed rock mass on the ridge directly above the hut should also be inspected (by helicopter). [*Priority 4: moderate significance - should be attended to when such events occur.*]

C8. QUALITATIVE RISK ASSESSMENT SUMMARY (Refer to Appendix 2 for risk criteria and definitions)

Hazard Type	Likelihood ¹	Consequences	Risk Level	Comments and Risk Management Options
1. Small rock falls (~1-10 m ³) ² - as have occurred at the site in the last few years.	Almost certain RP: 1-10 yrs AEP: 95-10 %	Insignificant	Very Low to Low	The risk from small rock falls (like those during the October 2007 earthquake) is acceptable because such falls do not reach the hut. Smaller rock falls tend to be channeled down gullies away (upstream or downstream) from the hut. However, the site and rock fall source areas should be inspected by an engineering geologist after such events in the future. The risk is <i>acceptable</i> with this management measure.
2. Small to moderate rock falls (~10 – 10 ² m ³ , with 1-2 m boulders)	Likely RP: 10-100 yrs AEP: 10-1.0 %	Insignificant	Low	Areas of 'younger' scrub-covered, rock fall debris near the hut suggest that small to moderate rock falls have occurred near the hut site periodically over the last few hundred years (probably during strong earthquakes), preventing growth of beech forest. Debris from such falls has travelled mainly down gullies away from the hut, and has not come to within c.80-100 m of the site. In addition, beech trees around the hut provide effective protection from smaller boulders (c.0.5-1 m), preventing them from reaching the hut. For these reasons the level of risk for <i>small to moderate rock falls</i> is thought to be <i>acceptable</i> .
3. Large earthquake-induced rock falls (~10 ³ m ³ or >, with 1-6 m boulders)	Possible RP: 100-1000 yrs AEP: 1.0-0.1 %	Major to Catastrophic	High to Very High	Geological and geomorphic evidence shows there is potential in the future for a large rock fall at the hut site (c.1000 m ³ or >, with 1-6 m boulders) especially during a large earthquake (≥ M 7.5-8.0; MM9-10) on the Alpine Fault or the Fiordland Subduction Zone. Earthquake-induced landslides typically affect high, steep slopes and ridges, where shaking effects are amplified ^{2,4} . There is a relatively high probability (up to ~30%) of an Alpine Fault earthquake in the next 50 years ^{7,11} . The <i>consequences</i> of large rock fall would be <i>major to catastrophic (damage and loss of life expected)</i> , and the <i>risk</i> of such an event is assessed as <i>High to Very High</i> . Treatment options to reduce risk at the site to an acceptable level are probably impractical, and this probably means that the hut should be moved to a new site.
4. Rainfall-induced Landslides	Almost certain RP: 1-10 yrs AEP: 95-10 %	Insignificant	Very Low to Low	Although rainfall-induced landslides (typically shallow slides and flows) occur frequently, there is no evidence of such failures in the immediate hut site area. The risk from such events is therefore <i>acceptable</i> .
5. Foundation failure	Rare (0.02-0.01 %)	Minor	Very Low	The materials on which the hut are built are not prone to collapse or erosion given the existing site conditions. Risk <i>acceptable</i> .
6. Flooding, debris flows	Inconceivable (< 0.01 %)	Insignificant	Very Low	The elevated hut site is well above river level and there are no tributary streams close to the hut. Risk <i>acceptable</i> .
7. Snow avalanches (associated rock and debris flows)	Unlikely RP: ~1000-5000 yrs AEP: ~0.10-0.02 %	Insignificant	Very Low	The closest known avalanche path (Mintaro - RP 20yrs) ⁶ does not affect the hut site. There is no known snow avalanche activity at the site. Risk <i>acceptable</i> .

Notes and additional comments:

- Likelihood (%) estimates are given as the approximate Return Periods (RP) and the annual probability, or and Annual Exceedance Probability (AEP)- Appendix 2⁵.
- The terms used to describe the relative size landslides and rock falls apply only in the context of this report. In most instances the terms used are qualified by an approximate landslide volume (m³). The volumetric estimates can be used to compare the size of rock falls listed above with terms used for the much greater range of landslide sizes in Appendix 3.
- References ^{2, 4, 5, 6 (etc)} are listed in Section C11.

C10. CONCLUSIONS and RECOMMENDATIONS

1. Mintaro Hut is sited on a knoll of old rock fall debris on the south side of the upper Clinton valley. Foundation material at the site is compact angular gravel and boulders, which is thought to be stable and resistant to erosion and collapse.
2. The hut site is potentially exposed to a range of geological hazards, and has been assigned an overall *Geological Hazard Rating of Moderate*, mainly because of the hut's location within a rock fall hazard zone, and the possible effects of a future large earthquake in the area.
3. The existing evidence suggests that rock falls from the ridge above Mintaro Hut large enough to reach the hut site (possibly 1000 m³ with boulders up to 6 m across) may occur every 100-200 years. The last rock falls to reach the site were probably triggered by earthquake shaking of MM8-9 or > (*Appendix 3*), which probably last occurred during the 1826 Fjordland Subduction Zone earthquake, and before that the 1717 Alpine Fault earthquake. Shaking of similar intensity (~MM8-9) in the future is expected to trigger further large rock falls at the site. The consequences of such an event could be catastrophic.
4. *Qualitative ratings of risk* posed by geological hazard at Mintaro Hut range from *Low to Very Low* for small and moderate sized rock falls, to *High to Very High* for a future large rock fall triggered by an Alpine Fault earthquake, or possibly a large subduction zone earthquake similar to the 1826 earthquake. Such a rock fall is likely to cause substantial damage to the hut and probably loss of life.
5. Because mitigation measures to reduce the risk from rock falls at Mintaro Hut to an acceptable level appear to be impractical, it is recommended that consideration should be given to moving the hut to a lower risk location as soon as reasonably practicable [*Priority 2*].

C11. REFERENCES

1. Downes, G. Cochran, U., Wallace, L, Reyners, M., Berryman, K., Walters, R., Callaghan, F., Barnes, P., Bell, R., 2005. Understanding local source tsunamis: 1820 Southland tsunamis. EQC Project 03/490. *GNS Science Client Report 2005/153*.
2. Hancox G.T., Perrin N.D., Dellow G.D., 1997. Earthquake-induced landsliding in New Zealand and implications for MM intensity and seismic hazard assessment. *GNS Client Report 43601B. 106 p.*
3. Hancox, G.T., 2000. Baseline Inspection Report on Mintaro Hut. GNS Hut Site Report. *GNS Science Baseline Geological Inspections of DoC Hut Sites, 11 April 2000*.
4. Hancox G.T., Perrin N.D., Dellow G.D., 2002. Recent studies of historical earthquake-induced landsliding, ground damage, and MM intensity in New Zealand. *Bulletin of the New Zealand Society for Earthquake Engineering 35(2): 59-95*.
5. Hancox, G.T., 2008. Revised Geological Hazard and Risk Assessment Method for DoC Backcountry Hut Sites and Camp Sites. *GNS Science Consultancy Report 2008/256, 16 October 2008*.
6. Owens, I.F., Fitzharris, R.R., 1985. Avalanche Atlas of the Milford Track and Assessment of the Hazard to Walkers. *NZ Mountain Safety Council, Avalanche Report No 8, November 1985*.
7. Rhoades, D.A., Van Dissen, R.J., 2003. Estimates of the time-varying hazard of rupture of the Alpine Fault, New Zealand, allowing for uncertainties. *New Zealand Journal of Geology and Geophysics 46, 479-488*.
8. Thomson, R., 2008. Seismic Impact on the Milford Track: Report on rock fall inspections 7 Dec 2007. *Consultancy report prepared for DoC Te Anau, January 2008*.
9. Turnbull, I.M., (compiler) 2000. Geology of the Wakatipu area. *Institute of Geological and Nuclear Sciences 1:250,000 Map 18*.
10. Wells, A., Yetton, M.D., Duncan, R.P., Stewart, G.H., 1999. Prehistoric dates of the most recent Alpine Fault earthquakes, New Zealand. *Geology, November 1999, Vol. No. 11, pp. 995-998*.
11. Biasi, G., Clark, K., Berryman, K., Cochran, U., Prior, C. 2010. Dating informed correlations and large earthquake recurrence at the Hokuri Creek paleoseismic, Alpine Fault, New Zealand. *Proceedings AGU Fall Meeting, 13-17, December 2010, San Francisco, Abstract T41C-08*.

Acknowledgements

The authors wish to thank their GNS Science Colleagues Grant Dellow and Chris Massey for reviewing this report, and also Ross Kerr (DoC Te Anau) for arranging access and accommodation at Mintaro Hut during our field work for this study. We also wish to thank Royden Thomson for providing information from his aerial inspection of the hut site following the 2007 earthquake.

Geological Inspection for: Mintaro Hut

Page 13 of 16

APPENDIX 1a: Geological Hazard Rating

Geological Hazard Rating is used to indicate the significance of a number of geological hazards (such as geologic and topographic site conditions, slope failure, seismicity, flooding, seiches and volcanic activity) at DoC Hut and Camp Sites. At specific sites, each hazard factor is subjectively assigned a **factor value** ranging from 0-5 (least to most hazardous), based on the site inspection, monitoring, history, and other relevant data. An overall **Geological Hazard Rating** (index) for the site is assigned by summing the factor values.

GEOLOGICAL HAZARD FACTORS (Place X in appropriate cell to indicate Factor Values)	FACTOR VALUE					
	0	1	2	3	4	5
1. Slope angle and local topographic effects at site			X			
2. Site geology and foundation materials		X				
3. Proximity to steep slope below site	X					
4. Hazard from slopes above site (rock and debris fall, avalanche, slide)						X
5. Foundation failure (none, possible, incipient, active)	X					
6. Earthquake effects (topographic-enhanced shaking, slope failure)						X
7. Heavy rainfall, flooding, erosion, debris flows/floods etc.	X					
8. Other (snow avalanches; faulting)		X				
Sum of Hazard Factor Values:	14					
GEOLOGICAL HAZARD RATING FOR: Mintaro Hut	14 (Moderate)					
TOTAL FACTOR VALUES FOR GEOLOGICAL HAZARD RATINGS:						
Very low: 0-5 Low: 6-12 Moderate: 13-18 High: 19-24 Very High: 25 or greater						

APPENDIX 1b: Priority Ratings For Recommendations:

The following **Priority Ratings** are used for rating Recommendations given in this report for mitigating geological hazards at DoC hut sites and camp sites. They are mainly based on the Geological Hazard Rating and Risk Level at a site, and indicate the time frame within which the recommendation should be attended to. Specific time frames for responding to unacceptable risk from any hazard should be specified in the Qualitative Risk Assessment (C8).

Priority 1: Recommendation of **very great significance** and **URGENT**, at a site where there is Very High geological hazard (Rating >25) or **Very High Risk** from one or more hazard. Should be attended to immediately.

Priority 2: Recommendation of **great significance**, at a site where there is High geological hazard rating or **High Risk** from one or more hazard. Should be attended to, as far as reasonably practicable, within next 12-18 months.

Priority 3: Recommendation of **considerable significance**, at a site where there is Moderate geological hazard (Rating 13-18), or **Moderate Risk** from one or more hazard. Should be attended to as far as reasonably practicable, within the next three years.

Priority 4: Recommendation of **moderate significance**, at a site where there is Low to Moderate geological hazard (Rating 6-18) or **Moderate to Low Risk** from one or more hazards. Should be attended to, as far as reasonably practicable, within the next five years.

Priority 5: Recommendation of **some significance**, at a site where there is low or very low geological hazard, or **Low Risk** or **Very Low Risk** from a hazard. Should be attended to within the next ten years.

APPENDIX 2: Qualitative Geological Hazard And Risk Assessment (see C8 and C9)**1- Qualitative Measures of Likelihood of Hazard Events**

Level	Descriptor	Description ¹	Indicative Probability ² (Return Period)	Annual Probability ² (%)
A	ALMOSTCERTAIN	The event is ongoing, or expected to occur (in next 50 years)	1–10 years	c. 95 – 10
B	LIKELY	The event is expected to occur under adverse conditions.	10–100 years	10 – 1.0
C	POSSIBLE	The event could occur under adverse conditions.	100–1000 years	1.0 – 0.10
D	UNLIKELY	The event might occur under very adverse conditions.	1,000–5,000 years	0.10 – 0.02
E	RARE	The event could occur under extreme conditions.	5,000–10,000 years	0.02 – 0.01
F	INCONCEIVABLE	The event is inconceivable under present conditions.	>10,000 years	< 0.01

Notes^{1,2}: 1. Descriptions define in words the likelihood of a hazard event occurring and impacting on a structure, house, hut site or camp site.

2. Probabilities are approximate and may vary depending on hazard types, site history, and period of concern –in this case the next 50 years.

2 - Qualitative Measures of Consequences to Property and People from Hazard Events

Level	Descriptor	Description ¹
1	CATASTROPHIC	Structure completely destroyed or large scale damage requiring engineering works for stabilisation. Fatalities and severe injuries are likely.
2	MAJOR	Extensive damage to most of structure, or extending beyond site boundaries requiring significant stabilisation works. Severe injuries to people and some fatalities possible.
3	MEDIUM	Moderate damage to some of structure, or significant part of site requiring stabilisation works. Injuries requiring medical treatment, hospitalisation; fatalities unlikely.
4	MINOR	Limited damage to part of structure or part of site requiring some reinstatement or stabilisation works. Minor injuries, without hospitalisation.
5	INSIGNIFICANT	Little damage. No injuries.

Note: 1. Examples of possible consequences are given as a general guide, and can be adapted to suit particular cases or sites.

3 - Qualitative Risk Analysis Matrix – Level of Risk to Property and People from Hazard Events

LIKELIHOOD	CONSEQUENCES to PROPERTY and PEOPLE				
	1: CATASTROPHIC	2: MAJOR	3: MEDIUM	4: MINOR	5: INSIGNIFICANT
A – ALMOST CERTAIN	VH	VH	H	M	L
B – LIKELY	VH	VH	H	M	L
C – POSSIBLE	VH	H	M	L	VL
D – UNLIKELY	H	M	L	L	VL
E – RARE	M	L	L	VL	VL
F – INCONCEIVABLE	L	VL	VL	VL	VL

4 - Risk Level Implications for Hazard Events

Risk Level	Implications and Response ⁽¹⁾	
VH	VERY HIGH RISK	Investigation, planning and implementation of treatment options essential to reduce risk to an acceptable level. This may be too expensive or not practical, and may require moving to a new site.
H	HIGH RISK	Investigation, planning and implementation of treatment options required to reduce risk to an acceptable level. May be too expensive or impractical, and require moving to a new site.
M	MODERATE RISK	Tolerable provided treatment plan is implemented to maintain or reduce risks. May be accepted, but requires investigation and planning of hazard mitigation measures.
L	LOW RISK	Usually acceptable. Some minor treatment options may need to be defined to maintain or reduce risk.
VL	VERY LOW RISK	Acceptable. Manage by normal inspection and monitoring procedures.

Notes: (1) The implications for a particular situation should be determined by all parties to the risk assessment; those given above are as a general guide only.

(2) Use of dual descriptors for Likelihood, Consequence and Risk to reflect uncertainty of the estimate may be appropriate in some cases.

Criteria for Qualitative Risk Assessment of landslides and geological hazards at DoC Hut Sites and Camp Sites.
(after Australian Geomechanics Society, 2000: Landslide Risk Management and Guidelines, Appendix G. Australian Geomechanics, 35 (1) 49–92.)

APPENDIX 3. Modified Mercalli (MM) Intensity Scale – Landslides and Environmental Criteria ⁽⁴⁾

- MM 6**
- Trees and bushes shake, or are heard to rustle. Loose material dislodged on some slopes, e.g. existing slides talus and scree slope.
 - A few very small (<10³ m³) soil and regolith slides and rock falls from steep banks and cuts.
 - A few minor cases of liquefaction (sand boil) in highly susceptible alluvial and estuarine deposits.

- MM 7**
- Water made turbid by stirred up mud.
 - Very small (<10³ m³) disrupted soil slides and falls of sand and gravel banks, and small rock falls from steep slopes and cuttings common.
 - Fine cracking on some slopes and ridge crests.
 - A few small to moderate landslides (10³–10⁵ m³), soil/rock falls on steep slopes (>30°) on coastal cliffs, gorges, road cuts/excavations etc.
 - Small discontinuous areas of minor shallow sliding and mobilisation of scree slopes in places. Minor to widespread small failures in road cuts in more susceptible materials.
 - A few instances of non-damaging liquefaction (small water and sand ejections) in alluvium.

- MM 8**
- Cracks appear on steep slopes and in wet ground.
 - Significant landsliding likely in susceptible areas.
 - Small to moderate (10³-10⁵ m³) slides widespread; many rock and disrupted soil falls on steeper slopes (terrace edges, gorges, cliffs, cuts etc).
 - Significant areas of shallow regolith landsliding, and some reactivation of scree slopes.
 - A few large (10⁵-10⁶ m³) landslides from coastal cliffs, and possibly large to very large (>10⁶ m³) rock slides and avalanches from steep mountain slopes.
 - Larger landslides in narrow valleys may form small temporary landslide-dammed lakes.
 - Roads damaged and blocked by small to moderate failures of cuts and slumping of road-edge fills.
 - Evidence of soil liquefaction common, with sand boils and water ejections in alluvium, and localised lateral spreading (fissuring, sand and water ejections) and settlements along banks of rivers, lakes, and canals etc.

- MM 9**
- Landsliding widespread and damaging in susceptible terrain, particularly on slopes steeper than 20°. Cracking on flat and sloping ground.
 - Extensive areas of shallow regolith failures and many rock falls and disrupted rock and soil slides on moderate and steep slopes (20°-35° or greater), cliffs, escarpments, gorges, and man-made cuts.
 - Many small to large (10³-10⁶ m³) failures of regolith and bedrock, and some very large landslides (10⁶ m³ or greater) on steep susceptible slopes.
 - Very large failures on coastal cliffs and low-angle bedding planes in Tertiary rocks. Large rock/debris avalanches on steep mountain slope in well-jointed greywacke and granitic rocks. Landslide-dammed lakes formed by large landslides in narrow valleys.
 - Damage to road and rail infrastructure widespread with moderate to large failures of road cuts slumping of road-edge fills. Small to large cut slope failures and rock falls in open mines and quarries.
 - Liquefaction effects widespread with numerous sand boils and water ejections on alluvial plains, and extensive, potentially damaging lateral spreading (fissuring and sand ejections) along banks of rivers, lakes, canals etc). Spreading and settlements of river stop banks likely.

- MM 10**
- Landsliding very widespread in susceptible terrain ⁽³⁾.
 - Similar effects to MM9, but more intensive and severe, with very large rock masses displaced on steep mountain slopes and coastal cliffs. Landslide-dammed lakes formed. Many moderate to large failures of road and rail cuts and slumping of road-edge fills and embankments may cause great damage and closure of roads and railway lines.
 - Liquefaction effects (as for MM9) widespread and severe. Lateral spreading and slumping may cause rents over large areas, causing extensive damage, particularly along river banks, and affecting bridges, wharfs, port facilities, and road and rail embankments on swampy, alluvial or estuarine areas.

NOTES:


- (1) "Some or 'a few' indicates that threshold for an effect or response has just been reached at that intensity. Effects below MM 6 generally insignificant in NZ.
- (2) Intensity is principally a measure of damage. Environmental damage (response criteria) occurs mainly on susceptible slopes and in certain materials, hence the effects described above may not occur in all places, but can be used to reflect the average or predominant level of damage (or MM intensity) in a given area.
- (3) Environmental criteria have not been proposed for MM11 and 12, as those levels of shaking have not been reported in New Zealand.
- (4) This appendix is based on Hancox et al. 1997², 2002⁴. The environmental criteria described above have now been formally incorporated in the New Zealand MM Intensity Scale (Dowrick, D.J., Hancox, G.T., Perrin, N.D., Dellow, G.D., 2008. The Modified Mercalli Intensity Scale – Revisions Arising From New Zealand Experience. *Bulletin of the NZ Society for Earthquake Engineering*, 41(3):193–205.)

APPENDIX 4. Beech Tree Diameter versus Tree-ring Age Data at Mintaro Hut

Mintaro Hut Site - Beech Tree Diameter to Age Data

Dbh* (cm)	Age (years)	Radius (core length, cm)	Core No	Comments
48	165	24.2	M/C-A	Mintaro Hut- Core A (Tree on boulder near Hut)
36	83	18	M/C-1	Mintaro Hut- Core 1
16	38	8	M/C-2	Mintaro Hut - Core 2
39	106	19.5	M/C-3	Mintaro Hut - Core 3
62	179	31	M/T	Mintaro Hut - Trunk
52	171	26	LM	Loch Maree Core

* Diameter of tree at chest height (cm)



Reference

Langridge, R., Duncan, R., Almond, P., Robinson, R. 2007. Indicators of recent paleoseismic activity along the western Hope Fault. *GNS Science Consultancy Report 2006/151*.



www.gns.cri.nz

Principal Location

1 Fairway Drive
Avalon
PO Box 30368
Lower Hutt
New Zealand
T +64-4-570 1444
F +64-4-570 4600

Other Locations

Dunedin Research Centre
764 Cumberland Street
Private Bag 1930
Dunedin
New Zealand
T +64-3-477 4050
F +64-3-477 5232

Wairakei Research Centre
114 Karetoto Road
Wairakei
Private Bag 2000, Taupo
New Zealand
T +64-7-374 8211
F +64-7-374 8199

National Isotope Centre
30 Gracefield Road
PO Box 31312
Lower Hutt
New Zealand
T +64-4-570 1444
F +64-4-570 4657