

6 Henderson Valley Road, Henderson, Auckland 0612 Private Bag 92250, Auckland 1142, New Zealand **Ph** 09 355 3553 **Fax** 09 355 3550

19 October 2017

Liam Tait fyi-request-6526-fa2135c8@requests.fyi.org.nz

Dear Mr Tait

Local Government Official Information and Meetings Act 1987

CAS-569362-D8H2N4

We refer to your request for information dated 7 September 2017 requesting information relating to the recently installed New North Road, Soljak Place and Bollard Ave intersection traffic lights.

Auckland Transport's response to your request for official information is as follows:

1. What decisions were made surrounding the implementation of traffic lights here?

The crash statistics for the last five years were analysed and the new signals were considered to improve on the crash results currently recorded.

The area network was modelled. The impacts of the signals were considered within the network and proximity to Hendon, New North Road Signals.

The signals improved the site safety for vehicles, pedestrian and cycling and the network capacity by using Bollard Avenue.

2. What are the typical timings for each phase of the traffic signals?

This intersection's green times are calculated by the traffic signal system (Scats), with the use of vehicle sensors which register the waiting and the passing vehicles at the traffic signals limit lines. The phasing time is automatically adjusted to allow an efficient traffic flow through this intersection for all motorists.

Auckland signalised intersections phasing is not on fixed time operation, including the intersection of New North Road, Soljak Place and Bollard Avenue.

All phasing has a minimum of six seconds green time. The maximum green time varies by the adaptive traffic signal system (Scats).

3. Any documentation around the sensitivity of the traffic sensors, particularly around registering small vehicles such as motorbikes.

The sensitivity of any traffic signal detector is adjusted to a degree that the sensor can detect any traffic mobility. However, this can compromise the operation of the intersection as the



sensor may pick up adjacent passing vehicles. Readjustment may sometimes be required to prevent frequent false detection from other vehicles, by reducing the sensitivity of the detector.

Attached is the "National Traffic Signal Specifications" and the "Traffic signal Controller Manual"

We trust the above information has addressed the matters raised however, should you believe that we have not responded appropriately to your request, you have the right in accordance with section 27(3) of the LGOIMA to make a complaint to the Office of the Ombudsman to seek an investigation and review in regard to this matter.

If you have any further queries, please contact Auckland Transport on (09) 355 3553 during business hours, quoting Local Government Official Information request number CAS-569362-D8H2N4.

Yours sincerely

Jo Naylor

Team Leader, Customer Liaison Team

Attached: National Traffic Signal Specifications

Traffic Signal Controller Manual



