



**Wellington Central Library, 101
Wakefield Street, Wellington**

Targeted Damage Evaluation Report
following the November 2016 Kaikoura
Earthquakes

Wellington City Council

15 February 2017

Revision: 0

Reference: 254449

*Bringing ideas
to life*

Document control record

Document prepared by:

Aurecon New Zealand Limited

Spark Central
 Level 8, 42-52 Willis Street
 Wellington 6011
 PO Box 1591
 Wellington 6140
 New Zealand

T +64 4 472 9589

F +64 4 472 9922

E wellington@aurecongroup.com


W aurecongroup.com

A person using Aurecon documents or data accepts the risk of:

- a) Using the documents or data in electronic form without requesting and checking them for accuracy against the original hard copy version.
- b) Using the documents or data for any purpose not agreed to in writing by Aurecon.

Document control		aurecon				
Report title		Targeted Damage Evaluation Report following the November 2016 Kaikoura Earthquakes				
Document ID		Project number		254449		
File path		\\aurecon.info\shares\NZWLG\Projects\HANEQ EARTHQUAKE ASSESSMENTS\HANEQ Building EQ Assess NOV-16\% INSPECTIONS NOV 2016[42] 254449 WCC Library_Victoria St\161114 HANEQ\004 - TDE\04 Report\Report Issue\254449 - 20170210 - WCC Library - TDE Report.docx				
Client		Wellington City Council				
Client contact		Tracy Morrah		Client reference		
Rev	Date	Revision details/status	Author	Reviewer	Verifier (if required)	Approver
0	15 February 2017	Issue	A. La Camera	S. Randall	D. Fleming	D. Fleming
Current revision		0				

Approval			
Author signature		Approver signature	
Name	Adonia La Camera	Name	Duncan Fleming
Title	Structural Engineer	Title	Technical Director



Contents

1	Executive Summary	1
2	Description of Structure	2
3	Inspections and Assessments Undertaken	4
3.1	Dates and Scope of Inspections and Assessments	4
3.2	Intrusive Investigations	4
3.3	Building Inspections	4
3.4	Pre-Earthquake Seismic Assessments	4
4	Information Sources	5
4.1	Available Documentation	5
5	Damage Observed	6
5.1	Overview of Damage Observed	6
6	Occupancy Recommendations	8
7	Further Actions Proposed	8

Appendices

Appendix A

Rapid Assessment Forms

Appendix B

Standardised Summary Table

Appendix C

Photographs of Damage



1 Executive Summary

This assessment has been carried out at the request of Aurecon's client, Wellington City Council for the Wellington Central Library at 101 Wakefield Street, Wellington.

The fundamental objective of a Targeted Damage Evaluation (TDE) requested by the Wellington City Council (WCC) is to identify and review the primary vertical and lateral load paths of specific buildings that fall under the Affected Building Profile and carry out an assessment of the damage to critical areas of the structure.

The document, *Engineering Guidelines for Targeted Damage Evaluation following the November 2016 Kaikoura Earthquakes, Version 1.1 – 25 January 2017* produced by the Society of Structural Engineers (SESOC), New Zealand Society for Earthquake Engineering (NZSEE) and WCC has been used as the basis of this investigation.

In this assessment, Aurecon structural engineers carried out intrusive investigations in specific locations to determine the extent of damage to the building. Cladding and lining materials were removed to expose the primary structure in various 'hot-spot' locations identified in a desktop study of the available documentation. The damage to the structure is discussed in Section 5.

From the 2016 Kaikoura earthquake the majority of the structure suffered only minor damage. Existing damage was observed in particular at the precast units of the ground floor level most of which have had support sections retrofitted in order to rectify any risk of failure in 2013.

The only area of concern identified in the inspections was a single precast floor unit at ground floor which was found to have a crack which could compromise its capacity (CDS A). This damage appears to be recent as no additional support has been installed to this unit, but it is typical when compared to previous damage to adjacent units which have had remedial works applied.

No evidence of plastic hinge formation was observed in seismic beams and columns, no beam elongation was observed and no loss of seating of the hollowcore floor units was seen. Several cracks were observed in the levelling compound floor topping in the proximity of the perimeter columns. Further investigations showed the cracks to be only superficial. The crack sizes were less than 0.5mm wide on the levelling compound.

Aside from the localised floor area mentioned above, it appears that the damage observed will not affect to the performance of the building or pose a risk in future earthquakes or aftershocks and it is therefore not necessary to change the current occupancy. The exterior cladding panels appear to be adequately fixed to the structure and do not pose a life safety hazard to occupants, passing pedestrians or neighbouring buildings. Furthermore, the internal egress paths including stairs do not appear to have any damage that would limit their performance or cause failure resulting in egress routes being blocked.

2 Description of Structure

As identified by the WCC, the Wellington City Library falls under the category of 'Affected Building Profile' due to a combination of its structural form, size and siting.

The building was designed and documented in 1989 in accordance with loading standards NZS4203:1984 and the concrete structures standard NZS3101:1982. The building is a six storey reinforced concrete frame structure constructed on flat ground. The building consists of a basement level, full height mezzanine level, three levels of library space and 2 levels for office use.

The structural system of the building consists of reinforced concrete moment resisting frames in the longitudinal and transverse directions with perimeter walls at basement level. The typical flooring system consists of precast pre-stressed hollowcore units with an in-situ topping spanning in the longitudinal direction of the building. Cladding to the structure includes precast concrete panels with window penetrations on three sides of the building, the remaining façade of the building has a glazed curtain wall system. The building foundations are made up of a series of bored reinforced concrete piles. Biaxial actions on "corner" columns has been limited by creating pin-end beam connections in one of the frame joining into these columns.

The concrete piles are generally belled at the base and are approximately 5-6m in length below the basement floor slab. The piles have been founded in dense gravels that underlie the site. The site is classified as 'Type C' subsoil in accordance with NZS 1170.5

Previous repair work to the building was observed at the basement level. Steel brackets have been installed to support hollowcore units due to transverse cracking. This repair work was designed by Holmes Consulting Group and installed in 2013/2014.

Figure 1 and 2 below show two views of the building, western elevation from Victoria Street and the eastern elevation from Civic Square. A typical floor plan of the building is shown in Figure 3.



Figure 1 - View of the Wellington City Library from Victoria Street



Figure 2 - View of the Wellington City Library from Civic Square





Figure 3 – First Floor Plan




Figure 4 – Fourth Floor Plan

3 Inspections and Assessments Undertaken

3.1 Dates and Scope of Inspections and Assessments

Following the November 2016 earthquakes, Rapid Assessment investigations were carried out by Aurecon engineers Adonia La Camera and Mehrdad Seifi on 14 November 2016. The Rapid Assessment Form is attached in Appendix A.

The TDE inspections were carried out in accordance with the procedures documented in the SESOC guidelines. Structural engineers from Aurecon, Adonia La Camera and Jagnesh Makwana, carried out inspections in January and February 2017.

The scope of these inspections was to investigate the extent of damage to the building and in particular focus on damage to specific areas as follows:

- Cracking to hollowcore units for all levels
- Elongation of frames and seating damage leading to loss of support for precast flooring systems
- Disconnection of gravity load system for diaphragms, particularly in frames running parallel to the floor span
- Damage to beams and columns
- Identification of critical damage to stairs
- Identification of critical damage to support points of heavy cladding systems

3.2 Intrusive Investigations

As part of this evaluation the carpet was rolled back in several locations to reveal the top of the floor slab and ceiling tiles were lifted to expose the underside of the floor slab. In a few locations on each floor 10mm from the top of the concrete slab was removed to check if surface cracks were penetrating deeper into the slab.

Plaster surrounding a column that was cracked was removed to investigate the integrity of the column. 10mm of cover concrete was removed from a beam to investigate if cracking observed was superficial or structural. Furthermore, some of the beam column joint cover concrete was removed to check the integrity of the beam to column pin end connection.


Wall linings and concrete topping were removed to expose the bottom connection of the precast panels.

3.3 Building Inspections

The initial inspection was carried out on the 27th of January 2017. Subsequent inspections were carried out on the 3rd, 7th, 9th, and 10th of February 2017.

3.4 Pre-Earthquake Seismic Assessments

A seismic assessment was undertaken by Holmes Consulting Group in 2013 which determined the building to have a global seismic rating of 60% NBS (New Buildings Standard). However the stairs were rated between 35-45% NBS. The precast panel connection scored 40% NBS and the precast hollowcore unit seating was between 35-45% NBS.



4 Information Sources

4.1 Available Documentation

Full structural and architectural drawings were available provided by the WCC Archives and the original building designers, Holmes Consulting Group and Athfield Architects. Only partial mechanical and electrical service documentation was retrieved from the WCC Archives.

5 Damage Observed

5.1 Overview of Damage Observed

The damage noted to the primary structure consisting of reinforced concrete moment resisting frames were minor or insignificant.

Damaged observed during the intrusive investigation is summarised below. Reference should be made to Appendix C for photographs of damage to specific areas of the building with comments.

- No evidence of plastic hinge formation in the seismic beams and columns observed. Hairline cracks were noted in the potential plastic hinge zones of beams in several locations but no spalling or growth in the length of the beams was observed. Spalling of concrete cover was observed at the bottom of the pin-end beam/column connections which are expected and do not downgrade the system capacity. No damage was observed to columns. In Appendix C see photos 18, 22, 23, 26.
- No separation of the floor slab from the perimeter frames was observed where precast hollowcore units run parallel to the perimeter beams.
- No loss of seating to the hollowcore units was noted at support beam locations. There was minor spalling showing signs of movement in a few locations but no loss of seating was observed.

Several cracks were noted in the levelling compound floor topping on several floor levels, in particular at the proximity of columns on the perimeter of the building. Several cracks propagate from the face of the columns are short and decrease in width. The width of the cracks were less than 0.5mm. In certain locations the floor levelling compound and 10mm of concrete topping was removed to check the vertical extension of the crack which was generally found to terminate within this 10mm depth. In one case the vertical crack penetrated through the entire slab depth. This was in the location where steel support brackets were provided following the earthquake in 2013.

No signs or damage or cracking was observed to the underside of hollowcore units above the ground floor. Several cracks were observed at the ground floor level. The majority of these cracks were already identified by investigations done by Holmes Consulting Group in 2013 and additional support brackets installed.

Only one crack is found on a single hollowcore precast unit to be of concern and classified as CDS A in accordance with the TDE Guidelines which will require repair work. This is a transverse crack across a hollowcore unit on ground level Grid 9/B-C. The dimension of the panel is 8m x 1.2m. Figure 5 shows the location.




Figure 5 – Location of transverse crack to hollowcore ground floor unit





Figure 6 – Transverse crack to hollowcore ground floor unit. CDS A damage.

Refer Appendix C for photos (No. 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 13, 14, 15, 16, 27, 28, 29, 30, 31) related to floor cracking.

- No structural damage was observed to the steel structure supporting the central stairs. In particular the connection of the stair landing to concrete beam showed no signs of movement or cracking. The precast concrete emergency stairs suffered only minor damage at the landing joint connection which does not compromise the safety of the stairs. The external stairs running from Civic Square had damage to tiles due to an insufficient gap between the external stairs and the building. Damaged tiles were replaced soon after the earthquake. Refer Appendix C photos (No. 24, 25) related to stairs investigations.
- No signs of damage or inadequate movement was observed for the precast cladding panels and their connections. Refer Appendix C for photos (No. 12, 13, 19, 20, 21) related to cladding panels.

Other damage noted to the structure thought to be unrelated to the 2016 Kaikoura earthquake include:

- Small cracks to the blockwork walls noted in the basement of the building which are not a concern.
- Shrinkage cracks (~0.1-0.5mm wide) seen in the concrete topping of the carpark floors.




6 Assessment

Based on the extent and nature of the damage observed, we believe there is no need for the occupancy of the building to be changed. However, the area above and below the damaged hollowcore unit needs to be vacant until propping has been provided. Repair works are required to restore the integrity of the floor unit in one location.

7 Further Actions Proposed

No further investigations are required.



Appendix A

Rapid Assessment Forms



EARTHQUAKE RAPID ASSESSMENT FORM

Complex Residential and all Non-Residential Buildings Level 2

ASSESSMENT

Fields with asterisks (*) are mandatory, others are optional.

1 Assessor Name* MEHRDAD SEIFI ADONIA CAMERA
Assessor ID* [] Authority* []

2 Assessment Date* 14/11/16 Assessment Time* 10:15 A AM B PM
Day Month Year Hour Minute (to nearest half hour)

BUILDING IDENTIFICATION

3 Building Name WELLINGTON CITY LIBRARY
Unit / Number* [] / []
Street* VICTORIA ST.
City/Town* WELLINGTON
GPS (Degree with 5 decimals after comma) South - [] East []
Other ID or access [] Photo taken A No B Yes Photo ID. []

4 Contact Name PETER BREMAN
Type A Owner B Tenant C Other Property Manager.
Phone (with area code) (0 21) 2278286

5 Existing Placard* None W Y1 R1 Y2 R2 Date* [] [] [] Team ID* [] [] []
Day Month Year

BUILDING DESCRIPTION

6	Dimensions	Constr. Age	Building Type	Structure Type	Cladding Type
	Storeys above ground incl. ground floor 05	A <input type="radio"/> <1935 B <input type="radio"/> 1935-1976 C <input type="radio"/> 1977-1984 D <input checked="" type="radio"/> 1985-2000 E <input type="radio"/> >2000 F <input type="radio"/> Unknown	A <input type="radio"/> Complex residential B <input type="radio"/> School C <input checked="" type="radio"/> Commercial/Office D <input type="radio"/> Industrial E <input type="radio"/> Critical facility F <input type="radio"/> Public assembly G <input type="radio"/> Other: []	A <input type="radio"/> Timber frame B <input type="radio"/> Steel frame C <input checked="" type="radio"/> Concrete frame D <input type="radio"/> Concrete shear wall E <input type="radio"/> Tilt-up concrete F <input type="radio"/> Reinforced masonry G <input type="radio"/> Unreinforced masonry H <input type="radio"/> Other: []	A <input type="radio"/> Brick veneer B <input checked="" type="radio"/> Concrete panels C <input type="radio"/> Steel D <input checked="" type="radio"/> Glass E <input type="radio"/> Lightweight F <input type="radio"/> Other: []
	Storeys below ground 01				
	Footprint (m²) 3500				

EXTERNAL RISKS

7	Potential Cause*	A Yes	B No
1	Objects falling from adjacent buildings. Adjacent building ID or address: not significant.	<input type="radio"/>	<input checked="" type="radio"/>
2	Land instability above	<input type="radio"/>	<input checked="" type="radio"/>
3	Land instability below	<input type="radio"/>	<input checked="" type="radio"/>
4	Other Some superficial damage observed on External facade.	<input type="radio"/>	<input type="radio"/>

If required add sketch on separate page showing extent and nature of the external risk factors.

DAMAGE ASSESSMENT

8

	Damage						Damage				
	N/A	Unknown	Minor or None	Moderate	Severe		N/A	Unknown	Minor or None	Moderate	Severe
Overall Hazard*	N/A	A	B	C	D	Non-structural Hazards*	N/A	A	B	C	D
1 Collapse or partial collapse	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	11 Parapets, ornamentation, chimneys	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
2 Building or storey leaning	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	12 Cladding, glazing	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>
3 Other: <input type="text"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	13 Ceilings, light fixtures	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Structural Hazards*	N/A	A	B	C	D	14 Interior walls, partitions	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
4 Foundations	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	15 Access/egress (elevators, stairs, exits)	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
5 Roofs, floors	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	16 Significant fire safety concerns	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
6 Gravity systems (columns, beams, etc)	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	17 Utilities (e.g. gas, electricity, waste water, plumbing)	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
7 Lateral systems (walls, frames, braces)	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	18 Other: <input type="text"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
8 Diaphragms, horizontal bracing	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	Comments: <input type="text" value="Stairs"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
9 Precast connections	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="text"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>
10 Other: <input type="text"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="text"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

9

Estimated Damage A None B 0-10% C 11-30% D 31-60% E 61-100%

SUGGESTED FURTHER ACTIONS

10

Recommended further Assessment*	Safety Cordon*	Barricades*	Urgency of suggested action*
A <input type="radio"/> None B <input checked="" type="radio"/> Level 2 Rapid Assessment (tick below if particular expertise is required) B1 <input checked="" type="radio"/> Structural Engineer B2 <input type="radio"/> Geotechnical Engineer B3 <input type="radio"/> Other: <input type="text"/> C <input checked="" type="radio"/> Further evaluation to be arranged by building owner. B-C joints and central stairs	A <input type="radio"/> None required B <input checked="" type="radio"/> Cordon required Describe extent (add diagram on separate sheet if required) Stairs from Civic square must be cordoned.	A <input type="radio"/> None required B <input type="radio"/> Barricades already in place C <input type="radio"/> Barricades required Describe extent (add diagram on separate sheet if required)	A <input type="radio"/> Standard B <input checked="" type="radio"/> Immediate action required

Plus stairs from Civic square.

SUMMARY

11

Observed Damage	Level 2 Rapid Assessment Outcome*
Light or no damage	W <input type="radio"/> CAN BE USED (From assessment no known dangers)
Moderate damage	Y1 <input type="radio"/> RESTRICTED ACCESS TO PART(S) OF THE BUILDING ONLY
	Y2 <input type="radio"/> RESTRICTED ACCESS - SHORT TERM ENTRY ONLY with or without supervision Access to be supervised A <input type="radio"/> Yes B <input type="radio"/> No
Heavy damage	R1 <input type="radio"/> ENTRY PROHIBITED (At risk from external factors)
	R2 <input type="radio"/> ENTRY PROHIBITED (Severe damage to building)

Assessor Signature*

12

Survey Extent*	
Exterior	A <input type="radio"/> Partial
	B <input checked="" type="radio"/> Complete
Interior	C <input type="radio"/> Not accessed
	D <input checked="" type="radio"/> Partial
	E <input type="radio"/> Complete


NOTES

13

Further check is required by inspecting the Beam-Column joints with chipping away the concrete cover.
 Internal stair connections requires further check.
 External stair from Civic square connection to be checked.

If required add a sketch on a separate sheet of paper showing building damage, access restrictions or cordoning areas. Identify the building on the sketch and staple the sheet to this assessment form.

Sketch included on separate page? Yes No



Appendix B

Standardised Summary

Table

Standardised Summary Table: Targeted Damage Evaluation Data

V1.23

All RED cells must be filled in prior to submission.
Submit drawings with form.

Location		Building Name: Bldg D - Wellington Central Library	Assessing Engineer: Adonia La Camera
Building Address: NA	Unit No: 101	Street: Wakefield Street	CPEng No:
Legal Description: Lot 1 DP 494594 CFR 724107			Company: Aurecon NZ Ltd
			Company project number: 254449
			Company phone number: 04 472 9589
GPS south:	Degrees	Min	Sec
GPS east:			
Building Unique Identifier (WCC BUFI number): 1000722			Date of submission:
			Inspection Date:
			Revision:
			Is there a full report with this summary?

Available documentation		original designer name/date	Athfield Architects Ltd / 1990
Architectural: full		original designer name/date	Holmes Consulting Group / 1990
Structural: full		original designer name/date	Rankine & Hill Limited / 1990
Mechanical: partial		original designer name/date	Rankine & Hill Limited / 1990
Electrical: partial		original designer name/date	Rankine & Hill Limited / 1990
Geotech report: none		original designer name/date	NA

Site		Max retaining height (m): 3.5
Surrounding Site slope: flat	Soil type: Other fill	Soil Profile (if available): Flat
Site Class (to NZS1170.5): C	In reclamation zone?: yes	If Ground improvement on site, describe: No
Proximity to ocean (m, if <100m):		Approx site elevation (m): 4.00

Building		Ground floor elevation (Absolute) (m): 4.00
No. of storeys above ground (excl. mezzanine): 5	Mezzanine?: yes	Ground floor elevation above ground (m): 0.00
Ground floor split?: no	Storeys below ground: 1	if Foundation type is other, describe:
Foundation type: bored cast-in-situ concrete piles	Building height (m): 23.00	Year of design: 1990
Floor footprint area (approx): 3360	Year of construction: 1990	If so, when (year)?
Is the building consistent with the Structural drawings?: yes	Seismic Strengthening/retrofit present?: no	And what load level?
Use/occupancy (ground floor): Commercial/Public Building	Use/occupancy (upper floors): Commercial/Public Building	Type of strengthening/retrofit:
Use/occupancy notes (if required): Library and office use	Importance level (to NZS1170.5): IL2	Securing of non-structural elements:
Plan irregularity: significant	Vertical irregularity: severe	First storey height (m): 6.80
Other irregularity:		Typical storey height (m): 4.50

Gravity Structure		slab thickness (mm): 65
Gravity System: frame system	Roof system: concrete	overall depth (mm): 865
Beams: precast concrete	Columns: cast-in-situ concrete	typical dimensions (mm x mm): 900 diameter
Walls: partially filled concrete masonry		thickness (mm): 190
Floor Diaphragm:		[describe using options below]
Type of floor system: precast concrete with topping	Topping thickness (slab if CIP) (mm): 65	describe if hollowcore units are spaced with timber infill
Topping (slab if CIP) reinforcement: Mesh (cold drawn)	Precast unit type: Hollowcore	
Precast unit depth (mm): 200	Precast unit seating detail: Hollow-core (no reinforcement into unit)	
Low friction bearing strip used: No	Link slab between precast units and frames: No	If yes, describe link slab (including width and thickness)
Beam to slab continuity reinforcement: Mild steel reinforcement	# bays of frames spanning parallel to single precast unit: 1	diagonal or straight column ties? Straight column ties
Ties from columns into floor (for least restrained column): Mild steel reinforcement		

Lateral load resisting structure (assumed for design)		Note: Define along and across in detailed report!	note typical bay length (m): 8
Lateral system along: ductile concrete moment frame	Closest direction to "along": NE-SW	Design Ductility assumed, μ : 3.00	estimate or calculation? calculated
Period along: 1.83	Total deflection (ULS) (mm): 457	maximum interstorey deflection (ULS) (mm): 130	estimate or calculation? calculated
Lateral system across: ductile concrete moment frame	Closest direction to "across": NW-SE	Design Ductility assumed, μ : 3.00	estimate or calculation? calculated
Period across: 1.45	Total deflection (ULS) (mm): 411	maximum interstorey deflection (ULS) (mm): 120	estimate or calculation? calculated

Separation from neighbouring structures:		leave blank if not relevant
north (mm):	east (mm):	
south (mm):	west (mm):	

Non-structural elements (fill in matrix)		Damaged in EQ?	Threat to Life Safety?	Threat to Egress?
Stairs: precast, full flight	Wall cladding: precast panels	no	no	no
Roof Cladding: Other (specify)	Glazing: aluminium frames	no	no	no
Ceilings: light tiles	Fire suppressant system: Sprinkler system with localised manual call points, smoke detectors and sounders	unknown	unknown	unknown
Heating and Ventilation system: VAV system to office floors generally, CV system to main public library area, with supplementary FCUs to perimeter glazing areas of office floors	Elevator: yes	unknown	unknown	unknown
Other heavy or hazardous elements: Machinery		no	no	no


Critical Damage States Evaluation for RC Buildings*		*reference Targeted Damage Evaluation Guidelines for description of each damage type	
Damage posing collapse risk (A and B)			
Where multiple cases observed, fill in for worst case			
Transverse crack at end of hollowcore (top of slab):		If cracked, how many units with damage:	10
Max crack width: < 0.5mm (including "hairline")	Web cracking?: none visible	Closest crack distance to beam support (mm):	0
Vertical offset at crack?: no			
Transverse crack at end of hollowcore (bottom of unit):		If cracked, how many units with damage:	1
Max crack width: 0.5-2mm	Web cracking?: none visible	Closest crack distance to beam support (mm):	150
Vertical offset at crack?: no			
Transverse crack at end of ribs:		If cracked, how many units with damage:	
Max crack width: Not Applicable	Inclination of crack: not applicable	Closest crack distance to beam support (mm):	
Vertical offset at crack?: not applicable			
Damage to support of precast unit: insignificant		If damaged, how many units with damage:	
Remaining precast unit support: 25-75 mm	Evidence of beam elongation: no	Estimated seating lost due to damage (mm):	0
		Estimated seating lost due to beam elongation (mm):	0

Loss of column lateral support:	insignificant	Note: Mesh does not count as ties	How many columns affected?	
Shear cracks in columns:	none		How many columns affected?	
Damage posing lower risk (C)				
Column Plastic Hinge damage - Criterion 1 met?	no damage	Hinge damage criteria: 1. Total crack width in plastic hinge > 0.005d 2. Sliding has occurred on a crack 3. Wide (>0.5mm) diagonal cracks 4. Concrete degradation, indicated by significant spalling (concrete cover can be removed by hand)	Describe damage as per criterion 1	
Criterion 2 met?	no damage		Describe damage as per criterion 2	
Criterion 3 met?	no damage		Describe damage as per criterion 3	
Criterion 4 met?	no damage		Describe damage as per criterion 4	
Location of critical column plastic hinge:	NA			
Beam Plastic Hinge damage - Criterion 1 met?	no damage		Describe damage as per criterion 1	
Criterion 2 met?	no damage		Describe damage as per criterion 2	
Criterion 3 met?	no damage		Describe damage as per criterion 3	
Criterion 4 met?	damage but criteria not met		Describe damage as per criterion 4	Occurred at the pinned beam locations
Location of critical beam plastic hinge:	NA			
Wall Plastic Hinge damage - Criterion 1 met?	no damage		Describe damage as per criterion 1	
Criterion 2 met?	no damage		Describe damage as per criterion 2	
Criterion 3 met?	no damage		Describe damage as per criterion 3	
Criterion 4 met?	no damage		Describe damage as per criterion 4	
Location of critical wall plastic hinge:	NA			
Web cracking of Hollowcore	none known		If cracked, how many units with damage:	
Longitudinal cracking of hollowcore	fully developed, with reinf in topping intact		If cracked, how many units with damage:	3
Mesh fracture	none observed			
Damage to other elements posing life-safety risk				
Stairs	no significant damage		Describe damage:	Minor damage at the landing joints
Heavy cladding	no significant damage		Describe damage:	
Heavy overhead non-structural elements	not applicable		Describe damage:	

Building Closure				
Was the building closed following the earthquake?	yes			
If yes, from when	14/11/2016	dd/mm/yyyy		
If yes, to when	17/11/2016	dd/mm/yyyy		
If yes, what was the reason(s) (use all that apply, in priority order) (if "other", please specify in notes)	Non-structural damage (including internal L1/L2 assessments)	greatest priority		




Recommendations				
Repair/strengthening recommended:	significant structural		Describe:	Repair Hollow core panel at Ground Floor Level
Building Consent required:	unknown		Describe:	
Interim occupancy recommendations:	Continued normal occupancy		Describe:	Vacate the area above damaged Hollow core panel until propping is been provided
External barricading of public spaces recommended?	no		Describe:	




Official Use only:				
Accepted By:		Initial WCC review by:		
Date:		Further review by (or indicate Not Required):		









Appendix C

Photographs of Damage




ID.	Location & comments	Photographs
1.	<p>Underside of Ground Floor Level Grid 3/B-C.</p> <p>Diagonal crack. This crack was existing as observed from a photo taken in 2013.</p>	
2.	<p>Underside of Ground Floor Level Grid 5/B-C.</p> <p>Longitudinal cracking in the direction of floor span. This crack was existing as observed from a photo taken in 2013.</p>	
3.	<p>Underside of Ground Floor Level Grid 6/C.</p> <p>Transverse cracking (perpendicular to the direction of floor span). Occurred following the earthquakes in 2013. Support brackets provided.</p>	




<p>4.</p>	<p>Underside of Ground Floor Level Grid 9/B-C. Significant transverse cracking (perpendicular to the direction of floor span). Its width range between 1 and 2 mm. The panel needs to be repaired.</p>	
<p>5.</p>	<p>Underside of Ground Floor Level Grid 9/B-C. Significant transverse cracking (perpendicular to the direction of floor span). Its width range between 1 and 2 mm. The panel needs to be repaired.</p>	
<p>6.</p>	<p>Underside of Ground Floor Level Grid 9/B-C. Significant transverse cracking (perpendicular to the direction of floor span). Its width range between 1 and 2 mm. The panel needs to be repaired.</p>	




7.	<p>Underside of Ground Floor Level Grid 7/A-B.</p> <p>Transverse cracking (perpendicular to the direction of floor span). This crack was existing as observed from a photo taken in 2013.</p>	
8.	<p>Underside of Ground Floor Level Grid 8/F.</p> <p>Transverse cracking (perpendicular to the direction of floor span). This crack was existing as observed from a photo taken in 2013.</p>	
9.	<p>Underside of Ground Floor Level Grid 6/B.</p> <p>Diagonal cracking (perpendicular to the direction of floor span) adjacent to column. This crack was existing as observed from a photo taken in 2013.</p>	




<p>10.</p>	<p>Ground Floor cracking adjacent to column near Grid 11/A.</p> <p>Crack width on the levelling compound less than 0.5mm.</p>	
<p>11.</p>	<p>Second Floor cracking adjacent to column near Grid 11/A.</p> <p>Further investigations showed the crack to be only superficial.</p>	
<p>12.</p>	<p>First Floor cracking adjacent to column on Grid 12/E.</p> <p>Those cracks behind the beams are not structural. They define the area above the bottom precast cladding connections.</p>	

13.	Ground Floor cracking adjacent to column on Grid 2/B.	
14.	No signs of cracking on Ground Floor adjacent to column on Grid 2/G	
15.	No signs of cracking on Ground Floor adjacent to column on Grid 4/E	

<p>16.</p>	<p>Second floor cracking adjacent to column on Grid 10/D.</p>	
<p>17.</p>	<p>Fourth floor cracking on perimeter of building adjacent to precast panels Grid 2/C. Those cracks behind the beams are not structural. They define the area above the bottom precast cladding connections.</p>	
<p>18.</p>	<p>No signs of cracking to column on Grid 4/A on mezzanine level.</p>	

19.	No signs of earthquake damage to precast panels connections on fourth level Grid 2-3/C.	
20.	No signs of earthquake damage to precast panels connections on third level Grid 10-11/A.	
21.	Extrusive investigation of third level slab at precast panel junction on Grid 11/A indicating no significant signs of earthquake damage.	


22.	Minor spalling to mezzanine level reinforced concrete beam on Grid 4/A.	
23.	No signs of recent earthquake damage to mezzanine level reinforced concrete beam on Grid 5/A.	
24.	No significant signs of earthquake damage to stair landing between third and fourth floor levels in south core stairwell.	

<p>25.</p>	<p>Gap opening of joint between stair units in Harris Street end stairwell.</p>	
<p>26.</p>	<p>No notable earthquake damage to ground floor columns and beams.</p>	
<p>27.</p>	<p>Superficial crack to ground floor on Grid 4/E-F</p>	

28.	Cracking to ground floor on Grid 6/F-G	
29.	<p>Ground floor cracking near Grid 9/F.</p> <p>Crack width ~1.0mm.</p> <p>Steel bracket supports are provided below this crack following the 2013 earthquake.</p>	
30.	<p>Ground floor cracking on the top of the slab near Grid 9-10/B.</p> <p>Crack width ~0.6mm.</p>	

31. Ground floor panels near Grid 9-10/B.

No crack observed in the area inside the red square.





Aurecon New Zealand Limited

Spark Central
Level 8, 42-52 Willis Street
Wellington 6011

PO Box 1591
Wellington 6140
New Zealand

T +64 4 472 9589

F +64 4 472 9922

E wellington@aurecongroup.com

W aurecongroup.com

Aurecon offices are located in:

Angola, Australia, Botswana, China,
Ghana, Hong Kong, Indonesia, Kenya,
Lesotho, Macau, Mozambique,
Namibia, New Zealand, Nigeria,
Philippines, Qatar, Singapore, South Africa,
Swaziland, Tanzania, Thailand, Uganda,
United Arab Emirates, Vietnam.