

## **Investigation Report**



along this road people are travelling at great speeds, coming down from Richardson Rd. there have been a accidents at the intersection of Ellis Rd and John Davis Rd, when people are turn out of Ellis onto John Davis and they were hit by on coming traffic, seeing whether an investigation can be done to see if speed humps can be put on the length of the road.

caller

**Response Type** 

24/08/2016

Puketapapa

**Site Location** John Davis Road, Mount Roskill, Auckland

**Case Reference** 

Link to case

**Engineer** Matthew Tansey

**Site Visit** 

**Site Visit Date** 29/06/2016 12:00 p.m.

**Site Notes** Went for preliminary site investigation and identified that it was a fast road with vehicles

exceeding speed limit in both directions

road already has a bit of signage and treatment on the bottom end with signage and a

central island and flush

**Recommendation** To perform new LATM investigation

Customer Key Points LATM Results: Speeds: 54.1 kph

Phone Call Made Accidents: No Speed related Accidents 2010-2016

Volumes: 3147 Vpd

Priority Score: 47/100

Phone Call Date

leave this road as is not high when compared to other roads on the Priority List

**Written Response Required** 

Outcome

Status In Progress

**Attachments** 

Status Active