



## Asbestos Management Survey Report

### LAMBIE BUILDING MANAGEMENT SURVEY



## Report Production

Survey Conducted by: Bruce Wakefield  
Date of Survey: 04<sup>th</sup> of April 2018  
Position in Company: Managing Director  
Assessor Number: AA16090111  
Expiry Date: 5 September 2021

Signature:



Survey Prepared by: Bruce Wakefield  
Date Survey Prepared: 04<sup>th</sup> of April 2018  
Position in Company: Managing Director  
Assessor Number: AA16090111  
Expiry Date: 5 September 2021

Signature:



Survey Reviewed by: Ali Lind  
Date of review: 5<sup>th</sup> of March 2018  
Position in Company: Operations Project Manager  
Assessor Number: AA17090140  
Expiry Date: 5 September 2022

Signature:



## **Contents Page**

### **Section 1**

- **Report Details**
- **Introduction**
- **Survey Methodology**
- **General Recommendations for Asbestos Cement Products**
- **General Recommendation for Asbestos Insulation, Coatings or Insulating Board (AIB)**
- **Survey Summary & Recommendations**
- **Risk Assessment Methods**

### **Section 2**

- **Identification & Photographic Register Sheets**
- **Survey Recommendations**
- **Survey Record Sheets**
- **Laboratory Certificate of Analysis**
- **Management Inspection Record**

## **Introduction**

Further to an invitation from **Grant Hood (Whanganui District Health Board)**

### **WHANGANUI HOSPITAL**

AISL - Asbestos Inspection Services Limited was requested to carry out a Management Survey at -

### **LAMBIE BUILDING-EXTERIOR & INTERNAL**

There are 2 designated categories of Asbestos surveys currently available. These are listed below:

#### **Management Survey**

Standard sampling, identification and assessment survey (Sampling Survey), the purpose of which is to locate as far as reasonably Practicable the presence and extent of any suspect asbestos containing materials in the building and their condition. This is done by the collection and analysis of samples of suspect asbestos containing materials.

#### **Refurbishment / Demolition Survey**

Full access sampling and identification survey (Pre-demolition/Major Refurbishment Survey). This type of survey is used to locate and describe as far as reasonably practicable, all asbestos containing materials in the building and may involve destructive inspection as necessary to gain access to all areas, including those that may be difficult to reach. A full sampling programme is undertaken to identify possible asbestos containing materials and estimates of the volume and surface areas of asbestos containing materials made.

Access arrangements were made with aid of Mr. Grant Hood (Whanganui District Health Board) to ensure all accessible areas were surveyed during the project.

The survey was carried out on 04/04/2018 and completed the same day.

The survey was to include for visual inspection within the above premises.

The survey was undertaken and completed by a member of the AISL – Asbestos Inspection Services Limited survey team.

During the survey the building remained semi-occupied.

## **Disclaimer**

**Every effort has been made to identify all asbestos materials so far as was reasonably practicable to do so within the scope of the survey and the attached report. Methods used to carry out the survey were agreed with the client prior to any works being commenced.**

**Survey techniques used involves trained and experienced surveyors using the combined approach about visual examination. and bulk sample collections where required.**

**It is always possible after a survey that asbestos based materials may remain in the property or area covered by that survey, this could be due to several reasons:**

- Asbestos materials existing outside the scope of the survey.**
- Materials may be concealed or hidden by other items or covered surfaces i.e. paint, over boarding, concealing etc. Where this is the case then its discovery will be limited.**
- Asbestos may well be hidden as part of the structure to a building and not visible until the structure is demolished later.**
- Fragments from previous asbestos removal projects may well be present in various areas; general asbestos fragments do not form part of this survey however all good intentions are made for its discovery.**

**Where an area has been formerly stripped of asbestos i.e. plant rooms, ducts etc. and new coverings added, it must be pointed out that asbestos removal techniques have improved steadily over the years since its initial introduction. Most particularly would be the Health and Safety at Work (Asbestos) Regulations 2016, that outline enforceable strategies. Asbestos removal prior to this regulation would not be of today's standard and therefore fragments may be present beneath new coverings.**

**This survey will detail areas accessed and all samples taken, where an area is not covered by this survey it will be due to No Access for one reason or other i.e. working technicians, delicate location or just simply no admittance. It may have been necessary for the restrictions of the surveyor's specialist to be confirmed prior to the survey.**

**Admittance for the survey may be restricted for many reasons outside our control such as height, deadlines to others, steady complications or confined space. Where electrical equipment is present and presumed in the way of the survey no access will be attempted until proof of its safe state is given. Our operatives have a duty of care under the Health and Safety at Work Act (2016) for both themselves and others.**

## **Disclaimer**

**In the structure where asbestos has been located and not all zones have been examined, any material that is found to be suspicious and not detailed as part of the survey should be treated with caution and sampled accordingly.**

**Certain materials contain asbestos to variable grades and some may be less densely contaminated at certain locations (Artex for example). Where this is the case the sample taken may not be representative of the whole product throughout, therefore composite sampling is therefore encouraged.**

**Where a survey is carried out under the guidance of the owner of the property or his representative, then the survey will be as per his/her instructions and supervision at that time.**

**Asbestos Inspection Services Limited cannot accept any liability for loss, injury, damage or penalty issues due to errors or oversights contained within this report.**

**Asbestos Inspection Services Limited cannot be held responsible for any damage caused as part of this survey carried out on your behalf. Due to the landscape and stipulation of sampling for asbestos some danger is inevitable and will be limited to just that necessary for the taking of the sample.**

## **General Recommendations for Asbestos Cement Products.**

**Work with cement products containing asbestos is covered by the Management and Removal of Asbestos (November 2016) Approved Code of Practice.**

**An assessment of all proposed works which may disturb any asbestos should be carried out to launch the risk existing, the appropriate precautions must be adopted to control any exposure. This should combine the succeeding over-all principles:**

- **Where work on asbestos cement is inevitable, keep the materials wet during work and avoid breakage wherever possible. Acceptable PPE must be worn always.**
- **Avoid using power tools. If deemed necessary to use power tools set at the lowest possible speed, exhaust ventilation such as cowls must be fitted to power tool and utilising the “investigation technique” with high efficiency H type vacuum units.**
- **Organise the work in a single controlled location where practicable, to streamline control and supervision. Isolate working areas using warning signs and tape barriers, or in case of significant fibre levels by means of a sealed polythene work enclosure and negative pressure equipment. Air tests must also be carried out by an independent asbestos assessor.**
- **Signify respirator zones where the Control Limit is likely to be exceeded and ensure that all persons entering the zones wear appropriate RPE/PPE are trained in its use.**
- **Ensure that those persons employed in working on asbestos cement are suitably trained in the correct working practices, control methods and anticipation of risks.**
- **Keep the work area clean during the work and use methods that abate dust creation, avoid sweeping and brushing, which will make dust airborne.**
- **Dispose of asbestos cement waste safely as Asbestos Waste under the statutory consignment note procedures in accordance with the Health and Safety at Work (Asbestos) Regulations 2016.**
- **Avoid further disturbance of asbestos cement products wherever possible by relocating or re-routing facilities.**
- **Clearly identify and label any asbestos cement products.**

## **General Recommendations for Asbestos Insulation, Coatings or Insulating Board (AIB)**

**Where the materials are in safe condition and the risk of disturbance is small, they can be maintained on site. They should be identified with adequate warning signs and routinely inspected for damages. All asbestos materials should not be drilled, abraded or disturbed in any way.**

**All asbestos containing materials should be removed prior to any planned refurbishment or demolition works, where damage is likely to be sustained during the occupant's activities or where future decline is likely.**

**Work on any of these items may only be carried out by a specialist contractor licensed under the Health & Safety at Work Act 2016. The selected contractor is required to notify the WSNZ at least 5 days prior to commencement of the works, and to provide a written Method Statement as follows:**

- **Full explanation of the works to be carried out and its duration.**
- **Type, quantity and location of asbestos to be removed.**
- **Anticipated exposure levels and persons affected.**
- **Enclosure construction details, layout and location, signage and ventilation.**
- **Protections to be adopted to minimize exposure to lowest possible level and to control release of asbestos fibre beyond the work area.**
- **Validation for any withdrawal from preferred methods, e.g. where wet stripping cannot be used.**
- **Type, use and decontamination of RPE/PPE**
- **Waste removal and disposal procedures**
- **Training and instruction of employees**
- **Emergency procedures on site**



total risk score of between 0 and 12 is calculated using four categories that are evaluated by the surveyor against given values. The criteria and the respective values are as follows:

### **Product Type**

- 1 Asbestos reinforced composites such as plastics, resins, mastic, roofing felt, vinyl tiles, paints and decorative finishes, asbestos cement products.
- 2 Asbestos insulation board, mill boards, other low-density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.
- 3 Thermal insulation (e.g. pipe and boiler lagging), sprayed asbestos, loose asbestos, asbestos mattresses and packing.

### **Condition/Extent of Damage**

- 0 Good condition, no visible damage.
- 1 Low damage, a few scratches or surface marks, broken edges on boards, tiles etc.
- 2 Medium damage, significant breakage of materials or several small areas where material has been damaged, revealing loose asbestos fibres.
- 3 High damage or delamination of materials, sprays and thermal insulation. Visible asbestos debris.

### **Surface Treatment**

- 0 Composite materials containing asbestos, such as reinforced plastics, resins, vinyl tiles.
- 1 Enclosed sprays and lagging, asbestos insulation board with exposed surface painted or encapsulated, asbestos cement products.
- 2 Unsealed asbestos insulation board or encapsulated lagging and sprays.
- 3 Unsealed lagging and sprays.

## **Material Assessment Methods**

### **Asbestos Type**

- 1 Chrysotile (white) asbestos.
- 2 Amosite (brown) asbestos.
- 3 Crocidolite (blue) asbestos.

The algorithms shown against each situation are added together to give a total material risk score, for conciseness, the register we have prepared contains only the total risk score rather than the component scores.

The total score for each situation can be broadly classified using the following bands:

### **Material Risk Score**

0 - 3 Very Low Risk

4 - 6 Low Risk

7 – 9 Medium Risk

10 – 12 High Risk

It is likely that high risk items will be highlighted in the report text and that some immediate action will be required.

Other items may also be measured for consideration where the decision of the surveyor recommends this would be beneficial.

## Priority Assessment Formula

A priority risk score of between 0 and 12 is calculated using four categories that are evaluated by the duty holder.

Although a surveyor may have some of the information which will contribute to the risk assessment and may be part of an assessment team, the duty holder is required to make a risk assessment based on the survey findings and their detailed knowledge of the activities carried out within the premises. The criteria and the respective values are as follows:

### Normal occupant activity

Assessment factor	Score	Examples of score variables
Main type of activity in area	0	Rare disturbance activity (e.g. little used store room)
	1	Low disturbance activities (e.g. office type activity)
	2	Periodic disturbance (e.g. industrial or vehicular activity which may contact ACMs)
	3	High levels of disturbance, (e.g. fire door with asbestos insulating board)
Secondary activities for area	As above	

## Priority Assessment Formula

### Likelihood of disturbance

Assessment factor	Score	Examples of score variables
Location	0	Outdoors
	1	Large rooms or well-ventilated areas
	2	Rooms up to 100 m <sup>2</sup>
	3	Confined spaces
Accessibility	0	Usually inaccessible or unlikely to be disturbed
	1	Occasionally likely to be disturbed
	2	Easily disturbed
	3	Routinely disturbed
Extent/amount	0	Small amounts or items (e.g. strings, gaskets)
	1	<10 m <sup>2</sup> or <10 m
	2	10 m <sup>2</sup> to 50 m <sup>2</sup> or 10 m to 50 m
	3	>50 m <sup>2</sup> or >50 m

### Human exposure potential

Assessment factor	Score	Examples of score variables
Number of occupants	0	None
	1	1 to 3
	2	4 to 10
	3	>10
Frequency of use of area	0	Infrequent
	1	Monthly
	2	Weekly
	3	Daily
Average time area is in use	0	<1 hour
	1	1 to 3 hours
	2	3 to 6 hours
	3	>6 hours

## Priority Assessment Formula

### Maintenance activity

Assessment factor	Score	Examples of score variables
Type of maintenance activity	0	Minor disturbance (e.g. possibility of contact when gaining access)
	1	Low disturbance (e.g. changing light bulbs in asbestos insulating board ceiling)
	2	Medium disturbance (e.g. lifting one or two asbestos insulating board ceiling tiles to access a valve)
	3	High levels of disturbance (e.g. removing many asbestos insulating board ceiling tiles to replace a valve or for re-cabling)
Frequency of maintenance activity	0	ACM unlikely to be disturbed for maintenance
	1	≤1 per year
	2	>1 per year
	3	>1 per month

The score for each variable is determined by calculating the average score of the appropriate factors.

The algorithms shown against each section are added together to give a total priority risk score, for conciseness, the register we have prepared contains only the overall risk score rather than the component scores.

### Priority Risk Score

0 - 3 Very Low Risk

4 - 6 Low Risk

7 – 9 Medium Risk

10 – 12 High Risk

## Overall Hazard Risk Assessment Formulae

The material and priority assessment scores provide an overall hazard risk score for each situation which can be broadly classified using the following table:

		Material Assessment			
		10-12	7-9	5-6	1-4
Priority Assessment	10-12				
	7-9				
	4-6				
	0-3				

Key		
	<b>High Risk</b>	<b>Total score = 19-24</b>
	<b>Medium Risk</b>	<b>Total score = 13-18</b>
	<b>Low Risk</b>	<b>Total score = 7-12</b>
	<b>Very Low Risk</b>	<b>Total score = 1-6</b>

Specific Locations that have been Analysed for asbestos based material's or Presumed to Contain Asbestos Containing material's.

**ID: CARD NO:001**

Floor.	Exterior
Location/Area	Exterior: Window Panels
Suspected Material Identified	ACM Board
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	1: ACM common characteristics
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	39.6m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:002**

Floor.	Exterior
Location/Area	Exterior: Bike Shed (Ceiling/Walls)
Suspected Material Identified	ACM Board
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	40.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:003**

Floor.	Exterior
Location/Area	Exterior: Wall Lining
Suspected Material Identified	ACM Board
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	37.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:004**

Floor.	Exterior
Location/Area	Exterior: Windows
Suspected Material Identified	Putty Compound
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	1896.0L/M



Additional evidence from PCBU: (That supports non-asbestos material/s).



**ID: CARD NO:005**

Floor.	Exterior
Location/Area	Exterior: Soffit Lining
Suspected Material Identified	ACM Board
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	2.5m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:006**

Floor.	Exterior
Location/Area	Exterior: Concrete Pad
Suspected Material Identified	ACM Board (Debris)
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	6.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:007**


Floor.	Ground Floor
Location/Area	CART: Entry
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	7.4m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:008**

Floor.	Ground Floor
Location/Area	CART: Toilet
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	3.9m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:009**


Floor.	Ground Floor
Location/Area	Reception: Corridor
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	15.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:010**

Floor.	Ground Floor
Location/Area	Referral Hub: Files
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	6.3m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:011**


Floor.	Ground Floor
Location/Area	Referral Hub: Office
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	17.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:012**

Floor.	Ground Floor
Location/Area	Reception: Accessible Toilet
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	6.3m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:013**

Floor.	Ground Floor
Location/Area	Cleaners Room: Floor
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	6.6m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:014**

Floor.	Ground Floor
Location/Area	Kitchen: Corridor
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	7.2m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:015**

Floor.	Ground Floor
Location/Area	Wheelchair Toilet
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	2.8m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:016**


Floor.	Ground Floor
Location/Area	Rubbish Cupboard
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	5.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:017**

Floor.	Ground Floor
Location/Area	Clinic Room 2
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	11.5m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:018**

Floor.	Ground Floor
Location/Area	Clinic Room 1
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	11.5m2



Additional evidence from PCBU: (That supports non-asbestos material/s).



**ID: CARD NO:019**


Floor.	Ground Floor
Location/Area	Kitchen Toilet
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	4.5m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:020**

Floor.	Ground Floor
Location/Area	Kitchen Floor
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	4.3m2



Additional evidence from PCBU: (That supports non-asbestos material/s).



**ID: CARD NO:021**


Floor.	Elevator
Location/Area	Elevator Floor
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	1.8m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:022**

Floor.	First Floor
Location/Area	Lavatory
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	6.5m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:023**


Floor.	First Floor
Location/Area	SI: Corridor
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	7.4m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:024**


Floor.	First Floor
Location/Area	SI: Wharepaku
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	4.5m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:025**

Floor.	First Floor
Location/Area	SI: Kitchen
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	.800m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:026**

Floor.	First Floor
Location/Area	Te Hau Ranga Ora: Toilet
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	4.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:027**


Floor.	First Floor
Location/Area	Te Hau Ranga Ora: Kitchen
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	Kitchen



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:028**


Floor.	First Floor
Location/Area	ICT Dept: Kitchen
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	5.2m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:029**


Floor.	First Floor
Location/Area	ICT Dept: Toilet
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	4.8m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:030**


Floor.	First Floor
Location/Area	ICT Dept: Accessible Toilet
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	2.6m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:031**


Floor.	Second Floor
Location/Area	Public Health: Unisex Toilet
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	3.2m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:032**

Floor.	Second Floor
Location/Area	Public Health: Cleaners Cupboard
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	1.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:033**

Floor.	Second Floor
Location/Area	Public Health: Kitchen
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	5.6m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:034**

Floor.	Second Floor
Location/Area	Public Health: Files Room
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	11.8m2



Additional evidence from PCBU: (That supports non-asbestos material/s).



**ID: CARD NO:035**

Floor.	Second Floor
Location/Area	Public Health: Female Toilet
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	3.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:036**

Floor.	Second Floor
Location/Area	Public Health: Male Toilet
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	3.3m2




Additional evidence from PCBU: (That supports non-asbestos material/s).



**ID: CARD NO:037**

Floor.	Second Floor
Location/Area	Public health: Unisex Toilet
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	4.6m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:038**

Floor.	Second Floor
Location/Area	Public Health: Kitchen
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	5.8m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:039**

Floor.	Second Floor
Location/Area	Public Health: Room 218
Suspected Material Identified	Vinyl Floor
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	7.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:040**

Floor.	Third Floor
Location/Area	Toilet: Floor
Suspected Material Identified	Vinyl Flooring
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	8.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:041**

Floor.	Third Floor
Location/Area	Kitchen: Floor
Suspected Material Identified	Vinyl Flooring
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	4.8m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:042**

Floor.	Third Floor
Location/Area	Boys Locker Room: Floor
Suspected Material Identified	Vinyl Flooring
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	5.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:043**


Floor.	Third Floor
Location/Area	Locker Room: Floor
Suspected Material Identified	Vinyl Flooring
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	14.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:044**

Floor.	Stairway
Location/Area	Stairway: Floor
Suspected Material Identified	Vinyl Flooring
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	78.5m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:045**

Floor.	Fourth Floor
Location/Area	Elevator Foyer: Floor
Suspected Material Identified	Vinyl Flooring
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	12.6m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:046**


Floor.	Fourth Floor
Location/Area	Corridor: Floor
Suspected Material Identified	Vinyl Flooring
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	17.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:047**

Floor.	Fourth Floor
Location/Area	Equipment Room: Floor
Suspected Material Identified	Vinyl Flooring
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	4.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:048**

Floor.	Fourth Floor
Location/Area	Store Cupboard: Floor
Suspected Material Identified	Vinyl Flooring
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	3.5m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:049**

Floor.	Fourth Floor
Location/Area	Storage Room: Floor
Suspected Material Identified	Vinyl Flooring
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	9.5m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:050**

Floor.	Fourth Floor
Location/Area	Store Room: Floor
Suspected Material Identified	Vinyl Flooring
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	12.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).



**ID: CARD NO:051**

Floor.	Plant Room
Location/Area	Plant Room: Gaskets
Suspected Material Identified	ACM Gaskets
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	20.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:052**

Floor.	Plant Room
Location/Area	Elevator Room: Fuse board
Suspected Material Identified	ACM Board
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Not Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	.200m2



Additional evidence from PCBU: (That supports non-asbestos material/s).



**ID: CARD NO:053**

Floor.	Exterior
Location/Area	Exterior: Roof Top
Suspected Material Identified	Waterproofing (Black)
Condition of Material Identified	Stable
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	2: Presumed ACM
Sample No.	Sample Taken
Laboratory Analysis Findings	Analysis Not Conducted
Quantity of Material Identified	30.0m2



Additional evidence from PCBU: (That supports non-asbestos material/s).

**ID: CARD NO:054**

Floor.	
Location/Area	
Suspected Material Identified	
Condition of Material Identified	
<b>Categories: (Assessment type).</b> 1: ACM common characteristics or 2: Presumed ACM or 3: Sample collected for analysis	
Sample No.	
Laboratory Analysis Findings	
Quantity of Material Identified	

Additional evidence from PCBU: (That supports non-asbestos material/s).



## Inspection Personnel

LAMBIE BUILDING

Date	Name	Company Name	Competency Attained	License No	Expiry Date	Phone Number	Email Address
20/04/2018	Ali Lind	Asbestos Inspection Services Limited	Licensed Asbestos Assessor	AA17090140	07 <sup>th</sup> of September 2022	+64 27 8565624	<a href="mailto:ali.lind@aisl.co.nz">ali.lind@aisl.co.nz</a>

## Survey Record Sheet

Ref: WDHB

Site Address: LAMBIE BUILDING-EXTERIOR & INTERNAL

Date: 20/04/18

Survey Type: **MANAGEMENT SURVEY**

ID Card No	FLOOR	Location/Area Description	Sample Ref Category No	Quantity	Product Description	Asbestos Type	Product Type	Condition	Surface Treatment	Asbestos Type	Material Risk Score	Normal Occupant Activity	Likelihood of Disturbance	Human Exposure Potential	Maintenance Activity	Priority Risk Score	Overall Risk Score	Action	
001	EXTERIOR	Exterior: Window Panels	1	39.6m2	Wall Lining	ACM Board	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
002	EXTERIOR	Bike Shed: Ceiling/Walls	2	40.0m2	Wall/Ceiling Lining	ACM Board	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
003	EXTERIOR	Exterior: Walls	2	37.0m2	Wall Lining	ACM Board	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
004	EXTERIOR	Exterior: Windows	2	1896.0L/M	Window Framing	Putty Compound	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
005	EXTERIOR	Exterior: Soffits	2	2.5m2	Soffit Lining	ACM Board	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
006	EXTERIOR	Exterior: Concrete Pad	1	6.0m2	Loose debris	ACM Board	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
007	GROUND	CART: Entry	2	7.4m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
008	GROUND	CART: Toilet Entry	2	3.9m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
009	GROUND	Reception: Corridor	2	15.0m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
010	GROUND	Referral Hub: Files	2	6.3m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.

## Survey Record Sheet

Ref: WDHB

Site Address: LAMBIE BUILDING-EXTERIOR & INTERNAL

Date: 20/04/18

Survey Type: **MANAGEMENT SURVEY**

ID Card No	Photo No	Location/Area Description	Sample Ref Category No	Quantity	Product Description	Asbestos Type	Product Type	Condition	Surface Treatment	Asbestos Type	Material Risk Score	Normal Occupant Activity	Likelihood of Disturbance	Human Exposure Potential	Maintenance Activity	Priority Risk Score	Overall Risk Score	Action	
011	GROUND	Referral Hub: Office	2	17.0m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
012	GROUND	Reception: Accessible toilet	2	6.3m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
013	GROUND	Corridor: Cleaners Cupboard	2	6.6m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
014	GROUND	Reception Area: Kitchen	2	7.2m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
015	GROUND	Wheelchair Toilet	2	2.8m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
016	GROUND	Rubbish Cupboard	2	5.0m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
017	GROUND	Clinic Room 2	2	11.5m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
018	GROUND	Clinic Room 1	2	11.3m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
019	GROUND	Kitchen-Toilet	2	4.5m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
020	GROUND	Kitchen Floor	2	4.3m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.

## Survey Record Sheet

Ref: WDHB

Site Address: LAMBIE BUILDING-EXTERIOR & INTERNAL

Date: 20/04/18

SurveyType:

**MANAGEMENT SURVEY**

ID Card No	Photo No	Location/Area Description	Sample Ref Category No	Quantity	Product Description	Asbestos Type	Product Type	Condition	Surface Treatment	Asbestos Type	Material Risk Score	Normal Occupant Activity	Likelihood of Disturbance	Human Exposure Potential	Maintenance Activity	Priority Risk Score	Overall Risk Score	Action	
021	GROUND	Elevator Floor	2	1.8m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
022	FIRST	Lavatory Floor	2	6.5m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
023	FIRST	SI: Corridor	2	7.4m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
024	FIRST	SI: Wharepaku	2	4.5m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
025	FIRST	SI: Kitchen	2	.800m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
026	FIRST	Te Hau Ranga Ora: Toilet	2	4.0m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
027	FIRST	Te Hau Ranga Ora: Kitchen	2	4.2m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
028	FIRST	ICT Dept: Kitchen	2	5.2m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
029	FIRST	ICT Dept: Toilet	2	4.8m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
030	FIRST	ICT Dept: Accessible toilet	2	2.6m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.

## Survey Record Sheet

Ref: WDHB

Site Address: LAMBIE BUILDING-EXTERIOR & INTERNAL

Date: 20/04/18

Survey Type: **MANAGEMENT SURVEY**

ID Card No	Photo No	Location/Area Description	Sample Ref Category No	Quantity	Product Description	Asbestos Type	Product Type	Condition	Surface Treatment	Asbestos Type	Material Risk Score	Normal Occupant Activity	Likelihood of Disturbance	Human Exposure Potential	Maintenance Activity	Priority Risk Score	Overall Risk Score	Action	
031	SECOND	Public Health: Unisex toilet	2	3.2m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
032	SECOND	Public Health: Cleaners Cupboard	2	1.0m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
033	SECOND	Public Health: Kitchen	2	5.6m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
034	SECOND	Public Health: Files	2	11.8m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
035	SECOND	Public Health: Female toilet	2	3.0m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
036	SECOND	Public Health: Male toilet	2	3.3m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
037	SECOND	Public Health: Unisex toilet	2	4.6m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
038	SECOND	Public Health: Kitchen	2	5.8m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
039	SECOND	Public Health: Room 218	2	7.0m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
040	THIRD	Toilet: Floor	2	8.0m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.

## Survey Record Sheet

Ref: WDHB

Site Address: LAMBIE BUILDING-EXTERIOR & INTERNAL

Date: 20/04/18

Survey Type: **MANAGEMENT SURVEY**

ID Card No	Photo No	Location/Area Description	Sample Ref Category No	Quantity	Product Description	Asbestos Type	Product Type	Condition	Surface Treatment	Asbestos Type	Material Risk Score	Normal Occupant Activity	Likelihood of Disturbance	Human Exposure Potential	Maintenance Activity	Priority Risk Score	Overall Risk Score	Action	
041	THIRD	Kitchen: Floor	2	4.8m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
042	THIRD	Boys Locker Rm: Floor	2	5.0m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
043	THIRD	Locker Room: Floor	2	14.0m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
044	STAIRWAY	Stairway: Floor	2	78.5m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
045	FOURTH	Elevator Foyer: Floor	2	12.6m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
046	FOURTH	Corridor: Floor	2	17.0m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
047	FOURTH	Equipment Room: Floor	2	4.0m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
048	FOURTH	Store Cupboard: Floor	2	3.5m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
049	FOURTH	Storage Room: Floor	2	9.5m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
050	FOURTH	Store Room: Floor	2	12.0m2	Vinyl Flooring	Vinyl or Backing	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.

## Survey Record Sheet

Ref: WDHB

Site Address: LAMBIE BUILDING-EXTERIOR & INTERNAL

Date: 20/04/18

SurveyType: **MANAGEMENT SURVEY**

ID Card No	Photo No	Location/Area Description	Sample Ref Category No	Quantity	Product Description	Asbestos Type	Product Type	Condition	Surface Treatment	Asbestos Type	Material Risk Score	Normal Occupant Activity	Likelihood of Disturbance	Human Exposure Potential	Maintenance Activity	Priority Risk Score	Overall Risk Score	Action	
051	PLANT RM	Plant Room: Pipes	2	20.0m2	Gaskets Material	ACM Gaskets	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
052	PLANT RM	Elevator Room: Fuse Board	2	.200m2	Backing Board	ACM Board	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
053	EXTERIOR	Roof top: Floor	2	30.0m2	Waterproofing Material	Backing Resin	1	0	0	1	0	0	0	0	0	0	0	Very low risk	Complete a Risk Assessment.
054																			
055																			
056																			
057																			
058																			
059																			
060																			