

Scope of Works



Document explanatory note:

This document provides a summary of the earthquake damage identified by the EQC assessment team. Land, building and room by room damage is listed along with an indication of how this damage is to be repaired. A glossary of terms describing the type of damage that may be listed on your Scope of Works is provided at the end of this document.

Customer: RJ HAMPTON

Assessment of Property at 25 WESTFIELD AVENUE, TEMPLETON, CHRISTCHURCH 8042 on 7/12/2011

Site

Element	Damage	Repair
Land (Exposed - Soil - 680.00 m2)		
Land (Under dwelling - Soil - 144.00 m2)		
Main Access (Drive - Concrete - 87.50 m2)		

Services

Element	Damage	Repair
Sewerage (Town Connection - PVC Pipe - 10.00 l/m)	No Earthquake Damage	
Water Supply (Town Connection - Plastic - 10.00 l/m)	No Earthquake Damage	

Main Building

Exterior

Elevation (North lower)

Element	Damage	Repair
Wall Cladding (Brick Veneer - Brick - 19.24 m2)	Cracking	Grind out and repoint mortar 2.00 l/m
Wall framing (Timber Frame - Timber - 19.24 m2)	No Earthquake Damage	

Elevation (South lower)

Element	Damage	Repair
Wall Cladding (Brick Veneer - Brick - 19.24 m2)	Cracking	Grind out and repoint mortar 3.00 l/m
Wall framing (Timber Frame - Timber - 19.24 m2)	No Earthquake Damage	

Elevation (East lower)

Element	Damage	Repair
Wall Cladding (Brick Veneer - Brick - 31.20 m2)	Cracking Damaged finish	Grind out and repoint mortar 3.00 l/m Relay and re-bed loose bricks 0.03 m2
Wall framing (Timber Frame - Timber - 31.20 m2)	No Earthquake Damage	

Elevation (West lower)

Element	Damage	Repair
No Damage		

Elevation (North upper)

Element	Damage	Repair
---------	--------	--------

No Damage

Elevation (South upper)

Element	Damage	Repair
---------	--------	--------

No Damage

Elevation (East upper)

Element	Damage	Repair
---------	--------	--------

No Damage

Elevation (West upper)

Element	Damage	Repair
---------	--------	--------

No Damage

Roof

Element	Damage	Repair
---------	--------	--------

No Damage

Foundations

Element	Damage	Repair
---------	--------	--------

No Damage

Interior**Ground Floor - Hallway**Room Size: $8.40 \times 1.20 = 10.08$ (length(m) x width(m) = Area Size(m²))

Stud Height: 2.40 m

Element	Damage	Repair
---------	--------	--------

No Damage

Ground Floor - ToiletRoom Size: $0.80 \times 1.40 = 1.12$ (length(m) x width(m) = Area Size(m²))

Stud Height: 2.40 m

Element	Damage	Repair
---------	--------	--------

No Damage

Ground Floor - BathroomRoom Size: $1.80 \times 2.40 = 4.32$ (length(m) x width(m) = Area Size(m²))

Stud Height: 2.40 m

Element	Damage	Repair
---------	--------	--------

No Damage

Ground Floor - LaundryRoom Size: $2.50 \times 3.50 = 8.75$ (length(m) x width(m) = Area Size(m²))

Stud Height: 2.40 m

Element	Damage	Repair
---------	--------	--------

No Damage

Ground Floor - Kitchen (Dining and lounge combined)

Room Size: 7.00 x 6.20 = 43.40 (length(m) x width(m) = Area Size(m2))

Stud Height: 2.40 m

Element	Damage	Repair	
Ceiling (Gib - Stipple - 43.40 m2)	No Earthquake Damage		
Door (External) (Sliding / Ranch sliding door - Aluminium - 1.00 No of)	No Earthquake Damage		
Door (Internal) (Single Hollow Core - Timber - 1.00 No of)	No Earthquake Damage		
Floor (Chipboard - Painted dust sealed - 43.40 m2)	No Earthquake Damage		
Kitchen joinery (Medium Spec - Laminate - 1.00 item)	Impact damage	Realign doors	4.00 No of
Range (Free standing oven) (Electric - Standard Electric - 1.00 item)	No Earthquake Damage		
Range Hood (Over Head - Standard spec - 1.00 item)	No Earthquake Damage		
Wall covering (Gib - Paint - 63.36 m2)	No Earthquake Damage		
Window (Aluminium Awning - Pane single glazed - 5.00 No of)	No Earthquake Damage		
Work top (Kitchen work top - Laminate - 6.00 l/m)	No Earthquake Damage		

Ground Floor - Conservatory

Room Size: 4.00 x 3.30 = 13.20 (length(m) x width(m) = Area Size(m2))

Stud Height: 2.10 m

Element	Damage	Repair	
No Damage			

First Floor - Bedroom (Right off stairwell)

Room Size: 4.80 x 4.30 = 20.64 (length(m) x width(m) = Area Size(m2))

Stud Height: 2.40 m

Element	Damage	Repair	
Ceiling (Hardboard - Paint - 20.64 m2)	Cosmetic Damage	Sand, gap fill and paint	20.64 m2
Door (Internal) (Single Hollow Core - Timber - 1.00 No of)	No Earthquake Damage		
Floor (Chipboard - Carpet - 20.64 m2)	No Earthquake Damage		
Wall covering (Gib - Paint - 43.68 m2)	No Earthquake Damage		
Window (Aluminium Awning - Pane single glazed - 2.00 No of)	No Earthquake Damage		

First Floor - Hallway (Landing)

Room Size: 2.30 x 2.80 = 6.44 (length(m) x width(m) = Area Size(m2))

Stud Height: 3.00 m

Element	Damage	Repair	
No Damage			

First Floor - Bedroom (Next to bathroom)

Room Size: 2.40 x 4.40 = 10.56 (length(m) x width(m) = Area Size(m2))

Stud Height: 2.40 m

Element	Damage	Repair	
No Damage			

First Floor - BedroomRoom Size: 2.40 x 4.40 = 10.56 (length(m) x width(m) = Area Size(m²))

Stud Height: 2.40 m

Element	Damage	Repair
---------	--------	--------

No Damage

First Floor - AtticRoom Size: 1.70 x 1.40 = 2.38 (length(m) x width(m) = Area Size(m²))

Stud Height: 2.40 m

Element	Damage	Repair
---------	--------	--------

No Damage

First Floor - BathroomRoom Size: 2.60 x 1.80 = 4.68 (length(m) x width(m) = Area Size(m²))

Stud Height: 2.40 m

Element	Damage	Repair
---------	--------	--------

No Damage

First Floor - StairwellRoom Size: 0.80 x 4.80 = 3.84 (length(m) x width(m) = Area Size(m²))

Stud Height: 3.40 m

Element	Damage	Repair
---------	--------	--------

No Damage

Garage**Exterior****Elevation (North)**

Element	Damage	Repair
---------	--------	--------

No Damage

Elevation (South)

Element	Damage	Repair
---------	--------	--------

No Damage

Elevation (West)

Element	Damage	Repair
---------	--------	--------

No Damage

Elevation (East)

Element	Damage	Repair
---------	--------	--------

No Damage

Roof

Element	Damage	Repair
---------	--------	--------

No Damage

Foundations

Element	Damage	Repair
---------	--------	--------

No Damage

Interior**Ground Floor - Internal Garage**Room Size: 5.60 x 8.60 = 48.16 (length(m) x width(m) = Area Size(m²))

Stud Height: 2.00 m

Element	Damage	Repair
No Damage		

Scope of Works - Glossary of Terms

Cosmetic Damage	Cosmetic damage is used to record repairs to an element that can be done in situ e.g. minor cracking to plasterboard. For example a repair strategy may state "rake, stop and paint" and this is carried out without needing to remove or replace the damaged element. Where the plasterboard for example needs to be removed and replaced, this will be recorded as 'structural damage'.
Impact Damage	Impact damage is where an element or part of a building sustains earthquake damage and then breaks away or collapses causing damage to another part of the building. An example is a chimney that has collapsed and caused damage to roof tiles.
Structural Damage	The term structural damage is used where a repair requires an element to be removed and replaced e.g. major cracking to plasterboard or external cladding that has been dislodged. This term does not relate to the structural integrity of the building as a whole, but to the individual element only.

Additional Information

Building Terms	The Department of Building and Housing website has a comprehensive list of common building terms: http://www.dbh.govt.nz/building-az-wxyz
-----------------------	---