SMS Incident Report

30/05/2017 13:45:31

Summary

CAD Number F2312989 Status Closed

Station Auckland City Station

Incident Started 24/05/2017 09:25:29 Incident Ended 24/05/2017 12:11:24

Incident Type 1101: Structure fire with damage

Common Name LANGHAM AUCKLAND HOTEL TOWER

Address 83 SYMONDS STREET GRAFTON

Alarm Method Sprinkler PFA Call Alarm Level 1

PFA Number 114622 **Zone** 142011

Map Grid E 1757217 Map Grid N 5919497


First Caller Contact

Incident Closed 24/05/2017 12:11:24

Report Completed 15:36, Thur 25 May 2017 by Dave Carroll

Responses

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
AUCK205	HPNP	09:27:30 24 May 2017	09:29:33 24 May 2017	09:31:04 24 May 2017	10:32:27 24 May 2017
PARN251	P1	09:25:51 24 May 2017	09:28:41 24 May 2017	09:33:28 24 May 2017	11:14:48 24 May 2017
GREY261	P1	09:25:47 24 May 2017	09:26:52 24 May 2017	09:35:35 24 May 2017	11:19:37 24 May 2017
REMU211	P1	09:27:33 24 May 2017	09:28:56 24 May 2017	09:35:40 24 May 2017	11:10:55 24 May 2017
PARN255	HPNP	09:29:20 24 May 2017	09:31:12 24 May 2017	09:36:22 24 May 2017	10:12:21 24 May 2017
AUCK207	PR 🕜	09:55:01 24 May 2017	09:55:50 24 May 2017	10:05:42 24 May 2017	10:47:24 24 May 2017
BALM6117	SU	09:47:31 24 May 2017	10:00:02 24 May 2017	10:05:48 24 May 2017	11:18:31 24 May 2017
ONEH221	P1	09:47:28 24 May 2017	09:48:43 24 May 2017		09:55:44 24 May 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
AUCK205	00:02:01	00:03:34	00:05:35	01:06:58
PARN251	00:00:22	00:07:37	00:07:59	01:49:19
GREY261	00:00:18	00:09:48	00:10:06	01:54:08
REMU211	00:02:04	00:08:07	00:10:11	01:45:26
PARN255	00:03:51	00:07:02	00:10:53	00:46:52
AUCK207	00:29:32	00:10:41	00:40:13	01:21:55
BALM6117	00:22:02	00:18:17	00:40:19	01:53:02
ONEH221	00:21:59			00:30:15

Notifications

Date	Time	Party Notified
24 May 2017	09:29:33	PARN255 COMMITTED PER REQUEST OF SM
24 May 2017	09:53:52	ADHOC SELCAL APPLIED TO BALMORAL STN
24 May 2017	09:58:42	ADHOC SELCAL APPLIED TO BALMORAL FIRE STATION

Message Log

Time	Message
09:25:30	AL: 114622 09:25:29 INITIAL - AL
09:25:30	PANEL: MAIN SPRINKLER HOUSE CNR SYMOND ST AND CITY
09:25:31	** LOI search completed at 24/05/17 09:25:31
09:25:38	** Recommended unit GREY261 for requirement PUMP (>2.3 km)
09:25:38	** Recommended unit PARN251 for requirement PUMP (>1.5 km)
09:26:05	GREY261 K4 ON T/OUT
09:26:11	PARN251 K6 ON T/OUT
09:26:51	INC INFO: SMOKE COMING FROM BUILDING
09:26:51	Duplicate Event:Location = 83 SYMONDS ST,GRAFTON,AUCKLAND: @LANGHAM AUCKLAND
09:26:51	HOTEL TOWER, Type = STRU - STRUCTURE FIRE, Caller Ph Number =, Caller
09:26:51	Address = SYMONDS ST, Call Source = 111Inc InfoSMOKE COMING FROM BUILDING
09:26:51	End of Duplicate Event data
09:26:52	Unit GREY261 [K1 : PROCEEDING TO INCIDENT]
09:27:11	** Event Type changed from SPRNKLR to STRU at: 24/05/17 09:27:11
09:27:23	** Recommended unit AUCK205 for requirement AERIAL (>0.4 km)
09:27:23	** Recommended unit REMU211 for requirement PUMP (>3.1 km)
09:27:30	INC INFO: ALARM SOUNDING
09:27:30	Duplicate Event:Location = 83 SYMONDS ST,GRAFTON,AUCKLAND: @LANGHAM AUCKLAND
09:27:30	HOTEL TOWER, Type = STRU - STRUCTURE FIRE, Caller Ph Number = , Call
09:27:30	Source = 111Inc InfoALARM SOUNDING

wo incluent Keport	12312303	7 13.43.3
09:27:30	End of Duplicate Event data	
09:28:11	EVACUATING	
09:28:15	Duplicate Event:Location = 83 SYMONDS ST,GRAFTON,AUCKLAND: @LANGHAM AUCK	LAND
09:28:15	INC INFO: BUILDING FIRE	
09:28:15	HOTEL TOWER, Type = STRU - STRUCTURE FIRE, Call Source = 111Inc InfoBUILDING	
09:28:15	FIRE	
09:28:15	End of Duplicate Event data	×
09:28:17	INC INFO: FIRE ON ROOF	
09:28:21	FIRE ON THE ROOF	
09:28:42	Unit PARN251 [K1 : PROCEEDING TO INCIDENT]	
09:28:43	Unit GREY261 [COMCEN COM : MESSAGE] UPGRADING TO STRU TURNOUT. REPORSMOKE	T OF
09:28:43	SHOWING	
09:28:56	Unit REMU211 [K1 : PROCEEDING TO INCIDENT]	
09:29:33	Unit AUCK205 [K1 : PROCEEDING TO INCIDENT]	
09:29:55	REPORTS OF GAS BOTTLES IN THE BUILDING	
09:31:05	Unit AUCK205 [K2 : IN ATTENDANCE AT INCIDENT]	
09:31:13	Unit PARN255 [K1 : PROCEEDING TO INCIDENT]	
09:32:28	Unit AUCK205 [K77 : NOTHING SHOWING] VERBAL	
09:33:28	Unit PARN251 [K2 : IN ATTENDANCE AT INCIDENT]	
09:35:02	Unit AUCK205 [KC : UNIT CALLING]	
09:35:35	Unit GREY261 [K2 : IN ATTENDANCE AT INCIDENT]	
09:35:40	Unit REMU211 [K2 : IN ATTENDANCE AT INCIDENT]	
09:36:04	Unit AUCK205 [SITREP :] SO CAROL. SPRINKLER GONG SOUNDING. PANEL SHOWIN	IG LVL
09:36:04	6.	
09:36:23	Unit PARN255 [K2 : IN ATTENDANCE AT INCIDENT]	
09:38:35	Unit AUCK205 [KC : UNIT CALLING]	
09:39:15	Unit AUCK205 [SITREP :] REPORT OF SMOKE ON 6TH FLOOR. WORKMEN WORKING	WITH
09:39:15	TORCH AND PLASTIC. CREWS WORKING IN BA TO FIND SOURCE	
09:46:17	Unit AUCK205 [KP : PRIORITY MESSAGE]	
09:46:39	Unit AUCK205 [KP : PRIORITY MESSAGE] MAKE ST"S ONE FOR SQUEEGIES	
09:48:44	Unit ONEH221 [K1 : PROCEEDING TO INCIDENT]	
09:48:48	Unit ONEH221 [K1 : PROCEEDING TO INCIDENT]	
09:48:53	Unit ONEH221 [K1 : PROCEEDING TO INCIDENT]	
09:52:13	Unit ONEH221 [KC : UNIT CALLING]	
09:53:32	Unit ONEH221 [SITREP :] CAN YOU ACTIVATE BALMORAL STATION ALARMS	
09:55:01	FM ONEH221 HAVE NO DRIVER FOR BALM6117 REQUEST RESPOND ANOTHER APP	LIANCE
09:55:46	Unit ONEH221 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	
09:55:51	Unit AUCK207 [K1 : PROCEEDING TO INCIDENT]	
09:57:59	Unit AUCK207 [KC : UNIT CALLING]	

Swis incluent Report	12312909 4/7 30/03/2017 13:43.31
09:58:18	Unit AUCK207 [SITREP :] ACTIVATE THE BELLS FOR BALMORAL STN
10:00:02	Unit BALM6117 [K1 : PROCEEDING TO INCIDENT]
10:00:15	Unit BALM6117 [K1 : PROCEEDING TO INCIDENT]
10:01:45	Unit AUCK205 [KC : UNIT CALLING]
10:02:31	Unit AUCK205 [SITREP :] COULD YOU ADVISE THE ST TO COME IN TO THE CITY RD END
10:02:31	OF THE LANGHAM
10:02:50	Unit AUCK207 [COMCEN COM : MESSAGE] DID YOU COPY
10:02:51	Unit BALM6117 [COMCEN COM : MESSAGE] DID YOU COPY
10:04:08	Unit AUCK205 [KC : UNIT CALLING]
10:04:52	Unit AUCK205 [SITREP :] CHANGE LAST MSG FROM CITY RD END TO SYMONDS ST MAIN
10:04:52	ENTRANCE OF THE LANGHAM
10:05:20	Unit AUCK207 [SITREP :] COPIED
10:05:21	Unit BALM6117 [SITREP :] COPIED
10:05:42	Unit AUCK207 [K2 : IN ATTENDANCE AT INCIDENT]
10:05:49	Unit BALM6117 [K2 : IN ATTENDANCE AT INCIDENT]
10:05:54	COVERING UNIT TITI691 DISPATCHED TO STATION BALMORAL AT
10:05:54	D0710063
10:06:34	COVERING UNIT DEVO811 DISPATCHED TO STATION AUCKLAND
10:06:34	TERMINAL: D0710063
10:12:23	Unit PARN255 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
10:32:28	Unit AUCK205 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
10:47:26	Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
11:10:57	Unit REMU211 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
11:12:49	Unit PARN251 [KC : UNIT CALLING]
11:13:59	Unit PARN251 [STOP : MESSAGE] INCIDENT LEFT WITH HOTEL MANAGMENT. GREY LYNN IS
11:13:59	RETURNING BALMORALS SALVAGE TENDER
11:14:50	Unit PARN251 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
11:18:33	Unit BALM6117 [K7 : AT NORMAL STATION]
11:19:39	Unit GREY261 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
12:11:23	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,
12:11:23	Qualifier 2:

Incident

CAD NumberF2312989Incident ReporterDave CarrollIncident ControllerDave Carroll

Distance Travelled (km) 1

Delay In Receiving Call

Property Details

Occupant Langham Hotel

Building Owner Owner occupied

General Property Use Hotel, Motel, Lodge, Timeshare
Special Property Use Flats, Apartments, Units over 40

Purpose Group

Actions

Persons Reported Trapped No

Evacuation Status Fully evacuated

Action Prior 1 Portable extinguisher (all types)

Action Prior 2

Action Taken Salvage only

Civilians

Civilians Rescued

Civilians Extricated

Civilians Assisted

Civilians Evacuated

Origin

Location Ceiling and roof assembly

Level 5th - 10th floor

Equipment Used

Quantity	Equipment
1	Sprinkler system
2	Dry/Wet vacuum eg. Aquavac
6	Hand tools - Crowbar, Saw, Hammer, Mop, Broom, Misc small gear

Equipment Involved

Equipment Involved

Year

Make

Model

Fire

Arrival Condition Out on arrival

Heat Source Gas or liquid powered welding torch: Spark,

Ember, Flame

Termination Stage Flame

First Object Ignited Exterior roof covering surface and finish

First Object Material Adhesive, Resin, Tar

Second Object Ignited Dust, Lint, Fibre, Wood chips, Sawdust,

Shavings, Bark

Second Object Material Fabric, Fibre (finished)

Indicated Cause Heat source too close to combustibles

Certainty of Cause High

Age of PersonPersons: 17 - 64 yrsEthnicityEuropean/Pakeha

Gender Male

FAIP Service Offered No FAIP Service Accepted No

Alarms

Type of Alarm Initiating Call Sprinkler

Performance of System Detector Not in Room operated AND was EFFECTIVE

Failure/Ineffectiveness of

system

operated

Number of sprinkler heads

Structure

Area of One Floor	1600

Age of Building 2006 onwards

Structural Frame Type Reinforced concrete with non-combustible cladding

Number of Floors

Number of Basements 0

Internal Wall Lining Metal: Aluminum, Alloy, Steel

Ceiling Lining No lining present

Material Generating Most FlameFood Fats, Grease, ButterMaterial Generating Most SmokeFood Fats, Grease, Butter

Avenue of Flame Travel

Air handling ducts

Avenue of Smoke Travel

Air handling ducts

Extent of Flame Damage Confined to part of room or area of origin

Area of Flame Damage

Extent of Smoke Damage No damage of this type

Area of Smoke Damage 0

Extent of Water Damage Confined to structure of origin

Area of Water Damage 100

Extent of Fire Control Damage No damage of this type