

### 7-9 Fanshawe Street Typical Floor Layout

**XXX.X** Surface Test (Lab  
Number)

**A0XXX** Air Test (Lab  
Number)

**7-9 Fanshawe Street  
Typical Floor Layout**

**XXX.X - Debris sample (Lab  
Number) - Positive for  
asbestos**

RELEASED UNDER THE  
OFFICIAL INFORMATION ACT



1782966.1

**Level 4**

**7-9 Fanshawe Street  
Typical Floor Layout**

**XXX Surface Test  
(Lab Id)**

**A0XXX Air Test  
(Lab Number)**



**Level S**



7-9 Fanshawe Street  
Typical Floor Layout

XXXX - Sample Lab  
Reference



Level 6



RELEASED UNDER THE  
OFFICIAL INFORMATION ACT

**APPENDIX C: CERTIFICATES OF ANALYSIS**



# Hill Laboratories

TRIED, TESTED AND TRUSTED

R J Hill Laboratories Limited  
1 Clyde Street Hamilton 3216  
Private Bag 3205  
Hamilton 3240 New Zealand

T 0508 HILL LAB (44 555 22)  
T +64 7 858 2000  
E mail@hill-labs.co.nz  
W www.hill-laboratories.com

## ANALYSIS REPORT

Page 1 of 2

<b>Client:</b> Accurate Consulting Limited	<b>Lab No:</b> 1782966	A2Pv1
<b>Contact:</b> 9(2)(a)	<b>Date Received:</b> 27-May-2017	
C/- Accurate Consulting Limited	<b>Date Reported:</b> 29-May-2017	
396 Great South Road	<b>Quote No:</b> 84313	
Greenlane	<b>Order No:</b>	
Auckland 1051	<b>Client Reference:</b> AC0117	
	<b>Add. Client Ref:</b> Sampled:27/05/17	
	<b>Submitted By:</b> S9(2)(a)	

### Sample Type: Building Material

Sample Name	Lab Number	Sample Category	Sample Weight on receipt	Asbestos Presence / Absence
S1 - Composite Debris Sample To Floor On Level 4	1782966.1	Debris	10.61	Asbestos Presence / Absence Crocidolite (Blue Asbestos) detected.
S2 - Composite Swab Outside Rear Stairs Level 3	1782966.2	Other	7.85	Asbestos NOT detected.
S3 - Composite Swab Outside Rear Stairs - Level 3	1782966.3	Other	7.84	Asbestos NOT detected.
S4 - Composite Swab To Surfaces In Main Office - Level 3	1782966.4	Other	7.91	Asbestos NOT detected.
S5 - Composite Swab Outside Rear Stairs - Level 3	1782966.5	Other	7.76	Asbestos NOT detected.
S6 - Composite Swab Outside Lifts - Level 3	1782966.6	Other	7.78	Asbestos NOT detected.
S7 - Composite Swab Outside Main Stairs - Level 3	1782966.7	Other	7.71	Asbestos NOT detected.
S8 - Composite Swab To 8no Computers Level 3	1782966.8	Other	7.60	Asbestos NOT detected.
S9 - Composite Swab To 8110 Computers - Level 3	1782966.9	Other	6.92	Asbestos NOT detected.
S10 - Composite Swab Outside Lifts - Level 2	1782966.10	Other	7.65	Asbestos NOT detected.
S11 - Composite Swab Outside Main Stairs - Level 2	1782966.11	Other	7.69	Asbestos NOT detected.
S12 - Composite Swab Outside Rear Stairs - Level 2	1782966.12	Other	7.56	Asbestos NOT detected.
S13 - Composite Swab Beside Rear Stairs - Level 2	1782966.13	Other	7.66	Asbestos NOT detected.
S14 - Composite To Computers And Equipment - Level 2	1782966.14	Other	7.63	Asbestos NOT detected.
S15 - Composite Swab To Computers And Equipment - Level 2	1782966.15	Other	7.62	Asbestos NOT detected.



**IANZ**  
ACCREDITED LABORATORY

This Laboratory is accredited by International Accreditation New Zealand (IANZ), which represents New Zealand in the International Laboratory Accreditation Cooperation (ILAC). Through the ILAC Mutual Recognition Arrangement (ILAC-MRA) this accreditation is internationally recognised. The tests reported herein have been performed in accordance with the terms of accreditation, with the exception of tests marked \*, which are not accredited.



Sample Type: Building Material				
Sample Name	Lab Number	Sample Category	Sample Weight on receipt	Asbestos Presence / Absence
S16 - Composite Swab To Tim O'Brien Office (AT&T) - Level 2	1782966.16	Other	8.56	Asbestos NOT detected.
S17 - Composite Swab To Computers And Equipment - Level 2	1782966.17	Other	5.17	Asbestos NOT detected.
S18 - Composite Swab To Lift Lobby - Level 1	1782966.18	Other	7.62	Asbestos NOT detected.
S19 - Composite Swab Outside Rear Stairs -Level 1	1782966.19	Other	7.74	Asbestos NOT detected.
S20 - Composite Swab Around Windowsill Near Standing Water - Level 1	1782966.20	Other	7.86	Asbestos NOT detected.
S21 - Composite Swab To Computers And Equipment - Level 1	1782966.21	Other	7.75	Asbestos NOT detected.
S22 - Composite Swab Outside Rear Stairs - Level 1	1782966.22	Other	7.50	Asbestos NOT detected.
S23 - Composite Swab To Computers And Equipment - Level 1	1782966.23	Other	7.56	Asbestos NOT detected.
S24 - Composite Swab Inside Left Lift - Ground Floor	1782966.24	Other	7.83	Asbestos NOT detected.

#### Analyst's Comments

Appendix No.1 - Chain of Custody

## SUMMARY OF METHODS

The following table gives a brief description of the methods used to conduct the analyses for this job. The detection limits given below are those attainable in a relatively clean matrix. Detection limits may be higher for individual samples should sufficient sample be available, or if the matrix requires that dilutions be performed during analysis.

Sample Type: Building Material			
Test	Method Description	Default Detection Limit	Sample No
Asbestos in Bulk Material			
Sample Category	Assessment of sample type. Analysed at Hill Laboratories - Asbestos; 72 Grafton Road, Auckland.	-	1-24
Sample Weight on receipt	Sample weight. Analysed at Hill Laboratories - Asbestos; 72 Grafton Road, Auckland.	0.01 g	1-24
Asbestos Presence / Absence	Examination using Low Powered Stereomicroscopy followed by 'Polarised Light Microscopy' including 'Dispersion Staining Techniques'. Analysed at Hill Laboratories - Asbestos; 72 Grafton Road, Auckland. AS 4964 (2004) - Method for the Qualitative Identification of Asbestos in Bulk Samples.	-	1-24

These samples were collected by yourselves (or your agent) and analysed as received at the laboratory.

Samples are held at the laboratory after reporting for a length of time depending on the preservation used and the stability of the analytes being tested. Once the storage period is completed the samples are discarded unless otherwise advised by the client.

This report must not be reproduced, except in full, without the written consent of the signatory.

9(2)(a)

Laboratory Technician - Asbestos



### CERTIFICATE OF ANALYSIS

#### Asbestos Identification

Certificate No: 17-0433

**Client:** Accurate Consulting Ltd  
**Client Contact:** S9(2)(c)  
**Telephone:** S9(2)(a)  
**Email:** @accurateconsulting.co.nz  
**Address:** 396 Great South Road  
 Greenlane, Auckland 1051  
**Site:** 7-9 Fanshawe Street, Auckland CBD

**Date Sampled:** 29/05/2017  
**Date Received:** 29/05/2017  
**Date Analysed:** 29/05/2017  
**Order No.:** AC0117  
**Sampled By:** As Received

**Test Method:**

Qualitative identification of asbestos types in bulk samples at PROLABS Laboratory by polarised light microscopy, including dispersion staining techniques using PROLABS in-house method ID-1, AS4964 (2004). The results contained within this report relate only to the sample(s) submitted for testing. PROLABS accepts no responsibility for the initial collection, packaging or transportation of samples submitted by external persons. This document may not be reproduced except in full.

Lab ID	Sample ID	Sample Details	Sample Type	Size / Weight cm/g	Fibres Identified	Asbestos Present
001	S1	Level 6	Dust / Debris	N/A	NAD, ORF	No
002	S2	Level 6	Dust / Debris	N/A	NAD, ORF	No
003	S3	Level 5	Dust / Debris	N/A	NAD, ORF	No
004	S4	Level 5	Dust / Debris	N/A	NAD, ORF, SMF	No
005	S5	Level 5	Dust / Debris	N/A	NAD, ORF, SMF	No
006	S6	Level 6	Dust / Debris	N/A	NAD, ORF	No
007	S7	Level 6	Dust / Debris	N/A	NAD, ORF, SMF	No
008	S8	Level 6	Dust / Debris	N/A	NAD, ORF, SMF	No
009	S9	Level 6	Dust / Debris	N/A	NAD, ORF	No
010	S10	Level 6	Dust / Debris	N/A	NAD, ORF	No
011	S11	Level 6	Dust / Debris	N/A	NAD, ORF	No
012	S12	Level 6	Dust / Debris	N/A	NAD, ORF	No
013	S13	Level 6	Dust / Debris	N/A	NAD, ORF	No
014	S14	Level 6	Dust / Debris	N/A	NAD, ORF, SMF	No
015	S15	Level 6	Dust / Debris	N/A	NAD, ORF	No
016	S16	Level 6	Dust / Debris	N/A	NAD, ORF, SMF	No
017	S17	Level 5	Dust / Debris	N/A	NAD, ORF, SMF	No
018	S18	Level 5	Dust / Debris	N/A	NAD, ORF	No
019	S19	Level 5	Dust / Debris	N/A	NAD, ORF, SMF	No
020	S20	Level 5	Dust / Debris	N/A	NAD, ORF	No
021	S21	Level 5	Dust / Debris	N/A	NAD, ORF, SMF	No
022	S22	Level 5	Dust / Debris	N/A	NAD, ORF, SMF	No
023	S23	Level 5	Dust / Debris	N/A	NAD, ORF, SMF	No
024	S24	Level 5	Dust / Debris	N/A	NAD, ORF, SMF	No
025	S25	Level 5	Dust / Debris	N/A	NAD, ORF	No
026	S26	Level 5	Dust / Debris	N/A	NAD, ORF	No
027	S27	Level 5	Dust / Debris	N/A	NAD, ORF, SMF	No

Lab ID	Sample ID	Sample Details	Sample Type	Size / Weight cm/g	Fibres Identified	Asbestos Present
028	S28	Level 5	Dust / Debris	N/A	NAD, ORF, SMF	No
029	S29	Level 5	Dust / Debris	N/A	NAD, ORF, SMF	No
030	S30	Level 5	Dust / Debris	N/A	NAD, ORF	No
031	S31	Level 5	Dust / Debris	N/A	NAD, ORF	No
032	S32	Level 5	Dust / Debris	N/A	NAD, ORF	No
033	S33	Level 5	Dust / Debris	N/A	NAD, ORF	No

**Fibre Identification Legend**

CHR	Chrysotile (white asbestos)	ORF	Organic Fibre
AMO	Amosite (Brown/Grey asbestos)	SMF	Synthetic Mineral Fibre
CRO	Crocidolite (Blue asbestos)	NFD	No Fibres Detected
LIMF	Unknown Mineral Fibre	NAD	No Asbestos Detected

9(2)(a)

RELEASED  
 OFFICIAL INFORMATION



## AIRBORNE FIBRE CONCENTRATION CERTIFICATE

Job N°	AC0112 20170526 MW01	Sampled by	Accurate Consulting Ltd
Date Received	26 <sup>th</sup> May 2017	Date Reported	27 <sup>th</sup> May 2017
Sampling Date	26 <sup>th</sup> May 2017	Date of Analysis	27 <sup>th</sup> May 2017
Client	Stride Properties	Client Reference	-
Attention:	59(2)(a)	Site	7-9 Fanshawe Street Auckland 1010
Client Address	Level 12 34 Shortland Street Auckland 1010		

Lab Reference	Location	Start (time)	End (time)	Total (mins)	Flow rate (L/min start)	Flow rate (L/min end)	Flow rate (L/min avg)	Fibre count	Fibres/ml
A0264	Level 1 – Main Stairwell	15.45	18.25	220	3.0	3.0	3.0	1.0	<0.01
A0265	Level 2 – Main Stairwell	15.47	19.28	221	3.0	3.0	3.0	1.0	<0.01
A0266	Level 3 – Main Stairwell	15.50	19.30	220	3.0	3.0	3.0	0	<0.01
A0267	Level 5 – Main Stairwell	15.58	19.32	214	3.0	3.0	3.0	2.0	<0.01
A0268	Level 6 – Main Stairwell	16.03	19.36	213	3.0	3.0	3.0	0	<0.01
A0304	Level 5 – Main Office	16.17	19.52	215	3.0	3.0	3.0	2.0	<0.01
A0305	Level 2 – Rear Stairwell	16.19	19.54	215	3.0	3.0	3.0	2.0	<0.01
A0306	Level 3 – Rear Stairwell	16.10	19.43	213	3.0	3.0	3.0	1.0	<0.01
A0307	Level 3 – Main Office	16.15	19.47	212	3.0	3.0	3.0	0	<0.01
A0308	Level 3 – Lift Lobby	16.22	19.58	216	3.0	3.0	3.0	3.0	<0.01





**Test Methods**

*Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres 2<sup>nd</sup> Edition [NOHSC:3003 (April 2005)].*

*In-house procedure – Section 15 Procedure Air Monitoring*

*In-house procedure – Section 17 Estimating Airborne Fibre Concentrations*

*In-house procedure – Section 18 Reporting of Results*

**Analyst**

9(2)(a)

**Signatory**

*Fibre count results (fibres/100 fields).*

Where the Air Monitoring is not conducted by Accurate Consulting Limited and information is supplied by the client Accurate Consulting Limited cannot be held responsible for any errors caused by sampling or equipment calibrations.

**End of Report**

RELEASED UNDER THE  
OFFICIAL INFORMATION ACT

## End of Report

This report was prepared solely for the purpose set out herein and it is not intended that any other person use or rely on it.

Whilst all due care is taken any information within this report that has relied on information from previous assessments made by others including visual inspections, laboratory testing and overall methodologies cannot be guaranteed for its accuracy or competency

This report is not intended to be used for the purposes of tendering, programming of works, dismantling or demolition works unless used in conjunction with a specification detailing the extent of the works. To ensure its contextual integrity, the report must be read in its entirety and should not be copied, distributed or referred to in part only. Measurements and calculations by volume of any material should not be used for contractual terms as the measurements represented are approximate.



Ref: AC0117  
14<sup>th</sup> June 2017

Att. 59(2)(a)  
Stride Property,  
Level 12, 34 Shortland Street  
Auckland 1010, New Zealand

Dear 59(2)(a)

### 7-9 Fanshawe Street – Basement to Level 5 Rear Staircase – Dust Sampling

On Tuesday 13<sup>th</sup> June 2017, 9(2)(a) of Accurate Consulting Ltd attended site at the above address to undertake surface testing for asbestos within the rear staircase where access has been restricted following the fire event on 26<sup>th</sup> May 2017. The following summarises our findings.

**Asbestos was detected** within the composite surface tests and debris samples taken from the following areas on 13<sup>th</sup> June:

- Sample 3 Ground debris to stairs – **Chrysotile**
- Sample 4 Level 1 debris to floor (Comp) Dust / Debris N/A – **Chrysotile**

**No Asbestos was detected** within the composite surface tests and debris samples taken from the following areas on 13<sup>th</sup> June:

- Sample 1 Basement Floor (Comp) Dust / Debris
- Sample 2 Basement/Ground debris to floor
- Sample 5 Level 2 debris to floor (Comp) Dust / Debris
- Sample 6 Level 3 debris to floor (Comp) Dust / Debris
- Sample 7 Level 4 wall (Comp) Dust / Debris
- Sample 8 Level 4 dust to floor (Comp) Dust / Debris
- Sample 9 Level 5 floor/ledge (Comp) Dust / Debris
- Sample 10 Level 4/5 debris (Comp) Dust / Debris

See **Appendix A** for full sample analysis results.

Please don't hesitate to get in touch if you have any questions regarding the information above.

Yours Sincerely,

9(2)(a)

9(2)(a)

Consultant  
Accurate Consulting Ltd



**APPENDIX A CERTIFICATE OF ANALYSIS**

RELEASED UNDER THE  
OFFICIAL INFORMATION ACT

## CERTIFICATE OF ANALYSIS Asbestos Identification

Certificate No: 17-0519

Client: Accurate Consulting Ltd

Date Sampled: 13/06/2017

Client Contact: 9(2)(a)

Date Received: 13/06/2017

Telephone: 9(2)(a)

Date Analysed: 13/06/2017

Email: 9(2)(a)

Order No.: AC0117

Address: 396 Great South Road  
 Greenlane, Auckland 1051

Sampled By: As Received

Site: 3-7 Fanshawe St - Rear Stairwell

### Test Method:

Qualitative identification of asbestos types in bulk samples at PROLABS Laboratory by polarised light microscopy, including dispersion staining techniques using PROLABS in-house method ID-1, AS4964 (2004). The results contained within this report relate only to the sample(s) submitted for testing. PROLABS accepts no responsibility for the initial collection, packaging or transportation of samples submitted by external persons. This document may not be reproduced except in full.

Lab ID	Sample ID	Sample Details	Sample Type	Size / Weight cm/g	Fibres Identified	Asbestos Present
001	Sample 1	Basement Floor (Comp)	Dust / Debris	N/A	NAD, ORF, SMF	No
002	Sample 2	Basement/Ground debris to floor (Comp)	Dust / Debris	N/A	NAD, ORF, SMF	No
003	Sample 3	Ground debris to stairs (Comp)	Dust / Debris	N/A	CHR, ORF, SMF	Yes
004	Sample 4	Level 1 debris to floor (Comp)	Dust / Debris	N/A	CHR, ORF, SMF	Yes
005	Sample 5	Level 2 debris to floor (Comp)	Dust / Debris	N/A	NAD, ORF, SMF	No
006	Sample 6	Level 3 debris to floor (Comp)	Dust / Debris	N/A	NAD, ORF, SMF	No
007	Sample 7	Level 4 wall (Comp)	Dust / Debris	N/A	NAD, SMF	No
008	Sample 8	Level 4 dust to floor (Comp)	Dust / Debris	N/A	NAD, ORF, SMF	No
009	Sample 9	Level 5 floor/ledge (Comp)	Dust / Debris	N/A	NAD, SMF	No
010	Sample 10	Level 4/5 debris (Comp)	Dust / Debris	N/A	NAD, SMF	No

### Fibre Identification Legend

CHR	Chrysotile (white asbestos)	ORF	Organic Fibre
AMO	Amosite (Brown/Grey asbestos)	SMF	Synthetic Mineral Fibre
CRO	Crocidolite (Blue asbestos)	NFD	No Fibres Detected
UMF	Unknown Mineral Fibre	NAD	No Asbestos Detected

9(2)(a)

RELEASED UNDER THE  
OFFICIAL INFORMATION ACT

End of Report

This report was prepared solely for the purpose set out herein and it is not intended that any other person use or rely on it.

Whilst all due care is taken any information within this report that has relied on information from previous assessments made by others including visual inspections, laboratory testing and overall methodologies cannot be guaranteed for its accuracy or competency

This report is not intended to be used for the purposes of tendering, programming of works, dismantling or demolition works unless used in conjunction with a specification detailing the extent of the works. To ensure its contextual integrity, the report must be read in its entirety and should not be copied, distributed or referred to in part only. Measurements and calculations by volume of any material should not be used for contractual terms as the measurements represented are approximate.





Accurate  
Consulting Ltd

## Clearance Certificate

### Stride Properties

Level 4 Lift Lobby  
7-9 Fanshawe Street  
Auckland 1010

Reference No: AC0122.51



Inspected by:	9(2)(a)
Reported By:	
Checked and Authorised by:	
Date of Inspection:	6 <sup>th</sup> July 2017
Date of Issue:	6 <sup>th</sup> July 2017
Client:	Spark NZ C/o TBIG
Revision:	Rev.0

# Clearance Certificate Friable Asbestos

This certificate is for attention of	Stride Properties
Site Address	7-9 Fanshawe Street, Auckland
Location	Level 4 Lift Lobby
Asbestos Removal Contractor	PDS
Supervisor	S (9) (2) (a)
Brief Description of Removal Works	Environmental clean of all surfaces inside level 4 lift lobby of potentially contaminated residue (Room fully wrapped in plastic).
Accurate Consulting Assessor	9(2)(a)
Authorised Signature	
Date	6 <sup>th</sup> July 2017 - 1100hrs



## Preliminary Check of Site Condition and Job Completeness (Stage 1)

<i>The following has been checked as satisfactory</i>	Yes	No	Not Assessed	Details
Asbestos Removal Control Plan (ARCP) available to and checked by Assessor	✓			
ARCP site layout diagram accurate (or amended appropriately)	✓			
ARCP description of material to be removed clear and accurate	✓			
Worksafe notification available to and checked by Assessor	✓			
<i>The following are operational</i>				
Negative pressure arrangements	✓			1 x AMS 1500
Vacuum cleaner	✓			
Hygiene facilities - hot/cold water, heating, NPI	✓			
Enclosure / work area - adequate lighting and essential inspection equipment	✓			
Enclosure / work area viewing panels	✓			
<i>The following are free of obvious risks, debris &amp; waste</i>				
Enclosure / work area & adjacent areas	✓			
Waste route and storage area	✓			
Transit route	✓			
Hygiene facilities	✓			
Additional notes				
Stage 1 Successful	Pass			
Stage 1 Assessor	9(2)(a)			
Stage 1 Assessor Signature				




Thorough Visual Inspection (Stage 2)				
The following were assessed and found to be satisfactory:	Yes	No	Not Assessed	Details
Enclosure air lock cleanliness	✓			
Enclosure dryness	✓			
Enclosure / work area condition & integrity	✓			
Plant / equipment covers removed			✓	
Ceiling / wall / floor surface cleanliness	✓			Plastic covers all walls, ceiling and floor - this will remain
Culvert / drain / sump cleanliness			✓	
Boiler / tank / pipe work etc. cleanliness (Inc. undersides)			✓	
Support bracket cleanliness			✓	
Trays / cable / conduit cleanliness			✓	
Nuts / bolts / flanges / nut hole cleanliness			✓	
Light fitting cleanliness			✓	
Ledge / window sill / shelf cleanliness			✓	
Screw holes / ground nuts cleaned or drilled			✓	
Plant / equipment covered or uncovered during removal cleanliness (esp. oily surfaces)			✓	
Portable equipment cleanliness	✓			
Polythene sheeting cleanliness (Inc. folds)	✓			
Enclosure / work area surface vacuum cleaning	✓			
Additional Notes				
Stage 2 Successful	Pass			
Stage 2 Assessor	9(2)(a)			
Stage 2 Assessor Signature				



### Clearance Air Monitoring (Stage 3)

The following were assessed and found to be satisfactory:	Yes	No	Not Assessed	Details
Original floor surface uncovered		√		
Enclosure surface disturbance method used	Brushing			
Duration of disturbance (minutes)	3			
NPU / Extractor switched off	√			
NPU / Extractor sealed	√			
NPU / Extractor pre-filter changed	√			

- NPU – Roving head
- ▤ DCU
- ✱ Air Sample



#### Enclosure Sketch

Enclosure Height (m)	2.5
Enclosure Area (m <sup>2</sup> )	12m <sup>2</sup>
Number of clearance samples required	2
Surface Testing Required Y/N	Y
Result of Surface Testing	No asbestos detected
Air Sample Results	<0.01f/ml
Additional Notes	-
Stage 3 Successful Yes/No	Yes
Stage 3 Assessor	9(2)(a)
Stage 3 Assessor Signature	

**LABORATORY RESULTS - Asbestos Air Monitoring**

RELEASED UNDER THE  
OFFICIAL INFORMATION ACT





## AIRBORNE FIBRE CONCENTRATION CERTIFICATE

Job N°	AC0117 20170706 ES01	Sampled by	Accurate Consulting Ltd
Date Received	6 <sup>th</sup> July 2017	Date Reported	6 <sup>th</sup> July 2017
Sampling Date	6 <sup>th</sup> July 2017	Date of Analysis	6 <sup>th</sup> July 2017
Client	Stride Properties	Client Reference	L4 Lift Lobby Clearance
Attention:	<b>S 9(2)(a)</b>	Site	7-9 Fanshawe Street Auckland 1010
Client Address	Level 12 34 Shortland Street Auckland 1010		

Lab Reference	Location	Start (time)	End (time)	Total (mins)	Flow rate (L/min start)	Flow rate (L/min end)	Flow rate (L/min avg)	Fibre count	Fibres/ml
A0747	Level 4 Lift Lobby	10.50	14.15	205	3.0	3.0	3.0	2.5	<0.01
A0748	Level 4 Lift Lobby	10.50	14.15	205	3.0	3.0	3.0	1	<0.01

**Test Methods**

*Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres 2<sup>nd</sup> Edition [NOHSC:3003 (April 2005)].*

*In-house procedure – Section 15 Procedure Air Monitoring*

*In-house procedure – Section 17 Estimating Airborne Fibre Concentrations*

*In-house procedure – Section 18 Reporting of Results*

**Analyst**

**9(2)(a)**

**Signatory**

*Fibre count results (fibres/100 fields).*

Where the Air Monitoring is not conducted by Accurate Consulting Limited and information is supplied by the client Accurate Consulting Limited cannot be held responsible for any errors caused by sampling or equipment calibrations.

**End of Report**

**LABORATORY RESULTS - Surface Testing**

RELEASED UNDER THE  
OFFICIAL INFORMATION ACT

FORM Y1

Version 1 - 12 July 2017

C:\Users\Emrhys\Documents\Sync\ACCURATE SERVER\Work 2017\Stride\7-9 Fanshawe Level 4 Lift  
Lobby\Clearance\AC0117 - Clearance Certificate - Level 4 Lift Lobby.docx

Uncontrolled when printed



## CERTIFICATE OF ANALYSIS

### Asbestos Identification

Certificate No: 17-0706

<b>Client:</b>	Accurate Consulting Ltd	<b>Date Sampled:</b>	6/07/2017
<b>Client Contact:</b>	9(2)(a)	<b>Date Received:</b>	6/07/2017
<b>Telephone:</b>	021 447 672	<b>Date Analysed:</b>	6/07/2017
<b>Email:</b>	9(2)(a)	<b>Order No.:</b>	AC0117
<b>Address:</b>	Level 1, 47A Mt Wellington Hwy Mt Wellington 1060	<b>Sampled By:</b>	As Received
<b>Site:</b>	7-9 Fanshawe Street - Level 4, lift lobby		

**Test Method:**

Qualitative identification of asbestos types in bulk samples at PROLABS Laboratory by polarised light microscopy, including dispersion staining techniques using PROLABS in-house method ID-1, AS4964 (2004). The results contained within this report relate only to the sample(s) submitted for testing. PROLABS accepts no responsibility for the initial collection, packaging or transportation of samples submitted by external persons. This document may not be reproduced, except in full.

Lab ID	Sample ID	Sample Details	Sample Type	Size / Weight cm/g	Fibres Identified	Asbestos Present
001	Sample 1	Clearance Swab taken from walls	Dust / Debris	N/A	NAD, ORF	No
002	Sample 2	Clearance Swab taken from floor surface	Dust / Debris	N/A	NAD, ORF	No

**Fibre Identification Legend**

CHR	Chrysotile (white asbestos)	ORF	Organic Fibre
AMO	Amosite (Brown/Grey asbestos)	SMF	Synthetic Mineral Fibre
CRO	Crocidolite (Blue asbestos)	NFD	No Fibres Detected
UMF	Unknown Mineral Fibre	NAD	No Asbestos Detected

9(2)(a)



Assessment of Site for Reoccupation (Stage 4)				
<i>The following were assessed and found to be satisfactory:</i>	Yes	No	Not Assessed	Details
Surrounds of the former work area / enclosure location cleanliness	✓			Plastic surrounds to remain.
Visible debris and waste removal	✓			
Transfer route and waste area cleanliness	✓			
Remaining asbestos containing material integrity	✓			Outer surface of plastic enclosure potentially still contaminated
Additional Notes	Plastic enclosure to remain as ceiling will be dropped after remediation of level 4 completed, then a final Stage 4 inspection will be performed.			
Stage 4 Successful	Pass			
Date	6 <sup>th</sup> July 2017			
<p><i>I declare that</i></p> <p><i>I found no visible asbestos residue from asbestos removal work in the area, or in the vicinity of the area, where the work was carried out; and</i></p> <p><i>All monitoring shows the respirable fibre level does not exceed 0.01 fibres/ml; and</i></p> <p><i>As far as can be determined from the clearance inspection, the asbestos removal area does not pose a risk to health and safety from exposure to asbestos.</i></p>				
Stage 4 Assessor	9(2)(a)			
Stage 4 Assessor Signature				
Clearance Granted	Granted			



**End of Report**

RELEASED UNDER THE  
OFFICIAL INFORMATION ACT



Accurate  
Consulting Ltd

## Integrity Test – Fail (1)

### Stride Properties

Level 4 Main Floor  
7-9 Fanshawe Street  
Auckland 1010

Reference No: AC0226.2



Inspected by:	9(2)(a)
Reported By:	
Checked and Authorised by:	
Date of Test:	10 <sup>th</sup> July 2017
Date of Issue:	10 <sup>th</sup> June 2017
Client:	Spark NZ C/o TBIG
Revision:	Rev.0



# Integrity Test – Smoke Test

This certificate is for attention of	Stride
Site Address	7-9 Fanshawe St
Location	Level 4 Main Floor
Asbestos Removal Contractor	PDS
Supervisor	S9(2)(a)
Brief Description of Removal Works	Removal of sprayed coating residue to Ceiling. Level 4 then suffered damage from a fire on Friday 26 <sup>th</sup> May which has contaminated the tenancy with the Spray Coating Residue. The scope of works now includes the environmental clean of level 4 as well as the removal of the remaining asbestos coating.
Accurate Consulting Assessor	9(2)(a)
Authorised Signature	9(2)(a)
Client Witness	S9(2)(a)
Contact Details	9(2)(a)
Date	10 <sup>th</sup> July 2017 – 1330hrs



Preliminary Check of Site Condition (Stage 1)				
The following has been checked as satisfactory:	Yes	No	Not Assessed	Details
Asbestos Removal Control Plan (ARCP) available to and checked by Assessor	✓			
ARCP site layout diagram accurate (or amended appropriately)	✓			
ARCP description of material to be removed clear and accurate	✓			
<i>The following are operational:</i>				
Negative pressure arrangements	✓			4 x AMS 4000 2 x AMS 1500
Vacuum cleaner	✓			
Hygiene facilities - hot/cold water heating, NPU	✓			4 stage wet dock
Enclosure / work area - adequate lighting and essential inspection equipment	✓			
Enclosure / work area viewing panels		✓		Not possible
<i>The following are free of obvious risks: debris &amp; waste:</i>				
Enclosure / work area & adjacent areas	✓			
Waste route and storage area	✓			
Transit route	✓			
Hygiene facilities	✓			
Additional notes				
Stage 1 Successful	Pass			
Stage 1 Assessor	9(2)(a)			
Stage 1 Assessor Signature				



Smoke Test (Stage 2)	
Enclosure Height (m)	3
Enclosure Area (m <sup>2</sup> )	600
Enclosure Area (m <sup>3</sup> )	1800
Number of clearance samples required (See Below)	8
Smoke Generated into Enclosure	Yes
Enclosure Inspected for Leaks	Yes - leaks observed to rear staircase, both sides
Time for Smoke to Leave in Minutes	
Approximate Air Changes per Hour	
Additional Notes	
Stage 2 Successful	Fail
Stage 2 Assessor	9(2)(a)
Stage 2 Assessor Signature	

### Clearance Samples Required

Enclosure Area M <sup>2</sup>	Enclosure Area M <sup>3</sup>	N <sup>o</sup> of Samples
50	150	2
200	600	4
500	1,500	6
1,000	3,000	9
5,000	15,000	16
10,000	30,000	20



Accurate  
Consulting Ltd

## Minor ACD Clearance Certificate

Reference No: AC0117.26

### Stride Properties

Level 1  
7-9 Fanshawe Street  
Auckland 1010



Inspected by:	9(2)(a)
Reported By:	
Checked and Authorised by:	
Date of Inspection:	8 <sup>th</sup> June 2017
Date of Issue:	8 <sup>th</sup> June 2017
Client:	Spark NZ C/o TBIG
Revision:	Rev.0



# Clearance Certificate

## Minor Asbestos Containing Dust / Debris

This certificate is for attention of	Stride Properties
Site Address	7-9 Fanshawe Street, Auckland
Location	Level 1 – Each area marked on plans
Asbestos Removal Contractor	PDS
Supervisor	59(2)(a)
Brief Description of Removal Works	Removal of any potentially asbestos contaminated materials and remediation of potentially contaminated water residue from level 1 of building.
Accurate Consulting Assessor	9(2)(a)
Authorised Signature	
Date	8 <sup>th</sup> June 2017



Preliminary Check of Site Condition and Job Completeness (Stage 1)				
The following has been checked as satisfactory:	Yes	No	Not Assessed	Details
Asbestos Removal Control Plan (ARCP) available to and checked by Assessor		✓		
ARCP site layout diagram accurate (or amended appropriately)		✓		
ARCP description of material to be removed clear and accurate		✓		
<i>The following are operational:</i>				
Vacuum cleaner		✓		
Hygiene facilities – Bucket/Wet Wipes/Overalls		✓		
Enclosure / work area – adequate lighting and essential inspection equipment if required		✓		
<i>The following are free of obvious risks, debris &amp; waste:</i>				
Enclosure / work area & adjacent areas	✓			
Waste route and storage area	✓			
Transit route	✓			
Hygiene facilities			✓	Semi controlled with respirator zones located in each work area
Additional notes	-			
Stage 1 Successful	Pass			
Stage 1 Assessor	9(2)(a)			
Stage 1 Assessor Signature				



## Thorough Visual Inspection (Stage 2)

The following were assessed and found to be satisfactory:	Yes	No	Not Assessed	Details
Enclosure dryness			✓	
Enclosure / work area condition & integrity	✓			
Plant / equipment covers removed			✓	
Ceiling / wall / floor surface cleanliness	✓			
Culvert / drain / sump cleanliness			✓	
Boiler / tank / pipe work etc. cleanliness	✓			
Support bracket cleanliness			✓	
Trays / cable / conduit cleanliness			✓	
Nuts / bolts / flanges / hatch cleanliness			✓	
Light fitting cleanliness			✓	
Ledge / window sill / shelf cleanliness	✓			
Screw holes / axonal nails cleaned or drilled			✓	
Plant / equipment (covered or uncovered during removal) cleanliness (esp. oily surfaces)			✓	
Portable equipment cleanliness			✓	
Polythene sheeting cleanliness (inc folds)			✓	
Enclosure / work area surface vacuum cleaning	✓			
Additional Notes	Work carried out as minor ACD, air monitoring performed during works all below 0.01f/ml. There were two areas of no access – the Vector room and a cupboard by the kitchen ( <b>Marked on plan</b> ).			
Stage 2 Successful	Pass			
Stage 2 Assessor	9(2)(a)			
Stage 2 Assessor Signature				
Clearance Granted	Granted			

**Appendix A – SURFACE TESTING RESULTS**

RELEASED UNDER THE  
OFFICIAL INFORMATION ACT



## CERTIFICATE OF ANALYSIS

### Asbestos Identification

Certificate No: 17-0476

**Client:** Accurate Consulting Ltd

**Date Sampled:** 8/06/2017

**Client Contact:** 9(2)(a)

**Date Received:** 8/06/2017

**Telephone:** 9(2)(a)

**Date Analysed:** 8/06/2017

**Email:** 9(2)(a)

**Order No.:** AC0117

**Address:** 396 Great South Road  
 Greenlane, Auckland 1051

**Sampled By:** As Received

**Site:** 7-9 Fanshawe Street, Level 1

**Test Method:**

Qualitative identification of asbestos types in bulk samples at PROLABS Laboratory by polarised light microscopy, including dispersion staining techniques using PROLABS in-house method ID-1, AS4964 (2004). The results contained within this report relate only to the sample(s) submitted for testing. PROLABS accepts no responsibility for the initial collection, packaging or transportation of samples submitted by external persons. This document may not be reproduced except in full.

Lab ID	Sample ID	Sample Details	Sample Type	Size / Weight cm/g	Fibres Identified	Asbestos Present
001	Sample 1	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
002	Sample 2	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
003	Sample 3	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
004	Sample 4	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
005	Sample 5	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
006	Sample 6	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
007	Sample 7	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
008	Sample 8	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
009	Sample 9	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
010	Sample 10	Refer to plan	Dust / Debris	N/A	NAD, ORF	No

**Fibre Identification Legend**

CHR	Chrysotile (white asbestos)	ORF	Organic Fibre
AMC	Amosite (Brown/Grey asbestos)	SMF	Synthetic Mineral Fibre
CRO	Crocidolite (Blue asbestos)	NFD	No Fibres Detected
UMF	Unknown Mineral Fibre	NAD	No Asbestos Detected


9(2)(a)

**Appendix B – LEVEL 1 SAMPLING PLAN**

RELEASED UNDER THE  
OFFICIAL INFORMATION ACT



### 7-9 Fanshawe Street Typical Floor Layout





Accurate  
Consulting Ltd

## Minor ACD Clearance Certificate

Reference No: AC0117.36

**Stride Properties**

Level 2

7-9 Fanshawe Street

Auckland 1010



Inspected by:	9(2)(a)
Reported By:	
Checked and Authorised by:	
Date of Inspection:	14 <sup>th</sup> June 2017
Date of Issue:	14 <sup>th</sup> June 2017
Client:	Spark NZ C/o TBIG
Revision:	Rev.0



# Clearance Certificate

## Minor Asbestos Containing Dust / Debris

This certificate is for attention of	Stride Properties
Site Address	7-9 Fanshawe Street, Auckland
Location	Level 2 - Each area marked on plans
Asbestos Removal Contractor	PDS
Supervisor	S 9(2)(a)
Brief Description of Removal Works	Removal of any potentially asbestos contaminated materials and remediation of potentially contaminated water residue from level 2 of building.
Accurate Consulting Assessor	9(2)(a)
Authorised Signature	
Date	14 <sup>th</sup> June 2017



<b>Preliminary Check of Site Condition and Job Completeness (Stage 1)</b>				
<i>The following has been checked as satisfactory</i>	Yes	No	Not Assessed	Details
Asbestos Removal Control Plan (ARCP) available to and checked by Assessor		✓		
ARCP site layout diagram accurate (or amended appropriately)		✓		
ARCP description of material to be removed clear and accurate		✓		
<i>The following are operational:</i>				
Vacuum cleaner	✓			
Hygiene facilities – Bucket/Wet Wipes/Overalls	✓			
Enclosure / work area – adequate lighting and essential inspection equipment if required	✓			
<i>The following are free of obvious risks, debris &amp; waste:</i>				
Enclosure / work area & adjacent areas	✓			
Waste route and storage area	✓			
Transit route	✓			
Hygiene facilities			✓	Semi controlled with respirator zones located in each work area
Additional notes	-			
Stage 1 Successful	Pass			
Stage 1 Assessor	9(2)(a)			
Stage 1 Assessor Signature				



## Thorough Visual Inspection (Stage 2)

The following were assessed and found to be satisfactory:	Yes	No	Not Assessed	Details
Enclosure dryness			√	
Enclosure / work area condition & integrity	√			
Plant / equipment covers removed			√	
Ceiling / wall / floor surface cleanliness	√			
Gully / drain / sump cleanliness			√	
Boiler / tank / pipe work etc. cleanliness	√			
Support bracket cleanliness			√	
Trays / cable / conduit cleanliness			√	
Nuts / bolts / flanges / hatch cleanliness			√	
Light fitting cleanliness			√	
Ledge / window sill / shelf cleanliness	√			
Screw holes / around nails cleaned or drilled			√	
Plant / equipment (covered or uncovered during removal) cleanliness (esp. oily surfaces)			√	
Portable equipment cleanliness			√	
Polythene sheeting cleanliness (inc. folds)			√	
Enclosure / work area surface vacuum cleaning	√			
Additional Notes	Work carried out as minor ACD, air monitoring performed during works all below 0.01f/ml. Bagged possessions remain to be viewed by occupant before disposal. Carpet remains below server in Epson office.			
Stage 2 Successful	Pass			
Stage 2 Assessor	9(2)(a)			
Stage 2 Assessor Signature				
Clearance Granted	Granted			



**Appendix A – SURFACE TESTING RESULTS**

RELEASED UNDER THE  
OFFICIAL INFORMATION ACT



## CERTIFICATE OF ANALYSIS

### Asbestos Identification

Certificate No: 17-0541

Client: Accurate Consulting Ltd

Date Sampled: 14/06/2017

Client Contact: 9(2)(a)

Date Received: 15/06/2017

Telephone: 9(2)(a)

Date Analysed: 15/06/2017

Email: 9(2)(a)

Order No.: AC0117

Address: 396 Great South Road  
 Greenlane, Auckland 1051

Sampled By: As Received

Site: 7-9 Fanshawe Street, Level 2

#### Test Method:

Qualitative identification of asbestos types in bulk samples at PROLABS Laboratory by polarised light microscopy, including dispersion staining techniques using PROLABS in-house method ID-1, AS4964 (2004). The results contained within this report relate only to the sample(s) submitted for testing. PROLABS accepts no responsibility for the initial collection, packaging or transportation of samples submitted by external persons. This document may not be reproduced except in full.

Lab ID	Sample ID	Sample Details	Sample Type	Size / Weight cm/g	Fibres Identified	Asbestos Present
001	Clearance Swab 1	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
002	Clearance Swab 2	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
003	Clearance Swab 3	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
004	Clearance Swab 4	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
005	Clearance Swab 5	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
006	Clearance Swab 6	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
007	Clearance Swab 7	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
008	Clearance Swab 8	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
009	Clearance Swab 9	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
010	Clearance Swab 10	Refer to plan	Dust / Debris	N/A	NAD, ORF	No
011	Clearance Swab 11	Refer to plan	Dust / Debris	N/A	NAD, ORF	No

#### Fibre Identification Legend

CHR	Chrysotile (white asbestos)	ORF	Organic Fibre
AMO	Amosite (Brown/Grey asbestos)	SMF	Synthetic Mineral Fibre
CRO	Crocidolite (Blue asbestos)	NFD	No Fibres Detected
UMF	Unknown Mineral Fibre	NAD	No Asbestos Detected

9(2)(a)

RELEASED UNDER THE  
OFFICIAL INFORMATION ACT



## AIRBORNE FIBRE CONCENTRATION CERTIFICATE

Job N°	AC0117 20170613 DM01	Sampled by	Accurate Consulting Ltd
Date Received	13 <sup>th</sup> June 2017	Date Reported	13 <sup>th</sup> June 2017
Sampling Date	13 <sup>th</sup> June 2017	Date of Analysis	13 <sup>th</sup> June 2017
Client	Stride Properties	Client Reference	-
Attention:	<b>59(2)(a)</b>	Site	7-9 Fanshawe Street Auckland 1010
Client Address	Level 12 34 Shortland Street Auckland 1010		

Lab Reference	Location	Start (time)	End (time)	Total (mins)	Flow rate (L/min start)	Flow rate (L/min end)	Flow rate (L/min avg)	Fibre count	Fibres/ml
A0523	Level 2 – South At&t Room	11.54	14.30	156	3.0	3.0	3.0	1	<0.01
A0524	Level 2 – Far East	11.56	14.31	155	3.0	3.0	3.0	0	<0.01
A0525	Level 2 – Epsom Lobby	11.58	14.38	155	3.0	3.0	3.0	1	<0.01
A0526	Level 3 – North West	12.02	14.36	154	3.0	3.0	3.0	0	<0.01
A0527	Level 3 – Main Stairwell	12.04	14.38	154	3.0	3.0	3.0	1	<0.01

### Test Methods

Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres 2<sup>nd</sup> Edition [NOHSC:3003 (April 2005)].

In-house procedure – Section 15 Procedure Air Monitoring

In-house procedure – Section 17 Estimating Airborne Fibre Concentrations

In-house procedure – Section 18 Reporting of Results

**Analyst**

**9(2)(a)**

**Signatory**

Fibre count results (fibres/100 fields).

Where the Air Monitoring is not conducted by Accurate Consulting Limited and information is supplied by the client Accurate Consulting Limited cannot be held responsible for any errors caused by sampling or equipment calibrations.

### End of Report

FORM Q

Version 4 - 14 June 2017

Page 1 of 1

C:\Users\admin\Documents\Sync\ACCURATE SERVER\IANZ Inspection & Surveying\Chemical Testing Management System\JOB FOLDER LABORATORY REPORTS\2017\05 June\STRIDE AC0117 FCT 20170613 DM01.docx

Uncontrolled when printed

**Appendix B – AIR TESTING RESULTS**

RELEASED UNDER THE  
OFFICIAL INFORMATION ACT



**Appendix C – LEVEL 2 SAMPLING PLAN**

RELEASED UNDER THE  
OFFICIAL INFORMATION ACT

**Level 2  
7-9 Fanshawe Street  
Typical Floor Layout**

