Dispatch Report

For selected dispatches - Ordered by Asset Type / ID

Dispatch Call Entered Location Call Completed

809/72038 22/09/2016 12:31 BEACH RD (PAPAKURA), PAHUREHURE [60052] 23/09/2016 06:43

(104m)

Response: 18 hours N (Normal / Routine)

Asset Type: Surfacing Call Type: Call Centre

External ID: CAS404652L9C2P7/160922/123058 Job Marker:

Fault: Bleeding

Notes: CRM Case Number: CAS-404652-L9C2P7

Address:

■ Beach Road, Pahurehure, Papakura 2113

Northing:5895379.39996815, Easting:1772625.52313402

Asset Type:102 Fault Type:018 Local Board: Description:

Client has rung today to inform transport that he has been living here for 18 years. the road has been repaired 3 times and it the worse it has been this time due to considerable increase in truck movements between 50kmph-80kmph/hour. There are no major signs exiting the m/way into beach road stating its a residential area as a result there should be no Engine Braking. Engine Braking is a constant issue on this street which has led to the roads deterioration even further this happens all hours of day and night. Client has notice his roof tiles are cracked because of the constant vibration caused by heavy truck and trailer traffic in his area. Client has requested for a Road Inspector to contact him as he is really tired if noise and so are the neighbours. The main reason there are Truck and Trailer movements from

Preferred Method of Contact: E-mail

Progress Notes

23/09/2016 06:42



No Action Required - Noise control is not Roadings responsibility - Refer to AT

1 dispatch printed

RAMM Contractor 6.1/1560.2——End of Report——Source: (fSumDispatchRpt)—