



Select Organisation is to
Logged in As: pi@futureandspark.co.nz

Inspections

< Add New Inspection >

2023

May

20/05/2023 - AMK

2020

100% APPROVED
0% IN PROGRESS
0% NOT APPROVED

Inspection Details

Type: [Redacted] Inspector: [Redacted]

Inspected: 20/05/2023 ... Start Time: 10:26 ... End Time: 10:34 ...

Weather Conditions: [Redacted] No Visitors: 0

Site Accessible? **Yes** Report Complete? **Yes**

Report Date: 20/05/2023 App Inspection? Yes v 5.6 IOs 1 - 2

Customer Order No. App Inspection? Yes v 5.6 IOs 1 - 2

Inspection Check Report

Inspection Message:

Facility Types - Add New > Playground Surfaces Wheeled Sports Area

Item Findings Site Information Inspection Comments

0

Wheeled Sports - Concrete Skate Park

Manufacturer: Unknown Surface: Concrete

Item Complex: N/A Surface Complex: N/A

Finding: Prop placed under pipe for stability
Remedial Action: Look at adding a new pipe to help with stability
Risk Assessment: **Low Risk (5)**
Type: Maintenance

Defect Tracking: [Image]

Highlighted: No

Finding: Portable skate ramps are present on site
Remedial Action: Ensure the ramps are used sensibly and that they are not left lying in the area when not in use
Risk Assessment: **Low Risk (10)**
Type: Maintenance

Defect Tracking: [Image]

Highlighted: No

Finding: Some cracks in surface
Remedial Action: Make sure cracks not raised
Risk Assessment: **Very Low Risk (1)**
Type: Maintenance

Defect Tracking: [Image]

Highlighted: No

Finding: A number of fixings has worked loose
Remedial Action: Secure all loose fixings
Risk Assessment: **Low Risk (5)**
Type: Maintenance

Defect Tracking: [Image]

Highlighted: No

Swings - 2 Bay (2 Flat, 2 Cradle)

Manufacturer: Playground Centre Surface: Woodchip

Item Complex: N/A Surface Complex: N/A

Finding: The bushes are showing signs of wear
Remedial Action: Monitor for any further deterioration and replace as required
Risk Assessment: **Very Low Risk (1)**
Type: Maintenance

Defect Tracking: [Image]

Highlighted: No

Finding: There is surface combs on present on the item
Remedial Action: Consider treating and repainting the item
Risk Assessment: **Low Risk (5)**
Type: Maintenance

Defect Tracking: [Image]

Highlighted: No

Swings - 1 Bay 1 Inclusive 1 Flat Swing

Manufacturer: Playground People Surface: Woodchip

Item Complex: N/A Surface Complex: N/A

Finding: This item is satisfactory - no work required
Remedial Action: Satisfactory
Risk Assessment: **Very Low Risk (1)**
Type: Satisfactory

Defect Tracking: [Image]

Highlighted: No

Swings - 1 Bay 1 Inclusive 1 Flat Swing

Manufacturer: Playground People Surface: Woodchip

Item Complex: N/A Surface Complex: N/A

Finding: This item is satisfactory - no work required
Remedial Action: Satisfactory
Risk Assessment: **Very Low Risk (1)**
Type: Satisfactory

Defect Tracking: [Image]

Highlighted: No

Rotor Play - Spinner Bowl

Manufacturer: Playground People Surface: Woodchip

Item Complex: N/A Surface Complex: N/A

Finding: This item is satisfactory - no work required
Remedial Action: Satisfactory
Risk Assessment: **Very Low Risk (1)**
Type: Satisfactory

Defect Tracking: [Image]

Highlighted: No

Rotor Play - Spinner Bowl

Manufacturer: Playground People Surface: Woodchip

Item Complex: N/A Surface Complex: N/A

Finding: This item is satisfactory - no work required
Remedial Action: Satisfactory
Risk Assessment: **Very Low Risk (1)**
Type: Satisfactory

Defect Tracking: [Image]

Highlighted: No

Activy Equipment - Multi Play (Junior)

Manufacturer: Playground People Surface: Woodchip

Item Complex: N/A Surface Complex: N/A

Finding: Cover is loose
Remedial Action: Secure all loose fixings
Risk Assessment: **Low Risk (5)**
Type: Maintenance

Defect Tracking: [Image]

Highlighted: No

Finding: The rope has worn and broken wire strands are exposed
Remedial Action: Replace rope or net
Risk Assessment: **Low Risk (5)**
Type: Maintenance

Defect Tracking: [Image]

Highlighted: No

Finding: There is surface combs on present on the item
Remedial Action: Consider treating and repainting the item
Risk Assessment: **Low Risk (5)**
Type: Maintenance

Defect Tracking: [Image]

Highlighted: No

Swings - Wheelchair Swing

Manufacturer: Unknown Surface: Matla

Item Complex: N/A Surface Complex: N/A

Finding: Fixings are damaged and/or have sharp edges
Remedial Action: Repair or replace as required
Risk Assessment: **Low Risk (5)**
Type: Maintenance

Defect Tracking: [Image]

Highlighted: No

Rocking Equipment - Spring See-Saw

Manufacturer: Playground People Surface: Woodchip

Item Complex: N/A Surface Complex: N/A

Finding: The paintwork on the spring has been damaged or worn exposing the metal underneath which is rusting
Remedial Action: Treat any rusting components and repaint
Risk Assessment: **Low Risk (5)**
Type: Maintenance

Defect Tracking: [Image]

Highlighted: No

Finding: Bolts show signs of rust
Remedial Action: Inspect and replace bolts, screws and or nuts as required
Risk Assessment: **Low Risk (10)**
Type: Maintenance

Defect Tracking: [Image]

Highlighted: No

Rotor Play - Supernova

Manufacturer: Playground People Surface: Woodchip

Item Complex: N/A Surface Complex: N/A

Finding: The surface has eroded and the foundations are exposed
Remedial Action: Reinstate surrounding surfaces to cover the foundations
Risk Assessment: **Low Risk (5)**
Type: Maintenance

Defect Tracking: [Image]

Highlighted: No

Activy Equipment - Activity Trail

Manufacturer: Unknown Surface: Woodchip

Item Complex: N/A Surface Complex: N/A

Finding: The timber on this item has severe rot
Remedial Action: Remove and replace all affected timber sections
Risk Assessment: **Moderate Risk (12)**
Type: Maintenance

Defect Tracking: [Image]

Highlighted: No

Surface - Safety surface

Manufacturer: Re Harvest Timber Surface: Woodchip

Item Complex: N/A Surface Complex: N/A

Finding: The level of loose fill surfacing has fallen significantly below the minimum 300mm recommended by NZS 5626:2015 Part 1
Remedial Action: Top up loose fill surfacing to recommended levels
Risk Assessment: **Low Risk (10)**
Type: Maintenance

Defect Tracking: [Image]

Highlighted: No

Activy Equipment - Monkey Bars

Manufacturer: Playground Centre Surface: Woodchip

Item Complex: N/A Surface Complex: N/A

Finding: The use of S hooks to connect chains is not recommended as they can catch users clothes or jewellery
Remedial Action: Recommend change to D shackle, monitor
Risk Assessment: **Very Low Risk (5)**
Type: Maintenance

Defect Tracking: [Image]

Highlighted: No

