# **SMS Incident Report**

25/06/2024 14:27:17

Summary		×
CAD Number	F3986927	Status Closed
Station	Otahuhu Station	
Incident Started	01/06/2024 10:30:12	Incident Ended 01/06/2024 19:31:52
Incident Type	1101: Structure fire with damage	
Common Name		
Address	15 Kaka Street Favona	
Alarm Method	111 Telephone	Alarm Level 3
PFA Number		çO.
Zone	143132	
Map Grid E	1763229	Map Grid N 5909215
First Caller		First Caller Contact
Incident Closed	S.	
Report Completed	13:47, Sun 09 Jun 2024 by	
Responses	0	

# Responses

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
OTAH311	P1	10:31:38 01 Jun 2024	10:32:54 01 Jun 2024	10:35:25 01 Jun 2024	12:36:11 02 Jun 2024
ELLE274	PM	10:31:41 01 Jun 2024	10:33:06 01 Jun 2024	10:40:25 01 Jun 2024	14:02:12 01 Jun 2024
MANG351	P1	10:31:34 01 Jun 2024	10:32:41 01 Jun 2024	10:43:50 01 Jun 2024	14:32:28 01 Jun 2024
PAPA344	PM	10:35:12 01 Jun 2024	10:36:37 01 Jun 2024	10:44:50 01 Jun 2024	14:02:57 01 Jun 2024
PAPA347	PR	10:35:12 01 Jun 2024	10:37:13 01 Jun 2024	10:44:54 01 Jun 2024	14:00:30 01 Jun 2024
PARN255	HPNP	10:41:38 01 Jun 2024	10:49:49 01 Jun 2024	10:55:57 01 Jun 2024	12:07:14 01 Jun 2024
AUCKOSU1	SV	10:36:29 01 Jun 2024	10:36:44 01 Jun 2024	10:58:24 01 Jun 2024	14:30:27 01 Jun 2024
OTAH3112	HL	10:45:22 01 Jun 2024	10:56:43 01 Jun 2024	10:59:05 01 Jun 2024	14:24:13 01 Jun 2024
PARN256	TL	10:41:35 01 Jun 2024	10:53:53 01 Jun 2024	10:59:12 01 Jun 2024	13:14:30 01 Jun 2024
ONEH221	P1	10:54:36 01 Jun 2024	10:55:03 01 Jun 2024	11:04:32 01 Jun 2024	13:38:52 01 Jun 2024
GMCOUMA01	OF	10:47:19 01 Jun 2024	10:52:58 01 Jun 2024	11:04:41 01 Jun 2024	13:08:23 01 Jun 2024

## SMS Incident Report F3986927

## 2/15

#### 25/06/2024 14:27:17

OTAR3318	СИНИ	10:35:09 01 Jun 2024	10:36:29 01 Jun 2024	11:05:51 01 Jun 2024	13:33:20 01 Jun 2024
OTAR331	P1	10:54:47 01 Jun 2024	10:56:56 01 Jun 2024	11:06:50 01 Jun 2024	12:51:57 01 Jun 2024
AVON607	PR	10:55:07 01 Jun 2024	10:57:08 01 Jun 2024	11:11:12 01 Jun 2024	13:04:06 01 Jun 2024
DMAUCKL	OF		11:01:04 01 Jun 2024	11:12:09 01 Jun 2024	11:54:01 01 Jun 2024
MTRO621	P1	10:54:40 01 Jun 2024	10:56:05 01 Jun 2024	11:14:46 01 Jun 2024	13:40:56 01 Jun 2024
GMAUCKL05	OF	10:44:26 01 Jun 2024	11:05:35 01 Jun 2024	11:15:04 01 Jun 2024	11:50:54 01 Jun 2024
FICOUMA05	FSO	10:56:28 01 Jun 2024	10:57:39 01 Jun 2024	11:45:59 01 Jun 2024	15:40:19 02 Jun 2024
AUCKOSU2	SV	11:33:28 01 Jun 2024	11:33:49 01 Jun 2024	11:55:38 01 Jun 2024	14:08:52 01 Jun 2024
AVON6015	BA	10:54:43 01 Jun 2024	10:57:58 01 Jun 2024	11:58:25 01 Jun 2024	16:57:29 01 Jun 2024
AUCKOSU4	CV	10:54:35 01 Jun 2024	11:45:40 01 Jun 2024	12:04:23 01 Jun 2024	14:33:47 01 Jun 2024
VSOCOUMA01	VSO	11:00:13 01 Jun 2024	11:02:26 01 Jun 2024	12:32:09 01 Jun 2024	14:03:29 01 Jun 2024
GREY261	P1	13:13:04 01 Jun 2024	13:14:11 01 Jun 2024	13:38:00 01 Jun 2024	17:22:44 01 Jun 2024
PUKE5519	ОТ	11:00:34 01 Jun 2024	, ci Clo	13:39:32 01 Jun 2024	16:26:50 01 Jun 2024
STHE241	P1	13:13:08 01 Jun 2024		13:49:15 01 Jun 2024	16:09:21 01 Jun 2024
HOWI3219	LU	12:42:25 02 Jun 2024	12:49:02 02 Jun 2024	13:14:56 02 Jun 2024	14:54:08 02 Jun 2024
EVENTNCC1	ОТ	Ú, K			08:21:26 02 Jun 2024
AUCKOSU7	ОТ	11:20:52 01 Jun 2024			14:14:34 01 Jun 2024
REMU211	P1	100			10:41:26 01 Jun 2024
AUCKOSU	SV	10:33:23 01 Jun 2024			15:00:05 01 Jun 2024
Start->Alert	57 min	10 min			
0 min			15 min		30 min
	Alert Arriv	->1st al			

# **Elapsed Times**

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
OTAH311	00:01:26	00:03:47	00:05:13	26:05:59
ELLE274	00:01:29	00:08:44	00:10:13	03:32:00

SMS Incident Report	F3986927	3/15		25/06/2024 14:27:17
MANG351	00:01:22	00:12:16	00:13:38	04:02:16
PAPA344	00:05:00	00:09:38	00:14:38	03:32:45
PAPA347	00:05:00	00:09:42	00:14:42	03:30:18
PARN255	00:11:26	00:14:19	00:25:45	01:37:02
AUCKOSU1	00:06:17	00:21:55	00:28:12	04:00:15
OTAH3112	00:15:10	00:13:43	00:28:53	03:54:01
PARN256	00:11:23	00:17:37	00:29:00	02:44:18
ONEH221	00:24:24	00:09:56	00:34:20	03:08:40
GMCOUMA01	00:17:07	00:17:22	00:34:29	02:38:11
OTAR3318	00:04:57	00:30:42	00:35:39	03:03:08
OTAR331	00:24:35	00:12:03	00:36:38	02:21:45
AVON607	00:24:55	00:16:05	00:41:00	02:33:54
DMAUCKL			00:41:57	01:23:49
MTRO621	00:24:28	00:20:06	00:44:34	03:10:44
GMAUCKL05	00:14:14	00:30:38	00:44:52	01:20:42
FICOUMA05	00:26:16	00:49:31	01:15:47	29:10:07
AUCKOSU2	01:03:16	00:22:10	01:25:26	03:38:40
AVON6015	00:24:31	01:03:42	01:28:13	06:27:17
AUCKOSU4	00:24:23	01:09:48	01:34:11	04:03:35
VSOCOUMA01	00:30:01	01:31:56	02:01:57	03:33:17
GREY261	02:42:52	00:24:56	03:07:48	06:52:32
PUKE5519	00:30:22	02:38:58	03:09:20	05:56:38
STHE241	02:42:56	00:36:07	03:19:03	05:39:09
HOWI3219	26:12:13	00:32:31	26:44:44	28:23:56
EVENTNCC1	20,			21:51:14
AUCKOSU7	00:50:40			03:44:22
REMU211				00:11:14
AUCKOSU	00:03:11			04:29:53
	5		•	•

# Notifications

	·	
Date	Time	Party Notified
01 Jun 2024	10:35:41	VECTOR
01 Jun 2024	10:35:53	AMBULANCE VIA INTERCAD
01 Jun 2024	10:35:53	POLICE VIA INTERCAD
01 Jun 2024	10:38:33	AUCK TRAIN CONTROL - NO TRAIN MOVEMENTS FOR THE TIME BEING BUT THERE ARE SOM
01 Jun 2024	10:40:02	GMWAITE04 ACKNOWLEDGED VIA AMS
01 Jun 2024	10:41:06	GMAUCKL05 ACKNOWLEDGED VIA AMS
01 Jun 2024	10:46:06	GMWAITE04 ACK
01 Jun 2024	10:55:28	AUCKLAND REGIONAL PUBLIC HEALTH SERVICE

01 Jun 2024	10:57:06	VECTOR
01 Jun 2024	10:57:09	GMWAITE04 ACKNOWLEDGED VIA AMS
01 Jun 2024	10:57:11	DMCOUMA
01 Jun 2024	10:57:11	GMCOUMA03 ACKNOWLEDGED VIA AMS
01 Jun 2024	10:57:26	GMCOUMA04 ACKNOWLEDGED VIA AMS
01 Jun 2024	10:57:35	DUTY GM / DM COUNTIES PAGED 3RD ALARM
01 Jun 2024	10:57:43	NATIONAL MEDIA SUPPORT RE THIRD ALARM FIRE
01 Jun 2024	10:57:49	NTLMEDIA1 ACKNOWLEDGED VIA AMS
01 Jun 2024	10:57:57	GM COUNTIES GROUP PAGED RE 3RD ALARM
01 Jun 2024	11:00:36	CIVIL DEFENCE AUCKLAND COUNCIL (DUTY) PAGED.
01 Jun 2024	11:03:29	TRAIN CONTROL RE FIRE NEAR LINES
01 Jun 2024	11:04:24	GREATER ALARM ATTENDANCE SHEET SENT TO ICU OTARA AND UPLOADED TO TEAMS
01 Jun 2024	11:05:32	HPO CALLED. PAGE ACKNOWLEDGED.
01 Jun 2024	11:46:03	VECTOR. THEY ADV ETA IS 10 -15 MINS
01 Jun 2024	12:34:49	AUCKLAND REGION PUBLIC SERVICE ASKING FOR UPDATE - PASSED
01 Jun 2024	13:13:15	TWO CREWS - STHE241 AND GREY261 - STAND BYS
01 Jun 2024	14:50:39	AUCKLAND COUNCIL
02 Jun 2024	12:41:49	AMON HOWICK VOLUNTEERS CALLS IN - HAPPY TO HELP

# Message Log

Time	Message
10:30:55	https://web.pcl.govt.nz/?ecn=
10:30:55	INC INFO: BUILDING FIRE
10:30:55	** LOI search completed at 01/06/24 10:30:55
10:31:07	** Recommended unit OTAH311 for requirement PUMP (>1.2 km) ** Recommended unit
10:31:07	MANG351 for requirement PUMP (>6.7 km)
10:31:18	** Requirement AERIAL added for alarm level 1
10:31:22	Recommended unit ELLE274 for requirement AERIAL (>6.0 km)
10:31:31	PA Selcal used to Initiate Alerting. (OTAH311 at 1431 OTAHUHU 182311)
10:31:31	MSU Selcal used to Initiate Alerting. (MANG351 D06D62)
10:31:31	PA Selcal used to Initiate Alerting. (ELLE274 at 1427 ELLERSLIE 182271)
10:31:34	ALERTING_COMPLETED MANG351
10:31:35	SINGLE STOREY BUILDING - WELL INVOLVED ON THE FRONT
10:31:38	ALERTING_COMPLETED OTAH311
10:31:41	ALERTING_COMPLETED ELLE274
10:32:41	Unit MANG351 [ K1 : PROCEEDING TO INCIDENT]
10:32:55	Unit OTAH311 [ K1 : PROCEEDING TO INCIDENT]

10:33:06	Unit ELLE274 [ K1 : PROCEEDING TO INCIDENT]
10:33:22	Pager used to Initiate Alerting.
10:33:23	ALERTING_COMPLETED AUCKOSU
10:33:41	** Requirement COMU added for alarm level 1
10:34:13	Unit OTAH311 [ KP : PRIORITY MESSAGE]
10:34:56	INC INFO: BUILDING FIRE K99 PROCEEDING TXT 2ND ALARM
10:35:02	** Alarm level updated to 2
10:35:02	** Recommended unit OTAR3318 for requirement COMU (>5.2 km) ** Recommended unit
10:35:02	PAPA347 for requirement PUMP (>5.4 km) ** Recommended unit PAPA344 for require
10:35:02	ment PUMP (>5.4 km)
10:35:05	PA Selcal used to Initiate Alerting. (OTAR3318 at 1433 OTARA 182331)
10:35:05	PA Selcal used to Initiate Alerting. (PAPA347 at 1434 PAPATOETOE 182345)
10:35:05	PA Selcal used to Initiate Alerting. (PAPA344 at 1434 PAPATOETOE 182347)
10:35:09	ALERTING_COMPLETED OTAR3318
10:35:12	ALERTING_COMPLETED PAPA347
10:35:13	ALERTING_COMPLETED PAPA344
10:35:25	Unit OTAH311 [ K99 : PROPERTY FIRE WELL INVOLVED]
10:35:42	FIR2POL FIR2AMB FYI ONLY 2ND ALARM
10:35:50	** Event A01223452 of AMBO/N copied from F3986927 of NZFS/AK at: 01/06/24 10:35:
10:35:50	50
10:35:51	** Event P058915403 of NZP/AS copied from F3986927 of NZFS/AK at: 01/06/24 10:35
10:35:51	:51
10:35:52	AMBO EVENT 0401-1-2024/06/01-FIR LINKED AT 01/06/2024 10:35:52
10:36:28	Pager used to Initiate Alerting.
10:36:29	ALERTING_COMPLETED AUCKOSU1
10:36:29	Unit OTAR3318 [ K1 : PROCEEDING TO INCIDENT]
10:36:37	Unit PAPA344 [ K1 : PROCEEDING TO INCIDENT]
10:36:41	Unit OTAR3318 [ K1 : PROCEEDING TO INCIDENT]
10:36:44	Unit AUCKOSU1 [ K1 : PROCEEDING TO INCIDENT]
10:37:14	Unit PAPA347 [ K1 : PROCEEDING TO INCIDENT]
10:38:33	E MAINTENANCE CREWS WORKING IN VICINITY
10:39:57	
10:40:07	NOT DUTY GM'S PAGED RE K99 TX 2
10:40:09	Unit PAPA347 [ KP : PRIORITY MESSAGE]
10:40:25	Unit ELLE274 [ K2 : IN ATTENDANCE AT INCIDENT]
10:40:30	Unit PAPA347 [ KP : PRIORITY MESSAGE] ATTACH HEAVY AERIAL TO THIS CALL
10:40:40	** Requirement AERIAL added for alarm level 2
10:40:45	** Recommended unit PARN256 for requirement AERIAL (>11.9 km)
	I

10:41:26	Unit REMU211 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
10:41:31	MSU Selcal used to Initiate Alerting. (PARN256 D07912)
10:41:31	MSU Selcal used to Initiate Alerting. (PARN255 D0F412)
10:41:35	ALERTING_COMPLETED PARN256
10:41:38	ALERTING_COMPLETED PARN255
10:41:38	Unit OTAH311 [ KC : UNIT CALLING]
10:43:18	Unit OTAH311 [ SITREP : ] SO
10:43:18	CAR WRECKERS APPROX 20X30 WELL INV IN FIRER 1 LPD 1 DECK MONITOR TYPE 4 IN USE
10:43:42	Unit OTAH311 [COMCEN COM : MESSAGE] BE ADVISED OPSUP ENROUTE
10:43:50	Unit MANG351 [ K2 : IN ATTENDANCE AT INCIDENT]
10:44:25	Pager used to Initiate Alerting.
10:44:26	ALERTING_COMPLETED GMAUCKL05
10:44:26	ALERTING_COMPLETED GMAUCKL05
10:44:51	Unit PAPA344 [ K2 : IN ATTENDANCE AT INCIDENT]
10:44:54	Unit PAPA347 [ K2 : IN ATTENDANCE AT INCIDENT]
10:45:05	Preempt Unit PARN256
10:45:19	PA Selcal used to Initiate Alerting. (OTAH3112 at 1431 OTAHUHU 182311)
10:45:22	ALERTING_COMPLETED OTAH3112
10:46:07	Unit PARN256 [ K0 : NOT AVAILABLE (STATE LOCATION)] 255 NOW IN COMMISION,
10:47:18	Pager used to Initiate Alerting.
10:47:19	ALERTING_COMPLETED GMCOUMA01
10:47:20	ALERTING_COMPLETED GMCOUMA01
10:47:44	Unit OTAR3318 [ KC : UNIT CALLING]
10:48:06	INC INFO: BUILDING FIRE K99 TX 2ND ALARM
10:48:25	Unit OTAR3318 [ SITREP : ] SEND ATTENDANCE SHEET TO OTAR3318 EMAIL
10:48:44	Unit OTAR3318 [COMCEN COM : MESSAGE] MSG RECEIVED STAND BY WILL BE THERE IN APPR
10:48:44	OX 2 MINS
10:49:49	Unit PARN255 [ K1 : PROCEEDING TO INCIDENT]
10:52:58	Unit GMCOUMA01 [ K1 : PROCEEDING TO INCIDENT]
10:53:07	Unit MANG351 [ KP : PRIORITY MESSAGE]
10:53:25	MSU Selcal used to Initiate Alerting. (PARN256 D07912)
10:53:29	ALERTING_COMPLETED PARN256
10:53:53	Unit PARN256 [ K1 : PROCEEDING TO INCIDENT]
10:53:57	Unit MANG351 [ KC : UNIT CALLING]
10:53:59	Unit MANG351 [ KP : PRIORITY MESSAGE] SSO
10:54:21	FIR2AMB - THIS IS NOW THIRD ALARM
10:54:28	FIR2POL - THIS IS NOW THIRD ALARM
10:54:29	** Alarm level updated to 3

## SMS Incident Report F3986927

10:54:29	** Recommended unit AVON6015 for requirement BAT (>13.1 km)
10:54:29	** Recommended unit AUCKOSU4 for requirement CANT (>1.3 km)
	** Recommended unit OTAR331 for requir
10:54:29	ement PUMP (>5.2 km) ** Recommended unit ONEH221 for requirement PUMP (>7.3 km)
10:54:29	** Recommended unit MTRO621 for requirement PUMP (>9.9 km)
10:54:33	PA Selcal used to Initiate Alerting. (AVON6015 at 1460 AVONDALE 182607)
10:54:33	Pager used to Initiate Alerting.
10:54:33	PA Selcal used to Initiate Alerting. (OTAR331 at 1433 OTARA 182331)
10:54:33	MSU Selcal used to Initiate Alerting. (ONEH221 D08022)
10:54:33	MSU Selcal used to Initiate Alerting. (MTRO621 D08082)
10:54:35	ALERTING_COMPLETED AUCKOSU4
10:54:36	ALERTING_COMPLETED ONEH221
10:54:40	ALERTING_COMPLETED MTRO621
10:54:43	ALERTING_COMPLETED AVON6015
10:54:47	ALERTING_COMPLETED OTAR331
10:55:03	Unit ONEH221 [ K1 : PROCEEDING TO INCIDENT]
10:55:07	Phone used to Initiate Alerting.
10:55:07	ALERTING_COMPLETED AVON607
10:55:30	INC INFO: BUILDING FIRE K99 TX 3RD ALARM
10:55:57	Unit PARN255 [ K2 : IN ATTENDANCE AT INCIDENT]
10:55:58	FIR2AMB SERT REQUEST THIRD ALARM
10:56:05	Unit MTRO621 [ K1 : PROCEEDING TO INCIDENT]
10:56:27	Pager used to Initiate Alerting.
10:56:28	ALERTING_COMPLETED FICOUMA05
10:56:28	ALERTING_COMPLETED FICOUMA05
10:56:43	Unit OTAH3112 [ K1 : PROCEEDING TO INCIDENT]
10:56:57	Unit OTAR331 [ K1 : PROCEEDING TO INCIDENT]
10:57:08	Unit AVON607 [ K1 : PROCEEDING TO INCIDENT]
10:57:26	DMAUCKL K38 VIA AMS
10:57:39	Unit FICOUMA05 [ K1 : PROCEEDING TO INCIDENT]
10:57:58	Unit AVON6015 [ K1 : PROCEEDING TO INCIDENT]
10:58:00	** Requirement AVON607 added for alarm level 3
10:58:24	INC INFO: BUILDING FIRE K99 TX 3RD ALARM TOC 1030 TOA 1035
10:58:24	Unit AUCKOSU1 [ K2 : IN ATTENDANCE AT INCIDENT]
10:59:05	Unit OTAH3112 [ K2 : IN ATTENDANCE AT INCIDENT]
10:59:12	Unit PARN256 [ K2 : IN ATTENDANCE AT INCIDENT]
11:00:04	RN TE HIKU NOTIFY IF INCREASES
11:00:11	Pager used to Initiate Alerting.

11:00:13	ALERTING_COMPLETED VSOCOUMA01
11:00:13	ALERTING_COMPLETED VSOCOUMA01
11:00:33	Phone used to Initiate Alerting.
11:00:34	ALERTING_COMPLETED PUKE5519
11:00:56	** Requirement ABLUTION added for alarm level 3
11:01:04	Unit DMAUCKL [ K1 : PROCEEDING TO INCIDENT]
11:02:26	Unit VSOCOUMA01 [ K1 : PROCEEDING TO INCIDENT]
11:04:32	Unit ONEH221 [ K2 : IN ATTENDANCE AT INCIDENT]
11:04:41	Unit GMCOUMA01 [ K2 : IN ATTENDANCE AT INCIDENT]
11:04:50	Unit OTAR3318 [ KC : UNIT CALLING]
11:05:32	Unit OTAR3318 [ K44 : COMMAND OR CONTROL POINT ESTABLISHED (STATE OIC AND LOCATI
11:05:32	ON)] 3318 KAKA COMMAND K45 SSO
11:05:35	Unit GMAUCKL05 [ K1 : PROCEEDING TO INCIDENT]
11:05:46	Unit OTAR3318 [ KC : UNIT CALLING]
11:05:49	Unit OTAR3318 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SSO
11:05:51	Unit OTAR3318 [ K2 : IN ATTENDANCE AT INCIDENT]
11:06:50	Unit OTAR331 [ K2 : IN ATTENDANCE AT INCIDENT]
11:07:28	Unit OTAR3318 [ SITREP : ] SSO
11:07:28	ND 3 LPD
11:09:53	FICOUNMA05 CALLED. DETAIL PASSED.
11:11:12	Unit AVON607 [ K2 : IN ATTENDANCE AT INCIDENT]
11:11:26	Unit AVON607 [ K2 : IN ATTENDANCE AT INCIDENT]
11:12:09	Unit DMAUCKL [ K2 · IN ATTENDANCE AT INCIDENT]
11:14:46	Unit MTRO621 [ K2 . IN ATTENDANCE AT INCIDENT]
11:15:04	Unit GMAUCKL05 [ K2 : IN ATTENDANCE AT INCIDENT]
11:15:31	Alarm Timer Extended: 0
11:16:53	Unit OTAR3318 [ KC : UNIT CALLING]
11:17:36	Unit OTAR3318 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] GM
11:17:36	
11:17:47	Unit OTAR3318 [COMCEN COM : MESSAGE] DO YOU REQUIRE ABULTIONS TRAILER, ATTENDANC
11:17:47	E SHEET HAS BEEN SENT AND IS ON THE TEAMS SHARED FILE
11:19:13	Unit OTAR3318 [ KC : UNIT CALLING]
11:19:36	Unit OTAR3318 [ SITREP : ] AFFIRMATIVE ON ABULTIONS TRAILER
11:20:45	INC INFO: BUILDING FIRE K99 TX 3RD ALARM ABULTIONS TRAILER REQUIRED
11:20:51	AUCKLAND EMERGENCY MANAGEMENT PUT THRU TO KAKA ST COMMAND
11:20:51	Pager used to Initiate Alerting.
11:20:52	ALERTING_COMPLETED AUCKOSU7
11:21:04	Alarm Timer Extended: 0

11:21:06	HOWI321 EN ROUTE TO PAPATOETOE STATION VIA HOWICK STATION TO UPLIFT SOME THINGS
11:21:29	KAKA STREET COMMAND
11:21:49	Unit AUCKOSU [ K22-1 : APPLIANCE AVAILABLE FOR A FURTHER INCIDENT]
11:22:23	HPO CALLED RE IF THERE'S ANY ASBESTO WITHIN THE BUILDING. ADV WE HAVEN'T RECEIVE
11:22:23	D ANY INFO RE OF THAT. ADV WILL CONTACT THEM IF IT HAS CONFIRMED.
11:27:28	Alarm Timer Extended: 0
11:27:28	Alarm Timer Extended: 0
11:27:29	Alarm Timer Extended: 0
11:31:00	Unit OTAR3318 [COMCEN COM : MESSAGE] DO YOU HAVE AN AERIAL AVAILABLE AS WE HAVE
11:31:00	A CHURCH ON FIRE IN MANGERE BRIDGE
11:33:27	Pager used to Initiate Alerting.
11:33:28	ALERTING_COMPLETED AUCKOSU2
11:33:49	Unit AUCKOSU2 [ K1 : PROCEEDING TO INCIDENT]
11:44:06	Unit OTAR3318 [ KP : PRIORITY MESSAGE]
11:44:40	Unit OTAR3318 [ KP : PRIORITY MESSAGE] K11 POWER TO THIS INCIDENT
11:45:41	Unit AUCKOSU4 [ K1 : PROCEEDING TO INCIDENT]
11:45:59	Unit FICOUMA05 [ K2 : IN ATTENDANCE AT INCIDENT]
11:48:25	Unit OTAR3318 [ KC : UNIT CALLING]
11:50:48	Unit OTAR3318 [ SITREP : ] 3 HEAVY AERIALS IN USE MULTIPAL LPD 1 GROUND MONITORS
11:50:48	FIRE NOW CONTAINED AND CONTROLLED RATIONALISING RESOURCES
11:50:54	Unit GMAUCKL05 [ K6 : ON PAGER (STATE LOCATION)]
11:52:19	Alarm Timer Extended: 0
11:52:19	Alarm Timer Extended: 0
11:52:20	Alarm Timer Extended: 0
11:52:21	Alarm Timer Extended: 0
11:52:26	Alarm Timer Extended: 0
11:53:45	Unit OTAR3318 [COMCEN COM : MESSAGE] NO AERIAL REQUIRED FROM MANGERE BRIDGE INCI
11:53:45	DENT
11:54:01	Unit DMAUCKL [ K6 : ON PAGER (STATE LOCATION)]
11:55:38	Unit AUCKOSU2 [ K2 : IN ATTENDANCE AT INCIDENT]
11:58:25	Unit AVON6015 [ K2 : IN ATTENDANCE AT INCIDENT]
12:04:23	Unit AUCKOSU4 [ K2 : IN ATTENDANCE AT INCIDENT]
12:07:14	Unit PARN255 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
12:16:55	Unit MTRO621 [ K2 : IN ATTENDANCE AT INCIDENT]

12:27:26 U	Jnit OTAR3318 [ KC : UNIT CALLING]
	Jnit OTAR3318 [ SITREP : ] UPDATED ATTENDANCE SHEET AND EMAILED TO DTAR3318
12:30:08 U	Jnit OTAR3318 [ KC : UNIT CALLING]
12:32:09 U	Jnit VSOCOUMA01 [ K2 : IN ATTENDANCE AT INCIDENT]
12:32:12 U G	Jnit OTAR3318 [ SITREP : ] AC 1 HEAVY AERIAL IN USE 1 TYPE 4 AERIAL 1
12:32:12 R	ROUND MONTIOR MULTIPLE LPS FIRE IS NOW IN OVERHAUL STAGE
12:40:17 A	Alarm Timer Extended: 0
12:40:17 A	Alarm Timer Extended: 0
12:40:17 A	Alarm Timer Extended: 0
12:51:58 U	Jnit OTAR331 [ K9 : OFF RT (STATE LOCATION)]
12:54:36 U	Jnit OTAR3318 [ KC : UNIT CALLING]
12:55:03 U	Jnit OTAR3318 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SSO
13:01:50 U	Jnit OTAR3318 [ SITREP : ] 2 PUMPS REQUIRED FOR 1330
13:03:33 U	Jnit OTAR3318 [ KC : UNIT CALLING]
13:04:06 U	Jnit AVON607 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
	Jnit OTAR3318 [ K44 : COMMAND OR CONTROL POINT ESTABLISHED (STATE OIC AND OCATI
13:04:25 O	DN)] DISESTABLISHING TO OTAH311
13:08:23 U	Jnit GMCOUMA01 [ K6 : ON PAGER (STATE LOCATION)]
13:13:01 P.	PA Selcal used to Initiate Alerting. (GREY261 at 1426 GREY LYNN 182261)
13:13:01 P.	PA Selcal used to Initiate Alerting. (STHE241 at 1424 ST HELIERS 182241)
13:13:04 A	ALERTING_COMPLETED GREY261
13:13:08 A	ALERTING_COMPLETED STHE241
13:14:05 U	Jnit PARN256 [ KC : UNIT CALLING]
13:14:11 U	Jnit GREY261 [ K1 : PROCEEDING TO INCIDENT]
13:14:30 U	Jnit PARN256 [ K10 : RE-COMMISSIONING APPLIANCE]
13:15:14 U	Jnit GREY261 [ KC : UNIT CALLING]
13:17:30 U	Jnit STHE241 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
13:32:34 U	Jnit OTAR3318 [ K2 : IN ATTENDANCE AT INCIDENT]
13:33:21 U	Jnit OTAR3318 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
13:38:01 U	Jnit GREY261 [ K2 : IN ATTENDANCE AT INCIDENT]
13:33:52 U	Jnit ONEH221 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
13:39:32 U	Jnit PUKE5519 [ K2 : IN ATTENDANCE AT INCIDENT]
13:39:35 A	Alarm Timer Extended: 0
13:39:35 A	Alarm Timer Extended: 0
13:39:36 A	Narm Timer Extended: 0
13:40:35 U	Jnit MTRO621 [ KC : UNIT CALLING]
13:40:56 U	Jnit MTRO621 [ K10 : RE-COMMISSIONING APPLIANCE]
13:49:15 U	Jnit STHE241 [ K2 : IN ATTENDANCE AT INCIDENT]

13:53:32	Unit PAPA347 [ KC : UNIT CALLING]
13:54:21	Unit PAPA347 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)]
	GREY261 SO
13:54:21	
14:00:30	Unit PAPA347 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
14:01:55	Unit ELLE274 [ KC : UNIT CALLING]
14:02:12	Unit ELLE274 [ K10 : RE-COMMISSIONING APPLIANCE]
14:02:32	Unit PAPA344 [ KC : UNIT CALLING]
14:02:57	Unit PAPA344 [ K10 : RE-COMMISSIONING APPLIANCE]
14:03:30	Unit VSOCOUMA01 [ K6 : ON PAGER (STATE LOCATION)]
14:05:31	Unit STHE241 [ K2 : IN ATTENDANCE AT INCIDENT]
14:08:52	Unit AUCKOSU2 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
14:14:34	Unit AUCKOSU7 [ K7 : AT NORMAL STATION]
14:16:41	Unit GREY261 [ KC : UNIT CALLING]
14:17:21	Unit GREY261 [ SITREP : ] SO GTWW 1 HPD AND FOAM AND 1 DECK MONITOR
14:19:33	Alarm Timer Extended: 0
14:19:33	Alarm Timer Extended: 0
14:23:35	Unit OTAH311 [ KC : UNIT CALLING]
14:24:04	Unit OTAH311 [ K10 : RE-COMMISSIONING APPLIANCE]
14:24:13	Unit OTAH3112 [ K10 : RE-COMMISSIONING APPLIANCE]
14:30:27	Unit AUCKOSU1 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
14:31:52	Unit MANG351 [ KC : UNIT CALLING]
14:32:28	Unit MANG351 [ K10 : RE-COMMISSIONING APPLIANCE]
14:33:47	Unit AUCKOSU4 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
14:43:38	Unit FICOUMA05 [ KC : UNIT CALLING]
14:44:22	Unit FICOUMA05 [ SITREP : ] RESTRICT AND PROHIBIT LEFT WITH CREWS ON SCENE DOING
14:44:22	MOP UP - ILL RETURN IN THE MORNING ONCE THE SCENE IS CLEAR
14:48:26	Unit FICOUMA05 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
14:49:51	Unit GREY261 [ SITREP : ] (PHONE) SO
14:49:51	THEM KNOW THERE WILL BE PLASTIC AND OIL RUNOFF FROM THE FIRE THAT WILL BE GOING
14:49:51	DOWN THE DRAIN GRADUTELY.
15:00:05	Unit AUCKOSU [ K7 : AT NORMAL STATION]
15:00:12	Alarm Timer Extended: 0
15:08:25	AUCKLAND COUNCIL POLLUTION - REF NO. INR60272180.
16:08:04	Unit STHE241 [ KC : UNIT CALLING]
16:09:17	Unit STHE241 [ SITREP : ] SO STAND BY REDUCED TO 1 PUMP GREY261 REMAINING
16:09:17	ON SCENE WITH SO
16:09:22	Unit STHE241 [ K10 : RE-COMMISSIONING APPLIANCE]

16:26:00	Unit GREY261 [ SITREP : ] CAN THE ON CALL FIRE INVESTIGATOR THAT ATTENDED
16:26:00	
16:26:50	Unit PUKE5519 [ K7 : AT NORMAL STATION]
16:28:53	FIRE INVESTIAGTOR PUT THRU TO GREY261
16:57:29	Unit AVON6015 [ K7 : AT NORMAL STATION]
16:59:51	MSU Selcal used to Initiate Alerting. (OTAH311 D0FE42)
16:59:54	ALERTING_COMPLETED OTAH311
17:00:19	Unit OTAH311 [ K1 : PROCEEDING TO INCIDENT]
17:19:00	Unit OTAH311 [ K2 : IN ATTENDANCE AT INCIDENT]
17:21:18	Unit GREY261 [ KC : UNIT CALLING]
17:22:39	Unit GREY261 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SO
17:22:44	Unit GREY261 [ K10 : RE-COMMISSIONING APPLIANCE]
18:01:06	Alarm Timer Extended: 0
18:33:45	Unit OTAH311 [ KC : UNIT CALLING]
18:34:19	Unit OTAH311 [ SITREP : ] POLICE IN ATTENDANCE
19:31:05	Unit OTAH311 [ KC : UNIT CALLING]
19:31:52	Unit OTAH311 [ K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM SITREP] POLICE WILL RE
19:31:52	MAIN AT INCIDENT UNTIL TOMORROW MORNING
19:32:17	Unit OTAH311 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
08:10:03	Pager used to Initiate Alerting.
08:10:04	ALERTING_COMPLETED FICOUMA05
08:10:04	ALERTING_COMPLETED FICOUMA05
08:10:22	Unit FICOUMA05 [ K1 · PROCEEDING TO INCIDENT]
08:21:27	Unit EVENTNCC1 [ K7 : AT NORMAL STATION]
08:35:56	Unit FICOUMA05 [ K2 : IN ATTENDANCE AT INCIDENT]
10:11:46	Alarm Timer Extended: 0
11:02:07	Unit FICOUMA05 [ SITREP : ] ATTACH AN APPLIANCE FOR MANPOWER AND ONE THAT HAS A
11:02:07	CENERATOR (VIA PHONE)
11:43:34	Radio used to Initiate Alerting.
11:43:35	ALERTING_COMPLETED OTAH311
11:43:57	Unit OTAH311 [ K22-1 : APPLIANCE AVAILABLE FOR A FURTHER INCIDENT]
11:45.18	Unit OTAH311 [ K2 : IN ATTENDANCE AT INCIDENT]
12:36:11	Unit OTAH311 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
12:38:05	Unit FICOUMA05 [ SITREP : ] ATTACH A GENERATOR FROM THE LIGHTING UNIT OR COMMAND
12:38:05	UNIT. WILL NEED IT FOR APPROX 1 HR IN 45 MINS TIME
12:39:47	HOWICK VOLUNTEERS PAGED TO CALL NORTHCOM
12:42:23	Phone used to Initiate Alerting.
12:42:25	ALERTING_COMPLETED HOWI3219

12:49:02	Unit HOWI3219 [ K1 : PROCEEDING TO INCIDENT]
13:14:56	Unit HOWI3219 [ K2 : IN ATTENDANCE AT INCIDENT]
13:56:41	Alarm Timer Extended: 0
14:54:09	Unit HOWI3219 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
14:58:59	Unit FICOUMA05 [ KC : UNIT CALLING]
14:59:10	Unit FICOUMA05 [ KC : UNIT CALLING]
14:59:22	Unit FICOUMA05 [ KC : UNIT CALLING]
14:59:32	Unit FICOUMA05 [ STOP : MESSAGE] INVESTIGATION COMPLETE PROPERTY LEFT WITH OWNER
14:59:34	Unit FICOUMA05 [ K22-1 : APPLIANCE AVAILABLE FOR A FURTHER INCIDENT]
15:40:20	Unit FICOUMA05 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

Incident	
CAD Number	F3986927
Incident Reporter	×0`
Incident Controller	
Distance Travelled (km	1)
Delay In Receiving Cal	
	S C
Property Details	
Occupant	car wrecker
Building Owner	
General Property Use	Storage, Warehousing
Special Property Use	Car wrecker, Scrapyard
Purpose Group	
Actions	
Persons Reported Trapped	3
	ully evacuated
Action Prior 1	
Action Prior 2	
Action Taken Ex	xtinguishment only: Includes isolating fuel/power
Civilians	
Civilians Rescued	C

**Civilians Extricated** 

**Civilians Assisted** 

**Civilians Evacuated** 

Origin	
Location	Outside area, multiple area - not classified above
Level	Ground level

# **Equipment Used**

Quantity	Equipment
4 4	Aerial Ladder/Platform
3 L	_ow pressure delivery
2	Monitor
Equipment Involve	ed
Equipment Involved	
Year	CO.
Make	
Model	SO.
Fire	
Arrival Condition	Totally involved fire
Heat Source	Information not recorded/Unknown
Termination Stage	
First Object Ignited	<b>O</b>
First Object Material	Solution and the second s
Second Object Ignited	d
Second Object Materi	ial
Indicated Cause	Undetermined
Certainty of Cause	Lovy
Age of Person	
Ethnicity	$\diamond$
Gender	
FAIP Service Offered	Unknown
000	
<u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u></u>	

6/9/2024 1:47:11 PM

**Reporter Comments** 

K99 proceeding tx 2nd alarm and went to a 3rd alarm . Car yard and mechanics shop well involved.

Fire investigators still unsure of cause awaiting more information.

ationAct

#### 6/25/2024 2:14:08 PM Reporter Comments

I attended this incident (F3986927) as a Specialist Fire Investigator to assist the OIC in determining the cause and origin of the fire.

The building was a mechanical workshop and yard, with an attached office. The building was in excess of 50 years old, and was timber framed with timber weatherboards. The roof was coloursteel or similar. The window joinery was timber.

The owner of the business was there at the time of the fire, as were at least two other workers, and customers. One of the customers parked out the front of the building noticed smoke in a pile of tyres, and alerted those inside. By the time they came outside the fire had developed to a point it could not be easily extinguished. Two cars were moved, and 111 was called.

The majority of the building was destroyed, along with a number of vehicles parked close to the building.

Fire patterns showed that the fire started at the front of the building near the entrance to the workshop, on the outside of the building, but against the wall in or near a pile of tyres. Partially obscured CCTV showed a small fire starting at or near to ground level in or near the tyres stacked against the building.

Above the pile of tyres had been an exterior sensor light. The light was always energized, however only turned on when the sensor was activated. Only minor remains of the light were found in the area of origin. The workers all smoked, and had been smoking that morning, They often discarded the cigarette butts on the ground.

It is my opinion that it is likley that the light above the pile of tyres had an electrical failure, caught fire and dropped in to the pile of tyres. Given the nature of the the work that was carried out at the premises, there was a large amount of liquid fuels present, and this has allowed the fire to spread rapidly.

It is also possible but less likely (the ground was wet pre fire) that a carelessly discarded cigarette butt ignited a flammable liquid in the vicinity of the tyres.

The exact cause is undetermined. Accidental.