

SMS Incident Report


06/06/2017 08:32:13

Summary

CAD Number F2310721 **Status** Closed
Station West Harbour Station
Incident Started 20/05/2017 17:59:18 **Incident Ended** 20/05/2017 19:22:50
Incident Type 1102: Structure fire with no damage
Common Name
Address 121 FERRY PARADE HERALD ISLAND
Alarm Method 111 Telephone **Alarm Level** 1
PFA Number
Zone 146772
Map Grid E 1748255 **Map Grid N** 5928553
First Caller [REDACTED] **First Caller Contact** [REDACTED]
Incident Closed 20/05/2017 19:22:50
Report Completed 11:46, Sat 03 Jun 2017 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
WEST671	P1	18:00:09 20 May 2017	18:00:38 20 May 2017	18:07:54 20 May 2017	18:31:30 20 May 2017
ALBA851	P1	18:01:33 20 May 2017	18:03:15 20 May 2017	18:14:33 20 May 2017	18:16:00 20 May 2017
GREE841	P1	18:01:29 20 May 2017	18:05:37 20 May 2017	18:15:42 20 May 2017	18:17:16 20 May 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
WEST671	00:00:51	00:07:45	00:08:36	00:32:12
ALBA851	00:02:15	00:13:00	00:15:15	00:16:42
GREE841	00:02:11	00:14:13	00:16:24	00:17:58

Message Log

Time	Message
17:59:56	INC INFO: SMOKE ALARM SOUNDING
17:59:57	** LOI search completed at 20/05/17 17:59:57
18:00:03	** Recommended unit WEST671 for requirement PUMP (>6.5 km)
18:00:18	** Event Type changed from MIN to STRU at: 20/05/17 18:00:18
18:00:18	** Event Priority changed from 2 to 1 at: 20/05/17 18:00:18
18:00:38	Unit WEST671 [K1 : PROCEEDING TO INCIDENT]
18:01:10	REAR HOUSE
18:01:24	** Recommended unit GREE841 for requirement PUMP (>0.8 km)
18:01:24	** Recommended unit ALBA851 for requirement CANBACKUP (>4.7 km)
18:01:55	NEIGHBOUR BELIEVES SMOKE SHOWING IN LOUNGE IS FROM FIREPLACE, NO ONE HOME AT PROPERTY
18:02:32	Unit WEST671 [COMCEN COM : MESSAGE] DETAILS PASSED
18:03:16	Unit ALBA851 [K1 : PROCEEDING TO INCIDENT]
18:05:38	Unit GREE841 [K1 : PROCEEDING TO INCIDENT]
18:07:55	Unit WEST671 [K77 : NOTHING SHOWING]
18:12:40	Unit WEST671 [KC : UNIT CALLING]
18:13:16	Unit WEST671 [SITREP :] [REDACTED]. SMOKE LOGGED HOUSE. ATTEMPTING TO GAIN ACCESS
18:14:34	Unit ALBA851 [K2 : IN ATTENDANCE AT INCIDENT]
18:15:42	Unit GREE841 [K2 : IN ATTENDANCE AT INCIDENT]
18:16:01	Unit ALBA851 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
18:17:17	Unit GREE841 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
18:29:55	Unit WEST671 [KC : UNIT CALLING]
18:30:20	Unit WEST671 [STOP : MESSAGE] SMOKE CLEARED WITH PPV FAN. LEFT IN HANDS OF OWNER
18:30:20	OWNER
18:31:31	Unit WEST671 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
19:22:50	** Assigned Result Code: STRU, Detailed Event Type: 1500, Qualifier 1: Q1,
19:22:50	Qualifier 2:

Incident

CAD Number	F2310721
Incident Reporter	[REDACTED]
Incident Controller	[REDACTED]
Distance Travelled (km)	8
Delay In Receiving Call	

Property Details

Occupant Unknown
 Building Owner Rented property
 General Property Use Single house
 Special Property Use Single house
 Purpose Group

Actions

Persons Reported Trapped No
 Evacuation Status Not occupied at time of incident
 Action Prior 1 No action taken by Civilian/Occupant/Passerby
 Action Prior 2 No action taken by Civilian/Occupant/Passerby
 Action Taken Extinguishment and ventilation

Civilians

Civilians Rescued 0
 Civilians Extricated 0
 Civilians Assisted 1
 Civilians Evacuated

Origin

Location Lounge, Common room, TV room, Sitting room, Music room
 Level Ground level

Equipment Used

Quantity	Equipment
1	Hand tools - Crowbar, Saw, Hammer, Mop, Broom, Misc small gear
1	Salvage/ventilation: PPV, Fan

Equipment Involved

Equipment Involved
 Year
 Make
 Model

Fire

Arrival Condition Smoke only
 Heat Source Hot object - not classified above
 Termination Stage Smoulder

First Object Ignited	Driftwood/Firewood		
First Object Material	Trees: dead, rotten wood (not felled)		
Second Object Ignited	Information not recorded		
Second Object Material	Information not recorded		
Indicated Cause	Combustible placed too close to heat source		
Certainty of Cause	High		
Age of Person	Persons: 17 - 64 yrs		
Ethnicity	European/Pakeha		
Gender	Male		
FAIP Service Offered	No	FAIP Service Accepted	No

Alarms

Type of Alarm Initiating Call	Domestic Smoke Alarms
Performance of System	Alerted neighbour/passersby - detector in room of origin
Failure/Ineffectiveness of system	
Number of sprinkler heads operated	

Released under the Official Information Act