SMS Incident Report

29/08/2017 07:56:16

Summary			X
CAD Number	F2369611	Status Closed	~0
Station	East Coast Bays Station		Y
Incident Started	28/08/2017 08:23:02	Incident Ended 28/08/2017 0	8:41:16
Incident Type	4402: Arcing, shorted electrical equipment		
Common Name			
Address	/ 459 East Coast Road Windsor Park		
Alarm Method	111 Telephone	Alarm Level 1	
PFA Number		çO.	
Zone	148385		
Map Grid E	1755004	Map Grid N 5933017	
First Caller	*	First Caller Contact	
Incident Closed	28/08/2017 08:41:16		
Report Completed	8:59, Mon 28 Aug 2017 by Mark Whittington		

Responses

Responses			Ø									
Call Sign	Туре	Station Alert	Enroute Time	е	Ar	rival Ti	me		De	epart	∋d	
EAST831	P1	08:25:56 28 Aug 2017	08:27:15 28 Aug	2017	08:30:2	26 28 A	ug 2017	7 08:	39:52	28 A	ug 20	17
Start->Alert	7 min	10 min										
		0										
n	6		15 min									n

Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
EAST831	00:02:54	00:04:30	00:07:24	00:16:50

Notifications

Date	Time	Party Notified
28 Aug 2017	08:25:40	VECTOR

Caution: The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside NZ Fire and Emergency without prior approval

SMS Incident Report	F2369611
----------------------------	----------

08:41:02

28 Aug 2017

2/3

VECTOR - RE POLE NUMBER

Μ	ess	ad	e l	_oq
IVI	C 33	au	ΓL	_uu

Time	Message
08:24:43	INC INFO: POWER LINES ON FIRE
08:24:44	** LOI search completed at 28/08/17 08:24:44
08:24:58	** Recommended unit EAST831 for requirement PUMP (>1.3 km)
08:25:21	CALLER SAID BETWEEN ROSEDALE ROAD AND RANGITOTO COLLEGE ON EAST COAST ROAD
08:27:15	Unit EAST831 [K1 : PROCEEDING TO INCIDENT]
08:30:27	Unit EAST831 [K77 : NOTHING SHOWING]
08:31:01	Unit EAST831 [KC : UNIT CALLING]
08:32:44	Unit EAST831 [SITREP :] DO YOU HAVE A STREET NUMBER FOR THIS INCIDENT?
08:32:44	(NEGATIVE - CALLER STATES BETWEEN ROSEDALE RD AND RANGITOTO COLLEGE)
08:35:48	Unit EAST831 [KC : UNIT CALLING]
08:37:03	Unit EAST831 [SITREP :] SO WHITTINGTON - NOTHING VISIBLE - COULD YOU CALL BACK
08:37:03	CALLER TO CLARIFY LOCATION?
08:38:00	Unit EAST831 [KC : UNIT CALLING]
08:38:49	Unit EAST831 [STOP : MESSAGE] BROKEN INSULATOR LOCATED - POLE 42744
08:39:11	THERE IS A SMALL BRIDGE - ON EAST SIDE YOU WILL SEE THE POLE
08:39:53	Unit EAST831 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
08:41:15	** Assigned Result Code: MIN, Detailed Event Type: 9900, Qualifier 1: Q1,
08:41:15	Qualifier 2:

Incident			
CAD Number	F2369611		
Incident Reporter	Mark Whittington		
Incident Controller	M Whittington		
Distance Travelled (km)	2		
Delay In Receiving Call			
0	2		
Property Details			
Occupant			
Building Owner			
General Property Use	Single house		
Special Property Use	Single house		
Purpose Group			
Actions			

Persons Reported Trapped

Caution: The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside NZ Fire and Emergency without prior approval

Evacuation Status

Action Prior 1

Action Prior 2 Action Taken

Referred to proper authority

Origin

Location	Road, Street, Parking lot, Highway, Motorway	X
Level	Ground level	NC S
		N .

Equipment Used

Quantity		Equipment	
2	Handheld Radio (or Cellphone)		0
Equipment Involved	-		
Equipment Involved		<u> </u>	
Year			
Make			
Model			
		c.C	
Comments	<i>Q</i> 1		
comments			
		8/28/2017 8:59:44 AM	Reporter Comments
power pole no 42744	insulators appear to be damaged but no fire		
referred to power		,	
			Mark Whittington
	0		
	6		
	25		
2	05		
	asedult		

3/3