

SMS Incident Report


03/10/2019 15:41:55

Summary

CAD Number F2847525 **Status** Closed
Station Motueka Volunteer Fire Brigade
Incident Started 20/09/2019 20:48:25 **Incident Ended** 20/09/2019 22:00:53
Incident Type 1102: Structure fire with no damage
Common Name SUPER LIQUOR MOTUEKA
Address / Motueka
Alarm Method Exchange phone **Alarm Level** 1
PFA Number
Zone 323640
Map Grid E 1600909 **Map Grid N** 5448620
First Caller [REDACTED] **First Caller Contact** [REDACTED]
Incident Closed 20/09/2019 22:18:22
Report Completed 23:20, Tue 24 Sep 2019 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
MOTU361	P1	20:49:18 20 Sep 2019	20:56:13 20 Sep 2019	20:58:20 20 Sep 2019	22:04:04 20 Sep 2019
MOTU367	PR	20:49:18 20 Sep 2019	20:58:36 20 Sep 2019	20:59:29 20 Sep 2019	21:24:30 20 Sep 2019
MOTU3611	WT	20:49:17 20 Sep 2019	20:59:39 20 Sep 2019	21:01:11 20 Sep 2019	21:11:33 20 Sep 2019



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
MOTU361	00:00:53	00:09:02	00:09:55	01:15:39
MOTU367	00:00:53	00:10:11	00:11:04	00:36:05

MOTU3611	00:00:52	00:11:54	00:12:46	00:23:08
----------	----------	----------	----------	----------

Message Log

Time	Message
20:49:04	INC INFO: SMELL OF ELECTRICAL BURNING
20:49:06	** LOI search completed at 20/09/19 20:49:05
20:49:10	** Recommended unit MOTU3611 for requirement TANKER (>0.6 km)
20:49:10	** Recommended un
20:49:10	it MOTU361 for requirement PUMP (>0.6 km)
20:49:10	** Recommended unit MOTU367 for requi
20:49:10	rement PUMP (>0.6 km)
20:49:14	Station Selcal used to Initiate Alerting. (████████)
20:49:15	Station Selcal used to Initiate Alerting. (████████)
20:49:15	Station Selcal used to Initiate Alerting. (████████)
20:49:18	ALERTING_COMPLETED
20:49:18	ALERTING_COMPLETED
20:49:18	ALERTING_COMPLETED
20:49:32	CALL CAME FROM BRIGADE MEMBER OF BRIGHTWATER FIRE
20:49:41	SMELL OF ELECTRICAL BURNING
20:49:44	EVAC UNDERWAY
20:56:13	Unit MOTU361 [K1 : PROCEEDING TO INCIDENT]
20:58:20	Unit MOTU361 [K77 : NOTHING SHOWING]
20:58:36	Unit MOTU367 [K1 : PROCEEDING TO INCIDENT]
20:59:29	Unit MOTU367 [K2 : IN ATTENDANCE AT INCIDENT]
20:59:39	Unit MOTU3611 [K1 : PROCEEDING TO INCIDENT]
21:01:11	Unit MOTU3611 [K2 : IN ATTENDANCE AT INCIDENT]
21:08:18	Unit MOTU361 [KC : UNIT CALLING]
21:09:07	Unit MOTU361 [SITREP :] CFO ██████████ - OVERHEATED SWITCH BOARD INVEST FURTHER
21:11:33	Unit MOTU3611 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
21:15:59	Unit MOTU361 [KC : UNIT CALLING]
21:17:43	Unit MOTU361 [SITREP :] AWAITING ELECTRICTIAN
21:24:30	Unit MOTU367 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
21:35:20	Unit MOTU361 [KC : UNIT CALLING]
21:35:57	Unit MOTU361 [SITREP :] SSO ██████████ - ELECTRICTIAN IN ATTENDANCE
21:47:19	Alarm Timer Extended: 0
21:56:50	Unit MOTU361 [KC : UNIT CALLING]
21:57:20	Unit MOTU361 [SITREP :] PERMISSION TO SPEAK TO MOTU367 (GO AHEAD)
22:00:32	Unit MOTU361 [KC : UNIT CALLING]

22:00:53	Unit MOTU361 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE]
22:04:04	Unit MOTU361 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
22:18:22	** Assigned Result Code: STRU, Detailed Event Type: 1100

Incident

CAD Number F2847525
 Incident Reporter [REDACTED]
 Incident Controller
 Distance Travelled (km)
 Delay In Receiving Call

Property Details

Occupant Super liquor
 Building Owner Owner occupied
 General Property Use Shop, Mall, Supermarket, Gas station, Sales, Other
 Special Property Use Liquor store
 Purpose Group

Actions

Persons Reported
 Trapped
 Evacuation Status Fully evacuated
 Action Prior 1
 Action Prior 2
 Action Taken Investigation only (Fire related)

Civilians

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	4

Origin

Location Kitchen, Cooking area
 Level Ground level

Equipment Used

Quantity	Equipment
1	Equipment Not Listed

Equipment Involved

Equipment Involved

Year

2005

Make

HPM

Model

CAT105 series

Fire**Arrival Condition**

No fire or smoke

Heat Source

Heat from electrical equip: Defective or faulty

Termination Stage**First Object Ignited****First Object Material****Second Object Ignited****Second Object Material****Indicated Cause**

Operating deficiency - not classified above

Certainty of Cause

Low

Age of Person

No person involved

Ethnicity**Gender****FAIP Service Offered**

Unknown