

Table 4 One way bridges on TCDR

SH	Name of bridge	AADT	Status
Out of scope			
12	Darby and Joan	350	Environmental concern with two significant Kauri trees adjacent the bridge. Good visibility. No safety or flooding issues. Low AADT.
Out of scope			
Out of scope			



The Darby and Joan bridge, shown in Figure 43 is located between two protected kauri trees. Widening the bridge is not feasible without damaging the trees or creating a new alignment that bypasses the trees.


Figure 43: SH12 Darby and Joan Bridge



Out of scope



Out of scope



Improvements to the Out of scope

'Darby and Joan' bridge in the Waipoua forest are not recommended. These bridges carry very low traffic volumes; Out of scope 350 vehicles per day respectively. No crashes have occurred at these locations and none have been closed due to flooding or slipping. As a result, these do not represent a resilience or safety risk and do not require increased capacity to carry higher traffic volumes. When traffic volumes increase significantly i.e. over 1200 AADT then further investigation could be warranted

Out of scope



Out of scope



PROACTIVELY RELEASED BY THE MINISTER OF TRANSPORT