

SMS Incident Report


12/11/2019 08:26:13

Summary

CAD Number F2232745 **Status** Closed
Station Invercargill Station
Incident Started 24/01/2017 21:59:21 **Incident Ended** 24/01/2017 23:50:30
Incident Type 8105: Wind storm, Tornado, Cyclone etc
Common Name JAMES HARGEST COLLEGE JUNIOR CAMPUS
Address 6 LAYARD STREET WINDSOR
Alarm Method 111 Telephone **Alarm Level** 1
PFA Number
Zone 38210300
Map Grid E 1243441 **Map Grid N** 4852049
First Caller [REDACTED] **First Caller Contact** [REDACTED]
Incident Closed 24/01/2017 23:59:03
Report Completed 21:52, Wed 25 Jan 2017 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
INVE211	P1	22:00:39 24 Jan 2017	22:01:39 24 Jan 2017	22:07:02 24 Jan 2017	23:50:58 24 Jan 2017
INVE214	PM	22:51:52 24 Jan 2017	22:52:11 24 Jan 2017	23:03:57 24 Jan 2017	23:53:30 24 Jan 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
INVE211	00:01:18	00:06:23	00:07:41	01:51:37
INVE214	00:52:31	00:12:05	01:04:36	01:54:09

Notifications

Date	Time	Party Notified
24 Jan 2017	22:16:06	KH ([REDACTED] - [REDACTED]) ADVISED, [REDACTED] WILL NOT BE RESPONDING

Message Log

Time	Message
22:00:21	INC INFO: LOOSE ROOFING IRON
22:00:23	** LOI search completed at 24/01/17 22:00:23
22:00:33	** Recommended unit INVE211 for requirement PUMP (>2.2 km)
22:01:33	** Event Type changed from MIN to NAT2 at: 24/01/17 22:01:33
22:01:34	** Event Priority changed from 2 to 4 at: 24/01/17 22:01:34
22:01:39	Unit INVE211 [K1 : PROCEEDING TO INCIDENT]
22:07:03	Unit INVE211 [K55 : SPECIAL SERVICE EVENT]
22:10:32	Unit INVE211 [KC : UNIT CALLING]
22:11:37	Unit INVE211 [SITREP :] SO [REDACTED], WE HAVE SOME ROOF FLASHING ROOF LOOSE,
22:11:37	FLAPPING IN THE WIND, TRYING TO GAIN ACCESS, IN ATRIUM/GYM AREA, ADVISE KH, FYI
22:11:37	ONLY NO REQUIREMENT TO RESPOND
22:27:47	Unit INVE211 [KC : UNIT CALLING]
22:29:13	Unit INVE211 [SITREP :] GTWW 10.5M EXTENSION LADDER TO GAIN ACCESS TO FLASHING
22:29:13	TO HOPEFULLY REMOVE [REDACTED] ADVISED, NOT RESPONDING)
22:50:48	Unit INVE211 [KC : UNIT CALLING]
22:51:41	Unit INVE211 [SITREP :] ATTACH 214, RESPOND THEM AT ROAD SPEED, RECIPROCATING
22:51:41	SAW REQUIRED
22:52:12	Unit INVE214 [K1 : PROCEEDING TO INCIDENT]
23:03:58	Unit INVE214 [K2 : IN ATTENDANCE AT INCIDENT]
23:48:55	Unit INVE214 [K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]
23:49:35	Unit INVE211 [KC : UNIT CALLING]
23:50:27	Unit INVE211 [SITREP :] FLASHING FINALLY REMOVED FROM BUILDING
23:50:30	Unit INVE211 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE]
23:50:59	Unit INVE211 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
23:53:31	Unit INVE214 [K7 : AT NORMAL STATION]
23:59:02	** Assigned Result Code: NAT2, Detailed Event Type: 9900, Qualifier 1: Q1,
23:59:02	Qualifier 2:

Incident

CAD Number

F2232745

Incident Reporter [REDACTED]
 Incident Controller SO [REDACTED]
 Distance Travelled (km) 3
 Delay In Receiving Call

Property Details

Occupant
 Building Owner
 General Property Use School: Pre-school through to Secondary/High
 Special Property Use Intermediate school
 Purpose Group

Actions

Persons Reported Trapped No
 Evacuation Status Not occupied at time of incident
 Action Prior 1 No action taken by Civilian/Occupant/Passerby
 Action Prior 2 No action taken by Civilian/Occupant/Passerby
 Action Taken Roof repair

Civilians

Civilians Rescued 0
 Civilians Extricated 0
 Civilians Assisted 0
 Civilians Evacuated

Origin

Location
 Level

Equipment Used

Quantity	Equipment
2	Ladder for Rescue
2	
1	
8	
1	

Equipment Involved

Equipment Involved

Year

Make

Model

Comments

1/25/2017 9:52:00 PM

Reporter Comments

Called by member of public to station about lose roofing iron at James Hargest Jr Campus. On arrival a large piece of flashing attached to atrium was insecure. Very limited access to flashing but was eventually was removed. School [REDACTED] was notified at time.

[REDACTED]

Released under the Official Information Act

SMS Incident Report


12/11/2019 08:26:44

Summary

CAD Number F2256018 **Status** Closed
Station Invercargill Station
Incident Started 28/02/2017 11:28:27 **Incident Ended** 28/02/2017 11:52:22
Incident Type 5103: Assist Police
Common Name AURORA COLLEGE
Address 234 REGENT STREET HEIDELBERG
Alarm Method 111 Telephone **Alarm Level** 1
PFA Number
Zone 38210300
Map Grid E 1245410 **Map Grid N** 4847707
First Caller [REDACTED] **First Caller Contact** [REDACTED]
Incident Closed 28/02/2017 12:07:36
Report Completed 17:5, Mon 03 Apr 2017 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
INVE214	PM	11:30:14 28 Feb 2017	11:30:53 28 Feb 2017	11:38:33 28 Feb 2017	11:52:32 28 Feb 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
INVE214	00:01:47	00:08:19	00:10:06	00:24:05

Message Log

Time	Message
10:57:59	AMBO EVENT 0165-3-2017/02/28-POL LINKED AT 28/02/2017 10:57:59
11:29:47	INC INFO: ASSIST POLICE
11:29:48	** Event Type changed from POL2FIR to MIN at: 28/02/17 11:29:48
11:30:53	Unit INVE214 [K1 : PROCEEDING TO INCIDENT]
11:31:06	Unit INVE214 [K1 : PROCEEDING TO INCIDENT]
11:32:42	.
11:32:52	FIR2POL - CONFIRM SFP - CARPARK ON REGENT OR TRAMWAY ?
11:32:53	.
11:34:03	Unit INVE214 [COMCEN COM : MESSAGE] FURTHER INFO GIVEN VIA PHONE
11:38:34	Unit INVE214 [K55 : SPECIAL SERVICE EVENT]
11:44:01	Unit INVE214 [KC : UNIT CALLING]
11:44:50	Unit INVE214 [SITREP :] SSO [REDACTED]. WE ARE ASSISTING POL AT LOWERING OCCUPANT
11:44:50	TO THE GROUND.
11:51:52	Unit INVE214 [KC : UNIT CALLING]
11:52:26	Unit INVE214 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE]
11:52:26	[REDACTED]
11:52:26	DOWN AND IN CARE WITH POLICE
11:52:34	Unit INVE214 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
12:07:35	** Assigned Result Code: MIN, Detailed Event Type: 3100, Qualifier 1: Q1,
12:07:35	Qualifier 2:

Incident

CAD Number F2256018

Incident Reporter [REDACTED]

Incident Controller SSO [REDACTED]

Distance Travelled (km) 3

Delay In Receiving Call

Property Details

Occupant

Building Owner

General Property Use School: Pre-school through to Secondary/High

Special Property Use Intermediate/high school classroom building

Purpose Group

Actions

Persons Reported

Trapped

Evacuation Status

Action Prior 1

Action Prior 2

Action Taken Special service incidents - not classified

Civilians

Civilians Rescued

0

Civilians Extricated

0

Civilians Assisted

0

Civilians Evacuated

Origin

Location

Level

Equipment Used

Quantity	Equipment
1	Ladder for Rescue

Equipment Involved

Equipment Involved

Year

Make

Model

Comments

4/3/2017 5:05:10 PM

Reporter Comments

Assist police with [redacted] who was on roof of school. [redacted] climbed down ladder on [redacted] own terms.

[redacted]

SMS Incident Report

12/11/2019 08:27:15

Summary

CAD Number F2258407 **Status** Closed

Station Invercargill Station

Incident Started 03/03/2017 13:21:31 **Incident Ended** 03/03/2017 13:46:44

Incident Type 2105: Overheating, Scorching, Excessive heat: No fire

Common Name SOUTHLAND BOYS HIGH SCHOOL

Address 181 HERBERT STREET GLADSTONE

Alarm Method Automatic PFA Call **Alarm Level** 1

PFA Number 620289

Zone 38210300

Map Grid E 1243260 **Map Grid N** 4851539


First Caller **First Caller Contact**

Incident Closed 03/03/2017 14:01:07

Report Completed 14:50, Fri 03 Mar 2017 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
INVE214	PM	13:22:21 03 Mar 2017	13:23:24 03 Mar 2017	13:27:02 03 Mar 2017	13:44:52 03 Mar 2017
INVE211	P1	13:22:23 03 Mar 2017	13:23:15 03 Mar 2017	13:27:08 03 Mar 2017	13:51:25 03 Mar 2017
KING227	PR	13:22:24 03 Mar 2017	13:23:27 03 Mar 2017	13:31:44 03 Mar 2017	13:34:17 03 Mar 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
INVE214	00:00:50	00:04:41	00:05:31	00:23:21
INVE211	00:00:52	00:04:45	00:05:37	00:29:54

KING227	00:00:53	00:09:20	00:10:13	00:12:46
---------	----------	----------	----------	----------

Message Log

Time	Message
13:21:32	AL: 620289 13:21:31 INITIAL - AL
13:21:32	PANEL: NORTH WEST CORNER OF MAIN BUILDING
13:21:33	** LOI search completed at 03/03/17 13:21:33
13:21:43	ACCESS NO: [REDACTED]
13:22:08	** Recommended unit INVE214 for requirement MONIT (>1.7 km)
13:22:08	** Recommended unit INVE211 for requirement PUMP (>1.7 km)
13:22:08	** Recommended unit KING227 for requirement PUMP (>5.8 km)
13:23:16	Unit INVE211 [K1 : PROCEEDING TO INCIDENT]
13:23:22	Unit INVE211 [K1 : PROCEEDING TO INCIDENT]
13:23:24	Unit INVE214 [K1 : PROCEEDING TO INCIDENT]
13:23:27	Unit KING227 [K1 : PROCEEDING TO INCIDENT]
13:23:32	Unit INVE214 [K1 : PROCEEDING TO INCIDENT]
13:24:21	Unit INVE214 [K1 : PROCEEDING TO INCIDENT]
13:26:34	Unit INVE211 [KC : UNIT CALLING]
13:27:03	Unit INVE214 [K2 : IN ATTENDANCE AT INCIDENT]
13:27:07	Unit INVE211 [SITREP :] (CANCEL THAT)
13:27:09	Unit INVE211 [K77 : NOTHING SHOWING]
13:27:48	Unit INVE211 [COMCEN COM : MESSAGE] 111 CALL INDICATES POSS FROM THE SCIENCE LAB
13:27:48	(ACK)
13:28:25	Unit INVE211 [KC : UNIT CALLING]
13:28:51	Unit INVE211 [SITREP :] SO [REDACTED]. BLOCK N SHOWING ON PANEL, INV FURTHER
13:31:44	Unit KING227 [K2 : IN ATTENDANCE AT INCIDENT]
13:33:48	Unit INVE211 [KC : UNIT CALLING]
13:34:19	Unit KING227 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
13:34:34	Unit INVE211 [SITREP :] DETECTOR 66 ACTIVATED, SMOKE LOGGED IN THIS AREA AND
13:34:34	GETTING TO WORK WITH PPV TO CLEAR FUMES.
13:44:54	Unit INVE214 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
13:46:17	Unit INVE211 [KC : UNIT CALLING]
13:46:45	Unit INVE211 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE]
13:48:25	Unit INVE211 [K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]
13:51:27	Unit INVE211 [K7 : AT NORMAL STATION]
14:01:07	** Assigned Result Code: STRU, Detailed Event Type: 9900, Qualifier 1: Q1,
14:01:07	Qualifier 2:

Incident

CAD Number F2258407

Incident Reporter [REDACTED]

Incident Controller [REDACTED]

Distance Travelled (km) 4

Delay In Receiving Call

Property Details

Occupant

Building Owner

General Property Use School: Pre-school through to Secondary/High

Special Property Use High school, College

Purpose Group

ActionsPersons Reported
Trapped

Evacuation Status

Action Prior 1

Action Prior 2

Action Taken Ventilation only

Origin

Location

Level

Equipment Used

Quantity	Equipment
1	
3	
4	
3	
1	
3	

Equipment Involved

Equipment Involved

Year

Make

Model

Comments

3/3/2017 2:50:15 PM

Reporter Comments

Alarm activation in science block due to excess smoke generated during lesson.
PPV used to clear area.
Smoke detector N 2-64.

[REDACTED]

Released under the Official Information Act

SMS Incident Report


12/11/2019 08:27:43

Summary

CAD Number F2338129 **Status** Closed
Station Invercargill Station
Incident Started 06/07/2017 17:13:20 **Incident Ended** 06/07/2017 17:44:37
Incident Type 1502: Outside Rubbish bin, Skip fire
Common Name JAMES HARGEST COLLEGE SENIOR CAMPUS
Address 288 LAYARD STREET WAVERLEY
Alarm Method 111 Telephone **Alarm Level** 1
PFA Number
Zone 38210300
Map Grid E 1245056 **Map Grid N** 4852164
First Caller [REDACTED] **First Caller Contact** [REDACTED]
Incident Closed 06/07/2017 17:47:20
Report Completed 22:6, Sun 16 Jul 2017 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
INVE211	P1	17:13:57 06 Jul 2017	17:14:48 06 Jul 2017	17:20:26 06 Jul 2017	17:44:41 06 Jul 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
INVE211	00:00:37	00:06:29	00:07:06	00:31:21

Message Log

Time	Message
17:13:43	INC INFO: SKIP BIN ON FIRE
17:13:47	** LOI search completed at 06/07/17 17:13:47
17:13:51	** Recommended unit INVE211 for requirement PUMP (>3.0 km)
17:13:58	ACCESS OFF RACECOURSE ROAD
17:14:48	Unit INVE211 [K1 : PROCEEDING TO INCIDENT]
17:15:34	Unit INVE211 [COMCEN COM : MESSAGE] ACCESS OFF RACECOURSE RD
17:20:27	Unit INVE211 [K66 : NON PROPERTY FIRE]
17:22:55	Unit INVE211 [KC : UNIT CALLING]
17:23:25	Unit INVE211 [SITREP :] SO [REDACTED]..1 LARGE BIN ON FIRE..USING HP HR AND 1 IN BA
17:43:55	Unit INVE211 [KC : UNIT CALLING]
17:44:24	Unit INVE211 [SITREP :] AFTER SPEAKING WITH CARETAKER OF SCHOOL..K12
17:44:30	Unit INVE211 [K12 : SUSPICIOUS FIRE]
17:44:38	Unit INVE211 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE]
17:44:43	Unit INVE211 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
17:47:19	** Assigned Result Code: MIN, Detailed Event Type: 1500, Qualifier 1: Q1,
17:47:19	Qualifier 2:

Incident

CAD Number F2338129
Incident Reporter [REDACTED]
Incident Controller SO [REDACTED]
Distance Travelled (km)
Delay In Receiving Call

Property Details

Occupant
Building Owner
General Property Use School: Pre-school through to Secondary/High
Special Property Use High school, College
Purpose Group

Actions

Persons Reported Trapped
Evacuation Status
Action Prior 1
Action Prior 2

Action Taken Extinguishment only: Includes isolating fuel/power

Origin

Location

Level

Equipment Used

Quantity	Equipment
1	Hose reel, high pressure delivery
1	
1	

Equipment Involved

Equipment Involved

Year

Make

Model

Fire

Arrival Condition

Heat Source

Termination Stage

First Object Ignited

First Object Material

Second Object Ignited

Second Object Material

Indicated Cause Unlawful

Certainty of Cause Medium

Age of Person Unknown

Ethnicity Unknown

Gender

FAIP Service Offered Unknown

Comments

7/16/2017 10:06:15 PM

Reporter Comments

Unknown reason for fire to have started.

Released under the Official Information Act

SMS Incident Report


12/11/2019 08:28:05

Summary

CAD Number F2353190 **Status** Closed
Station Invercargill Station
Incident Started 29/07/2017 23:39:51 **Incident Ended** 30/07/2017 00:26:47
Incident Type 1511: Outside fire: Material burnt has definable value
Common Name SOUTHLAND GIRLS HIGH SCHOOL
Address 328 TWEED STREET GEORGETOWN
Alarm Method 111 Telephone **Alarm Level** 1
PFA Number
Zone 382104
Map Grid E 1243922 **Map Grid N** 4849213
First Caller PREPAID/SPARK **First Caller Contact** [REDACTED]
Incident Closed 30/07/2017 00:33:47
Report Completed 20:16, Thur 10 Aug 2017 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
INVE211	P1	23:41:19 29 Jul 2017	23:42:47 29 Jul 2017	23:45:39 29 Jul 2017	00:32:23 30 Jul 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
INVE211	00:01:28	00:04:20	00:05:48	00:52:32

Notifications

Date	Time	Party Notified
30 Jul 2017	00:19:29	FROM TRAIN CONTROL TRAIN HAVE STOPPED FOR THE NIGHT

30 Jul 2017	00:29:20	TRAIN CONTROL THAT WE HAVE COMPLETED OPERATIONS
-------------	----------	---

Message Log

Time	Message
23:41:05	INC INFO: FENCE ON FIRE AT THE BACK OF
23:41:09	** LOI search completed at 29/07/17 23:41:09
23:41:13	** Recommended unit INVE211 for requirement PUMP (>1.1 km)
23:42:47	Unit INVE211 [K1 : PROCEEDING TO INCIDENT]
23:43:30	Unit INVE211 [KC : UNIT CALLING]
23:43:54	BY THE WALKWAY
23:44:05	Unit INVE211 [SITREP :] ANY FURTHER INFO
23:45:40	Unit INVE211 [K77 : NOTHING SHOWING]
23:50:51	Unit INVE211 [KC : UNIT CALLING]
23:51:27	Unit INVE211 [K11P : POLICE REQUIRED]
23:51:46	Unit INVE211 [SITREP :] FEW SPOT FIRES ALONG THE FENCE
23:52:16	FIR2POL POLICE REQUIRED SUPICIOUS FIRE FENCE FIRE
00:01:14	Unit INVE211 [KC : UNIT CALLING]
00:01:58	Unit INVE211 [SITREP :] SO [REDACTED] MULT SPOT FIRES ALONG FENCE LINE GTW WITH
00:01:58	EXTENGUISHER
00:16:22	Unit INVE211 [KC : UNIT CALLING]
00:17:17	Unit INVE211 [SITREP :] CONTACT TRAIN CONTROL TO MAKE SURE THERE ARE NO TRAINS
00:17:17	DUE AS WE NEED TO PUT A FEED ACROSS THE TRAIN TRACKS
00:19:41	Unit INVE211 [COMCEN COM : MESSAGE] ALL TRAINS HAVE STOPPED FOR THE NIGHT
00:26:19	Unit INVE211 [KC : UNIT CALLING]
00:26:47	Unit INVE211 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] 1 FENCE
00:26:47	FIRE EXT WITH HR
00:26:52	Unit INVE211 [K12 : SUSPICIOUS FIRE]
00:32:24	Unit INVE211 [K7 : AT NORMAL STATION]
00:33:46	** Assigned Result Code: MIN, Detailed Event Type: 1500, Qualifier 1: Q1,
00:33:46	Qualifier 2:

Incident

CAD Number F2353190
Incident Reporter [REDACTED]
Incident Controller [REDACTED]
Distance Travelled (km)

Delay In Receiving Call**Property Details****Occupant****Building Owner****General Property Use** School: Pre-school through to Secondary/High**Special Property Use** High school, College**Purpose Group****Actions****Persons Reported****Trapped****Evacuation Status****Action Prior 1****Action Prior 2****Action Taken** Extinguishment only: Includes isolating fuel/power**Origin****Location****Level****Equipment Used**

Quantity	Equipment
1	Hose reel, high pressure delivery
1	

Equipment Involved**Equipment Involved****Year****Make****Model****Fire****Arrival Condition****Heat Source****Termination Stage****First Object Ignited****First Object Material****Second Object Ignited**

Second Object Material

Indicated Cause	Deliberately lit fire - not classified above
Certainty of Cause	High
Age of Person	Unknown
Ethnicity	Unknown
Gender	
FAIP Service Offered	Unknown

Comments

8/10/2017 8:16:23 PM Reporter Comments

Fire behind school in trees and wooden fence line.



Released under the Official Information Act

SMS Incident Report

12/11/2019 08:28:42

Summary

CAD Number F2502834 **Status** Closed

Station Invercargill Station

Incident Started 15/03/2018 15:13:25 **Incident Ended** 15/03/2018 16:12:34

Incident Type 1101: Structure fire with damage

Common Name JAMES HARGEST COLLEGE SENIOR CAMPUS ADMINISTRATION

Address / Hargest

Alarm Method Manual PFA Call **Alarm Level** 1

PFA Number 620533

Zone 38210300

Map Grid E 1245056 **Map Grid N** 4852164


First Caller **First Caller Contact**

Incident Closed 15/03/2018 16:12:34

Report Completed 22:12, Sat 24 Mar 2018 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
INVE214	PM	15:13:42 15 Mar 2018	15:15:05 15 Mar 2018	15:20:31 15 Mar 2018	16:03:18 15 Mar 2018
INVE211	P1	15:13:42 15 Mar 2018	15:14:36 15 Mar 2018	15:26:01 15 Mar 2018	15:59:55 15 Mar 2018
KING227	PR	15:13:44 15 Mar 2018	15:14:50 15 Mar 2018	15:37:50 15 Mar 2018	15:37:52 15 Mar 2018



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
INVE214	00:00:17	00:06:49	00:07:06	00:49:53
INVE211	00:00:17	00:12:19	00:12:36	00:46:30

KING227	00:00:19	00:24:06	00:24:25	00:24:27
---------	----------	----------	----------	----------

Notifications

Date	Time	Party Notified
15 Mar 2018	16:40:42	FI REGION 5
15 Mar 2018	16:49:33	FI REGION 5 ACK PAGE (██████████) PUT THRU TO ██████████

Message Log

Time	Message
15:13:26	AL: 620533 15:13:25 INITIAL - AL
15:13:26	PANEL: SOUHTSIDE OF ADMIN
15:13:28	** LOI search completed at 15/03/18 15:13:28
15:13:33	** Recommended unit INVE214 for requirement MONIT (>3.0 km)
15:13:33	** Recommended unit INVE211 for requirement PUMP (>3.0 km)
15:13:33	** Recommended unit KING227 for requirement PUMP (>6.3 km)
15:14:36	Unit INVE211 [K1 : PROCEEDING TO INCIDENT]
15:14:50	Unit KING227 [K1 : PROCEEDING TO INCIDENT]
15:15:06	Unit INVE214 [K1 : PROCEEDING TO INCIDENT]
15:20:32	Unit INVE214 [K2 : IN ATTENDANCE AT INCIDENT]
15:21:04	Unit INVE214 [KC : UNIT CALLING]
15:21:44	Unit INVE214 [SITREP :] SSO ██████████ CONFIRMED FIRE INVESTIGATING FURTHER ENSURING
15:21:44	EVAC IS COMPLETE
15:26:01	Unit INVE211 [K77 : NOTHING SHOWING]
15:26:05	Unit INVE211 [KC : UNIT CALLING]
15:26:42	Unit INVE211 [SITREP :] FIRE IN CARDBOARD BELIEVED OUT. GTW PPV
15:29:02	Unit INVE214 [KC : UNIT CALLING]
15:29:18	Unit INVE214 [K12 : SUSPICIOUS FIRE]
15:29:45	Unit INVE214 [SITREP :] SOMEBODY HAS LIT A TOILET ROLL ON FIRE
15:29:58	Unit INVE214 [K11P : POLICE REQUIRED] POLICE IN ATTENDANCE
15:30:38	FIR2POL-- SUSPICIOUS FIRE
15:30:53	Unit KING227 [K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]
15:37:50	Unit KING227 [K2 : IN ATTENDANCE AT INCIDENT]
15:37:54	Unit KING227 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
15:56:39	Unit INVE211 [KC : UNIT CALLING]
15:57:07	Unit INVE211 [STOP : MESSAGE] SO ██████████ - SCENE LEFT WITH POLICE
15:57:23	Unit INVE211 [K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]
15:59:56	Unit INVE211 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
16:03:20	Unit INVE214 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

16:12:33	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,
16:12:33	Qualifier 2:
16:40:05	.
16:40:18	INVERCARGILL CIB REQUEST A CALL FROM THE ON CALL FI
16:40:26	TO CALL [REDACTED]
16:40:28	.
16:42:19	.
16:51:31	.
16:51:44	** Event F2502834 has been reopened at: 15/03/18 16:51:44
16:51:47	** LOI search completed at 15/03/18 16:51:47
17:21:52	Unit FISOUTHLD2 [K6 : ON TELEPAGER]
17:22:34	Unit FISOUTHLD2 [K1 : PROCEEDING TO INCIDENT]
17:23:33	Unit FISOUTHLD2 [K1 : PROCEEDING TO INCIDENT]
17:23:41	Unit FISOUTHLD2 [K1 : PROCEEDING TO INCIDENT]
17:23:53	Unit FISOUTHLD2 [K1 : PROCEEDING TO INCIDENT]
17:28:34	Unit FISOUTHLD2 [KC : UNIT CALLING]
17:29:50	Unit FISOUTHLD2 [K2 : IN ATTENDANCE AT INCIDENT]
18:08:40	Unit FISOUTHLD2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
18:58:26	** Assigned Result Code: STRU, Detailed Event Type: 1500, Qualifier 1: Q1,
18:58:26	Qualifier 2:

Incident

CAD Number F2502834
Incident Reporter [REDACTED]
Incident Controller
Distance Travelled (km)
Delay In Receiving Call

Property Details

Occupant James Hargest High School
Building Owner State owned
General Property Use School: Pre-school through to Secondary/High
Special Property Use High school, College
Purpose Group

Actions

Persons Reported Trapped
Evacuation Status Fully evacuated

Action Prior 1**Action Prior 2****Action Taken** Extinguishment, salvage and ventilation**Civilians**

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	0

Origin

Location Unable to classify
Level Ground level

Equipment Used

Quantity	Equipment
1	Hose reel, high pressure delivery
1	Fire Extinguisher
1	Building/Site/Private Fire Equipment
1	Equipment Not Listed

Equipment Involved

Equipment Involved

Year**Make****Model****Fire****Arrival Condition** Small fire**Heat Source** Cigarettes, matches and candles - Other**Termination Stage****First Object Ignited****First Object Material****Second Object Ignited****Second Object Material****Indicated Cause** Unlawful**Certainty of Cause** High**Age of Person****Ethnicity**

Gender

FAIP Service Offered Unknown

Alarms

Type of Alarm	Smoke Detector System (Monitored)
Initiating Call	
Performance of System	Alerted occupants - detector in room of origin
Failure/Ineffectiveness of system	
Number of sprinkler heads operated	0

Comments

3/24/2018 10:12:54 PM

Reporter Comments

Fire in toilet block of school locker area. Police involved in investigation

3/28/2018 9:18:10 AM

Reporter Comments

I was requested by police to attend and investigate the cause and origin of a fire within the male toilets in Block B of James Hargest High School, Senior Campus complex. I was informed by attending firefighters that a small fire had been found within a toilet cubicle.

I arrived at the address at 18:10pm on 15 March 2018. A police scene guard was in place. I liaised with Police.

The corridor immediately outside the toilet revealed slight smoke staining only. The interior of the toilet revealed smoke and soot condensate adhered to the ceiling and walls. The south side toilet cubicle contained the remains of a burned plastic toilet roll holder. The plastic had melted dripping onto the floor. A large portion of the toilet paper roll still remained but burning across the exposed surface of the paper and the wall adjacent was evident.

Damage was also evident on the wall lining supporting the toilet roll holder.

A smoke detector in the toilet had been removed from its fitting by an attending fire alarm agent. It was found to have some paper forced into the orifice possibly in an effort to reduce the units ability to detect smoke. This detector had a protective cage around it and with paper covering the air inlets would have reduced units effectiveness to pick up smoke. The cage was in place when the firefighters arrived and given the effort required to unscrew and remove it; it is likely that this paper was set in place at some time prior to this event.

Cause: There was no evidence of an ignition source found. Ignition of the paper within the toilet roll holder would not have been difficult and is likely to have been initiated with a naked flame from a cigarette lighter or matches.

This fire event is classified as incendiary.

Released under the Official Information Act

SMS Incident Report


12/11/2019 08:29:11

Summary

CAD Number F2558700 **Status** Closed
Station Invercargill Station
Incident Started 08/06/2018 13:38:22 **Incident Ended** 08/06/2018 13:54:06
Incident Type 5104: Assist Public: General
Common Name VERDON COLLEGE
Address / 210 Rockdale Road Rockdale
Alarm Method 111 Telephone **Alarm Level** 1
PFA Number
Zone 38210300
Map Grid E 1246231 **Map Grid N** 4849433
First Caller [REDACTED] **First Caller Contact** [REDACTED]
Incident Closed 08/06/2018 14:20:33
Report Completed 9:53, Fri 15 Jun 2018 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
INVE211	P1	13:39:13 08 Jun 2018	13:39:47 08 Jun 2018	13:46:50 08 Jun 2018	13:54:00 08 Jun 2018



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
INVE211	00:00:51	00:07:37	00:08:28	00:15:38

Message Log

Time	Message
13:38:46	INC INFO: PERSON STUCK IN ELEVATOR
13:38:49	** LOI search completed at 08/06/18 13:38:49
13:38:54	.
13:39:02	APPROX 5 PERSONS STILL INSIDE
13:39:06	** Recommended unit INVE211 for requirement PUMP (>4.4 km)
13:39:48	Unit INVE211 [K1 : PROCEEDING TO INCIDENT]
13:39:55	HAS USED THE PHONE AND NO ONE PICKED
13:41:31	.
13:41:37	ELEVATOR IN THE DOMINIC BLOCK
13:41:40	IS AT THE VERY TOP STOREY
13:41:41	.
13:46:50	Unit INVE211 [K55 : SPECIAL SERVICE EVENT]
13:53:11	Unit INVE211 [KC : UNIT CALLING]
13:53:52	.
13:53:55	.
13:54:01	Unit INVE211 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
13:54:06	Unit INVE211 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] SO [REDACTED]
13:54:06	STUDENTS NOW OUT OF LIFT
14:20:32	** Assigned Result Code: MIN, Detailed Event Type: 3100, Qualifier 1: Q1,
14:20:32	Qualifier 2:

Incident

CAD Number F2558700
Incident Reporter [REDACTED]
Incident Controller
Distance Travelled (km)
Delay In Receiving Call

Property Details

Occupant
Building Owner
General Property Use School: Pre-school through to Secondary/High
Special Property Use High school, College
Purpose Group

Actions

Persons Reported

Trapped

Evacuation Status

Action Prior 1

Action Prior 2

Action Taken Lock-out, Gain entry

Civilians

Civilians Rescued 0

Civilians Extricated 0

Civilians Assisted 6

Civilians Evacuated 0

Origin

Location

Level

Equipment Used

Quantity	Equipment
1	Equipment Not Listed

Equipment Involved

Equipment Involved

Year

Make

Model

Comments

6/15/2018 9:53:04 AM

Reporter Comments

Assist with 6 students stuck in a lift



SMS Incident Report

12/11/2019 08:29:33

Summary

CAD Number F2590905 **Status** Closed

Station Invercargill Station

Incident Started 06/08/2018 10:47:11 **Incident Ended** 06/08/2018 11:13:17

Incident Type 1599: Other Fire - not classified above

Common Name AURORA COLLEGE

Address / 234 Regent Street Heidelberg

Alarm Method Manual PFA Call **Alarm Level** 1

PFA Number 620816

Zone 38210300

Map Grid E 1245410 **Map Grid N** 4847707


First Caller **First Caller Contact**

Incident Closed 06/08/2018 11:24:06

Report Completed 17:37, Mon 06 Aug 2018 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
INVE211	P1	10:47:34 06 Aug 2018	10:48:26 06 Aug 2018	10:53:58 06 Aug 2018	11:13:19 06 Aug 2018
KING227	PR	10:47:28 06 Aug 2018	10:48:38 06 Aug 2018	10:55:08 06 Aug 2018	11:05:47 06 Aug 2018
INVE214	PM	10:47:34 06 Aug 2018	10:48:30 06 Aug 2018	10:55:16 06 Aug 2018	11:21:20 06 Aug 2018



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
INVE211	00:00:23	00:06:24	00:06:47	00:26:08
KING227	00:00:17	00:07:40	00:07:57	00:18:36

INVE214	00:00:23	00:07:42	00:08:05	00:34:09
---------	----------	----------	----------	----------

Message Log

Time	Message
10:47:12	AL: 620816 10:47:11 INITIAL - AL
10:47:12	PANEL: MAIN OFFICE BLOCK A
10:47:14	** LOI search completed at 06/08/18 10:47:14
10:47:20	** Recommended unit INVE214 for requirement MONIT (>3.1 km)
10:47:20	** Recommended unit INVE211 for requirement PUMP (>3.1 km)
10:47:20	** Recommended unit KING227 for requirement PUMP (>2.0 km)
10:48:06	ACCESS NO: ■
10:48:22	Unit KING227 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
10:48:27	Unit INVE211 [K1 : PROCEEDING TO INCIDENT]
10:48:30	Unit INVE214 [K1 : PROCEEDING TO INCIDENT]
10:48:39	Unit KING227 [K1 : PROCEEDING TO INCIDENT]
10:53:59	Unit INVE211 [K77 : NOTHING SHOWING]
10:55:09	Unit KING227 [K2 : IN ATTENDANCE AT INCIDENT]
10:55:16	Unit INVE214 [K2 : IN ATTENDANCE AT INCIDENT]
10:56:22	Unit INVE211 [KC : UNIT CALLING]
10:57:13	Unit INVE211 [SITREP :] SO ■. INDICATOR PANEL SHOWING CIRCUIT 3, D
10:57:13	BLOCK AND WALKWAY, BEEN ADVISED THAT ■ HAS LIT PLASTIC BAG ON
10:57:13	WALKWAY. INV FURTHER.
10:58:55	Unit KING227 [K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]
11:05:49	Unit KING227 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
11:12:03	Unit INVE214 [K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]
11:12:29	Unit INVE211 [KC : UNIT CALLING]
11:13:17	Unit INVE211 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE]
11:13:17	PLASTIC
11:13:17	TOILET ROLL HOLDER SET ON FIRE OUTSIDE THE STRUCTURE, K12 LEFT IN THE
11:13:17	HANDS OF
11:13:17	THE SCHOOL
11:13:20	Unit INVE211 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
11:13:27	Unit INVE211 [K12 : SUSPICIOUS FIRE]
11:21:22	Unit INVE214 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
11:24:06	** Assigned Result Code: STRU, Detailed Event Type: 7100, Qualifier 1: Q1,
11:24:06	Qualifier 2:

Incident

CAD Number F2590905

Incident Reporter [REDACTED]

Incident Controller

Distance Travelled (km)

Delay In Receiving Call

Property Details

Occupant

Building Owner

General Property Use School: Pre-school through to Secondary/High

Special Property Use Intermediate/high school classroom building

Purpose Group

ActionsPersons Reported
Trapped

Evacuation Status

Action Prior 1

Action Prior 2

Action Taken Investigation only (Fire related)

Civilians

Civilians Rescued 0

Civilians Extricated 0

Civilians Assisted 0

Civilians Evacuated 0

Origin

Location

Level

Equipment Used

Quantity	Equipment
0	No equipment used

Equipment Involved

Equipment Involved

Year

Make

Model

Fire

Arrival Condition	Out on arrival
Heat Source	Cigarette, Cigar or Smoking materials
Termination Stage	
First Object Ignited	
First Object Material	
Second Object Ignited	
Second Object Material	
Indicated Cause	Suspicious
Certainty of Cause	High
Age of Person	Persons: [REDACTED]
Ethnicity	Unknown
Gender	[REDACTED]
FAIP Service Offered	FAIP was offered but not accepted

Comments

8/6/2018 5:37:04 PM

Reporter Comments

Detector head 3/48 activated due to a plastic toilet roll holder been set on fire outside the building but the smoke has entered the building and set off the alarm. The principle has identified the [REDACTED] that lit the fire and is dealing with it. FAIP was offered and the principle will e-mail me the details if they would like it.

[REDACTED]

SMS Incident Report


12/11/2019 08:29:57

Summary

CAD Number F2671308 **Status** Closed
Station Invercargill Station
Incident Started 14/12/2018 15:15:18 **Incident Ended** 14/12/2018 15:35:39
Incident Type 1599: Other Fire - not classified above
Common Name SOUTHLAND GIRLS HIGH SCHOOL EAST WING
Address / 366 Tweed Street Georgetown
Alarm Method 111 Telephone **Alarm Level** 1
PFA Number
Zone 38210300
Map Grid E 1244053 **Map Grid N** 4849162
First Caller **First Caller Contact** [REDACTED]
Incident Closed 14/12/2018 16:22:22
Report Completed 18:16, Sun 23 Dec 2018 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
INVE211	P1	15:16:38 14 Dec 2018	15:18:09 14 Dec 2018	15:20:52 14 Dec 2018	15:35:44 14 Dec 2018



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
INVE211	00:01:20	00:04:14	00:05:34	00:20:26

Notifications

Date	Time	Party Notified
14 Dec 2018	15:25:24	POLICE VIA INTERCAD

14 Dec 2018	15:29:48	SCHOOL SUPPORT LIMITED () - FYI RE TREE FIRE BETWEEN 2 BUILDINGS
-------------	----------	---

Message Log

Time	Message
15:16:22	** LOI search completed at 14/12/18 15:16:22
15:16:22	INC INFO: TREE FIRE
15:16:32	TREE FIRE AT TEH SCHOOL BETWEEN 2 BLDGS
15:16:33	** Recommended unit INVE211 for requirement PUMP (>1.2 km)
15:16:36	PA Selcal used to Initiate Alerting. ()
15:16:38	ALERTING_COMPLETED
15:18:09	kcode [K1 : PROCEEDING TO INCIDENT]
15:18:09	Unit INVE211 [K1 : PROCEEDING TO INCIDENT]
15:18:12	ACCESS ()
15:18:17	kcode [K1 : PROCEEDING TO INCIDENT]
15:18:17	Unit INVE211 [K1 : PROCEEDING TO INCIDENT]
15:20:20	Unit INVE211 [COMCEN COM : MESSAGE] TREE FIRE AT THE SCHOOL BETWEEN 2 BLDGS ACCE
15:20:20	SS NUMBER () .
15:20:52	kcode [K66 : NON PROPERTY FIRE]
15:20:53	Unit INVE211 [K66 : NON PROPERTY FIRE]
15:22:46	Unit INVE211 [KC : UNIT CALLING]
15:23:53	Unit INVE211 [SITREP :] 1 FIRE IN BUSHES BETWEEN 2 BUILDING 1 HR IN USE
15:24:21	Unit INVE211 [K12 : SUSPICIOUS FIRE] CRICKET PITCH HAS BE BEEN TORN UP AND SET
15:24:21	A LIGHT
15:24:28	Unit INVE211 [K11P : POLICE REQUIRED]
15:25:13	FIR2POLS USPICIOUS FIRE CRICKET PITCH AND BUSHES HAS BEEN SET ALIGHT
15:29:06	**
15:29:49	**
15:35:07	Unit INVE211 [KC : UNIT CALLING]
15:35:39	Unit INVE211 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] SO ()
15:35:39	() POLICE IN ATTEND INV
15:35:44	kcode [K4 : ON RT INSIDE NORMAL TURNOUT
15:35:44	Unit INVE211 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
16:22:22	** Assigned Result Code: VEG, Detailed Event Type: 1300

Incident

CAD Number F2671308
 Incident Reporter [REDACTED]
 Incident Controller
 Distance Travelled (km)
 Delay In Receiving Call

Property Details

Occupant
 Building Owner
 General Property Use School: Pre-school through to Secondary/High
 Special Property Use High school, College
 Purpose Group

Actions

Persons Reported Trapped
 Evacuation Status
 Action Prior 1
 Action Prior 2
 Action Taken Extinguishment, salvage and ventilation

Civilians

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	0

Origin

Location
 Level

Equipment Used

Quantity	Equipment
1	Hose reel, high pressure delivery

Equipment Involved

Equipment Involved
 Year
 Make

Model

Fire

Arrival Condition	Small fire
Heat Source	Information not recorded/Unknown
Termination Stage	
First Object Ignited	
First Object Material	
Second Object Ignited	
Second Object Material	
Indicated Cause	Unlawful
Certainty of Cause	High
Age of Person	Unknown
Ethnicity	Unknown
Gender	
FAIP Service Offered	Unknown

Comments

12/23/2018 6:16:22 PM

Reporter Comments

Deliberately lit fire between the bike sheds and school block. turf from the cricket nets and magazines were used to start a fire in the trees. police attended



Released under the Official Information Act

SMS Incident Report


12/11/2019 08:30:28

Summary

CAD Number F2780552 **Status** Closed
Station Invercargill Station
Incident Started 30/05/2019 07:03:10 **Incident Ended** 30/05/2019 07:53:35
Incident Type 1102: Structure fire with no damage
Common Name JAMES HARGEST COLLEGE SENIOR CAMPUS ADMINISTRATION
Address / 288 Layard Street Waverley
Alarm Method Manual PFA Call **Alarm Level** 1
PFA Number 620533
Zone 38210300
Map Grid E 1245056 **Map Grid N** 4852164
First Caller **First Caller Contact**
Incident Closed 30/05/2019 07:53:35
Report Completed 11:6, Sat 01 Jun 2019 by ██████████

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
INVE211	P1	07:03:25 30 May 2019	07:05:05 30 May 2019	07:10:22 30 May 2019	07:27:45 30 May 2019
INVE214	PM	07:03:25 30 May 2019	07:04:42 30 May 2019	07:10:27 30 May 2019	07:28:22 30 May 2019
KING227	PR	07:03:28 30 May 2019	07:04:22 30 May 2019	07:13:02 30 May 2019	07:27:40 30 May 2019



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
INVE211	00:00:15	00:06:57	00:07:12	00:24:35
INVE214	00:00:15	00:07:02	00:07:17	00:25:12

KING227	00:00:18	00:09:34	00:09:52	00:24:30
---------	----------	----------	----------	----------

Message Log

Time	Message
07:03:10	AL: 620533 07:03:09 INITIAL - ALARM
07:03:10	** LOI search completed at 30/05/19 07:03:10
07:03:18	** Recommended unit INVE214 for requirement MONIT (>3.0 km) ** Recommended unit
07:03:18	INVE211 for requirement PUMP (>3.0 km) ** Recommended unit KING227 for require
07:03:18	ment PUMP (>6.3 km)
07:03:22	Access No: ■
07:03:22	PA Selcal used to Initiate Alerting.(■■■■)
07:03:23	PA Selcal used to Initiate Alerting.(■■■■)
07:03:23	PA Selcal used to Initiate Alerting.(■■■■)
07:03:25	ALERTING_COMPLETED
07:03:26	ALERTING_COMPLETED
07:03:28	ALERTING_COMPLETED
07:03:31	Directions: RP: J2
07:03:55	Pager turnout error - request Id 0
07:03:55	Pager turnout error - request Id 0
07:04:22	Unit KING227 [K1 : PROCEEDING TO INCIDENT]
07:04:42	Unit INVE214 [K1 : PROCEEDING TO INCIDENT]
07:04:50	Unit INVE214 [K1 : PROCEEDING TO INCIDENT]
07:05:05	Unit INVE211 [K1 : PROCEEDING TO INCIDENT]
07:10:23	Unit INVE211 [K77 : NOTHING SHOWING]
07:10:27	Unit INVE214 [K2 : IN ATTENDANCE AT INCIDENT]
07:12:00	Unit INVE211 [KC : UNIT CALLING]
07:13:02	Unit KING227 [K2 : IN ATTENDANCE AT INCIDENT]
07:13:16	Unit INVE211 [SITREP :] SO ■■■■■ PANEL SHOWING SMOKE SECTOR E1
07:15:45	Unit INVE211 [KC : UNIT CALLING]
07:17:02	Unit INVE211 [SITREP :] ZONE E/ADMIN SLIGHT SMELL OF SMOKE. ELECTRICAL. L1/Z1D
07:17:02	60 CREWS INVESTIGATING FURTHER
07:26:18	Unit INVE211 [KC : UNIT CALLING]
07:26:55	Unit INVE211 [SITREP :] 1 DETECTOR HEAD ACTIVATED AND LEAVING IN THE HANDS OF
07:26:55	THE ALARM AGENT
07:27:20	Unit INVE211 [KC : UNIT CALLING]

07:27:41	Unit KING227 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
07:27:43	Unit INVE211 [STOP : MESSAGE] SCENE LEFT IN THE HANDS OF ALARM AGENT
07:27:46	Unit INVE211 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
07:28:23	Unit INVE214 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
07:53:34	** Assigned Result Code: STRU, Detailed Event Type: 7100

Incident

CAD Number F2780552
Incident Reporter XXXXXXXXXX
Incident Controller
Distance Travelled (km)
Delay In Receiving Call

Property Details

Occupant James Hargest Sewnior Campus
Building Owner State owned
General Property Use School: Pre-school through to Secondary/High
Special Property Use High school, College
Purpose Group

Actions

Persons Reported Trapped
Evacuation Status Not occupied at time of incident
Action Prior 1
Action Prior 2
Action Taken Investigation only (Fire related)

Civilians

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	0

Origin

Location Hallway, Passageway, Corridor, Walkway in mall
Level Ground level

Equipment Used

Quantity	Equipment
0	No equipment used

Equipment Involved

Equipment Involved

Year

Make

Model

Fire**Arrival Condition** Out on arrival**Heat Source** Heat from electrical equip: Defective or faulty**Termination Stage****First Object Ignited****First Object Material****Second Object Ignited****Second Object Material****Indicated Cause** Short circuit, earth fault**Certainty of Cause** High**Age of Person****Ethnicity****Gender****FAIP Service Offered** Unknown**Alarms**

Type of Alarm Smoke Detector System (Monitored)

Initiating Call

Performance of System Alerted occupants - detector in room of origin

Failure/Ineffectiveness of system

Number of sprinkler heads operated

Comments

6/1/2019 11:06:41 AM

Reporter Comments

Light ballast that has shorted out and blown. Smell of electrical burning on arrival - smoke detector activated right next to the light fixture. Left the scene in the hands of the alarm agent who was fixing the light fixture.

Released under the Official Information Act

SMS Incident Report


12/11/2019 08:31:00

Summary

CAD Number F2783666 **Status** Closed
Station Invercargill Station
Incident Started 04/06/2019 13:37:28 **Incident Ended** 04/06/2019 14:01:48
Incident Type 1312: Vegetation Fire
Common Name SOUTHLAND GIRLS HIGH SCHOOL
Address / 328 Tweed Street Georgetown
Alarm Method 111 Telephone **Alarm Level** 1
PFA Number
Zone 382104
Map Grid E 1243853 **Map Grid N** 4849099
First Caller VODAFONE NEW ZEALAND LTD **First Caller Contact** [REDACTED]
Incident Closed 04/06/2019 14:08:26
Report Completed 16:12, Tue 04 Jun 2019 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
INVE211	P1	13:38:35 04 Jun 2019	13:40:04 04 Jun 2019	13:43:38 04 Jun 2019	14:05:57 04 Jun 2019



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
INVE211	00:01:07	00:05:03	00:06:10	00:28:29

Message Log

Time	Message

Incident

CAD Number F2783666
Incident Reporter [REDACTED]
Incident Controller
Distance Travelled (km)
Delay In Receiving Call

Property Details

Occupant
Building Owner
General Property Use School: Pre-school through to Secondary/High
Special Property Use
Purpose Group

Actions

Persons Reported Trapped
Evacuation Status
Action Prior 1
Action Prior 2
Action Taken Extinguishment only: Includes isolating fuel/power

Civilians

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	0

Origin

Location
Level

Equipment Used

Quantity	Equipment
1	Fire Extinguisher

Equipment Involved

Equipment Involved

Year

Make

Model

Fire

Arrival Condition

Heat Source Matchers or Lighters(Suspicious)

Termination Stage

First Object Ignited

First Object Material

Second Object Ignited

Second Object Material

Indicated Cause Incendiaries / Suspicious

Certainty of Cause High

Age of Person Persons: [REDACTED]

Ethnicity

Gender

FAIP Service Offered FAIP was not offered - not relevant to this incident

Released under the Official Information Act

SMS Incident Report

12/11/2019 08:31:24

Summary

CAD Number F2787470 **Status** Closed

Station Invercargill Station

Incident Started 11/06/2019 08:58:49 **Incident Ended** 11/06/2019 09:32:09

Incident Type 1102: Structure fire with no damage

Common Name SOUTHLAND GIRLS HIGH SCHOOL WEST WING

Address MA1 / 328 Tweed Street Georgetown

Alarm Method Manual PFA Call **Alarm Level** 1

PFA Number 620336

Zone 38210400

Map Grid E 1243814 **Map Grid N** 4849136


First Caller **First Caller Contact**

Incident Closed 11/06/2019 09:32:09

Report Completed 17:34, Tue 11 Jun 2019 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
INVE211	P1	08:59:16 11 Jun 2019	09:00:11 11 Jun 2019	09:01:16 11 Jun 2019	09:12:03 11 Jun 2019
INVE214	PM	08:59:12 11 Jun 2019	08:59:58 11 Jun 2019	09:02:48 11 Jun 2019	09:12:35 11 Jun 2019
KING227	PR	08:59:18 11 Jun 2019	09:00:39 11 Jun 2019	09:03:18 11 Jun 2019	09:08:28 11 Jun 2019



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
INVE211	00:00:27	00:02:00	00:02:27	00:13:14
INVE214	00:00:23	00:03:36	00:03:59	00:13:46

KING227	00:00:29	00:04:00	00:04:29	00:09:39
---------	----------	----------	----------	----------

Message Log

Time	Message
08:58:49	AL: 620336 08:58:49 INITIAL - ALARM
08:58:49	PANEL: SOUTH EAST CORNER
08:58:49	** LOI search completed at 11/06/19 08:58:49
08:59:05	** Recommended unit INVE214 for requirement MONIT (>1.0 km)
08:59:05	** Recommended unit
08:59:05	INVE211 for requirement PUMP (>0.5 km)
08:59:05	** Recommended unit KING227 for require ment PUMP (>0.2 km)
08:59:08	MSU Selcal used to Initiate Alerting.(████████)
08:59:09	MSU Selcal used to Initiate Alerting.(████████)
08:59:09	MSU Selcal used to Initiate Alerting.(████████)
08:59:12	ALERTING_COMPLETED
08:59:16	ALERTING_COMPLETED
08:59:18	ALERTING_COMPLETED
08:59:58	Unit INVE214 [K1 : PROCEEDING TO INCIDENT]
09:00:11	Unit INVE211 [K1 : PROCEEDING TO INCIDENT]
09:00:39	Unit KING227 [K1 : PROCEEDING TO INCIDENT]
09:00:47	Unit KING227 [K1 : PROCEEDING TO INCIDENT]
09:01:17	Unit INVE211 [K77 : NOTHING SHOWING]
09:02:48	Unit INVE214 [K2 : IN ATTENDANCE AT INCIDENT]
09:02:53	Unit INVE211 [KC : UNIT CALLING]
09:03:18	Unit KING227 [K2 : IN ATTENDANCE AT INCIDENT]
09:03:55	Unit INVE211 [SITREP :] SO ██████████ - IPS Q WEST WING POSSIBLE LIGHT BALLAST
09:03:55	- INV FURTHER
09:05:08	Unit INVE211 [KC : UNIT CALLING]
09:05:38	Unit INVE211 [SITREP :] LIGHT BALLAST BURNT OUT MANUAL CPT ACTIVATED BY STAFF
09:08:28	Unit KING227 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
09:09:35	Unit INVE211 [KC : UNIT CALLING]
09:10:09	Unit INVE211 [STOP : MESSAGE] SO ██████████ - POWER ISOLATED TO LIGHT - SCENE H
09:10:09	ANDED TO SCHOOL CARE TAKERS
09:12:03	Unit INVE211 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
09:12:35	Unit INVE214 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
09:32:09	** Assigned Result Code: SPRNKLR, Detailed Event Type: 7100

Incident

CAD Number F2787470

Incident Reporter

Incident Controller

Distance Travelled (km)

Delay In Receiving Call

Property Details

Occupant Ministry of Education

Building Owner

General Property Use School: Pre-school through to Secondary/High

Special Property Use High school, College

Purpose Group

ActionsPersons Reported
Trapped

Evacuation Status Fully evacuated

Action Prior 1

Action Prior 2

Action Taken Investigation only (Fire related)

Civilians

Civilians Rescued 0

Civilians Extricated 0

Civilians Assisted 0

Civilians Evacuated 0

Origin

Location Unable to classify

Level Ground level

Equipment Used

Quantity	Equipment
1	Equipment Not Listed

Equipment Involved

Equipment Involved

Year

Make**Model****Fire**

Arrival Condition	Out on arrival
Heat Source	Fluorescent light ballast
Termination Stage	
First Object Ignited	
First Object Material	
Second Object Ignited	
Second Object Material	
Indicated Cause	Part failure, leak or break
Certainty of Cause	High
Age of Person	
Ethnicity	
Gender	
FAIP Service Offered	Unknown

Alarms

Type of Alarm	Sprinkler
Initiating Call	
Performance of System	Did not operate - detector in room of origin
Failure/Ineffectiveness of system	No discharge heads/detectors in room or space of fire origin
Number of sprinkler heads operated	0

Comments

6/11/2019 5:34:56 PM

Reporter Comments

Burnt out light ballast in office/Admin area of the West wing. Contained to light only. Did not get hot enough to activate sprinkler head. Staff member activate MCP to raise alarm. The fuse had blown and scene was left to the caretaker to sort out.

SMS Incident Report


12/11/2019 08:31:48

Summary

CAD Number F2839837 **Status** Closed
Station Invercargill Station
Incident Started 09/09/2019 10:59:27 **Incident Ended** 09/09/2019 11:21:43
Incident Type 1312: Vegetation Fire
Common Name JAMES HARGEST COLLEGE JUNIOR CAMPUS
Address / 6 Layard Street Windsor
Alarm Method 111 Telephone **Alarm Level** 1
PFA Number
Zone 38210300
Map Grid E 1243441 **Map Grid N** 4852049
First Caller [REDACTED] **First Caller Contact** [REDACTED]
Incident Closed 09/09/2019 11:21:43
Report Completed 11:55, Mon 09 Sep 2019 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
INVE211	P1	11:00:23 09 Sep 2019	11:01:12 09 Sep 2019	11:05:42 09 Sep 2019	11:16:43 09 Sep 2019



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
INVE211	00:00:56	00:05:19	00:06:15	00:17:16

Message Log

Time	Message
11:00:09	Multiple subscribers for caller number [REDACTED]. TESA lookup recommended.
11:00:09	INC INFO: FIRE IN BACK FIELD AT SCHOOL
11:00:11	** LOI search completed at 09/09/19 11:00:10
11:00:18	** Recommended unit INVE211 for requirement PUMP (>2.2 km)
11:00:21	PA Selcal used to Initiate Alerting. ([REDACTED])
11:00:23	ALERTING_COMPLETED
11:00:25	KIDS HAVE RUN IN AND TOLD TEACHER THERE IS A FIRE IN THE BACK FIELD
11:00:33	NO BUILDINGS NEARBY, POSS A FENCE FIRE?
11:01:13	Unit INVE211 [K1 : PROCEEDING TO INCIDENT]
11:02:23	Unit INVE211 [KC : UNIT CALLING]
11:03:52	Unit INVE211 [K35 : VERIFY ADDRESS OF EVENT] DETAILS OF LOCATION PASSED (ACK)
11:05:42	Unit INVE211 [K66 : NON PROPERTY FIRE]
11:11:08	Unit INVE211 [KC : UNIT CALLING]
11:11:51	Unit INVE211 [STOP : MESSAGE] SO [REDACTED] SMALL FLAX TREE EXTINGUISHED ON ARRIVAL
11:11:51	- K12 - POLICE NOT REQUIRED
11:12:05	Unit INVE211 [K12 : SUSPICIOUS FIRE] POLICE NOT REQUIRED
11:16:43	Unit INVE211 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
11:21:43	** Assigned Result Code: MIN, Detailed Event Type: 1500

Incident

CAD Number F2839837
Incident Reporter [REDACTED]
Incident Controller
Distance Travelled (km)
Delay In Receiving Call

Property Details

Occupant
Building Owner
General Property Use School: Pre-school through to Secondary/High
Special Property Use Intermediate school
Purpose Group

Actions

Persons Reported Trapped

Evacuation Status

Action Prior 1

Action Prior 2

Action Taken Extinguishment, salvage and ventilation

Civilians

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	0

Origin

Location

Level

Equipment Used

Quantity	Equipment
1	Equipment Not Listed

Equipment Involved

Equipment Involved

Year

Make

Model

Fire

Arrival Condition

Heat Source Matchers or Lighters(Suspicious)

Termination Stage

First Object Ignited

First Object Material

Second Object Ignited

Second Object Material

Indicated Cause Incendiaries / Suspicious

Certainty of Cause High

Age of Person Persons: [REDACTED]

Ethnicity Unknown

Gender [REDACTED]

FAIP Service Offered FAIP was not offered - not relevant to this incident

Comments

9/9/2019 11:55:11 AM

Reporter Comments

Teacher saw [REDACTED] walking away from a cabbage tree that had been lit on fire. Left in the hands of school principal and community constable.

[REDACTED]

Released under the Official Information Act

SMS Incident Report


12/11/2019 08:32:13

Summary

CAD Number F2857296 **Status** Closed
Station Invercargill Station
Incident Started 07/10/2019 07:19:38 **Incident Ended** 07/10/2019 14:39:36
Incident Type 1102: Structure fire with no damage
Common Name SOUTHLAND GIRLS HIGH SCHOOL
Address / Georgetown
Alarm Method Police Call **Alarm Level** 1
PFA Number
Zone 382104
Map Grid E 1243853 **Map Grid N** 4849099
First Caller [REDACTED] **First Caller Contact**
Incident Closed 07/10/2019 14:39:36
Report Completed 18:37, Wed 09 Oct 2019 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
INVE211	P1	07:20:05 07 Oct 2019	07:20:56 07 Oct 2019	07:23:45 07 Oct 2019	10:54:45 07 Oct 2019
INVE214	PM	07:20:06 07 Oct 2019	07:21:34 07 Oct 2019	07:27:54 07 Oct 2019	07:59:41 07 Oct 2019



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
INVE211	00:00:27	00:03:40	00:04:07	03:35:07
INVE214	00:00:28	00:07:48	00:08:16	00:40:03

Notifications

Date	Time	Party Notified
07 Oct 2019	07:30:43	██████████ (FIRES IN SCHOOL)
07 Oct 2019	07:33:20	PAGED RFO SOUTHERN RFD RE DIGGER
07 Oct 2019	07:34:14	AREA SOUTHLAND PAGED
07 Oct 2019	07:35:05	CARETAKER
07 Oct 2019	07:40:24	RURAL ██████████ ACK PAGE
07 Oct 2019	07:40:45	AREA SOUTHLAND (██████████) ACK PAGE
07 Oct 2019	07:48:55	FROM ██████████ DRAINAGE ON THE WAY TO ASSESS THE SITUATION

Message Log

Time	Message
07:19:54	** Event Type changed from POL2FIR to STRU at: 07/10/19 07:19:54
07:19:55	** Event Priority changed from 2 to 1 at: 07/10/19 07:19:55
07:19:56	INC INFO: SMOKE SHOWING FROM BACK SHED
07:20:00	** Recommended unit INVE211 for requirement PUMP (>1.1 km) ** Recommended unit
07:20:00	INVE214 for requirement PUMP (>1.1 km)
07:20:03	PA Selcal used to Initiate Alerting.(██████████)
07:20:03	PA Selcal used to Initiate Alerting.(██████████)
07:20:06	ALERTING_COMPLETED
07:20:06	ALERTING_COMPLETED
07:20:56	Unit INVE211 [K1 : PROCEEDING TO INCIDENT]
07:21:08	Unit INVE211 [K1 : PROCEEDING TO INCIDENT]
07:21:34	Unit INVE214 [K1 : PROCEEDING TO INCIDENT]
07:22:21	Unit INVE211 [KC : UNIT CALLING]
07:23:31	SMOKE COMING FROM BACK SHED - COMING FROM COAL BUNKER
07:23:45	Unit INVE211 [K88 : PROPERTY SMALL]
07:23:49	Unit INVE211 [KC : UNIT CALLING]
07:23:49	Unit INVE211 [SITREP :] FURTHER INFO? (SMOKE SHOWING FROM BACK SHED. POL ON SC
07:23:49	ENE. SMOKE COMING FROM COAL BUNKER) ACK
07:24:34	Unit INVE211 [SITREP :] SO ██████████ COAL BUNKER. SMOKE SHOWING. CUTTING GATES TO
07:24:34	MAKE ACCESS.
07:27:03	Unit INVE211 [KC : UNIT CALLING]
07:27:47	Unit INVE211 [SITREP :] CAN YOU SOURCE A SMALL DIGGER. COAL BUNKER IS DEEP AND
07:27:47	LONG AND HAS RESTRICTED ACCESS.
07:27:54	Unit INVE214 [K2 : IN ATTENDANCE AT INCIDENT]

07:30:29 Unit INVE211 [KC : UNIT CALLING]

07:31:18 Unit INVE211 [SITREP :] CAN A REP FROM THE SCHOOL/CARETAKER ATTEND AS WELL. MA

07:31:18 Y HAVE SOME INFOMATION TO ASSIST

07:33:24 Unit INVE211 [KC : UNIT CALLING]

07:33:37 ***

07:34:22 CONTACTED INVERCARGILL CITY COUNCIL NO DIGGERS

07:35:19 CARETAKER [REDACTED] WILL BE ON SCENE WITHIN 30MIN

07:35:41 Unit INVE211 [SITREP :] 2 IN BA. 1 HR IN USE. EXPECTING TO BE ENGAGED FOR SOME

07:35:41 TIME

07:36:24 CARETAKER HAS ADVISED IT OFTEN SMOKES AND [REDACTED] NORMALLY PUTS SOME WATER ON IT WITH

07:36:24 A HOSE.

07:36:52 Unit INVE211 [COMCEN COM : MESSAGE] CARETAKER WILL BE ON SCENE WITHIN 30 MIN. CA

07:36:52 RETAKER HAS ADVISED IT OFTEN SMOKES AND [REDACTED] NORMALLY PUTS SOME WATER ON IT WITH A

07:36:52 HOSE. (ACK THIS IS A SUPSTANTIAL COAL FIRE)

07:40:35 PUT THRU TO INVE211 TO DISCUSS DIGGER SIZE ETC

07:50:26 Unit INVE211 [KC : UNIT CALLING]

07:51:03 Unit INVE211 [SITREP :] DIGGER NO LONGER REQUIRED

07:52:59 Unit INVE211 [COMCEN COM : MESSAGE] [REDACTED] DRAINAGE ON THE WAY TO ASSESS THE

07:52:59 SITUATION. WOULD YOU LIKE THEM STOOD DOWN OR STILL RESPOND JUST TO ASSESS? (KEEP

07:52:59 THEM RESPONDING)

07:59:41 Unit INVE214 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

08:09:38 Alarm Timer Extended: 0

08:20:08 Unit INVE211 [KC : UNIT CALLING]

08:21:04 Unit INVE211 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

08:21:04 Unit INVE211 [STOP : MESSAGE] BUNKER IS CLEAR OF HOT SPOTS. CARE TAKER AND DRAI

08:21:04 NAGE CONTRACTOR HAVE DECIDED TO EMPTY BUNKER. DIGGER DUE IN 2 HOURS. BRGIADE LEA

08:21:04 VING IN CARE OF AGENT AND CARETAKER

10:34:30 .

10:34:38 PA Selcal used to Initiate Alerting. ([REDACTED])

10:34:40 .

10:34:40 ALERTING_COMPLETED

10:35:07 FROM PRFO [REDACTED] - CONTRACTOR ON SITE REQUESTING 1 APPLIANCE FOR WATER

10:35:29 Unit INVE211 [K1 : PROCEEDING TO INCIDENT]

10:38:33 Unit INVE211 [K77 : NOTHING SHOWING]

10:40:42 Unit INVE211 [KC : UNIT CALLING]

10:41:16	Unit INVE211 [SITREP :] SO [REDACTED] GTWW LPD TO COOL THE COAL IN THE BUNKER
10:49:23	Unit INVE211 [KC : UNIT CALLING]
10:49:54	Unit INVE211 [STOP : MESSAGE] DAMPENED DOWN THE COAL. POSSIBILITY WE COULD GET
10:49:54	CALLED BACK AGAIN
10:54:45	Unit INVE211 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
14:39:36	** Assigned Result Code: STRU, Detailed Event Type: 1100

Incident

CAD Number F2857296

Incident Reporter [REDACTED]

Incident Controller

Distance Travelled (km)

Delay In Receiving Call

Property Details

Occupant Southland Girls High School

Building Owner

General Property Use School: Pre-school through to Secondary/High

Special Property Use High school, College

Purpose Group

Actions

Persons Reported

Trapped

Evacuation Status Not occupied at time of incident

Action Prior 1

Action Prior 2

Action Taken Extinguishment and ventilation

Civilians

Civilians Rescued 0

Civilians Extricated 0

Civilians Assisted 0

Civilians Evacuated 0

Origin

Location Duct: Air, Heating, Cable, Exhaust

Level Ground level

Equipment Used

Quantity	Equipment
1	Hose reel, high pressure delivery

Equipment Involved

Equipment Involved

Year

Make

Model

Fire**Arrival Condition** Small fire**Heat Source** Coal fuelled equipment: Spark, Ember, Flame**Termination Stage****First Object Ignited****First Object Material****Second Object Ignited****Second Object Material****Indicated Cause** Operating deficiency - not classified above**Certainty of Cause** High**Age of Person****Ethnicity****Gender****FAIP Service Offered** Unknown**Comments**

10/9/2019 6:37:02 PM

Reporter Comments

Coal bunker, Orger clogged up with coal and jammed causing burn back through the coal.

