SMS Incident Report

05/08/2020 15:00:34

Summary

CAD Number F3047758 Status Closed

Station Harewood Station

Incident Started 27/07/2020 19:19:16 Incident Ended 28/07/2020 08:57:58

Incident Type 1101: Structure fire with damage

Common Name

Address / McLeans Island

Alarm Method Exchange phone Alarm Level 1

PFA Number

Zone 342616 **Man Grid F** 1559596

Map Grid E 1559596 Map Grid N 5184838

First Caller Contact

First Caller CHRISTCHURCH INTERNATIONAL

AIRPORT


Incident Closed 29/07/2020 16:20:00

Report Completed 6:50, Wed 05 Aug 2020 by

Responses

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
HARE261	P1	19:20:59 27 Jul 2020	19:22:08 27 Jul 2020	19:31:25 27 Jul 2020	08:57:58 28 Jul 2020
REDW231	P1	19:26:36 27 Jul 2020	19:28:14 27 Jul 2020	19:38:03 27 Jul 2020	07:46:55 28 Jul 2020
CHRI2111	WT	19:26:33 27 Jul 2020	19:28:11 27 Jul 2020	19:45:17 27 Jul 2020	22:50:20 27 Jul 2020
WEST9511	WT	19:35:23 27 Jul 2020	19:44:32 27 Jul 2020	19:55:04 27 Jul 2020	21:42:31 27 Jul 2020
CHRISTCH1	OF	19:38:29 27 Jul 2020	19:42:40 27 Jul 2020	19:58:41 27 Jul 2020	21:33:29 27 Jul 2020
FICANT1	FSO	20:26:59 27 Jul 2020	20:27:00 27 Jul 2020	20:49:27 27 Jul 2020	15:11:05 29 Jul 2020
FICHRI1	FSO	20:27:33 27 Jul 2020	20:27:38 27 Jul 2020	21:14:17 27 Jul 2020	15:14:05 29 Jul 2020
FICHRI2	FSO	20:56:12 27 Jul 2020	20:57:40 27 Jul 2020	21:39:19 27 Jul 2020	22:28:32 27 Jul 2020
CHRI214	PM	22:30:21 27 Jul 2020	22:30:22 27 Jul 2020	22:54:26 27 Jul 2020	00:35:43 28 Jul 2020
WOOL241	P1	00:02:39 28 Jul 2020	00:02:45 28 Jul 2020	00:24:53 28 Jul 2020	02:35:27 28 Jul 2020

SPRE221	P1	02:03:11 28 Jul 2020	02:03:12 28 Jul 2020	02:26:54 28 Jul 2020	04:44:18 28 Jul 2020
ANZA271	P1	22:04:26 27 Jul 2020	22:05:00 27 Jul 2020	04:22:22 28 Jul 2020	06:42:42 28 Jul 2020
FICHRI4	FSO	08:12:20 28 Jul 2020	08:12:20 28 Jul 2020	09:01:19 28 Jul 2020	15:14:51 29 Jul 2020
EVENTSCC1	ОТ				15:12:42 29 Jul 2020
EVENTSCC3	ОТ				23:54:35 27 Jul 2020



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
HARE261	00:01:43	00:10:26	00:12:09	13:38:42
REDW231	00:07:20	00:11:27	00:18:47	12:27:39
CHRI2111	00:07:17	00:18:44	00:26:01	03:31:04
WEST9511	00:16:07	00:19:41	00:35:48	02:23:15
CHRISTCH1	00:19:13	00:20:12	00:39:25	02:14:13
FICANT1	01:07:43	00:22:28	01:30:11	43:51:49
FICHRI1	01:08:17	00:46:44	01:55:01	43:54:49
FICHRI2	01:36:56	00:43:07	02:20:03	03:09:16
CHRI214	03:11:05	00:24:05	03:35:10	05:16:27
WOOL241	04:43:23	00:22:14	05:05:37	07:16:11
SPRE221	06:43:55	00:23:43	07:07:38	09:25:02
ANZA271	02:45:10	06:17:56	09:03:06	11:23:26
FICHRI4	12:53:04	00:48:59	13:42:03	43:55:35
EVENTSCC1				43:53:26
EVENTSCC3				04:35:19

Notifications

Date	Time	Party Notified
27 Jul 2020	19:28:58	RFO CHCH SELWYN PAGED
27 Jul 2020	19:30:50	RFO CHCH/SELWYN () ACK PAGE
27 Jul 2020	19:31:38	POWER
27 Jul 2020	19:34:59	POLICE VIA INTERCAD



Message Log

Time	Message
19:20:39	INC INFO: INVESTIGATE GLOW SEEN FROM AIRPORT TOWER
19:20:41	** LOI search completed at 27/07/20 19:20:41
19:20:52	LARGE GLOW SEEN FROM AIRPORT TOWER
19:20:54	** Recommended unit HARE261 for requirement PUMP (>4.6 km)
19:20:56	PA Selcal used to Initiate Alerting. (HARE261 at 3426 HAREWOOD 193261)
19:20:59	ALERTING_COMPLETED HARE261
19:21:01	BEST GUESS IS SAVILLS RD AREA
19:21:16	SAID WE WILL INVESTIGATE DUE TO IT BEING DARK HOURS
19:22:09	Unit HARE261 [K1 : PROCEEDING TO INCIDENT]
19:22:52	Unit HARE261 [COMCEN COM : MESSAGE] FURTHER INFO PASSED
19:26:20	** Event Type changed from MIN to STRU at: 27/07/20 19:26:20
19:26:20	** Event Location changed from "SAVILLS RD,YALDHURST,CHRISTCHURCH CITY" to "CONS"

19:26:20	ERVATORS RD,MCLEANS ISLAND,CHRISTCHURCH CITY" at: 27/07/20 19:26:20
19:26:21	** Event Priority changed from 2 to 1 at: 27/07/20 19:26:21
19:26:22	INC INFO: HOUSE FIRE
19:26:24	** LOI search completed at 27/07/20 19:26:24
19:26:26	** Recommended unit CHRI2111 for requirement TANKER (>12.2 km) ** Recommended u
19:26:26	nit REDW231 for requirement PUMP (>8.8 km)
19:26:29	PA Selcal used to Initiate Alerting. (CHRI2111 at 3422 SPREYDON 192221)
19:26:29	PA Selcal used to Initiate Alerting. (REDW231 at 3423 REDWOOD 193231)
19:26:33	ALERTING_COMPLETED CHRI2111
19:26:36	ALERTING_COMPLETED REDW231
19:27:02	Pager turnout error - request Id 0
19:27:41	
19:27:52	Unit HARE261 [KC : UNIT CALLING]
19:28:11	Unit CHRI2111 [K1 : PROCEEDING TO INCIDENT]
19:28:14	Unit REDW231 [K1 : PROCEEDING TO INCIDENT]
19:28:24	** Cross Referenced to Event # F3047760 at: 27/07/20 19:28:24
19:28:47	Unit REDW231 [COMCEN COM : MESSAGE] FURTHER INFO PASSED
19:28:47	Unit HARE261 [COMCEN COM : MESSAGE] FURTHER INFO PASSED
19:28:47	Unit CHRI2111 [COMCEN COM : MESSAGE] FURTHER INFO PASSED
19:28:54	Si Cita
19:28:59	
19:31:26	Unit HARE261 [K99 : PROPERTY FIRE WELL INV]
19:31:32	*
19:31:33	INC INFO: K99 HOUSE FIRE
19:33:36	Unit HARE261 [K99 : PROPERTY FIRE WELL INV]
19:33:51	Unit HARE261 [KC : UNIT CALLING]
19:34:39	
19:34:39	Unit HARE261 [SITREP :] SO HOUSE FIRE WELL INVOLVED, 2 IN BA GTWW 1 HPD
19:34:39	UNTIL WE GET TANKERS, SUSPECTED PERSON INSIDE
19:34:42	·
19:34:49	INC INFO: K99 HOUSE FIRE - PERSONS REPORTED
19:34:52	
19:34:58	AMBO EVENT 0472-3-2020/07/27-FIR LINKED AT 27/07/2020 19:34:58
19:35:02	FIR2POL&AMB - PERSON REPORTED HOUSE FIRE
19:35:16	** Requirement TORT added for alarm level 1
19:35:18	** Recommended unit WEST9511 for requirement ADHOC TORT (>11.3 km)
19:35:21	Station Selcal used to Initiate Alerting. (WEST9511 at 3495 WEST MELTON 193951)
19:35:23	ALERTING_COMPLETED WEST9511

19:35:25	SM ATTACHED 2ND TANKER
19:36:33	Unit HARE261 [KC : UNIT CALLING]
19:37:01	Unit HARE261 [K11E : ELECTRICAL AUTHORITY REQUIRED]
19:37:19	Unit HARE261 [COMCEN COM : MESSAGE] ORION DISPATCHED AT TIME OF YOUR ARRIVAL, FY
19:37:19	I SECOND TANKER DISPATCHED
19:38:03	Unit REDW231 [K2 : IN ATTENDANCE AT INCIDENT]
19:38:21	Pager used to Initiate Alerting.
19:38:29	ALERTING_COMPLETED CHRISTCH1
19:42:40	Unit CHRISTCH1 [K1 : PROCEEDING TO INCIDENT]
19:44:33	Unit WEST9511 [K1 : PROCEEDING TO INCIDENT]
19:45:18	Unit CHRI2111 [K2 : IN ATTENDANCE AT INCIDENT]
19:52:29	INFO PASSED TO CHCH1
19:55:02	
19:55:04	Unit WEST9511 [K2 : IN ATTENDANCE AT INCIDENT]
19:55:24	FIR2AMB - POSSIBLY 70, BUT NOT CONFIRMED, DRIVEWAY IS BEFORE THE FIRST 90 DEGREE
19:55:24	TURN
19:55:52	CORRECTION, DRIVEWAY COMES OFF AT THE FIRST 90 DEGREE TURN
19:57:11	FIRE ACK
19:58:42	Unit CHRISTCH1 [K2 : IN ATTENDANCE AT INCIDENT]
20:05:49	
20:06:16	CHRI2111 - GET SSO CHCH CITY TO RING
20:09:02	Unit CHRISTCH1 [K11F : FIRE SAFETY REQUIRED] 2 FI"S REQUIRED
20:09:43	SSO ADVISED TO CALL NUMBER ABOVE
20:10:53	*
20:16:17	Alarm Timer Extended: 0
20:18:32	Alarm Timer Extended: 0
20:21:45	Unit HARE261 [KC : UNIT CALLING]
20:23:28	Unit HARE261 [SITREP :] DO YOU HAVE A STREET NUMBER FOR THIS PROPERTY?
20:23:28	7, BUT APPEARS TO BE NUMBER 70 FROM THE MAP, ARE YOU ABLE TO CONFIRM?) WILL TRY
20:23:28	TO CONFIRM, CANT AT THIS STAGE
20:25:30	Alarm Timer Extended: 0
20:25:38	Unit HARE261 [KC : UNIT CALLING]
20:26:01	Unit HARE261 [SITREP :] SO 2 HPD, 2 CREWS IN BA
20:26:07	Unit HARE261 [K41 : FATALITY - NUMBER] ONE
20:27:00	Unit FICANT1 [K1 : PROCEEDING TO INCIDENT]
20:27:32	Radio used to Initiate Alerting.
20:27:33	ALERTING_COMPLETED FICHRI1
20:27:38	Unit FICHRI1 [K1 : PROCEEDING TO INCIDENT]

20:35:57	Alarm Timer Extended: 0
20:38:51	Alarm Timer Extended: 0
20:38:54	Alarm Timer Extended: 0
20:49:28	Unit FICANT1 [K2 : IN ATTENDANCE AT INCIDENT]
20:56:04	FROM SPREYDON STATION - CHRI216 IS NOW CREWED AND AVAILABLE
20:56:11	Radio used to Initiate Alerting.
20:56:12	ALERTING_COMPLETED FICHRI2
20:56:41	FILE IS RESPONDING TO UPLIFT THE ABLUTIONS UNIT FROM ANZAC STN
	THEN HEAD
20:56:41	TO SCENE
20:57:41	Unit FICHRI2 [K1 : PROCEEDING TO INCIDENT]
21:05:59	FIRE
21:14:17	Unit FICHRI1 [K2 : IN ATTENDANCE AT INCIDENT]
21:30:58	Alarm Timer Extended: 0
21:33:29	Unit CHRISTCH1 [K6 : ON TELEPAGER]
21:39:20	Unit FICHRI2 [K2 : IN ATTENDANCE AT INCIDENT]
21:39:29	Unit FICHRI2 [KC : UNIT CALLING]
21:40:11	Unit FICHRI2 [SITREP :] INCIDENT SUPPORT TRAILER FROM ANZAC HAS ARRIVED AT INC
21:40:11	IDENT
21:42:32	Unit WEST9511 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
21:45:42	
21:46:34	CORRECTION - ABOVE ON WRONG EVENT
21:46:35	
21:52:34	·
21:55:06	Unit REDW231 [KC : UNIT CALLING]
21:55:17	Alarm Timer Extended: 0
21:55:27	Unit REDW231 [K10 : RECOMMISSIONING]
21:55:49	SSO ROSTER FOR ONE PUMP TO BE ON SITE THROUGHOUT NIGHT - RING ABO
21:55:49	UT HOUR BEFORE TO GIVE CREWS 'WAKE UP' CALL - ANZA271 2230-0030, WOOL241 0030-02
21:55:49	30, SPRE221 0230-0430, REDW231 0430-0630, HARE261 0630-CHANGEOVER
21:56:19	
22:04:19	** Event Location changed from "CONSERVATORS RD,MCLEANS ISLAND,CHRISTCHURCH CITY
22:04:19	" to "70 CONSERVATORS RD,MCLEANS ISLAND,CHRISTCHURCH CITY" at: 27/07/20 22:04:19
22:04:24	** LOI search completed at 27/07/20 22:04:23
22:04:25	Radio used to Initiate Alerting.
22:04:26	ALERTING_COMPLETED ANZA271
22:05:00	Unit ANZA271 [K1 : PROCEEDING TO INCIDENT]
22:08:42	Unit ANZA271 [KP : PRIORITY MESSAGE]

22:08:56	Preempt Unit ANZA271
22:14:25	Unit HARE261 [COMCEN COM : MESSAGE] FYI I HAVE REDIRECTED THE ANZAC CREW TO A
22:14:25	CALL, THEY WILL BE LATE FOR YOUR RELIEF
22:15:03	ANZA271 RESPONDED TO F3047819 MARSHLAND RD
22:15:06	
22:19:53	Alarm Timer Extended: 0
22:23:42	
22:24:06	SSO - ADVISED THAT ANZA271 WILL BE SOME TIME AT OTHER EVENT - CHRI214 WI
22:24:06	LL TAKE THEIR 2230-0030 SLOT INSTEAD
22:24:08	
22:25:10	HARE261 ADVISED OF MOVEMENTS UPDATE
22:25:13	
22:28:33	Unit FICHRI2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
22:30:20	Phone used to Initiate Alerting.
22:30:21	ALERTING_COMPLETED CHRI214
22:30:23	Unit CHRI214 [K1 : PROCEEDING TO INCIDENT]
22:37:06	ADVISES THE ABLUTIONS UNIT IS ESTABLISHED ON SITE
22:48:45	Unit FICANT1 [SITREP :] RETURNING TO THE SCENE TOMORROW MORNING, KEEP EVENT OP
22:48:45	EN
22:48:49	Unit FICANT1 [K6 : ON TELEPAGER]
22:50:21	Unit CHRI2111 [K7 : AT NORMAL STATION]
22:54:26	Unit CHRI214 [K2 : IN ATTENDANCE AT INCIDENT]
23:13:32	Unit HARE261 [KC : UNIT CALLING]
23:14:37	Unit HARE261 [SITREP :] CITY TRUCK HAS JUST ARRIVED ON SCENE (IS CITY GOING TO
23:14:37	STAY ON SCENE INSTEAD OF ANZA271) AFFIRM - ANZA271 COPIED
23:18:49	Unit FICHRI1 [K6 : ON TELEPAGER]
23:35:11	Alarm Timer Extended: 0
23:35:24	Unit HARE261 [K7 : AT NORMAL STATION]
00:02:38	Phone used to Initiate Alerting.
00:02:39	ALERTING_COMPLETED WOOL241
00:02:45	Unit WOOL241 [K1 : PROCEEDING TO INCIDENT]
00:24:54	Unit WOOL241 [K2 : IN ATTENDANCE AT INCIDENT]
00:35:24	Unit CHRI214 [KC : UNIT CALLING]
00:35:43	Unit CHRI214 [K10 : RECOMMISSIONING]
00:37:56	<u> </u> .
00:38:42	CHANGE TO ROSTER - ANZA271 0430-0630, REDW231 0630-CHANGEOVER
00:39:48	NEITHER ARE AWARE - SET OFF TONES 30 MINS BEFORE
00:39:55	

01:13:03	Alarm Timer Extended: 0
01:48:47	
01:49:31	SPRE221 GIVEN WAKE UP CALL - LEAVING SHORTLY FOR 0230-0430 SHIFT
01:49:32	
02:03:13	Unit SPRE221 [K1 : PROCEEDING TO INCIDENT]
02:25:52	Unit SPRE221 [KC : UNIT CALLING]
02:26:42	Unit SPRE221 [SITREP :] WE HAVE ARRIVED AND TAKING OVER FROM WOOLSTON
02:26:55	Unit SPRE221 [K2 : IN ATTENDANCE AT INCIDENT]
02:34:42	Unit WOOL241 [KC : UNIT CALLING]
02:35:04	Unit WOOL241 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SO SPRE221
02:35:28	Unit WOOL241 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
02:43:36	Unit SPRE221 [K2 : IN ATTENDANCE AT INCIDENT]
03:35:38	Alarm Timer Extended: 0
03:50:23	ANZA271 ALERTED - CREW RESPONDING SHORTLY FOR 0430-0630 SHIFT
03:50:26	
03:58:07	Unit ANZA271 [KC : UNIT CALLING]
03:59:05	Unit ANZA271 [K1 : PROCEEDING TO INCIDENT]
03:59:14	Unit ANZA271 [SITREP :] CAN YOU ATTACH US (FURTHER INFO PASSED)
04:22:22	Unit ANZA271 [K2 : IN ATTENDANCE AT INCIDENT]
04:44:18	Unit SPRE221 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
05:06:50	Alarm Timer Extended: 0
06:27:01	Unit REDW231 [KC : UNIT CALLING]
06:27:35	Unit REDW231 [KC : UNIT CALLING]
06:28:08	Unit REDW231 [K1 : PROCEEDING TO INCIDENT]
06:37:42	Unit REDW231 [K2 : IN ATTENDANCE AT INCIDENT]
06:42:43	Unit ANZA271 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
06:53:18	Unit FICANT1 [K1 : PROCEEDING TO INCIDENT]
07:14:29	Unit FICHRI1 [K1 : PROCEEDING TO INCIDENT]
07:18:20	Alarm Timer Extended: 0
07:32:39	Unit FICANT1 [K2 : IN ATTENDANCE AT INCIDENT]
07:40:49	Unit HARE261 [K1 : PROCEEDING TO INCIDENT]
07:46:56	Unit REDW231 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
07:52:41	Unit HARE261 [K2 : IN ATTENDANCE AT INCIDENT]
08:12:20	Unit FICHRI4 [K1 : PROCEEDING TO INCIDENT]
08:12:48	Unit FICHRI1 [KC : UNIT CALLING]
08:13:03	Unit FICHRI1 [K2 : IN ATTENDANCE AT INCIDENT]
08:13:15	Unit FICHRI1 [SITREP :] JUST ARRIVING ON SCENE
08:15:49	Alarm Timer Extended: 0
08:57:59	Unit HARE261 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

08:57:59	Unit HARE261 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] SCENE HAN
08:57:59	DED OVER TO FIRE INVESTIGATOR
08:58:27	STOP MSG PUT IN BY SSO HARE261
09:00:45	Alarm Timer Extended: 0
09:01:19	Unit FICHRI4 [K2 : IN ATTENDANCE AT INCIDENT]
09:01:36	Unit FICHRI4 [K2 : IN ATTENDANCE AT INCIDENT]
09:42:03	Alarm Timer Extended: 0
16:37:03	Unit FICHRI1 [K6 : ON TELEPAGER]
16:48:03	Unit FICHRI4 [K6 : ON TELEPAGER]
16:54:49	Unit FICANT1 [K6 : ON TELEPAGER]
16:56:50	Unit FICANT1 [SITREP :] WE HAVE FINISHED FOR THE EVENING, POLICE HAVE A SCENE
16:56:50	GUARD IN PLACE FOR THE NIGHT. WE WILL BE RETURNING IN THE MORNING
07:06:19	Unit FICHRI1 [K1 : PROCEEDING TO INCIDENT]
07:18:12	Unit FICANT1 [K1 : PROCEEDING TO INCIDENT]
07:45:36	Unit FICHRI1 [K2 : IN ATTENDANCE AT INCIDENT]
07:51:10	Unit FICANT1 [K2 : IN ATTENDANCE AT INCIDENT]
08:34:21	Alarm Timer Extended: 0
08:34:22	Alarm Timer Extended: 0
08:44:16	Radio used to Initiate Alerting.
08:44:17	ALERTING_COMPLETED FICHRI4
08:44:35	Unit FICHRI4 [K1 : PROCEEDING TO INCIDENT]
08:53:14	Unit FICHRI4 [K2 : IN ATTENDANCE AT INCIDENT]
09:33:27	Alarm Timer Extended: 0
15:11:05	Unit FICANT1 [K6 : ON TELEPAGER]
15:12:35	Unit FICANT1 [STOP: MESSAGE] (VIA PHONE) FENZ HAVE COMPLETED WORK WITH THE SCE
15:12:35	NE, HANDED OVER TO POLICE, THEY WILL HAND OVER TO THE OCCUPIERS
15:12:42	Unit EVENTSCC1 [K7 : AT NORMAL STATION]
15:14:05	Unit FICHRI1 [K6 : ON TELEPAGER]
15:14:52	Unit FICHRI4 [K6 : ON TELEPAGER]
15:15:15	Unit FICHRI1 [SITREP :] (VIA PHONE) FI TAKING THE OPS SUPPORT TRAILER
15:15:15	O CHESTER ST TO BE REFURBISHED TOMORROW MORNING
16:19:37	UNIT 'FICANT1' ALERT TIME '[NULL]' ADJUSTED TO '20200727202659NS' AT '29/07/2020
16:19:38	UNIT 'SPRE221' ALERT TIME '[NULL]' ADJUSTED TO '20200728020311NS' AT '29/07/2020
16:19:38	UNIT 'FICHRI4' ALERT TIME '[NULL]' ADJUSTED TO '20200728081219NS' AT '29/07/2020
16:19:58	UNIT 'FICANT1' ALERT TIME '[NULL]' ADJUSTED TO '20200727202659NS' AT '29/07/2020
16:19:59	UNIT 'SPRE221' ALERT TIME '[NULL]' ADJUSTED TO '20200728020311NS' AT '29/07/2020
16:19:59	UNIT 'FICHRI4' ALERT TIME '[NULL]' ADJUSTED TO '20200728081219NS' AT '29/07/2020
16:20:00	** Assigned Result Code: STRU, Detailed Event Type: 1100

Incident

CAD Number F3047758

Incident Reporter

Incident Controller

Distance Travelled (km)

Delay In Receiving Call

Property Details

Occupant

Building Owner

General Property Use Farming, Horticulture, Agricultural use

Special Property Use Single house

Purpose Group

Actions

Persons Reported

Trapped

Evacuation Status No evacuation

Action Prior 1
Action Prior 2

Action Taken Extinguishment only: Includes isolating fuel/power

Civilians

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	0

Origin

Location Kitchen, Cooking area

Level Ground level

Equipment Used

Quantity	Equipment
2	Hose reel, high pressure delivery
1	Portable pump
1	Mobile Ablution Trailer

Equipment Involved

Equipment Involved

Year

Make

Model

Fire

Arrival Condition Totally involved fire

other Action Act **Heat Source** Heat from other solid fuelled equipment

Termination Stage First Object Ignited First Object Material Second Object Ignited Second Object Material

Indicated Cause Carelessness with heat source - Other

Certainty of Cause High

Age of Person Persons:

Gender

FAIP Service Offered Unknown

Alarms

Ethnicity

Type of Alarm Initiating Call

Domestic Smoke Alarms

Performance of

System

Detector not in room of origin - Other

Failure/Ineffectiven ess of system Number of sprinkler

heads operated

Casualties

Casualty Number 1

Gender

Age

Apparent Injury

Ethnicity

Severity of Injury

Bleeding

Action by Fire Fighters

No action taken/required

Condition Before Injury Unknown
How Removed Other
Location at Ignition Unknown

Factor Preventing Escape

Activity When Injured Unknown

Cause of Injury Fire Products

Victim Aware of Fire Unknown

Room Where Victim Found Working area

Location Where Victim Found

Familiarity With Property Familiar with premises

Comments

8/5/2020 6:50:34 AM Reporter Comments

Fire investigation believed that it was accidental starting in front of the range in the in the kitchen. It appears that was feeding the fire with long branches which may have fallen out of the range.