

# SMS Incident Report

15/03/2021 08:25:18

## Summary

**CAD Number** F3077307 **Status** Closed  
**Station** East Coast Bays Station  
**Incident Started** 15/09/2020 20:25:18 **Incident Ended** 16/10/2020 11:55:39  
**Incident Type** 1101: Structure fire with damage  
**Common Name** KINETIC ENGINEERING DESIGN  
**Address** 30 Triton Drive Rosedale  
**Alarm Method** 111 Telephone **Alarm Level** 3  
**PFA Number**  
**Zone** 148367  
**Map Grid E** 1753954 **Map Grid N** 5932409  
**First Caller** [REDACTED] **First Caller Contact** 0 [REDACTED]  
**Incident Closed** 16/10/2020 11:55:39  
**Report Completed** 18:52, Wed 23 Sep 2020 by [REDACTED]

## Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
EAST831	P1	20:25:58 15 Sep 2020	20:27:29 15 Sep 2020	20:31:13 15 Sep 2020	00:07:28 16 Sep 2020
ALBA851	P1	20:26:01 15 Sep 2020	20:27:44 15 Sep 2020	20:32:12 15 Sep 2020	10:53:04 16 Sep 2020
DEVO812	P2	20:29:44 15 Sep 2020	20:30:42 15 Sep 2020	20:38:19 15 Sep 2020	23:39:47 15 Sep 2020
WEST671	P1	20:29:50 15 Sep 2020	20:30:03 15 Sep 2020	20:40:34 15 Sep 2020	00:59:08 16 Sep 2020
AUCK206	HPNP	20:27:46 15 Sep 2020	20:29:32 15 Sep 2020	20:42:02 15 Sep 2020	00:58:57 16 Sep 2020
WAITEMATA4	OF	20:34:16 15 Sep 2020	20:38:06 15 Sep 2020	20:46:04 15 Sep 2020	23:13:56 15 Sep 2020
TAKA807	PR	20:39:19 15 Sep 2020	20:39:25 15 Sep 2020	20:46:17 15 Sep 2020	06:48:09 16 Sep 2020
AUCK2018	CUHU	20:29:47 15 Sep 2020	20:34:27 15 Sep 2020	20:46:56 15 Sep 2020	00:59:17 16 Sep 2020
SILV901	P1	20:35:27 15 Sep 2020	20:35:59 15 Sep 2020	20:47:09 15 Sep 2020	23:33:15 15 Sep 2020
WEST672	P2	20:35:50 15 Sep 2020	20:39:20 15 Sep 2020	20:50:11 15 Sep 2020	23:04:19 15 Sep 2020
BIRK822	P2	20:35:53 15 Sep 2020	20:39:45 15 Sep 2020	20:52:17 15 Sep 2020	22:58:29 15 Sep 2020

TEAT664	PM	20:35:44 15 Sep 2020	20:37:49 15 Sep 2020	20:52:31 15 Sep 2020	23:50:51 15 Sep 2020
AUCKOSU2	SV	20:32:13 15 Sep 2020	20:32:22 15 Sep 2020	20:52:52 15 Sep 2020	01:10:15 16 Sep 2020
PARN255	HPNP	20:35:41 15 Sep 2020	20:37:38 15 Sep 2020	20:55:03 15 Sep 2020	00:10:23 16 Sep 2020
SILV907	PR	20:35:27 15 Sep 2020	20:39:35 15 Sep 2020	20:59:43 15 Sep 2020	23:24:33 15 Sep 2020
OTAH3112	HL	20:36:00 15 Sep 2020	20:37:39 15 Sep 2020	21:01:03 15 Sep 2020	23:28:34 15 Sep 2020
AVON607	PR	20:35:47 15 Sep 2020	20:37:45 15 Sep 2020	21:01:19 15 Sep 2020	23:28:55 15 Sep 2020
REGION1C	OF	20:33:50 15 Sep 2020	20:41:10 15 Sep 2020	21:01:45 15 Sep 2020	01:00:31 16 Sep 2020
AUCKOSU6	FPOL	20:49:42 15 Sep 2020	20:49:53 15 Sep 2020	21:06:30 15 Sep 2020	22:26:36 15 Sep 2020
AVON6015	BA	20:35:47 15 Sep 2020	20:38:25 15 Sep 2020	21:07:36 15 Sep 2020	23:21:38 15 Sep 2020
VSOWAITEM1	VSO	20:33:44 15 Sep 2020	20:47:13 15 Sep 2020	21:08:00 15 Sep 2020	01:07:23 16 Sep 2020
COUNTIES1	OF	20:41:00 15 Sep 2020	20:48:26 15 Sep 2020	21:09:15 15 Sep 2020	22:38:06 15 Sep 2020
OTAH311	P1	20:35:58 15 Sep 2020	20:37:33 15 Sep 2020	21:20:35 15 Sep 2020	23:28:33 15 Sep 2020
AUCKOSU4	CV	20:35:10 15 Sep 2020	21:03:20 15 Sep 2020	21:32:22 15 Sep 2020	01:10:25 16 Sep 2020
VSOWAITEM3	VSO	21:15:43 15 Sep 2020	21:15:44 15 Sep 2020	21:37:10 15 Sep 2020	22:21:23 15 Sep 2020
BIRK8219	LU	21:48:20 15 Sep 2020	21:51:22 15 Sep 2020	22:03:22 15 Sep 2020	23:56:21 15 Sep 2020
FIWAITEM1	FSO	22:33:54 15 Sep 2020	22:33:59 15 Sep 2020	22:34:02 15 Sep 2020	11:47:36 17 Sep 2020
BIRK821	P1	23:02:28 15 Sep 2020	23:02:47 15 Sep 2020	23:08:16 15 Sep 2020	01:50:55 16 Sep 2020
AUCKOSU3	SV	23:27:36 15 Sep 2020	23:27:36 15 Sep 2020	00:39:45 16 Sep 2020	01:03:54 16 Sep 2020
ELLE274	PM	00:58:26 16 Sep 2020	00:58:27 16 Sep 2020	00:58:40 16 Sep 2020	04:09:56 16 Sep 2020
DEVO811	P1	01:20:02 16 Sep 2020	01:20:03 16 Sep 2020	01:20:09 16 Sep 2020	03:15:11 16 Sep 2020
GREY261	P1	02:34:35 16 Sep 2020	02:34:55 16 Sep 2020	02:54:14 16 Sep 2020	06:07:09 16 Sep 2020
FIWAITEM3	FSO	06:52:44 16 Sep 2020	06:55:51 16 Sep 2020	07:45:27 16 Sep 2020	11:30:42 17 Sep 2020
EVENTNCC1	OT				11:31:26 16 Oct 2020
AUCKOSU	SV	20:29:01 15 Sep 2020			20:47:10 15 Sep 2020

Start-&gt;Alert

7 min

10 min

0

15

30

min

min

min

Alert->1st  
Arrival**Elapsed Times**

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
EAST831	00:00:40	00:05:15	00:05:55	03:42:10
ALBA851	00:00:43	00:06:11	00:06:54	14:27:46
DEVO812	00:04:26	00:08:35	00:13:01	03:14:29
WEST671	00:04:32	00:10:44	00:15:16	04:33:50
AUCK206	00:02:28	00:14:16	00:16:44	04:33:39
WAITEMATA4	00:08:58	00:11:48	00:20:46	02:48:38
TAKA807	00:14:01	00:06:58	00:20:59	10:22:51
AUCK2018	00:04:29	00:17:09	00:21:38	04:33:59
SILV901	00:10:09	00:11:42	00:21:51	03:07:57
WEST672	00:10:32	00:14:21	00:24:53	02:39:01
BIRK822	00:10:35	00:16:24	00:26:59	02:33:11
TEAT664	00:10:26	00:16:47	00:27:13	03:25:33
AUCKOSU2	00:06:55	00:20:39	00:27:34	04:44:57
PARN255	00:10:23	00:19:22	00:29:45	03:45:05
SILV907	00:10:09	00:24:16	00:34:25	02:59:15
OTAH3112	00:10:42	00:25:03	00:35:45	03:03:16
AVON607	00:10:29	00:25:32	00:36:01	03:03:37
REGION1C	00:08:32	00:27:55	00:36:27	04:35:13
AUCKOSU6	00:24:24	00:16:48	00:41:12	02:01:18
AVON6015	00:10:29	00:31:49	00:42:18	02:56:20
VSOWAITEM1	00:08:26	00:34:16	00:42:42	04:42:05
COUNTIES1	00:15:42	00:28:15	00:43:57	02:12:48
OTAH311	00:10:40	00:44:37	00:55:17	03:03:15
AUCKOSU4	00:09:52	00:57:12	01:07:04	04:45:07
VSOWAITEM3	00:50:25	00:21:27	01:11:52	01:56:05
BIRK8219	01:23:02	00:15:02	01:38:04	03:31:03
FIWAITEM1	02:08:36	00:00:08	02:08:44	39:22:18
BIRK821	02:37:10	00:05:48	02:42:58	05:25:37
AUCKOSU3	03:02:18	01:12:09	04:14:27	04:38:36
ELLE274	04:33:08	00:00:14	04:33:22	07:44:38
DEVO811	04:54:44	00:00:07	04:54:51	06:49:53
GREY261	06:09:17	00:19:39	06:28:56	09:41:51
FIWAITEM3	10:27:26	00:52:43	11:20:09	39:05:24

EVENTNCC1			35:06:08
AUCKOSU	00:03:43		00:21:52

## Notifications

Date	Time	Party Notified
15 Sep 2020	20:28:32	AAC WAITEMATA PAGED
15 Sep 2020	20:28:45	AAC REGION1C PAGED
15 Sep 2020	20:29:14	POLICE VIA INTERCAD
15 Sep 2020	20:29:14	AMBULANCE VIA INTERCAD
15 Sep 2020	20:29:18	OSU VIA PAGER
15 Sep 2020	20:29:33	VECTOR RE 2ND ALARM
15 Sep 2020	20:30:36	VECTOR POWER
15 Sep 2020	20:30:52	VSO WAITEMATA 1 PAGED
15 Sep 2020	20:31:04	AAC WAITEMATA PAGED 2ND ALARM
15 Sep 2020	20:31:15	AAC REGION1C PAGED 2ND ALARM
15 Sep 2020	20:32:15	REGION1C PAGE ACK
15 Sep 2020	20:33:57	POWER RE 3RD ALARM
15 Sep 2020	20:34:42	VSO WAITEMATA 1 PAGED 3RD ALARM
15 Sep 2020	20:35:36	FI WAITEMATA 1 PAGED 3RD ALARM
15 Sep 2020	20:36:56	AAC REGION1C PAGED 3RD ALARM
15 Sep 2020	20:37:09	AC COUNTIES1 PAGED 3RD ALARM
15 Sep 2020	20:37:20	NATIONA MEDIA SUPPORT PAGED 3RD ALARM
15 Sep 2020	20:40:24	AC COUNTIES1 PAGE ACK
15 Sep 2020	20:42:50	FIWAITEM1 ACK PAGE - DETAILS PASSED WILL WAIT UNTIL REQUESTED TO ATTEND
15 Sep 2020	20:57:16	GREATER ALARM ATTENDANCE SHEET EMAILED TO ICU AUCKALND
15 Sep 2020	21:00:41	COUNTIES1 REQ LATEST SITREP. ADV. SAYING IS JUST PASSING HARBOUR BRIDGE NOW.
15 Sep 2020	22:11:07	FIWAITEMATA1 PAGED TO RING IN
16 Sep 2020	02:10:21	GREY LYN FIRE STATION VIA PHONE RE RELIEF CREW FOR 0245/0300
16 Sep 2020	04:59:05	ATOC PHONE TO CONFIRM STATUS OF THIS INCIDENT, CAN WE KEEP THEM UPDATED ON F
16 Sep 2020	06:14:09	FIWAITEM1 PAGED
16 Sep 2020	06:14:30	JTOC
16 Sep 2020	06:16:44	FROM FIWAITEM1 CHRISTINE MCGINTY MY ETA IS APPROX 0800 - 0830
16 Sep 2020	06:17:48	FROM TAKA807 CONTACT ██████████ RE UPLIFTING HOSE ██████████
16 Sep 2020	06:21:11	TAKA807 EXTERNAL ALERT
16 Sep 2020	06:22:53	██████████ - ETA 0800
16 Sep 2020	06:27:48	FI IVESTIGATOR PUT THRU TO TAKA807
16 Sep 2020	06:32:34	██████████ UPDATED. UNABLE TO TOW TRAILER, BELIEVES VSO MAY HAVE TA

16 Sep 2020	06:35:30	VSO WAITEMATA1 [REDACTED] PAGED
16 Sep 2020	06:39:52	VSO WAITEMATA1 SAID ITS OPERATION SUPPORT THAT NORMALLY DOES THIS. THEY HAVE
16 Sep 2020	06:41:53	AUCKOSU PAGED RE. PICKING UP ABULTION TRAILER.
16 Sep 2020	06:53:38	FI WAITEMATA1 CHRISTINE MCGINTY - ATTACH ME TO THE CALL
16 Sep 2020	06:55:27	OSU AUCKLAND RE PAGED
16 Sep 2020	06:59:06	AUCKLAND OSU WILL PICK UP THE ABLUSIONS TRALIER AT ABOUT 0830 - 0900

## Message Log

Time	Message
20:25:45	<a href="https://web.pcl.govt.nz/?ecn=[REDACTED]">https://web.pcl.govt.nz/?ecn=[REDACTED]</a>
20:25:45	INC INFO: BUILDING FIRE @ KINETIC
20:25:46	** LOI search completed at 15/09/20 20:25:45
20:25:49	NEXT TO SPEC SAVERS
20:25:52	** Recommended unit EAST831 for requirement PUMP (>2.5 km) ** Recommended unit
20:25:52	ALBA851 for requirement PUMP (>2.2 km)
20:25:54	PA Selcal used to Initiate Alerting. (EAST831 at 1483 EAST COAST BAYS 182831)
20:25:54	PA Selcal used to Initiate Alerting. (ALBA851 at 1485 ALBANY 182851)
20:25:58	ALERTING_COMPLETED EAST831
20:26:01	ALERTING_COMPLETED ALBA851
20:26:09	WINDOWS BREAKING
20:26:15	** Event Location changed from "26 TRITON DR,ROSEDALE,AUCKLAND" to "30 TRITON DR
20:26:15	** LOI search completed at 15/09/20 20:26:15
20:26:15	,ROSEDALE,AUCKLAND: @KINETIC ENGINEERING DESIGN" at: 15/09/20 20:26:15
20:26:41	INC INFO: BUILDING ON FIRE
20:26:50	INC INFO: BUILDING FIRE
20:27:29	Unit EAST831 [ K1 : PROCEEDING TO INCIDENT]
20:27:37	** Requirement AERIAL added for alarm level 1
20:27:42	PA Selcal used to Initiate Alerting. (AUCK206 at 1420 AUCKLAND CITY 182201)
20:27:44	Unit ALBA851 [ K1 : PROCEEDING TO INCIDENT]
20:27:46	ALERTING_COMPLETED AUCK206
20:28:24	INC INFO: BUILDING FIRE
20:28:55	Unit AUCKOSU failed to contact via Selcal
20:28:55	Pager used to Initiate Alerting.
20:28:56	Unit EAST831 [COMCEN COM : MESSAGE] MULTIPLE CALLS & HYDRANT BETWEEN 30 & 34
20:28:59	FIR2POL 2ND ALARM BUILDING FIRE
20:29:01	ALERTING_COMPLETED AUCKOSU

20:29:06 FIR2AMB 2ND ALARM BUILDING FIR  
20:29:08 Unit EAST831 [ SITREP : ] TXT 2ND ALARM  
20:29:18 INC INFO: BUILDING FIRE TXT 2ND ALARM  
20:29:18 AMBO EVENT 0714-1-2020/09/15-FIR LINKED AT 15/09/2020 20:29:18  
20:29:32 Unit AUCK206 [ K1 : PROCEEDING TO INCIDENT]  
20:29:34 \*\* Alarm level updated to 2  
20:29:34 \*\* Recommended unit AUCK2018 for requirement COMU (>13.1 km)  
\*\* Recommended uni  
20:29:34 t DEVO812 for requirement PUMP (>4.3 km)  
\*\* Recommended unit WEST671 for requir  
20:29:34 ement PUMP (>12.9 km)  
20:29:40 PA Selcal used to Initiate Alerting. (AUCK2018 at 1420 AUCKLAND CITY 182201)  
20:29:40 MSU Selcal used to Initiate Alerting. (DEVO812 D0F182)  
20:29:40 PA Selcal used to Initiate Alerting. (WEST671 at 1467 WEST HARBOUR 182671)  
20:29:44 ALERTING\_COMPLETED DEVO812  
20:29:47 ALERTING\_COMPLETED AUCK2018  
20:29:50 ALERTING\_COMPLETED WEST671  
20:30:04 Unit WEST671 [ K1 : PROCEEDING TO INCIDENT]  
20:30:10 INC INFO: BUILDING FIRE  
20:30:43 Unit DEVO812 [ K1 : PROCEEDING TO INCIDENT]  
20:30:47 Unit AUCK2018 [ KC : UNIT CALLING]  
20:30:49 CALLER ADVISED WELL INVOLVED BUILDING FIRE  
20:30:53 INC INFO: BUILDING FIRE  
20:31:13 Unit EAST831 [ K99 : PROPERTY FIRE WELL INVOLVED]  
20:31:40 INC INFO: BUILDING FIRE  
20:31:45 Unit AUCK2018 [ SITREP : ] DELAYED T/O REMOVING PODS  
20:31:47 Unit EAST831 [ K99 : PROPERTY FIRE WELL INVOLVED]  
20:32:08 Pager used to Initiate Alerting.  
20:32:08 Unit AUCKOSU2 failed to contact via Selcal  
20:32:12 Unit ALBA851 [ K2 : IN ATTENDANCE AT INCIDENT]  
20:32:13 ALERTING\_COMPLETED AUCKOSU2  
20:32:18 Unit ALBA851 [ K2 : IN ATTENDANCE AT INCIDENT]  
20:32:22 Unit AUCKOSU2 [ K1 : PROCEEDING TO INCIDENT]  
20:32:25 Unit AUCKOSU2 [ K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]  
20:33:10 Unit EAST831 [ KP : PRIORITY MESSAGE]  
20:33:29 Unit EAST831 [ KP : PRIORITY MESSAGE] TXT 3RD ALARM  
20:33:32 FIR2AMB 3RD ALARM PLEASE RESPOND  
20:33:37 FIR2POL 3RD ALARM  
20:33:37 Pager used to Initiate Alerting.  
20:33:37 INC INFO: BUILDING FIRE TXT 3RD ALARM

20:33:39 Pager used to Initiate Alerting.

20:33:44 ALERTING\_COMPLETED VSOWAITEM1

20:33:50 ALERTING\_COMPLETED REGION1C

20:33:56 ALERTING\_COMPLETED VSOWAITEM1

20:33:59 Unit VSOWAITEM1 [ K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]

20:33:59 WILL RESPOND TO TAKAPUNA TO PICK UP THE TRAILER AND RESPOND TO THE INCIDENT

20:34:02 ETA FOR VECTOR 15 MINUTES

20:34:02 ALERTING\_COMPLETED VSOWAITEM1

20:34:11 Pager used to Initiate Alerting.

20:34:16 ALERTING\_COMPLETED WAITEMATA4

20:34:26 Preempt Unit OTAH311

20:34:28 Unit AUCK2018 [ K1 : PROCEEDING TO INCIDENT]

20:34:33 \*\* Alarm level updated to 3

20:34:33 \*\* Recommended unit SILV907 for requirement CANBACKUP (>15.3 km)  
\*\* Recommended

20:34:33 unit PARN255 for requirement AERIAL (>13.1 km)  
\*\* Recommended unit TEAT664 for

20:34:33 requirement AERIAL (>14.7 km)  
\*\* Recommended unit AVON6015 for requirement BAT

20:34:33 (>17.4 km)  
\*\* Recommended unit AUCKOSU4 for requirement CANT (>24.2 km)  
\*\* Re

20:34:33 commended unit WEST672 for requirement PUMP (>12.9 km)  
\*\* Recommended unit BIRK

20:34:33 822 for requirement PUMP (>7.7 km)  
\*\* Recommended unit SILV901 for requirement

20:34:33 PUMP (>15.3 km)  
\*\* Recommended unit OTAH3112 for requirement HOSEL (>24.3 km)

20:34:53 VSOWAITEM4 [REDACTED] ACK PAGE REQ ATTACH

20:34:56 Unit EAST831 [ KP : PRIORITY MESSAGE]

20:35:02 PA Selcal used to Initiate Alerting. (SILV907 at 1490 SILVERDALE 182907)

20:35:02 PA Selcal used to Initiate Alerting. (PARN255 at 1425 PARNELL 182251)

20:35:02 PA Selcal used to Initiate Alerting. (TEAT664 at 1466 TE ATATU 182661)

20:35:02 PA Selcal used to Initiate Alerting. (AVON6015 at 1460 AVONDALE 182607)

20:35:02 Pager used to Initiate Alerting.

20:35:02 PA Selcal used to Initiate Alerting. (WEST672 at 1467 WEST HARBOUR 182672)

20:35:02 PA Selcal used to Initiate Alerting. (BIRK822 at 1482 BIRKENHEAD 182822)

20:35:03 PA Selcal used to Initiate Alerting. (SILV901 at 1490 SILVERDALE 182901)

20:35:03 PA Selcal used to Initiate Alerting. (OTAH3112 at 1431 OTAHUHU 182311)

20:35:03 MSU Selcal used to Initiate Alerting. (OTAH311 D0FE42)

20:35:03 PA Selcal used to Initiate Alerting. (AVON607 at 1460 AVONDALE 182607)

20:35:04 Unit AUCKOSU4 failed to contact via Selcal

20:35:10 ALERTING\_COMPLETED AUCKOSU4  
20:35:15 ALERTING\_COMPLETED AUCKOSU4  
20:35:21 Unit OTAH311 failed to contact via Selcal  
20:35:27 ALERTING\_COMPLETED SILV907  
20:35:27 ALERTING\_COMPLETED SILV901  
20:35:34 Pager turnout error - request Id 0  
20:35:34 Pager turnout error - request Id 0  
20:35:34 Pager turnout error - request Id 0  
20:35:34 Pager turnout error - request Id 0  
20:35:34 Pager turnout error - request Id 0  
20:35:34 Pager turnout error - request Id 0  
20:35:34 Pager turnout error - request Id 0  
20:35:34 Pager turnout error - request Id 0  
20:35:34 Pager turnout error - request Id 0  
20:35:35 Pager turnout error - request Id 0  
20:35:35 Pager turnout error - request Id 0  
20:35:41 ALERTING\_COMPLETED PARN255  
20:35:44 ALERTING\_COMPLETED TEAT664  
20:35:47 ALERTING\_COMPLETED AVON6015  
20:35:47 ALERTING\_COMPLETED AVON607  
20:35:50 ALERTING\_COMPLETED WEST672  
20:35:54 ALERTING\_COMPLETED BIRK822  
20:35:57 ALERTING\_COMPLETED SILV907  
20:35:57 ALERTING\_COMPLETED SILV901  
20:35:58 ALERTING\_COMPLETED OTAH311  
20:36:00 Unit SILV901 [ K1 : PROCEEDING TO INCIDENT]  
20:36:00 ALERTING\_COMPLETED OTAH3112  
20:36:43 NTO AAC WAITEMATA PAGED 3RD ALARM  
20:37:33 Unit OTAH311 [ K1 : PROCEEDING TO INCIDENT]  
20:37:38 Unit PARN255 [ K1 : PROCEEDING TO INCIDENT]  
20:37:39 Unit OTAH3112 [ K1 : PROCEEDING TO INCIDENT]  
20:37:46 Unit AVON607 [ K1 : PROCEEDING TO INCIDENT]  
20:37:49 Unit TEAT664 [ K1 : PROCEEDING TO INCIDENT]  
20:38:00 \*\* Requirement PUMP added for alarm level 3  
20:38:02 \*\* Requirement PUMP added for alarm level 3  
20:38:06 Unit WAITEMATA4 [ K1 : PROCEEDING TO INCIDENT]  
20:38:20 Unit DEVO812 [ K2 : IN ATTENDANCE AT INCIDENT]  
20:38:24 Unit EAST831 [ KP : PRIORITY MESSAGE] FIRECOM DIDN'T RESPOND DUE TO T/O 3RD ALAR  
20:38:24 M  
20:38:26 Unit AVON6015 [ K1 : PROCEEDING TO INCIDENT]  
20:38:30 AL: PAGING ACK TIMED OUT FOR STATION: 1466 at 15/09/20 20:38:30



20:39:01 MSU Selcal used to Initiate Alerting. (TAKA807 D09D02)

20:39:08 Unit TAKA807 [ STOP : MESSAGE]

20:39:17 Unit TAKA807 failed to contact via Selcal

20:39:19 ALERTING\_COMPLETED TAKA807

20:39:20 Unit WEST672 [ K1 : PROCEEDING TO INCIDENT]

20:39:26 Unit TAKA807 [ K1 : PROCEEDING TO INCIDENT]

20:39:35 Unit SILV907 [ K1 : PROCEEDING TO INCIDENT]

20:39:46 Unit BIRK822 [ K1 : PROCEEDING TO INCIDENT]

20:40:24 Unit BIRK822 [ K1 : PROCEEDING TO INCIDENT]

20:40:34 Unit WEST671 [ K2 : IN ATTENDANCE AT INCIDENT]

20:40:52 Pager used to Initiate Alerting.

20:41:00 ALERTING\_COMPLETED COUNTIES1

20:41:11 Unit REGION1C [ K1 : PROCEEDING TO INCIDENT]

20:42:02 Unit AUCK206 [ K2 : IN ATTENDANCE AT INCIDENT]

20:43:03 Unit EAST831 [ KC : UNIT CALLING]

20:43:45 INC INFO: SMOKE IN AREA

20:43:50 \*\* Requirement AERIAL removed for alarm level 1

20:44:08 Unit EAST831 [ SITREP : ] SO [REDACTED] BUILDING FIRE 2 STOREY APPROX 200X 50M USED

20:44:08 AN ENGINERRING SHOP 2 LPD EXTERNAL FF CARRIED OUT BRIG ATTEMPTING TO GAIN ACCES

20:44:08 S

20:45:28 Unit SILV907 [ KC : UNIT CALLING]

20:45:36 \*\* Requirement PUMP added for alarm level 3

20:45:50 \*\* Requirement PUMP removed for alarm level 3

20:46:04 Unit WAITEMATA4 [ K2 : IN ATTENDANCE AT INCIDENT]

20:46:13 Unit SILV907 [ KC : UNIT CALLING]

20:46:17 Unit TAKA807 [ K2 : IN ATTENDANCE AT INCIDENT]

20:46:24 Unit TAKA807 [ K2 : IN ATTENDANCE AT INCIDENT]

20:46:27 Unit WAITEMATA4 [ K2 : IN ATTENDANCE AT INCIDENT]

20:46:43 Unit SILV907 [ SITREP : ] CAN YOU PUT COVER MOVE INTO SILVERDALE (JUST TRYING TO

20:46:43 DO ORGANISE IT NOW)

20:46:56 Unit AUCK2018 [ K2 : IN ATTENDANCE AT INCIDENT]

20:47:09 Unit SILV901 [ K2 : IN ATTENDANCE AT INCIDENT]

20:47:10 Unit AUCKOSU [ K7 : AT NORMAL STATION]

20:47:13 BY PHONE

20:47:13 Unit VSOWAITEM1 [ K1 : PROCEEDING TO INCIDENT] BY PHONE

20:48:27 Unit COUNTIES1 [ K1 : PROCEEDING TO INCIDENT]

20:49:36 Pager used to Initiate Alerting.

20:49:36 Unit AUCKOSU6 failed to contact via Selcal

20:49:42 ALERTING\_COMPLETED AUCKOSU6

20:49:52 Unit AUCKOSU6 [ K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]

20:49:53 Unit AUCKOSU6 [ K1 : PROCEEDING TO INCIDENT]

20:50:00 Unit AUCKOSU6 [ K39 : RE-TRANSMIT YOUR CURRENT STATUS (VERBAL OR MSU)]

20:50:12 Unit WEST672 [ K2 : IN ATTENDANCE AT INCIDENT]

20:52:17 Unit BIRK822 [ K2 : IN ATTENDANCE AT INCIDENT]

20:52:31 Unit TEAT664 [ K2 : IN ATTENDANCE AT INCIDENT]

20:52:52 Unit AUCKOSU2 [ K2 : IN ATTENDANCE AT INCIDENT]

20:54:33 Unit AUCKOSU6 [ K1 : PROCEEDING TO INCIDENT]

20:55:03 Unit PARN255 [ K2 : IN ATTENDANCE AT INCIDENT]

20:58:43 [https://web.pcl.govt.nz/?ecn=\[REDACTED\]](https://web.pcl.govt.nz/?ecn=[REDACTED])

20:58:43 [https://web.pcl.govt.nz/?ecn=\[REDACTED\]](https://web.pcl.govt.nz/?ecn=[REDACTED])

20:58:44 [https://web.pcl.govt.nz/?ecn=\[REDACTED\]](https://web.pcl.govt.nz/?ecn=[REDACTED])

20:59:43 ENTERED BY FIRECOM AS SHOWING IN ATT

20:59:43 Unit SILV907 [ K2 : IN ATTENDANCE AT INCIDENT] ENTERED BY FIRECOM AS SHOWING IN

20:59:43 ATT

21:00:01 Unit OTAH3112 [ KC : UNIT CALLING]

21:00:41

21:01:03 Unit OTAH3112 [ K2 : IN ATTENDANCE AT INCIDENT]

21:01:19 Unit AVON607 [ K2 : IN ATTENDANCE AT INCIDENT]

21:01:45 Unit REGION1C [ K2 : IN ATTENDANCE AT INCIDENT]

21:02:42 Unit OTAH3112 [ SITREP : ] CONTACT IC IF THEY WANT ADDITIONAL WATER BOUGHT IN WI

21:02:42 TH THE HOSE LAYER AND IF THEY DO WHAT END IOF TRITON DR DO THEY NEED IT BOUGHT I

21:02:42 N FROM AND WE ARE CURRENTLY STANDING BY TRITON/ROSEDALE

21:03:20 Unit AUCKOSU4 [ K1 : PROCEEDING TO INCIDENT]

21:04:54 COVERING UNIT EAST832 DISPATCHED TO STATION EAST COAST BAYS AT 15/09/20  
21:04:54

21:06:10 Unit AUCK2018 [ SITREP : ] OTAH3112 ARE WANTING TO KNOW IF ANY ADDITIONAL WATER

21:06:10 NEEDS TO BE BOUGHT IN WITH THE HOSE LAYER AND IF THEY DO WHAT END IOF TRITON DR

21:06:10 DO THEY NEED IT BOUGHT IN FROM AND WE ARE CURRENTLY STANDING BY TRITON/ROSEDALE

21:06:30 Unit AUCKOSU6 [ K2 : IN ATTENDANCE AT INCIDENT]

21:06:33 CFO [REDACTED] FROM GREENHITHE PHONES IN TO FIND OUT WHY THEY WERE

21:06:33 NOT IN THE JOB - ADVISED UNSURE WE FOLLOWED THE PDA - [REDACTED] WILL FOLLOW UP WITH [REDACTED]

21:06:33 [REDACTED]

21:07:37 Unit AVON6015 [ K2 : IN ATTENDANCE AT INCIDENT]

21:08:00 Unit VSOWAITEM1 [ K2 : IN ATTENDANCE AT INCIDENT]

21:09:15 Unit AUCK2018 [ KC : UNIT CALLING]  
21:09:16 Unit COUNTIES1 [ K2 : IN ATTENDANCE AT INCIDENT]  
21:09:23 Unit AUCK2018 [ KC : UNIT CALLING]  
21:09:39 Unit AUCK2018 [ KC : UNIT CALLING]  
21:10:30 Unit AUCK2018 [ K44 : COMMAND OR CONTROL POINT ESTABLISHED (STATE OIC AND LOCATI  
21:10:30 Unit AUCK2018 [ KC : UNIT CALLING]  
21:10:30 ON)] TRITON COMMAND AAM [REDACTED]  
21:11:00 Unit AUCK2018 [ SITREP : ] GTWW AERIALS & MULTI LPDS  
21:12:02 Alarm Timer Extended: 0  
21:12:10 INC INFO:  
21:13:52 Alarm Timer Extended: 0  
21:15:40 Pager used to Initiate Alerting.  
21:15:44 Unit VSOWAITEM3 [ K1 : PROCEEDING TO INCIDENT]  
21:15:45 ALERTING\_COMPLETED VSOWAITEM3  
21:15:56 Unit VSOWAITEM3 [ K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]  
21:17:01 Unit AUCK2018 [ KC : UNIT CALLING]  
21:17:31 Unit AUCK2018 [ SITREP : ] DANGEROUS GOODS AT SECTOR 4 PAINT THINNERS  
21:19:59 FM TEAT FIRE 662 FULLY MANNED AND ON STATION  
21:20:35 ENTERED BY FIRECOM  
21:20:36 Unit OTAH311 [ K2 : IN ATTENDANCE AT INCIDENT] ENTERED BY FIRECOM  
21:21:11 Alarm Timer Extended: 0  
21:21:12 Alarm Timer Extended: 0  
21:25:48 Alarm Timer Extended: 0  
21:32:22 Unit AUCKOSU4 [ K2 : IN ATTENDANCE AT INCIDENT]  
21:34:22 Alarm Timer Extended: 0  
21:34:23 Alarm Timer Extended: 0  
21:34:23 Alarm Timer Extended: 0  
21:34:24 Alarm Timer Extended: 0  
21:34:24 Alarm Timer Extended: 0  
21:34:25 Alarm Timer Extended: 0  
21:34:26 Alarm Timer Extended: 0  
21:35:12 RE-ENTERED BY FIRECOM  
21:35:12 Unit VSOWAITEM3 [ K1 : PROCEEDING TO INCIDENT] RE-ENTERED BY FIRECOM  
21:37:11 Unit VSOWAITEM3 [ K2 : IN ATTENDANCE AT INCIDENT]  
21:39:50 Unit OTAH311 [ K2 : IN ATTENDANCE AT INCIDENT]  
21:41:24 Alarm Timer Extended: 0  
21:41:24 Alarm Timer Extended: 0  
21:41:24 Alarm Timer Extended: 0  
21:41:25 Alarm Timer Extended: 0

21:42:04 Unit AUCK2018 [ SITREP : ] TO ADVISE STAGING AREA IS NOW SET UP AT THE REAR OF 2

21:42:04 018

21:47:36 Unit AUCK2018 [ SITREP : ] K11 BIRK8219

21:47:55 \*\* Cross Referenced to Event # F3077333 at: 15/09/20 21:47:55

21:47:57 INC INFO: BUILDING FIRE TXT 3RD ALARM - LIGHTING UNIT REQUIRED

21:48:17 PA Selcal used to Initiate Alerting. (BIRK8219 at 1482 BIRKENHEAD 182823)

21:48:20 ALERTING\_COMPLETED BIRK8219

21:48:35 Alarm Timer Extended: 0

21:48:35 Alarm Timer Extended: 0

21:48:36 Alarm Timer Extended: 0

21:48:37 Alarm Timer Extended: 0

21:51:22 Unit BIRK8219 [ K1 : PROCEEDING TO INCIDENT]

22:01:00 Unit AUCK2018 [ SITREP : ] SO [REDACTED] (VIA PHONE) 2 STOREY. 80X50M USED AS EN

22:01:00 GINEERING FACTORY. 2 AERIALS IN USE. MULTIPLE LPD. STAGING AREA SET UP AT THE RE

22:01:00 AR OF AUCK2018.

22:03:23 Unit BIRK8219 [ K2 : IN ATTENDANCE AT INCIDENT]

22:03:31 Unit BIRK8219 [ K2 : IN ATTENDANCE AT INCIDENT]

22:05:52 Unit AUCK2018 [ SITREP : ] LPDS BEING USED FOR INTERNAL ATTACK

22:09:22 Unit AUCK2018 [ SITREP : ] ONCALL FI TO CONTACT 2018

22:13:35 FIWAITEMATA1 (CHRISTINE MCCINTY) ACK PAGE TRANSFERED TO TRITON COMMAND

22:18:11 Alarm Timer Extended: 0

22:18:12 Alarm Timer Extended: 0

22:18:13 Alarm Timer Extended: 0

22:21:24 Unit VSOWAITEM3 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

22:26:36 Unit AUCKOSU6 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

22:33:54 Radio used to Initiate Alerting.

22:33:54 ALERTING\_COMPLETED FIWAITEM1

22:33:59 Unit FIWAITEM1 [ K1 : PROCEEDING TO INCIDENT]

22:34:02 Unit FIWAITEM1 [ K2 : IN ATTENDANCE AT INCIDENT]

22:34:23 Unit FIWAITEM1 [ SITREP : ] (VIA PHONE) - CAN YOU PLEASE PUT ME K2 AT TRITON

22:36:19 Alarm Timer Extended: 0

22:38:06 Unit COUNTIES1 [ K6 : ON PAGER (STATE LOCATION)]

22:43:04 Unit AUCK2018 [ SITREP : ] CREWS CONTINUING WITH INTERNAL ATTACK 2 X AERIALS STI

22:43:04 LL IN OPERATION

22:58:30 Unit BIRK822 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

22:59:04 Unit AUCK2018 [ SITREP : ] (VIA PHONE) COULD WE GET BIRK821 TO COME QND RELIEVE

22:59:04 SILVERDALE FOR 2330.

23:00:29 BIRK821 NOTIFIED BY PHONE TO RESPOND TO FIRE FOR 2330

23:01:06 REMUERA ADV TO HEAD TO TAKAPUNA TO COVER STATION FOR 2330

23:01:43 Unit WEST672 [ K22-1 : APPLIANCE AVAILABLE FOR A FURTHER INCIDENT]

23:01:46 Unit AUCK2018 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SSO  
[REDACTED]

23:01:46 FIRE IS NOW EXT CREWS DAMPENING DOWN HOTSPOTS CURRENTLY RELEASING  
RESOURCES AND

23:01:46 SECURING SITE

23:02:11 MSU Selcal used to Initiate Alerting. (BIRK821 D006B2)

23:02:27 Unit BIRK821 failed to contact via Selcal

23:02:28 ALERTING\_COMPLETED BIRK821

23:02:38 Unit AUCK2018 [ SITREP : ] DEVO811 TO BE ON SITE HERE FOR 0030

23:02:47 Unit BIRK821 [ K1 : PROCEEDING TO INCIDENT]

23:03:03 Alarm Timer Extended: 0

23:03:04 Unit AUCK2018 [ SITREP : ] (BY PHONE) DEVO811 TO BE ON SITE HERE FOR 0030

23:04:20 Unit WEST672 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

23:05:27 DEVO811 NOTIFIED BY PHONE FOR STANDBY AT 0030 - WAKE UP CALL AT 0000

23:08:16 Unit BIRK821 [ K2 : IN ATTENDANCE AT INCIDENT]

23:13:57 Unit WAITEMATA4 [ K6 : ON PAGER (STATE LOCATION)]

23:17:27 ADV TE ATATU VOLLYS CAN RETURN HOME NOW AND RESPOND FROM HOME IF  
REQ

23:21:39 Unit AVON6015 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

23:24:34 Unit SILV907 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

23:27:36 Unit AUCKOSU3 [ K1 : PROCEEDING TO INCIDENT]

23:27:41 Unit OTAH3112 [ KC : UNIT CALLING]

23:28:24 Unit OTAH3112 [ SITREP : ] 311 & 3112 K10

23:28:34 Unit OTAH311 [ K10 : RE-COMMISSIONING APPLIANCE]

23:28:35 Unit OTAH3112 [ K10 : RE-COMMISSIONING APPLIANCE]

23:28:56 Unit AVON607 [ K7 : AT NORMAL STATION]

23:33:16 Unit SILV901 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

23:39:25 Unit DEVO812 [ KC : UNIT CALLING]

23:39:30 Unit DEVO812 [ KC : UNIT CALLING]

23:39:47 Unit DEVO812 [ K10 : RE-COMMISSIONING APPLIANCE]

23:39:52 Alarm Timer Extended: 0

23:50:51 Unit TEAT664 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

23:55:10 Unit FIWAITEM1 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

23:56:22 Unit BIRK8219 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

00:01:52 Unit AUCK2018 [ SITREP : ] FIRE INV ON SCENE CREWS CARRYING OUT OVERHAUL  
FURTHER

00:01:52 CREWS BEING RELEASED

00:02:02 Alarm Timer Extended: 0

00:07:08 Unit EAST831 [ KC : UNIT CALLING]

00:07:28 Unit EAST831 [ K10 : RE-COMMISSIONING APPLIANCE]

00:10:23 Unit PARN255 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

00:19:14 ELLERSLIE CALLED TO HEAD TO JOB TO REPLACE TE ATATU

00:20:27 Unit AUCK2018 [ SITREP : ] (VIA PHONE) COULD YOU CONTACT ELLERSLIE TO COME AND R

00:20:27 EPLACE TE ATATU BY 0100.

00:37:28 Unit ALBA851 [ K7 : AT NORMAL STATION]

00:39:46 Unit AUCKOSU3 [ K2 : IN ATTENDANCE AT INCIDENT]

00:50:11 Unit AUCK2018 [ SITREP : ] (BY PHONE) WE"RE HEADING HOME, SSO [REDACTED] STILL IN CH

00:50:11 ARGE COMMS VIA BIRK821

00:58:13 MSU Selcal used to Initiate Alerting. (ELLE274 D0E682)

00:58:27 Unit ELLE274 [ K1 : PROCEEDING TO INCIDENT]

00:58:30 Unit ELLE274 failed to contact via Selcal

00:58:32 ALERTING\_COMPLETED ELLE274

00:58:33 Unit ELLE274 [ K1 : PROCEEDING TO INCIDENT]

00:58:40 Unit ELLE274 [ K2 : IN ATTENDANCE AT INCIDENT]

00:58:57 Unit AUCK206 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

00:59:08 Unit WEST671 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

00:59:18 Unit AUCK2018 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

01:00:31 Unit REGION1C [ K6 : ON PAGER (STATE LOCATION)]

01:03:54 Unit AUCKOSU3 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

01:06:07 Unit BIRK821 [ KC : UNIT CALLING]

01:06:35 Unit BIRK821 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SO [REDACTED]

01:06:35 [REDACTED]

01:07:23 Unit VSOWAITEM1 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

01:10:15 Unit AUCKOSU2 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

01:10:26 Unit AUCKOSU4 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

01:12:07 Unit TAKA807 [ KC : UNIT CALLING]

01:12:41 Unit TAKA807 [ SITREP : ] TAKA807 K10 FOR APPROX 30 MINS

01:12:46 Unit TAKA807 [ K10 : RE-COMMISSIONING APPLIANCE]

01:20:03 Unit DEVO811 [ K1 : PROCEEDING TO INCIDENT]

01:20:09 Unit DEVO811 [ K2 : IN ATTENDANCE AT INCIDENT]

01:28:33 Unit BIRK821 [ SITREP : ] (VIA PHONE) GREY261 TO BE AT THE FIREGROUND AS RELIF C

01:28:33 REW AT 0245 - IF THATS NOT OKAY TAKA807 COULD COME BACK BIRK821 WILL BE LEAVING

01:28:33 IN ABOUT HALF AN HOUR

01:42:23 Unit BIRK821 [ KC : UNIT CALLING]

01:43:04 Unit BIRK821 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SO [REDACTED]

01:43:04 FOR TRITON INCIDENT

01:43:37 CORRECTION: SO [REDACTED]  
01:50:32 Unit BIRK821 [ KC : UNIT CALLING]  
01:50:55 Unit BIRK821 [ K10 : RE-COMMISSIONING APPLIANCE]  
01:51:49 IGNORE CORRECTION SO [REDACTED]  
02:09:15 Alarm Timer Extended: 0  
02:09:16 Alarm Timer Extended: 0  
02:09:16 Alarm Timer Extended: 0  
02:34:33 Phone used to Initiate Alerting.  
02:34:35 ALERTING\_COMPLETED GREY261  
02:34:56 Unit GREY261 [ K1 : PROCEEDING TO INCIDENT]  
02:54:14 Unit GREY261 [ K2 : IN ATTENDANCE AT INCIDENT]  
03:14:26 Unit DEVO811 [ KC : UNIT CALLING]  
03:14:31 Unit DEVO811 [ KC : UNIT CALLING]  
03:15:02 Unit DEVO811 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SO  
[REDACTED] GR  
03:15:02 EY261  
03:15:11 Unit DEVO811 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]  
03:46:15 Alarm Timer Extended: 0  
03:46:33 Unit GREY261 [ KC : UNIT CALLING]  
03:47:20 Unit GREY261 [ SITREP : ] SO [REDACTED] TYPE 4 BRONTO IN USE DAMPENING DOWN HOT  
SPOTS  
03:47:20 ON FIRST FLOOR  
04:09:56 Unit ELLE274 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]  
04:16:47 Unit GREY261 [ KC : UNIT CALLING]  
04:17:26 Unit GREY261 [ SITREP : ] DAMPENING DOWN HOT SPOTS 1 HPD  
04:48:19 Unit GREY261 [ KC : UNIT CALLING]  
04:49:43 Unit GREY261 [ K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL  
DEVELOPMENTS] CAN  
04:49:43 YOU CONFIRM IF ANY FURTHER STANDBYS ARE PLANNED (WE HAVE NOTHING  
FURTHER AFTER Y  
04:49:43 OURSELVES)  
04:52:01 Unit GREY261 [ SITREP : ] (VIA PHONE) COULD WE PLEASE HAVE TAKAPUNA COME  
UP TO T  
04:52:01 RITON FOR 0600  
04:53:18 PHONED TAKAPUNA TO ADV FOR THEM TO HEAD TO TRITON FOR 0600  
04:59:05 URTHER STANDBYS, AND WHEN WE LEAVE  
05:20:38 Unit GREY261 [ KC : UNIT CALLING]  
05:21:17 Unit GREY261 [ K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]  
05:44:49 Phone used to Initiate Alerting.  
05:45:00 ALERTING\_COMPLETED TAKA807  
05:45:07 Unit TAKA807 [ K2 : IN ATTENDANCE AT INCIDENT]  
06:07:05 Unit TAKA807 [ KC : UNIT CALLING]  
06:07:09 Unit GREY261 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

06:07:29 Unit TAKA807 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SSO  
[REDACTED]

06:07:56 Unit TAKA807 [COMCEN COM : MESSAGE] ATOC ARE ASKING HOW LONG FURTHER  
STANDBYS AR

06:07:56 E REQUIRED FOR AND THE STATUS OF THE ROAD

06:09:23 Unit TAKA807 [ SITREP : ] STANDBY WILL CONFIRM

06:13:44 INC INFO: BUILDING FIRE TXT 3RD ALARM - TOC 2025 TOA 2031

06:20:52 Unit TAKA807 [COMCEN COM : MESSAGE] NO RESPONSE VIA R/T X3

06:25:26 Unit TAKA807 [ KC : UNIT CALLING]

06:25:46 Unit TAKA807 [ SITREP : ] WERE YOU CALLING

06:26:15 Unit TAKA807 [ K36 : CONTACT COMMUNICATIONS CENTRE BY PHONE] TO BE PUT  
THROUGH T

06:26:15 O FIRE INVESTIGATOR

06:26:18 Alarm Timer Extended: 0

06:30:28 Unit TAKA807 [ SITREP : ] ADVISE [REDACTED] HOSES LOCATED AT TOTS  
ON TR

06:30:28 ITON @ 23 TRITON DR. ABULTION TRAILER ALSO HERE

06:31:47 ,

06:32:34 KEN IT.

06:39:52 NOTHING TO DO WITH IT, NORMALLY JUST THE UNIFORM TRAILER.

06:46:53 Unit TAKA807 [ KC : UNIT CALLING]

06:47:09 Unit TAKA807 [ STOP : MESSAGE] SCENE LEFT WITH POLICE

06:48:09 Unit TAKA807 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

06:52:33 Pager used to Initiate Alerting.

06:52:33 Pager used to Initiate Alerting.

06:52:44 ALERTING\_COMPLETED FIWAITEM1

06:52:44 ALERTING\_COMPLETED FIWAITEM3

06:53:48 Unit FIWAITEM1 [ K1 : PROCEEDING TO INCIDENT]

06:54:12 Unit EVENTNCC1 [ K6 : ON PAGER (STATE LOCATION)]

06:55:51 Unit FIWAITEM3 [ K1 : PROCEEDING TO INCIDENT]

07:06:37 Unit FIWAITEM1 [ K2 : IN ATTENDANCE AT INCIDENT]

07:45:27 Unit FIWAITEM3 [ K2 : IN ATTENDANCE AT INCIDENT]

07:51:30 Alarm Timer Extended: 0

08:23:11 Unit FIWAITEM1 [ SITREP : ] ALBA851 REQUIRED FOR HOT SPOTS, NORMAL TRAFFIC  
OK

08:23:20 MSU Selcal used to Initiate Alerting. (ALBA851 D072F2)

08:23:24 ALERTING\_COMPLETED ALBA851

08:24:37 Unit ALBA851 [ K1 : PROCEEDING TO INCIDENT]

08:25:13 Unit ALBA851 [COMCEN COM : MESSAGE] CONFIRMING YOU COPIED MY RESPOND  
NORMAL TRAF

08:25:13 FIC

08:25:18 Unit ALBA851 [ SITREP : ] AFFIRM

08:26:35 Alarm Timer Extended: 0



08:34:43 Unit ALBA851 [ K2 : IN ATTENDANCE AT INCIDENT]

08:45:07 Unit ALBA851 [ KC : UNIT CALLING]

08:45:40 Unit ALBA851 [ SITREP : ] SO [REDACTED] DAMPENING DOWN HOTSPOTS AND GTWW ONE HPD

09:16:32 Alarm Timer Extended: 0

09:38:21 Unit ALBA851 [ KC : UNIT CALLING]

09:38:49 Unit ALBA851 [ K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]

10:49:22 Unit ALBA851 [ KC : UNIT CALLING]

10:49:41 Unit ALBA851 [ SITREP : ] NO FURHTER STANDBYS REQUIRED. SCENE LEFT WITH FIRE RIS

10:49:41 K MANAGMENT

10:52:53 Unit ALBA851 [ KC : UNIT CALLING]

10:53:05 Unit ALBA851 [ K10 : RE-COMMISSIONING APPLIANCE]

13:32:15 Unit FIWAITEM1 [COMCEN COM : MESSAGE] VIA PHONE - JUST CHECKING YOU GUYS ARE OK?

13:32:32 Unit FIWAITEM1 [ SITREP : ] VIA PHONE - WE"RE ALRIGHT, TWO OF US ON SCENE. POLIC

13:32:32 E ARE HERE TOO

13:34:26 [https://web.pcl.govt.nz/?ecn=\[REDACTED\]](https://web.pcl.govt.nz/?ecn=[REDACTED])

13:34:26 [https://web.pcl.govt.nz/?ecn=\[REDACTED\]](https://web.pcl.govt.nz/?ecn=[REDACTED])

13:34:27 [https://web.pcl.govt.nz/?ecn=\[REDACTED\]](https://web.pcl.govt.nz/?ecn=[REDACTED])

16:20:59 Unit FIWAITEM1 [COMCEN COM : MESSAGE] VIA PHONE - JUST DOING ANOTHER WELFWARE CH

16:20:59 ECK

16:21:28 Unit FIWAITEM1 [ SITREP : ] VIA PHONE - JUST ABOUT TO DEPART, WILL BE BACK TOMOR

16:21:28 ROW

16:29:42 Unit FIWAITEM3 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

16:29:46 Unit FIWAITEM1 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

16:47:46 UNIT 'VSOWAITEM3' ALERT TIME '[NULL]' ADJUSTED TO '20200915211543NS' AT '16/09/2

16:47:47 UNIT 'AUJCKOSU3' ALERT TIME '[NULL]' ADJUSTED TO '20200915232736NS' AT '16/09/202

16:47:47 UNIT 'ELLE274' ALERT TIME '[NULL]' ADJUSTED TO '20200916005826NS' AT '16/09/2020

16:47:47 UNIT 'DEVO811' ALERT TIME '[NULL]' ADJUSTED TO '20200916012002NS' AT '16/09/2020

16:47:47 \*\* Assigned Result Code: STRU, Detailed Event Type: 1100

06:50:10 REOPENED FOR FIRE INVESTIGATION

06:50:18 \*\* Event F3077307 has been reopened at: 17/09/20 06:50:18

06:50:19 \*\* LOI search completed at 17/09/20 06:50:19

06:50:39 Pager used to Initiate Alerting.

06:50:45 ALERTING\_COMPLETED FIWAITEM3

06:51:02 Unit FIWAITEM3 [ K1 : PROCEEDING TO INCIDENT]

06:56:46 Pager used to Initiate Alerting.

06:56:52 ALERTING\_COMPLETED FIWAITEM1

06:56:58 Unit FIWAITEM1 [ K1 : PROCEEDING TO INCIDENT]

06:57:05 Unit FIWAITEM1 [ K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]

06:57:05 VIA PHONE

07:06:47 Unit FIWAITEM3 [ K2 : IN ATTENDANCE AT INCIDENT]

07:10:04 Unit FIWAITEM1 [ K2 : IN ATTENDANCE AT INCIDENT]

07:47:32 Alarm Timer Extended: 0

07:50:19 Alarm Timer Extended: 0

11:30:42 Unit FIWAITEM3 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

11:47:36 Unit FIWAITEM1 [ K6 : ON PAGER (STATE LOCATION)]

11:54:44 [https://web.pcl.govt.nz/?ecn=\[REDACTED\]](https://web.pcl.govt.nz/?ecn=[REDACTED])

11:54:44 [https://web.pcl.govt.nz/?ecn=\[REDACTED\]](https://web.pcl.govt.nz/?ecn=[REDACTED])

11:54:45 [https://web.pcl.govt.nz/?ecn=\[REDACTED\]](https://web.pcl.govt.nz/?ecn=[REDACTED])

14:21:03 UNIT 'OTAH311' ALERT TIME '20200915203558NS' ADJUSTED TO '20200915203732NS' AT '

14:21:03 UNIT 'PARN255' ALERT TIME '20200915203541NS' ADJUSTED TO '20200915203737NS' AT '

14:21:03 UNIT 'VSOWAITEM1' ALERT TIME '20200915203402NS' ADJUSTED TO '20200915204712NS' A

14:21:03 UNIT 'AUCKOSU4' ALERT TIME '20200915203515NS' ADJUSTED TO '20200915210219NS' AT

14:21:03 UNIT 'AUCKOSU3' ALERT TIME '[NULL]' ADJUSTED TO '20200915232735NS' AT '17/09/202

14:21:43 UNIT 'OTAH311' ALERT TIME '20200915203558NS' ADJUSTED TO '20200915203732NS' AT '

14:21:43 UNIT 'PARN255' ALERT TIME '20200915203541NS' ADJUSTED TO '20200915203737NS' AT '

14:21:43 UNIT 'VSOWAITEM1' ALERT TIME '20200915203402NS' ADJUSTED TO '20200915204712NS' A

14:21:43 UNIT 'AUCKOSU4' ALERT TIME '20200915203515NS' ADJUSTED TO '20200915210319NS' AT

14:21:44 UNIT 'AUCKOSU3' ALERT TIME '[NULL]' ADJUSTED TO '20200915232735NS' AT '17/09/202

14:21:44 \*\* Assigned Result Code: STRU, Detailed Event Type: 1100

10:28:33

10:28:45 \*\* Event F3077307 has been reopened at: 16/10/20 10:28:45

10:28:46 \*\* LOI search completed at 16/10/20 10:28:46

10:30:36 \*\* Event held for 60 minutes

11:31:26 Unit EVENTNCC1 [ K7 : AT NORMAL STATION]

11:55:39 \*\* Assigned Result Code: STRU, Detailed Event Type: 1100

## Incident

**CAD Number** F3077307

**Incident Reporter** [REDACTED]

**Incident Controller**

Distance Travelled (km)

Delay In Receiving Call

**Property Details**

Occupant kinetic engineering

Building Owner

General Property Use Industrial, Manufacturing

Special Property Use Manufacture: Machinery, Engines, Parts

Purpose Group

**Actions**

Persons Reported  
Trapped

Evacuation Status Not occupied at time of incident

Action Prior 1

Action Prior 2

Action Taken Extinguishment, salvage and ventilation

**Civilians**

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	0

**Origin**

Location Office

Level 1st floor

**Equipment Used**

Quantity	Equipment
2	Hose reel, high pressure delivery
3	Low pressure delivery
2	Monitor
3	Aerial Ladder/Platform

**Equipment Involved**

Equipment Involved

Year

Make

**Model****Fire**

---

<b>Arrival Condition</b>	Large fire
<b>Heat Source</b>	Unable to classify
<b>Termination Stage</b>	
<b>First Object Ignited</b>	
<b>First Object Material</b>	
<b>Second Object Ignited</b>	
<b>Second Object Material</b>	
<b>Indicated Cause</b>	Unable to classify
<b>Certainty of Cause</b>	Medium
<b>Age of Person</b>	
<b>Ethnicity</b>	
<b>Gender</b>	
<b>FAIP Service Offered</b>	Unknown

**Alarms**

---

Type of Alarm	Smoke Detector/Security Alarm System
Initiating Call	
Performance of System	Alerted public - detector in room of origin
Failure/Ineffectiveness of system	Unable to classify
Number of sprinkler heads operated	

**Comments**

11/11/2020 12:50:24 PM

Reporter Comments

This was a large fire in a two story office/warehouse. The last person left the building at approximately 5.30pm, they locked up but didn't turn the lights off or set the alarm. The building was secure on Fire and Emergency arrival. The building was constructed of steel and timber framing with a long run iron roof and glass exterior in the upstairs office area.

Burn patterns to the warehouse and downstairs offices indicate fire and smoke spread from the office area upstairs. The offices upstairs displayed minor to severe fire damage. The offices were timber framing and glass. An open plan office space for the engineers was located in the centre of the floor in front of the central stairs

Burn patterns to the offices, cubicle's, stairs and filing area indicate fire spread from the engineer's office space.

The data room located in front of the engineer's area was examined, burn patterns in this area were consistent with fire spread at a high level and fuel loading.

The desks in the engineer's area were examined. Burn patterns to the desks against the walls indicate fire spread from the desk at the northern end of the space.

This desk contained a laptop, two screens and a multi-board. Parts of the metal bars of a multi-board were located in the debris in this area, I was unable to locate the rest of the bars of the board amid the debris. This could be an indication that the board had malfunctioned.

The lights in the upstairs offices were fluorescent tube lights and I was unable to locate the capacitors in the debris.

Due to the amount and severity of the fire damage I was unable to determine if the fire had originated in the ceiling space and dropped down into the engineering space or if it had originated on the desk top and spread upwards to the ceiling.

Therefore, based on the evidence available at the time of this investigation, the classification of this incident has been recorded as Accidental, and the cause Undetermined.

Photo's available in I drive.

Christine McGinty

11/16/2020 2:44:22 PM

Reporter Comments

FSO Requested at incident F3077307 on 15 Sep 2020

Christine McGinty