

SMS Incident Report

21/07/2021 12:04:16

Summary

CAD Number F3273709 **Status** Closed
Station Roslyn Station
Incident Started 29/06/2021 00:17:08 **Incident Ended** 30/06/2021 15:49:27
Incident Type 1101: Structure fire with damage
Common Name BELLEKNOWES GOLF CLUB
Address 3 Lawson Street Roslyn
Alarm Method 111 Telephone **Alarm Level** 2
PFA Number
Zone 362408
Map Grid E 1405028 **Map Grid N** 4917003
First Caller [REDACTED] **First Caller Contact** [REDACTED]
Incident Closed 30/06/2021 15:57:20
Report Completed 12:12, Fri 02 Jul 2021 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
ROSL241	P1	00:17:49 29 Jun 2021	00:21:15 29 Jun 2021	00:24:08 29 Jun 2021	14:23:25 30 Jun 2021
DUNE211	P1	00:17:51 29 Jun 2021	00:19:07 29 Jun 2021	00:24:45 29 Jun 2021	03:58:10 29 Jun 2021
STKI221	P1	00:28:39 29 Jun 2021	00:29:19 29 Jun 2021	00:29:20 29 Jun 2021	08:42:33 29 Jun 2021
LOOK237	PR	00:28:41 29 Jun 2021	00:31:21 29 Jun 2021	00:40:19 29 Jun 2021	07:07:13 29 Jun 2021
DUNE2126	SU	01:11:45 29 Jun 2021	01:11:57 29 Jun 2021	01:19:32 29 Jun 2021	03:57:26 29 Jun 2021
FIOTAGO4	FSO	01:00:20 29 Jun 2021	01:13:38 29 Jun 2021	01:31:46 29 Jun 2021	15:51:55 30 Jun 2021
DUNE212	P2	03:14:31 29 Jun 2021	03:14:50 29 Jun 2021	03:24:38 29 Jun 2021	04:35:31 29 Jun 2021
WILL257	PR	04:10:22 29 Jun 2021	04:10:38 29 Jun 2021	04:14:32 29 Jun 2021	06:06:37 29 Jun 2021
DUNE2118	CUHU	10:29:41 29 Jun 2021	10:29:42 29 Jun 2021	10:41:25 29 Jun 2021	15:53:21 29 Jun 2021
DUNE216	TL				10:37:00 29 Jun 2021
EVENTSCC2	OT				09:38:24 30 Jun 2021

29 Jun 2021	01:40:29	REGION 5 EXEC
29 Jun 2021	01:42:07	██████████ REGION 5 EXEC ACK PAGE
29 Jun 2021	01:42:58	NATIONAL COMANDERS GROUP
29 Jun 2021	01:45:34	██████████ NATIONAL COMANDERS GROUP ACK PAGE
29 Jun 2021	01:45:40	HSO REGION 5

Message Log

Time	Message
00:17:31	https://web.pcl.govt.nz/?ecn=██████████
00:17:31	INC INFO: BUILDING FIRE
00:17:33	** LOI search completed at 29/06/21 00:17:32
00:17:44	** Recommended unit ROSL241 for requirement PUMP (>1.0 km)
00:17:44	** Recommended unit DUNE211 for requirement PUMP (>1.7 km)
00:17:47	PA Selcal used to Initiate Alerting. (ROSL241 at 3624 ROSLYN 195241)
00:17:47	PA Selcal used to Initiate Alerting. (DUNE211 at 3621 DUNEDIN 195211)
00:17:49	ALERTING_COMPLETED ROSL241
00:17:51	ALERTING_COMPLETED DUNE211
00:17:54	.
00:18:09	██████████ - BUILDING WELL ABLAZE
00:18:11	-
00:18:34	Zone 362408 - Roslyn - BFLW24
00:19:07	Unit DUNE211 [K1 : PROCEEDING TO INCIDENT]
00:19:45	Unit DUNE211 [COMCEN COM : MESSAGE] MULTIPLE CALLS INDICATING FULLY INVOLVED POW
00:19:45	ER HAVE BEEN NOTIFIED
00:19:58	Unit DUNE211 [SITREP :] COPY
00:19:58	Unit ROSL241 [SITREP :] COPY
00:20:48	-
00:21:15	Unit ROSL241 [K1 : PROCEEDING TO INCIDENT]
00:21:35	Unit ROSL241 [K1 : PROCEEDING TO INCIDENT]
00:22:38	Unit ROSL241 [SITREP :] LET OTHER APPLIANCES KNOW WE HAVE 2 INCHES OF SNOW UP
00:22:38	AT HIGHGATE
00:22:44	Unit DUNE211 [SITREP :] COPY
00:24:00	Unit DUNE211 [COMCEN COM : MESSAGE] 2 HYDRANTS 150ML ONE OUTSIDE THE GOLF CLUB TH
00:24:00	Unit ROSL241 [COMCEN COM : MESSAGE] 2 HYDRANTS 150ML ONE OUTSIDE THE GOLF CLUB TH
00:24:00	E OTHER OUTSIE 10 LAWSON
00:24:00	E OTHER OUTSIE 10 LAWSON

00:24:08 PROCEEDING

00:24:08 Unit ROSL241 [K99 : PROPERTY FIRE WELL INVOLVED] PROCEEDING

00:24:13 Unit DUNE211 [SITREP :] COPY

00:24:40 Unit ROSL241 [K99 : PROPERTY FIRE WELL INVOLVED]

00:24:45 Unit DUNE211 [K2 : IN ATTENDANCE AT INCIDENT]

00:26:11 Unit ROSL241 [KP : PRIORITY MESSAGE]

00:27:08 Unit ROSL241 [KP : PRIORITY MESSAGE] TX 2ND ALARM 1 2 STORY BUILDING WELL IN SP

00:27:08 READING TO HEDGE WE DO HAVE EXPOSURES SFP LAWSON STREET REAR OF APPLIANCE

00:27:23 ** Alarm level updated to 2

00:27:23 ** Recommended unit WILL257 for requirement PUMP (>2.9 km)

00:27:23 ** Recommended unit
LOOK237 for requirement PUMP (>3.1 km)

00:27:27 .

00:27:40 FIR2AMB - FYI - NOTIFICATION ONLY - 2ND

00:27:44 ALARM BUILDING FIRE

00:27:45 .

00:28:36 MSU Selcal used to Initiate Alerting. (STKI221 D918F2)

00:28:36 PA Selcal used to Initiate Alerting. (LOOK237 at 3623 LOOKOUT POINT 195231)

00:28:39 ALERTING_COMPLETED STKI221

00:28:41 ALERTING_COMPLETED LOOK237

00:28:55 -

00:29:08 AMBO EVENT 0005-3-2021/06/29-FIR LINKED AT 29/06/2021 00:29:08

00:29:20 Unit STKI221 [K55 : SPECIAL SERVICE INCIDENT]

00:30:04 Unit STKI221 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

00:30:11 Unit STKI221 [K1 : PROCEEDING TO INCIDENT]

00:30:25 Radio used to Initiate Alerting.

00:30:26 ALERTING_COMPLETED STKI221

00:30:31 Unit STKI221 [K1 : PROCEEDING TO INCIDENT]

00:31:10 Unit ROSL241 [KC : UNIT CALLING]

00:31:22 Unit LOOK237 [K1 : PROCEEDING TO INCIDENT]

00:31:49 Unit ROSL241 [SITREP :] HAVE POWER BEEN NOTIFIED? (AFFIRM PRIOR TO K99)

00:32:40 Unit LOOK237 [COMCEN COM : MESSAGE] SFP BEHIND APPLIANCE ON LAWSON ST

00:32:41 Unit STKI221 [COMCEN COM : MESSAGE] SFP BEHIND APPLIANCE ON LAWSON ST

00:33:37 -

00:34:38 Unit ROSL241 [KC : UNIT CALLING]

00:35:29 Unit STKI221 [KC : UNIT CALLING]

00:35:49 Unit ROSL241 [SITREP :] SO [REDACTED] - ONE 2 STORY BUILDING FULL INV APPROX 300SQM

00:35:49 2 CREWS EXTERNAL ATTACK AND EXPOSURE PROTECT OF HEDGE AND NEIGHBOURING BOWLING

00:35:49 CLUB

00:36:13 Unit STKI221 [SITREP :] CONFIRM WHAT ALARM LEVEL WE ARE CURRENTLY AT?
(2ND ALA

00:36:13 RM)

00:36:52 SSO [REDACTED] UPDATED

00:39:21 -

00:40:20 Unit LOOK237 [K2 : IN ATTENDANCE AT INCIDENT]

00:43:01 Unit STKI221 [K2 : IN ATTENDANCE AT INCIDENT]

00:46:07 ** Cross Referenced to Event # F3273712 at: 29/06/21 00:46:07

00:48:02 Unit ROSL241 [KC : UNIT CALLING]

00:48:10 -

00:49:14 Unit ROSL241 [SITREP :] PARTIAL BUILDING COLLAPSE CREWS ATWW EXPOSURE 3
DELIVE

00:49:14 RIES IN USE IN DEFENSIVE MODE

00:52:48 Unit ROSL241 [KC : UNIT CALLING]

00:53:04 Unit STKI221 [K2 : IN ATTENDANCE AT INCIDENT]

00:53:22 Unit ROSL241 [K11F : FIRE RISK MANAGEMENT REQUIRED]

00:54:25 Unit STKI221 [KC : UNIT CALLING]

00:56:28 Unit STKI221 [K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] - SSO
[REDACTED]

00:56:28 [REDACTED] SECTOR 1 SO [REDACTED] SECTOR 3 SO [REDACTED] SECTION EXPOSURE PROTECTION
SFF [REDACTED]

00:56:28 - SAFETY SO [REDACTED] MULTIPLE LPD AND GROUND MONITORS EXTERNAL FIRE
ATTACK

01:00:19 Pager used to Initiate Alerting.

01:00:20 ALERTING_COMPLETED FIOTAGO4

01:05:00 \

01:05:11 Alarm Timer Extended: 0

01:05:12 Alarm Timer Extended: 0

01:07:58 Unit ROSL241 [SITREP :] SO [REDACTED] - FIRE IS IN THE RROM CONTAINED NO FURTHER
RE

01:07:58 SOURCES REQUIRERD AT THIS STAGE

01:11:34 PA Selcal used to Initiate Alerting. (DUNE2126 at 3621 DUNEDIN 195211)

01:11:44 Unit DUNE2126 failed to contact via Selcal

01:11:45 ALERTING_COMPLETED DUNE2126

01:11:57 Unit DUNE2126 [K1 : PROCEEDING TO INCIDENT]

01:13:38 Unit FIOTAGO4 [K1 : PROCEEDING TO INCIDENT]

01:18:51 Unit ROSL241 [KC : UNIT CALLING]

01:19:33 Unit DUNE2126 [K2 : IN ATTENDANCE AT INCIDENT]

01:19:44 Unit ROSL241 [K11A : AMBULANCE REQUIRED] FOR STANDBY DUE TO HIGH WINDS
AND DEVR

01:19:44 IS FLYING

01:19:55 FIR2AMB REQUESTING YOU STANDBY ON SCENE HERE DUE TO HIGH WINDS AND
DEBRIS FLYING

03:42:12 Unit FIOTAGO4 [SITREP :] RELEASED FROM SCENE LIKELY TO RETURN TOMORROW TO FURT

03:42:12 HER PLAN INV DEPENDING ON WEATHER

03:42:37 Unit FIOTAGO4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

03:57:27 Unit DUNE2126 [K7 : AT NORMAL STATION]

03:57:45 Unit DUNE211 [KC : UNIT CALLING]

03:58:11 Unit DUNE211 [K10 : RE-COMMISSIONING APPLIANCE]

04:05:35 Alarm Timer Extended: 0

04:10:21 Phone used to Initiate Alerting.

04:10:22 ALERTING_COMPLETED WILL257

04:10:31 Unit WILL257 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]

04:10:36 Unit WILL257 [K39-1 : TRANSMIT K1]

04:10:38 Unit WILL257 [K1 : PROCEEDING TO INCIDENT]

04:13:45 AL: PAGING ACK TIMED OUT FOR STATION: 3625 at 06-29-21 04:13:45

04:14:32 Unit WILL257 [K2 : IN ATTENDANCE AT INCIDENT]

04:15:07 Unit ROSL241 [KC : UNIT CALLING]

04:15:35 Unit ROSL241 [SITREP :] RETURNING TO DUNEDIN CITY STATION TO GET SOME MORE HOS

04:15:35 E

04:15:41 Unit ROSL241 [K10 : RE-COMMISSIONING APPLIANCE]

04:16:02 Unit STKI221 [KC : UNIT CALLING]

04:16:28 Unit STKI221 [K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SO [REDACTED] ON

04:16:28 DUNE212

04:16:34 Unit STKI221 [K10 : RE-COMMISSIONING APPLIANCE]

04:35:32 Unit DUNE212 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

04:35:33 Unit DUNE212 [K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SO [REDACTED]

04:55:45 Alarm Timer Extended: 0

05:49:54 Unit LOOK237 [K1 : PROCEEDING TO INCIDENT]

05:57:33 Unit LOOK237 [K2 : IN ATTENDANCE AT INCIDENT]

06:06:37 Unit WILL257 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

06:13:37 Unit LOOK237 [KC : UNIT CALLING]

06:14:01 Unit LOOK237 [K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SO [REDACTED]

06:51:03 Alarm Timer Extended: 0

06:54:30 Unit STKI221 [K2 : IN ATTENDANCE AT INCIDENT]

07:06:46 Unit STKI221 [KC : UNIT CALLING]

07:07:14 Unit LOOK237 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

07:07:48 Unit STKI221 [K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SSO [REDACTED]

08:03:21 Alarm Timer Extended: 0

08:20:42 Unit ROSL241 [K2 : IN ATTENDANCE AT INCIDENT]

08:41:37 Unit STKI221 [KC : UNIT CALLING]

08:42:26 Unit STKI221 [K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] FM SSO [REDACTED]

08:42:26 [REDACTED] TO SO [REDACTED] ROSL241

08:42:33 Unit STKI221 [K10 : RE-COMMISSIONING APPLIANCE]

09:02:49 Alarm Timer Extended: 0

09:33:58 Unit FIOTAGO4 [K1 : PROCEEDING TO INCIDENT]

09:38:19 Unit ROSL241 [KC : UNIT CALLING]

09:39:12 Unit ROSL241 [SITREP :] MONITORING SITUATION - AWAITING FI (FIOTAGO4 HAS BEEN

09:39:12 K1 FOR 5 MIN)

09:41:10 Unit FIOTAGO4 [K2 : IN ATTENDANCE AT INCIDENT]

10:17:51 Unit ROSL241 [KC : UNIT CALLING]

10:18:41 Unit ROSL241 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

10:18:57 Unit ROSL241 [K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] FIOTAGO4 [REDACTED]

10:18:57 [REDACTED]

10:23:42 Alarm Timer Extended: 0

10:29:42 Unit DUNE2118 [K1 : PROCEEDING TO INCIDENT]

10:37:01 Unit DUNE216 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

10:41:25 Unit DUNE2118 [K2 : IN ATTENDANCE AT INCIDENT]

10:41:41 Unit DUNE2118 [K2 : IN ATTENDANCE AT INCIDENT]

11:23:23 Alarm Timer Extended: 0

12:44:45 Unit FIOTAGO4 [KC : UNIT CALLING]

12:45:10 Unit FIOTAGO4 [K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]

15:51:08 Unit FIOTAGO4 [SITREP :] (BY PHONE) HAVE A DIGGER HERE, MAKING SCENE SAFE, PIC

15:51:08 KING AWAY SOME OBSTACLES AROUND THE AREA OF ORIGIN, I AM SUPERVISING THAT, LEAVE

15:51:08 THE EVENT OPEN TONIGHT AND I"LL BE RETURNING IN THE MORNING 30/06, I"LL CALL YO

15:51:08 U WHEN I"M LEAVING SCENE TONIGHT

15:53:22 Unit DUNE2118 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

16:31:52 Unit FIOTAGO4 [KC : UNIT CALLING]

16:32:49 Unit FIOTAGO4 [SITREP :] CLEAR OF THE SCENE RETURNING TO DUNEDIN STATION TO RE

16:32:49 COMMISSION WE WILL BE RETURNING TO THE SITE TOMORROW

17:17:05 Unit FIOTAGO4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

09:31:22 Unit FIOTAGO4 [K1 : PROCEEDING TO INCIDENT]

09:40:46 Unit FIOTAGO4 [K2 : IN ATTENDANCE AT INCIDENT]

10:22:47 Alarm Timer Extended: 0

13:33:10 Unit ROSL241 [K2 : IN ATTENDANCE AT INCIDENT]

13:33:44 Unit ROSL241 [SITREP :] ASSISTING FIRE SAFETY

14:14:00	Alarm Timer Extended: 0
14:14:22	ROSL241 HOOKED INTO HYDRANT, AVAILABLE FOR GREATER ALARMS
14:14:23	.
14:23:01	Unit ROSL241 [KC : UNIT CALLING]
14:23:25	Unit ROSL241 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
15:47:46	Unit FIOTAGO4 [KC : UNIT CALLING]
15:49:16	Unit FIOTAGO4 [SITREP :] SCENE EXAMINATION COMPLETE, LEFT IN HANDS OF THE CLUB
15:49:16	MEMBERS REP
15:49:27	Unit FIOTAGO4 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM SITREP]
15:51:56	Unit FIOTAGO4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
15:57:15	UNIT STKI221 RESPONSE TIME [NULL] ADJUSTED TO 20210629002919NS AT 30/06/2021 15:
15:57:19	UNIT 'DUNE2118' ALERT TIME '[NULL]' ADJUSTED TO '20210629102941NS' AT '30/06/202
15:57:19	** Assigned Result Code: STRU, Detailed Event Type: 1100

Incident

CAD Number F3273709
Incident Reporter XXXXXXXXXX
Incident Controller
Distance Travelled (km)
Delay In Receiving Call

Property Details

Occupant Golf club
Building Owner
General Property Use Sports club, Health club
Special Property Use Sportsclub with restaurant
Purpose Group

Actions

Persons Reported Trapped
Evacuation Status Not occupied at time of incident
Action Prior 1
Action Prior 2
Action Taken Extinguishment only: Includes isolating fuel/power

Civilians

Civilians Rescued

0

Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	0

Origin

Location	Unable to classify
Level	Ground level

Equipment Used

Quantity	Equipment
4	Low pressure delivery
2	Monitor
1	Equipment Not Listed

Equipment Involved

Equipment Involved

Year

Make

Model

Fire

Arrival Condition	Totally involved fire
Heat Source	Unable to classify
Termination Stage	
First Object Ignited	
First Object Material	
Second Object Ignited	
Second Object Material	
Indicated Cause	Undetermined
Certainty of Cause	High
Age of Person	
Ethnicity	
Gender	
FAIP Service Offered	Unknown

Comments

7/2/2021 12:12:45 PM

Reporter Comments

K99 on arrival well involved.
Multiple deliveries and two monitors used in an external defensive fire attack only.
Forced entry into basement to protect contents with the use of a monitor.
Fire Safety called and all relevant details passed on to [REDACTED] at time of incident.
Power authority isolated power just after arrival.
No signs of break in on arrival.
Strong wind with snow and hail during incident.

[REDACTED]

Released under the Official Information Act 1982