

Moana Wyatt

From: Richard Hopkins
Sent: Tuesday, 12 October 2021 11:47 AM
To: Torrey McDonnell
Subject: FW: titahi bay surf club
Attachments: MHWS_Titahi Bay.pdf

Hi Torrey,
Sending to save the advice recently.
As per our discussion on MHWS the Titahi Bay example.

Ngā mihi,

[Richard Hopkins](#)

Team Leader Monitoring and Enforcement
Kaiārahi Rōpū Aroturuki me te Whakaūnga

[porirucity](#)

Tel: 04 237 5089
porirucity.govt.nz

From: Iain Dawe <Iain.Dawe@gw.govt.nz>
Sent: Wednesday, 9 October 2019 3:51 PM
To: Richard Hopkins <Richard.Hopkins@porirucity.govt.nz>
Cc: Jo Frances <Jo.Frances@gw.govt.nz>; Nicola Fenn <Nicola.Fenn@gw.govt.nz>
Subject: RE: titahi bay surf club

Thanks Richard,

The wall appears to exceed its old footprint and could be considered reclamation and seems to have quite a bit of associated disturbance.

Attached is a map showing the approx. MHWS. The 'sea-fence' may be just above this or right on the line, depending on the state of the beach

Ngā mihi
Iain

Dr Iain Dawe | Senior Policy Advisor (Hazards)
Greater Wellington Regional Council | *Te Pane Matua Taiao*