


Case Summary Report

Case #:	200603/9658			
Current Assignment Offences	Filed, t: Waikato District HQ		Assigned:	15/10/2021 08:02:39
			_	niorn.
			KiCial	
Date/Time:			Reported	:
Location:	(Outside)	First Name	let the	
Persons		at No	, see	
Gender	Family Or Nickname	First Name	Birth Date	Age Links
		at the state of th		
				• =
Narrative				
ji do adil				











Created by MTM832 22/06/2020 11:45

Traffic Crash Occurred Date/Time: 03/06/2020 21:30

WHAT HAPPENED
Officer Notes:
Stolen vehicle observed by police travelling on Stan Heather Drive near Deanwell Avenue.
Attempt made to stop the vehicle by activating lights and sirens. Vehicle failed to stop and accelerated, turning onto Deanwell Avenue towards Joanna Place.
Vehicle then turned onto Joanna Place before turning into Anderson road.
Continued for a short distance on Anderson road before attempting to negotiate a sharp left hand
corner.
Vehicle crossed the centreline, colliding with vehicle parked on the opposite side of the road
outside number .
Offending vehicle then struck a concrete retaining wall at the front of the property at number
before travelling approximately a further 10 metres and colliding with a power pole and coming to a
stop. Extensive damage to both vehicles as a result of the crash. Very minor damage to the power pole.
No persons in vehicle at the time of the crash and both the driver and passenger of vehicle
located and arrested by police.
· KA
Objects Hit:
Car vs parked car, concrete wall and power pole
our va parked our, corrorete warrand power pole
WHY CRASH HAPPENED
Road & Roadside Factors:
Dead auto- auto- at the state of the search Hallman is the contributed to be a state of a search of
Road surface wet at the time of the crash. Unknown if this contributed to loss of control as there were no obvious said marks located.
there were no obvious sand marks located.
Road User Factors:
Driver driving recklessly in an attempt to flee police Prior to crash vehicle was observed driving
over the top of the small roundabout at the intersection of Deanwell Ave and Joanna Place.
<u> </u>
Vehicle Factors:
?
N/a
Speed Factors:
Main contributor. Driver of vehicle attempting to evade police.
Speed too great to safely negotiate 90 degree corner.
Environmental Costore:
Environmental Factors:

