

SMS Incident Report

20/04/2022 10:01:19

Summary

CAD Number F3464967 **Status** Closed

Station Christchurch City Station

Incident Started 17/04/2022 11:28:09 **Incident Ended** 17/04/2022 14:22:06

Incident Type 1101: Structure fire with damage

Common Name SOUTHERN CROSS HOSPITAL CHRISTCHURCH

Address 131 Bealey Avenue Christchurch Central

Alarm Method Sprinkler PFA Call **Alarm Level** 1

PFA Number 511283

Zone 34210305

Map Grid E 1570484 **Map Grid N** 5181351


First Caller **First Caller Contact**

Incident Closed 17/04/2022 16:27:17

Report Completed 14:39, Sun 17 Apr 2022 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
CHRI217	PR	11:28:41 17 Apr 2022	11:30:21 17 Apr 2022	11:34:31 17 Apr 2022	13:36:22 17 Apr 2022
CHRI214	PM	11:28:41 17 Apr 2022	11:30:36 17 Apr 2022	11:35:15 17 Apr 2022	
SPRE221	P1	11:28:28 17 Apr 2022	11:30:00 17 Apr 2022	11:36:48 17 Apr 2022	11:47:51 17 Apr 2022
WOOL241	P1	12:13:41 17 Apr 2022	12:16:02 17 Apr 2022	12:27:30 17 Apr 2022	13:40:45 17 Apr 2022
CHRI2116	HU	12:13:42 17 Apr 2022	12:20:50 17 Apr 2022	13:06:16 17 Apr 2022	13:58:32 17 Apr 2022



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
CHRI217	00:00:32	00:05:50	00:06:22	02:08:13
CHRI214	00:00:32	00:06:34	00:07:06	
SPRE221	00:00:19	00:08:20	00:08:39	00:19:42
WOOL241	00:45:32	00:13:49	00:59:21	02:12:36
CHRI2116	00:45:33	00:52:34	01:38:07	02:30:23

Notifications

Date	Time	Party Notified
17 Apr 2022	11:44:24	ADT
17 Apr 2022	11:52:20	0800FPISNZ - DOES NOT CONNECT
17 Apr 2022	11:54:26	FIRE PROTECTION INSPECTION SERVICES - NO ANSWER - NO OTHER CONTACT
17 Apr 2022	13:27:14	PAGED FICANTE02 (██████████)
17 Apr 2022	13:33:52	FI ██████ ACK PAGE - PUT THRU TO CHRI217
17 Apr 2022	13:36:50	FI ██████ IS NOT RESPONDING HAPPY WITH CAUSE

Message Log

Time	Message
11:28:09	AL: 511283 11:28:08 INITIAL - ALARM
11:28:09	PANEL: SPRINKLER ROOM
11:28:09	** LOI search completed at 17/04/22 11:28:09
11:28:13	** PFA/CPN search completed
11:28:16	ACCESS NO CURRENT: -
11:28:21	** Recommended unit CHRI217 for requirement PUMP (>1.9 km)
11:28:21	** Recommended unit
11:28:21	CHRI214 for requirement PUMP (>1.9 km)
11:28:21	** Recommended unit SPRE221 for requirement PUMP (>4.1 km)
11:28:24	PA Selcal used to Initiate Alerting. (CHRI217 at 3421 CHRISTCHURCH 193211)
11:28:24	PA Selcal used to Initiate Alerting. (CHRI214 at 3421 CHRISTCHURCH 193211)
11:28:25	MSU Selcal used to Initiate Alerting. (SPRE221 D9FE32)
11:28:28	ALERTING_COMPLETED SPRE221
11:28:41	ALERTING_COMPLETED CHRI217
11:28:41	ALERTING_COMPLETED CHRI214
11:30:00	Unit SPRE221 [K1 : PROCEEDING TO INCIDENT]
11:30:21	Unit CHRI217 [K1 : PROCEEDING TO INCIDENT]
11:30:36	Unit CHRI214 [K1 : PROCEEDING TO INCIDENT]
11:31:15	***

11:31:20 NSOF OR FIRE

11:32:05 PANEL IS SHOWING SPRINKLER ACTIVATION ... BUT NO ZONE

11:32:39 CAN NOT CONFIRM IF SPRINKLER HAS PHYSICALLY ACTIVATED

11:32:58 Unit CHRI214 [SITREP :] FURTHER INFO PASSED

11:32:59 Unit CHRI217 [SITREP :] FURTHER INFO PASSED

11:32:59 Unit SPRE221 [SITREP :] FURTHER INFO PASSED

11:34:31 Unit CHRI217 [K77 : NOTHING SHOWING]

11:34:57 Unit CHRI217 [KC : UNIT CALLING]

11:35:15 Unit CHRI214 [K2 : IN ATTENDANCE AT INCIDENT]

11:35:26 Unit CHRI217 [SITREP :] SPRINKLER GONG ACTIVATED - INV

11:36:48 Unit SPRE221 [K2 : IN ATTENDANCE AT INCIDENT]

11:43:04 Unit CHRI217 [KC : UNIT CALLING]

11:44:02 ** PFA/CPN search completed

11:44:27 Unit CHRI217 [SITREP :] DO WE HAVE FIRE PROTECTION SERVICES RESPONDING TO THIS

11:44:27 CALL

11:47:52 Unit SPRE221 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

11:50:15 Unit CHRI217 [COMCEN COM : MESSAGE] VIA PHONE - DO YOU HAVE A NUMBER FOR FPS? [0

11:50:15 800FPISNZ}

11:56:06 **

11:56:15 Unit CHRI217 [COMCEN COM : MESSAGE] WE HAVE BEEN UNABLE TO CONTACT ANYONE RE YOU

11:56:15 R QUERY (CHUBB SECURITY HAS JUST ARRIVED)

11:56:25 ADT ADVISE TECH HAS ARRIVED

12:09:25 Unit CHRI217 [KC : UNIT CALLING]

12:10:17 Unit CHRI217 [SITREP :] SO [REDACTED] - SWITCHBOARD FIRE HAS MELTED WATER PIPE CA

12:10:17 USEING LARGE FLOODING

12:11:35 Unit CHRI214 [KC : UNIT CALLING]

12:12:08 Unit CHRI214 [SITREP :] MAKE SALVAGE TENDER 1

12:13:38 PA Selcal used to Initiate Alerting. (WOOL241 at 3424 WOOLSTON 193241)

12:13:38 PA Selcal used to Initiate Alerting. (CHRI2116 at 3424 WOOLSTON 193241)

12:13:41 ALERTING_COMPLETED WOOL241

12:13:42 ALERTING_COMPLETED CHRI2116

12:16:02 Unit WOOL241 [K1 : PROCEEDING TO INCIDENT]

12:17:05 Alarm Timer Extended: 0

12:17:06 Alarm Timer Extended: 0

12:20:50 Unit CHRI2116 [K1 : PROCEEDING TO INCIDENT]

12:27:30 Unit WOOL241 [K2 : IN ATTENDANCE AT INCIDENT]

13:06:16 Unit CHRI2116 [K2 : IN ATTENDANCE AT INCIDENT]

13:08:32 Alarm Timer Extended: 0

13:25:29	Unit CHRI217 [KC : UNIT CALLING]
13:25:55	Unit CHRI217 [K11F : FIRE RISK MANAGEMENT REQUIRED]
13:29:01	Unit CHRI217 [KC : UNIT CALLING]
13:30:02	Unit CHRI217 [SITREP :] DO YOU HAVE ETA OF FIRE SAFETY (WE HAVE ONLY JUST PAGE
13:30:02	D [REDACTED]
13:33:21	Unit CHRI214 [KC : UNIT CALLING]
13:35:55	Unit CHRI217 [KC : UNIT CALLING]
13:36:23	Unit CHRI217 [K10 : RE-COMMISSIONING APPLIANCE]
13:36:35	Unit CHRI214 [K10 : RE-COMMISSIONING APPLIANCE]
13:39:38	Unit WOOL241 [KC : UNIT CALLING]
13:40:16	Unit WOOL241 [SITREP :] WE ARE RETURNING TO WOOLSTON
13:40:45	Preempt Unit WOOL241
13:47:28	Unit WOOL241 [SITREP :] SSO [REDACTED] SMELL OF GAS APPEARS TO BE COMING FROM CYLI
13:47:28	NDERS ATTACHED TO CARAVAN
13:48:13	Alarm Timer Extended: 0
13:58:32	Unit CHRI2116 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
14:22:06	Unit CHRI217 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM SITREP] - MANUAL TIME
14:22:06	ENTERED 17/04/22 14:21:47
16:27:17	** Assigned Result Code: SPRNKLR, Detailed Event Type: 1100

Incident

CAD Number F3464967
Incident Reporter [REDACTED]
Incident Controller
Distance Travelled (km)
Delay In Receiving Call

Property Details

Occupant [REDACTED]
Building Owner Owner occupied
General Property Use Hospital, Hospice, Rest home, Rehab centre
Special Property Use General hospital: Public and private
Purpose Group

Actions

Persons Reported Trapped
Evacuation Status Not occupied at time of incident

Action Prior 1

Action Prior 2

Action Taken Extinguishment, salvage and ventilation

Civilians

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	0

Origin

Location Wall assembly: Concealed wall space
 Level 2nd floor

Equipment Used

Quantity	Equipment
1	Hose reel, high pressure delivery
1	Low pressure delivery

Equipment Involved

Equipment Involved
 Year 2000
 Make unknown
 Model unknown

Fire

Arrival Condition Out on arrival
 Heat Source Heat from electrical equip: Defective or faulty
 Termination Stage
 First Object Ignited
 First Object Material
 Second Object Ignited
 Second Object Material
 Indicated Cause Short circuit, earth fault
 Certainty of Cause High
 Age of Person Unknown
 Ethnicity Unknown
 Gender ████

FAIP Service Offered Unknown

Alarms

Type of Alarm	Sprinkler
Initiating Call	
Performance of System	Detector in Room operated AND was EFFECTIVE
Failure/Ineffectiveness of system	
Number of sprinkler heads operated	2

Comments

4/17/2022 2:39:06 PM Reporter Comments

fire started from fuse box/switching gear used in relation to MRI and SCAN machine.
 overheating inside fuse board/switching gear has heated and in turn set fire to plywood of surrounding wall area.
 both sprinkler heads and melted plastic water pipe ,held the fire to extinguish flame,but still smouldering and burning were taking place in roof salvage

[Redacted]

4/20/2022 7:14:49 AM Reporter Comments

[Redacted]

[Redacted]

Released Under the Official Information Act