

SMS Incident Report


02/06/2017 11:56:14

Summary

CAD Number F2308064 **Status** Closed
Station Otara Station
Incident Started 16/05/2017 12:42:13 **Incident Ended** 16/05/2017 17:28:06
Incident Type 1101: Structure fire with damage
Common Name
Address / 43 Tyrone Street Otara
Alarm Method 111 Telephone **Alarm Level** 1
PFA Number
Zone 143307
Map Grid E 1767690 **Map Grid N** 5908945
First Caller **First Caller Contact** ██████████
Incident Closed 16/05/2017 17:28:06
Report Completed 19:0, Fri 19 May 2017 by T Liavaa

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
OTAR331	P1	12:43:44 16 May 2017	12:44:43 16 May 2017	12:46:43 16 May 2017	16:12:04 16 May 2017
OTAH311	P1	12:43:48 16 May 2017	12:44:59 16 May 2017	12:53:07 16 May 2017	14:14:49 16 May 2017
FICOUNT2	FSO	13:04:31 16 May 2017	13:06:04 16 May 2017	13:15:12 16 May 2017	16:57:38 16 May 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
OTAR331	00:01:31	00:02:59	00:04:30	03:29:51
OTAH311	00:01:35	00:09:19	00:10:54	01:32:36
FICOUNT2	00:22:18	00:10:41	00:32:59	04:15:25

Notifications

Date	Time	Party Notified
16 May 2017	13:00:09	VECTOR
16 May 2017	13:23:54	HOUSING NZ
16 May 2017	13:30:09	HOUSING NZ - DETAILS PASSED - THEY WILL PHONE BACK RE ETA

Message Log

Time	Message
12:43:05	INC INFO: HOUSE FIRE
12:43:06	** LOI search completed at 16/05/17 12:43:06
12:43:24	** Event Location changed from "43A TYRONE ST,OTARA,AUCKLAND" to "43 TYRONE
12:43:24	ST,OTARA,AUCKLAND" at: 16/05/17 12:43:24
12:43:26	** LOI search completed at 16/05/17 12:43:26
12:43:34	** Recommended unit OTAR331 for requirement PUMP (>0.8 km)
12:43:34	** Recommended unit OTAH311 for requirement PUMP (>4.1 km)
12:43:45	LAWN MOWER ON FIRE NEXT TO HOUSE
12:43:46	..
12:43:57	ASSRESS GIVEN AS 43A TYRONE ST
12:43:59	..
12:44:18	INC INFO: SMOKE IN VICINITY
12:44:18	Duplicate Event:Location = TYRONE ST,OTARA,AUCKLAND, Type = STRU - STRUCTURE
12:44:18	FIRE, Caller Ph Number = [REDACTED], Call Source = 111Inc InfoSMOKE IN VICINITY
12:44:18	, Event Source = Fire 111
12:44:18	End of Duplicate Event data
12:44:43	Unit OTAR331 [K1 : PROCEEDING TO INCIDENT]
12:44:56	INC INFO: HOUSE FIRE
12:44:56	Duplicate Event:Location = 43 TYRONE ST,OTARA,AUCKLAND, Type = STRU - STRUCTURE
12:44:56	FIRE, Caller Ph Number = [REDACTED], Call Source = 111Inc InfoHOUSE FIRE, Event
12:44:56	Source = Fire 111
12:44:56	End of Duplicate Event data
12:44:59	FIRST CALLER SAID HE THINK THE LAWN MOWER CAUGHT ON FIRE, AND IS UP AGAINST THE
12:44:59	Unit OTAH311 [K1 : PROCEEDING TO INCIDENT]
12:44:59	HOUSE
12:45:12	T3 TAKING SITREP F230 8051
12:46:04	Duplicate Event:Location = TYRONE ST,OTARA,AUCKLAND, Type = MIN - MINOR, Caller
12:46:04	INC INFO: SMOKE IN VICINITY
12:46:04	Name = VODAFONE NEW ZEALAND LTD, Caller Ph Number = [REDACTED], Caller Address =
12:46:04	[REDACTED] STREET, OTARA, AUCKLAND CITY, Call Source = 111Inc InfoSMOKE IN VICINITY
12:46:04	, Event Source = Fire 111

12:46:04	End of Duplicate Event data
12:46:43	Unit OTAR331 [K99 : PROPERTY FIRE WELL INV]
12:47:29	Unit OTAR331 [K99 : PROPERTY FIRE WELL INV]
12:48:01	Unit OTAR331 [COMCEN COM : MESSAGE] FURTHER DETAILS PASSED
12:50:21	Duplicate Event:Location = TYRONE ST,OTARA,AUCKLAND, Type = MIN - MINOR, Caller
12:50:21	INC INFO: HOUSE FIRE
12:50:21	Name = HYNDS LIMITED, Caller Ph Number = [REDACTED], Caller Address = TELECOM
12:50:21	CELLULAR 027, OAMARU, WAITAKI DISTRICT, Call Source = 111Inc InfoHOUSE FIRE,
12:50:21	Event Source = Fire 111
12:50:21	End of Duplicate Event data
12:51:07	Duplicate Event:Location = TYRONE ST,OTARA,AUCKLAND, Type = MIN - MINOR, Caller
12:51:07	Name = AUCKLAND KINDERGARTEN ASSOCIATION, Caller Ph Number = [REDACTED], Caller
12:51:07	Address = [REDACTED] BAKER DRIVE, OTARA, AUCKLAND CITY, Call Source = 111Inc
12:51:07	InfoSMOKE IN THE VICINITY OF, Event Source = Fire 111
12:51:08	INC INFO: SMOKE IN THE VICINITY OF
12:51:08	End of Duplicate Event data
12:51:54	Unit OTAR331 [KC : UNIT CALLING]
12:53:08	Unit OTAH311 [K2 : IN ATTENDANCE AT INCIDENT]
12:53:19	Unit OTAR331 [SITREP :] SSO WRIGHT 1 HOUSE INVOLVED IN FIRE 1HPD, ALL PERSONS
12:53:19	ACCOUNTED FOR
12:55:23	INC INFO: SMOKE IN VICINITY
12:55:23	Duplicate Event:Location = TYRONE ST,OTARA,AUCKLAND, Type = MIN - MINOR, Caller
12:55:23	Name = [REDACTED], Caller Ph Number = [REDACTED], Call Source = 111Inc InfoSMOKE IN
12:55:23	PASSING TRUCK DRIVER
12:55:23	VICINITY, Event Source = Fire 111
12:55:23	End of Duplicate Event data
12:58:13	Unit OTAR331 [KP : PRIORITY MESSAGE]
12:58:59	Unit OTAR331 [KP : PRIORITY MESSAGE] K11 AMB 1 PERSON WITH SMOKE INHALATION
12:59:07	AMBO EVENT 0436-1-2017/05/16-FIR LINKED AT 16/05/2017 12:59:07
12:59:19	*****
12:59:35	FIR2 AMB RESPONSE REQUIRED FOR A PATIENT WITH SMOKE INALATION
13:00:01	Unit OTAR331 [KC : UNIT CALLING]
13:00:18	AMBO update to 0436-1-2017/05/16-FIR:
13:00:19	Location = 43 Tyrone St,OTARA,
13:00:19	Caller Name = , Caller Phone = [REDACTED], Headline = WAIA711 WATER LEAKAGE
13:00:19	PLS PHONE F/COMM
13:00:21	Problem changed to: RED - Carbon Monoxide/Inhalation/HAZMAT/CBRN
13:00:48	AMBO update to 0436-1-2017/05/16-FIR:
13:00:49	Location = 43 Tyrone St,OTARA,
13:00:49	Caller Name = R27, Caller Phone = 10210344316, Headline = WAIA711 WATER

13:00:49	LEAKAGE PLS PHONE F/COMM
13:01:08	Unit OTAR331 [SITREP :] CAN YOU GIVE US AN ARRIVAL TIME?? (1246)
13:01:27	Unit OTAR331 [COMCEN COM : MESSAGE] DO YOU REQUIRE POWER TO THIS INCIDENT?
13:02:29	Unit OTAR331 [KC : UNIT CALLING]
13:03:13	Unit OTAR331 [K11F : FIRE SAFETY REQUIRED]
13:03:35	INC INFO: HOUSE FIRE TOC 1243 TOA 1246
13:06:04	Unit FICOUNT2 [K1 : PROCEEDING TO INCIDENT]
13:07:47	Unit OTAR331 [KC : UNIT CALLING]
13:08:52	Unit OTAR331 [SITREP :] DISREGARD, AMB IN ATTENDANCE
13:09:15	Unit OTAR331 [COMCEN COM : MESSAGE] DO YOU REQUIRE POWER TO THIS INCIDENT?
13:09:15	(AFFIRMATIVE)
13:15:13	Unit FICOUNT2 [K2 : IN ATTENDANCE AT INCIDENT]
13:22:13	Unit OTAR331 [KC : UNIT CALLING]
13:23:18	Unit OTAR331 [SITREP :] K11 HOUSING NZ REP, HOUSE IS UNLIVEABLE
13:42:13	Unit OTAR331 [KC : UNIT CALLING]
13:43:07	Unit OTAR331 [K11P : POLICE REQUIRED]
13:43:17	Unit OTAR331 [K12 : SUSPICIOUS FIRE]
13:43:26	RRRR
13:43:41	FIR2POL YOUR ATTENDANCE REQUIRED FOR SUSPICIOUS FIRE
13:44:42	** Event Type changed from FIR2POL to 1F(2) at: 16/05/17 13:44:42
13:58:52	Incident Closed. Reason: 510 ACC Assess and Treat Only
13:58:52	** Cancel Event:Event Canceled by InterCAD
14:04:10	**ALL OK
14:08:06	**CIB REQUESTED
14:14:13	Unit OTAH311 [KC : UNIT CALLING]
14:14:50	Unit OTAH311 [K10 : RECOMMISSIONING]
15:03:49	Unit OTAR331 [KC : UNIT CALLING]
15:04:13	Unit OTAR331 [K26 : UNIT WILL BE ENGAGED AT INCIDENT - STATE TIME] 1
16:11:31	Unit OTAR331 [KC : UNIT CALLING]
16:11:59	Unit OTAR331 [STOP : MESSAGE] SCENE LEFT WITH POLICE
16:12:06	Unit OTAR331 [K10 : RECOMMISSIONING]
16:57:23	Unit FICOUNT2 [SITREP :] PER PHONE - MY UTE HAS DIED - I AM CLEAR OF THE SCENE
16:57:23	AND BACK K6 - I WILL BE RESPONDING IN FICOUNTIES3 VEHICLE FOR NOW
16:57:40	Unit FICOUNT2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] ENTERED BY FIRECOM
17:28:06	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,
17:28:06	Qualifier 2:

Incident

CAD Number F2308064
Incident Reporter T Liavaa

Incident Controller Colin Wright
 Distance Travelled (km)
 Delay In Receiving Call

Property Details

Occupant tenant
 Building Owner Housing NZ
 General Property Use Single house
 Special Property Use Single house
 Purpose Group

Actions

Persons Reported Trapped No
 Evacuation Status Fully evacuated
 Action Prior 1 Bucket/Container of water, bucket pump
 Action Prior 2
 Action Taken Extinguishment and ventilation

Civilians

Civilians Rescued 0
 Civilians Extricated 0
 Civilians Assisted 1
 Civilians Evacuated

Origin

Location Wall surface (exterior)
 Level Ground level

Equipment Used

Quantity	Equipment
1	Hose reel, high pressure delivery
4	BA set
2	Vehicle Radio (LMR)
8	Handheld Radio (or Cellphone)
4	Hand tools - Crowbar, Saw, Hammer, Mop, Broom, Misc small gear
1	Thermal Imaging Camera
1	PPV - Passive Use (eg. Ventilation/Salvage)

Equipment Involved

Equipment Involved

Year

Make

Model

Fire

Arrival Condition Large fire

Heat Source Unable to classify

Termination Stage Flame

First Object Ignited Exterior side wall covering surface, Cladding (included eaves)

First Object Material Wood: sawn, finished timber

Second Object Ignited

Second Object Material

Indicated Cause Suspicious

Certainty of Cause High

Age of Person Unknown

Ethnicity Unknown

Gender

FAIP Service Offered No

FAIP Service Accepted No

Structure

Area of One Floor		49
Age of Building	2006 onwards	
Structural Frame Type	Timber frame unprotected (normal housing)	
Number of Floors		1
Number of Basements		0
Internal Wall Lining	Gypsum board (e.g. Gib board, Elephant board)	
Ceiling Lining	Gypsum board (e.g. Gib board, Elephant board)	
Material Generating Most Flame	Wood: Sawn, Finished timber	
Material Generating Most Smoke	Wood: Sawn, Finished timber	
Avenue of Flame Travel	Exterior spread	
Avenue of Smoke Travel	Exterior spread	
Extent of Flame Damage	Confined to structure of origin	
Area of Flame Damage		10
Extent of Smoke Damage	Confined to structure of origin	
Area of Smoke Damage		40
Extent of Water Damage	Confined to structure of origin	
Area of Water Damage		10

Extent of Fire Control Damage

Confined to structure of origin

Area of Fire Control Damage

20

Released under the Official Information Act

Exposure Number 1

Incident Type 1511: Outside fire: Material burnt has definable value
Address 43 Tyrone Street Otara
Distance Exposure Travelled
Surface Material of Exterior Wall
Construction Material of Roof
Method of Heat Transfer

Property Details

Occupant
Building Owner
General Property Use Single house
Special Property Use Residential Property - not classified above
Purpose Group

Actions

Persons Reported Trapped
Evacuation Status
Action Prior 1
Action Prior 2
Action Taken Extinguishment only: Includes isolating fuel/power supply

Origin

Location
Level

Equipment Used

Quantity	Equipment
1	Hose reel, high pressure delivery

Equipment Involved

Equipment Involved
Year
Make
Model

Fire

Arrival Condition
Heat Source
Termination Stage

First Object Ignited

First Object Material

Second Object Ignited

Second Object Material

Indicated Cause Suspicious

Certainty of Cause High

Age of Person Unknown

Ethnicity Unknown

Gender

FAIP Service Offered No

FAIP Service Accepted No

Comments

5/17/2017 3:55:10 PM

Reporter Comments

FSO Requested at incident F2308064 on 16 May 2017 12:42
Fire involving household and other items stored at the rear of the dwelling.
No viable source of accidental ignition found in this location.
Circumstances of the fire are such that strong suspicion of incendiary cause of fire.

Phil Faidley

5/19/2017 6:59:43 PM

Reporter Comments

Cause of fire under investigation.
Exposure fire was a fence unable to classify.

T Liavaa

Released under the Official Information Act