

SMS Incident Report

10/07/2017 13:19:01


Summary

CAD Number F2333436 **Status** Closed
Station West Harbour Station
Incident Started 28/06/2017 14:13:36 **Incident Ended** 30/06/2017 09:40:47
Incident Type 1102: Structure fire with no damage
Common Name PINEPAC GROUP COMPANIES
Address / 2-6 Airport Road Whenuapai
Alarm Method 111 Telephone **Alarm Level** 3
PFA Number
Zone 146703
Map Grid E 1744284 **Map Grid N** 5926841
First Caller MONITOR NZ LIMITED - WENDY **First Caller Contact** [REDACTED]
Incident Closed 30/06/2017 09:40:47
Report Completed 11:3, Sun 09 Jul 2017 by Dave Smith

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
WEST671	P1	14:14:52 28 Jun 2017	14:16:13 28 Jun 2017	14:20:10 28 Jun 2017	09:24:04 30 Jun 2017
KUME867	PR	14:14:48 28 Jun 2017	14:19:38 28 Jun 2017	14:27:23 28 Jun 2017	18:43:04 28 Jun 2017
TEAT664	PM	14:20:06 28 Jun 2017	14:21:50 28 Jun 2017	14:30:52 28 Jun 2017	21:22:42 28 Jun 2017
GLEN641	P1	14:20:23 28 Jun 2017	14:21:20 28 Jun 2017	14:33:34 28 Jun 2017	01:46:35 29 Jun 2017
WAIT771	P1	14:20:35 28 Jun 2017	14:23:41 28 Jun 2017	14:36:42 28 Jun 2017	18:10:51 28 Jun 2017
AUCK2018	CUHU	14:20:01 28 Jun 2017	14:22:20 28 Jun 2017	14:37:24 28 Jun 2017	20:52:42 28 Jun 2017
AUCKOSU1	SV	14:24:05 28 Jun 2017	14:24:05 28 Jun 2017	14:39:54 28 Jun 2017	18:57:35 28 Jun 2017
VSOWAITEM2	VSO	14:21:54 28 Jun 2017	14:26:53 28 Jun 2017	14:51:54 28 Jun 2017	20:29:17 28 Jun 2017
AUCKOSU2	SV	14:46:18 28 Jun 2017	14:46:18 28 Jun 2017	15:01:00 28 Jun 2017	20:46:51 28 Jun 2017
WAITEMATA2	OF	14:23:01 28 Jun 2017	14:25:19 28 Jun 2017	15:09:05 28 Jun 2017	20:40:22 28 Jun 2017
HEND657	PR	15:47:47 28 Jun 2017	15:47:47 28 Jun 2017	15:49:45 28 Jun 2017	07:42:00 29 Jun 2017
ALBA851	P1	15:59:42 28 Jun 2017	16:01:36 28 Jun 2017	16:05:26 28 Jun 2017	15:28:34 29 Jun 2017
WAITEMATA3	OF	15:58:02 28 Jun 2017	15:59:38 28 Jun 2017	16:11:38 28 Jun 2017	19:35:33 28 Jun 2017
AVON607	PR	15:59:50 28 Jun 2017	16:01:50 28 Jun 2017	16:16:48 28 Jun 2017	17:17:19 28 Jun 2017
FIWAITEM2	FSO	15:58:46 28 Jun 2017	16:03:39 28 Jun 2017	16:24:20 28 Jun 2017	17:29:49 28 Jun 2017
TITI691	P1	15:59:46 28 Jun 2017	16:01:36 28 Jun 2017	16:38:38 28 Jun 2017	18:03:40 28 Jun 2017

AUCK205	HPNP	16:20:43 28 Jun 2017	16:22:00 28 Jun 2017	16:48:01 28 Jun 2017	21:17:03 28 Jun 2017
AUCKOSU4	CV	16:03:08 28 Jun 2017	16:31:19 28 Jun 2017	16:54:39 28 Jun 2017	20:45:47 28 Jun 2017
TEAT6619	LU	16:31:46 28 Jun 2017	16:47:46 28 Jun 2017	17:14:56 28 Jun 2017	18:42:50 28 Jun 2017
KUME861	P1	17:33:10 28 Jun 2017	17:33:17 28 Jun 2017	17:41:36 28 Jun 2017	20:42:24 28 Jun 2017
VSOWAITEM1	VSO	17:15:49 28 Jun 2017	17:23:03 28 Jun 2017	18:22:40 28 Jun 2017	21:01:46 28 Jun 2017
TEAT662	P2	18:05:48 28 Jun 2017	18:05:48 28 Jun 2017	18:24:52 28 Jun 2017	19:10:18 28 Jun 2017
AUCKOSU3	SV	18:59:03 28 Jun 2017	18:59:03 28 Jun 2017	18:59:46 28 Jun 2017	20:49:01 28 Jun 2017
WEST672	P2	17:49:11 28 Jun 2017	17:49:11 28 Jun 2017	19:13:12 28 Jun 2017	21:34:09 28 Jun 2017
EVENTNCC1	OT	16:54:20 29 Jun 2017	16:54:20 29 Jun 2017	16:54:20 29 Jun 2017	09:29:02 30 Jun 2017
COUNTIES4	OF	15:57:16 28 Jun 2017	15:59:55 28 Jun 2017		20:18:15 28 Jun 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
WEST671	00:01:16	00:05:18	00:06:34	43:10:28
KUME867	00:01:12	00:12:35	00:13:47	04:29:28
TEAT664	00:06:30	00:10:46	00:17:16	07:09:06
GLEN641	00:06:47	00:13:11	00:19:58	11:32:59
WAIT771	00:06:59	00:16:07	00:23:06	03:57:15
AUCK2018	00:06:25	00:17:23	00:23:48	06:39:06
AUCKOSU1	00:10:29	00:15:49	00:26:18	04:43:59
VSOWAITEM2	00:08:18	00:30:00	00:38:18	06:15:41
AUCKOSU2	00:32:42	00:14:42	00:47:24	06:33:15
WAITEMATA2	00:09:25	00:46:04	00:55:29	06:26:46
HEND657	01:34:11	00:01:58	01:36:09	17:28:24
ALBA851	01:46:06	00:05:44	01:51:50	25:14:58
WAITEMATA3	01:44:26	00:13:36	01:58:02	05:21:57
AVON607	01:46:14	00:16:58	02:03:12	03:03:43
FIWAITEM2	01:45:10	00:25:34	02:10:44	03:16:13
TITI691	01:46:10	00:38:52	02:25:02	03:50:04
AUCK205	02:07:07	00:27:18	02:34:25	07:03:27
AUCKOSU4	01:49:32	00:51:31	02:41:03	06:32:11
TEAT6619	02:18:10	00:43:10	03:01:20	04:29:14
KUME861	03:19:34	00:08:26	03:28:00	06:28:48
VSOWAITEM1	03:02:13	01:06:51	04:09:04	06:48:10

Caution: The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside the NZ Fire Service or the National Rural Fire Authority without prior approval

TEAT662	03:52:12	00:19:04	04:11:16	04:56:42
AUCKOSU3	04:45:27	00:00:43	04:46:10	06:35:25
WEST672	03:35:35	01:24:01	04:59:36	07:20:33
EVENTNCC1	26:40:44	00:00:00	26:40:44	43:15:26
COUNTIES4	01:43:40			06:04:39

Notifications

Date	Time	Party Notified
28 Jun 2017	14:20:41	VECTOR
28 Jun 2017	14:20:55	AAC WAITEMATA GROUP VIA PAGER RE 2ND ALARM
28 Jun 2017	14:21:18	OSU AUCKLAND
28 Jun 2017	14:21:24	AAC WAITEMATA 2 VIA PAGER RE 2ND ALARM
28 Jun 2017	14:21:46	AAC COUNTIES4\ VIA PAGER RE 2ND ALARM
28 Jun 2017	14:22:22	VSO WAITEMATA2 ACK PAGER, REQUESTED TO BE ATTACHED
28 Jun 2017	14:23:18	AAC BOOTH ACK PAGER - RESPONDING..
28 Jun 2017	14:24:31	AAC DELFOS ACK PAGER - MONITORING..
28 Jun 2017	14:24:33	VECTOR REF 1-241 823 0493
28 Jun 2017	14:28:42	AC PURCELL PER PHONE - UPDATED..
28 Jun 2017	14:46:29	VSOWAITEMATA2 WILL SORT LADDER OUT WHILST ENROUTE
28 Jun 2017	15:12:39	GREATER ALARM ATTENDANCE SHEET SENT @ 1512
28 Jun 2017	15:55:11	AAC WAITEMATA / AAC DELFOS PER PAGER - 2ND AM/AAM REQUIRED
28 Jun 2017	15:57:31	AAC DELFOS ACK PAGER - RESPONDING..
28 Jun 2017	15:57:56	AAC MACKERETH - RESPONDING
28 Jun 2017	16:00:23	WAITEMATA AREA 3RD ALARM /AC PURCELL PER PAGER - 3RD ALARM..
28 Jun 2017	16:01:33	AVON607 ADDED IN PLACE OF HEND657 AS PART OF 3RD ALARM T/O.
28 Jun 2017	16:01:54	NORTHCOM OPS MANAGER ERIC SMITH ACK PAGER
28 Jun 2017	16:04:52	VECTOR REF 1-241 823 0493 ADVSD OF THIRD ALARM
28 Jun 2017	16:04:57	AC PURCELL ACK PAGER - IS A 3RD AM/AAM NEEDED
28 Jun 2017	16:07:21	VOLUNTEER [REDACTED] (HENDERSON) PHONES IN TO ADVISE THEY WILL BE ABLE TO CREW
28 Jun 2017	16:08:17	MTRO621 - K25 AVONDALE
28 Jun 2017	16:10:05	WEST672, TEAT662 K25 TO STATION VIA PAGER
28 Jun 2017	16:18:54	AUCKOSU4 - DRIVERS STUCK IN TRAFFIC
28 Jun 2017	16:18:58	AMBULANCE CALLED IN TO CHECK WHETHER OR NOT THEY WERE REQUIRED
28 Jun 2017	16:26:50	3RD ALARM ATTENDANCE SENT TO ICU AUCKALND
28 Jun 2017	16:27:02	WEST HARBOUR [REDACTED]) ADVSS ONLY HIM ON STATION, THERE ARE A COUPLE OF
28 Jun 2017	16:35:23	AUCKLAND COUNCIL -- ON HOLD
28 Jun 2017	16:39:08	[REDACTED] FROM TE ATATU VOLUNTEERS CALLS IN AND ADVISES THERE IS A CREW

28 Jun 2017	16:46:23	MEDIA TRANSFERRED TO AAC VAUGHAN MACKERETH
28 Jun 2017	16:52:19	AUCKLAND COUNCIL STILL ON HOLD
28 Jun 2017	16:53:50	TRYING AUCKLAND COUNCIL AGAIN. TRYING POLLUTION LINE [REDACTED]
28 Jun 2017	16:55:57	AUCKLAND COUNCIL - WILL CALL BACK WITH AN ETA
28 Jun 2017	17:10:48	SSO MORISON - REPLACEMENT CREWS FOR AERIAL AND CU ARE HEADING OUT IN THE VAN
28 Jun 2017	17:12:11	WORKSHOPS VIA PAGER
28 Jun 2017	17:13:01	TEAT662 -- FULLY MANNED
28 Jun 2017	17:20:28	TITI692 - FULLY CREWED
28 Jun 2017	17:23:53	PRESTIGE ACK PAGE [REDACTED] - DETAILS PASSED RE FUEL REQUIRED - HE IS
28 Jun 2017	17:30:29	AUCKLAND COUNCIL REP ETA 20MINS, [REDACTED]
28 Jun 2017	17:32:28	KUMEU FIRE ([REDACTED]) AAC MACKERETH REQUESTS KUME861 FOR RELIEVE CREW
28 Jun 2017	17:43:31	COUNCIL REP ETA + PH# PASSED VIA PH
28 Jun 2017	19:25:22	[REDACTED] FROM TE ATAU REQUESTS TEAT662 COVER MOVE TO STATION AS TEAT664 WILL BE
28 Jun 2017	20:21:12	GLEN EDEN FIRE RE STANDBYS
28 Jun 2017	20:23:22	ALBANY FIRE RE STANDBYS
28 Jun 2017	20:25:49	HENDERSON FIRE RE STANDBYS
28 Jun 2017	21:03:50	AUCK OSU 4 RE TELEBOARD LEFT BEHIND
28 Jun 2017	21:06:01	OSU AUCK
29 Jun 2017	09:26:28	WEST 671 ADVISED AS PER AAC JOHN BOOTH ALBA851 TO COVER FROM 1200
29 Jun 2017	10:27:14	SO BUTTER ALBA851
30 Jun 2017	09:14:57	ALERT WEST671

Message Log

Time	Message
14:14:28	[REDACTED]
14:14:28	INC INFO: BUILDING FIRE
14:14:30	** LOI search completed at 28/06/17 14:14:30
14:14:38	** Recommended unit WEST671 for requirement PUMP (>2.8 km)
14:14:38	** Recommended unit KUME867 for requirement PUMP (>6.9 km)
14:14:54	SOMEONE WILL MEET BRIGADE AT THE GATE
14:15:47	CHIP CONTAINER IN KILN BUILDING
14:16:13	Unit WEST671 [K1 : PROCEEDING TO INCIDENT]
14:17:09	Unit WEST671 [COMCEN COM : MESSAGE] DETAILS PASSED
14:19:00	Unit WEST671 [KP : PRIORITY MESSAGE]
14:19:17	FIR2POL - FYI 2ND ALARM
14:19:21	FIR2AMB - FYI 2ND ALARM
14:19:22	Unit WEST671 [KP : PRIORITY MESSAGE] TX 2ND ALARM - MAKE AERIALS ONE

14:19:28 AMBO EVENT 0572-1-2017/06/28-FIR LINKED AT 28/06/2017 14:19:28

14:19:38 INC INFO: BUILDING FIRE: TX 2ND ALARM - MAKE AERIAL ONE

14:19:39 Unit KUME867 [K1 : PROCEEDING TO INCIDENT]

14:19:52 ** Alarm level updated to 2

14:19:52 ** Recommended unit TEAT664 for requirement AERIAL (>8.0 km)

14:19:52 ** Recommended unit AUUCK2018 for requirement COMU (>11.5 km)

14:19:52 ** Recommended unit GLEN641 for requirement PUMP (>10.2 km)

14:19:52 ** Recommended unit WAIT771 for requirement PUMP (>9.0 km)

14:20:11 Unit WEST671 [K88 : PROPERTY SMALL]

14:20:16 Unit WEST671 [K88 : PROPERTY SMALL]

14:20:20 Unit WEST671 [K88 : PROPERTY SMALL]

14:20:29 Unit WEST671 [K88 : PROPERTY SMALL]

14:21:20 Unit GLEN641 [K1 : PROCEEDING TO INCIDENT]

14:21:50 Unit TEAT664 [K1 : PROCEEDING TO INCIDENT]

14:21:55 Unit WEST671 [K88 : PROPERTY SMALL]

14:22:20 Unit AUUCK2018 [K1 : PROCEEDING TO INCIDENT]

14:23:25 AL: PAGING ACK TIMED OUT FOR STATION: 1466 at 28/06/17 14:23:25

14:23:41 Unit WAIT771 [K1 : PROCEEDING TO INCIDENT]

14:24:05 Unit AUUCKOSU1 [K1 : PROCEEDING TO INCIDENT]

14:24:12 Unit AUUCKOSU1 [K38 : ASSOCIATE THIS UNIT TO EVENT - EVENT ADDRESS]

14:24:15 Unit AUUCKOSU1 [K39 : RE-TRANSMIT YOUR CURRENT STATUS]

14:24:21 Unit WEST671 [KC : UNIT CALLING]

14:25:15 Unit WEST671 [KP : PRIORITY MESSAGE]

14:25:20 Unit WEST671 [SITREP :] [REDACTED]. PINEPAC GROUP. AIRPORT ROAD. INVESTIGATING

14:25:20 Unit WAITEMATA2 [K1 : PROCEEDING TO INCIDENT]

14:25:20 FIRE IN WOOD SHAVINGS FIORDLAND.

14:26:04 Unit WEST671 [KP : PRIORITY MESSAGE] HAVE 2ND RESPONDING APPLIANCE BRING IN

14:26:04 WATER BRIGHAM CREEK.

14:26:42 Unit KUME867 [COMCEN COM : MESSAGE] DID YOU COPY? (ACK)

14:26:53 COVERING UNIT TITI691 DISPATCHED TO STATION HENDERSON

14:26:53 D0710063

14:26:54 Unit VSOWAITEM2 [K1 : PROCEEDING TO INCIDENT]

14:27:23 Unit KUME867 [K2 : IN ATTENDANCE AT INCIDENT]

14:27:31 COVERING UNIT ALBA851 DISPATCHED TO STATION WEST

14:27:31 TERMINAL: D0710063

14:30:48 FIR2POL -, JUST FYI AS FIRE IS NOW 2ND ALARM

14:30:53 Unit TEAT664 [K2 : IN ATTENDANCE AT INCIDENT]

14:33:35 Unit GLEN641 [K2 : IN ATTENDANCE AT INCIDENT]

14:36:42 Unit WAIT771 [K2 : IN ATTENDANCE AT INCIDENT]

14:37:25 Unit AUUCK2018 [K2 : IN ATTENDANCE AT INCIDENT]

14:39:55	Unit AUCKOSU1 [K2 : IN ATTENDANCE AT INCIDENT]
14:44:14	Unit WEST671 [KC : UNIT CALLING]
14:45:28	Unit WEST671 [SITREP :] CAN YOU PAGE WEST HARBOUR VOLLIES AND ADV WEST672 AND
14:45:28	ADVISE THAT THEIR 10.5 LADDER IS ON THE APRON OF THE STATION AND WILL REQUIRE TO
14:45:28	BE MADE UP.
14:46:18	Unit AUCKOSU2 [K1 : PROCEEDING TO INCIDENT]
14:46:23	Unit AUCKOSU2 [K38 : ASSOCIATE THIS UNIT TO EVENT - EVENT ADDRESS]
14:46:26	Unit AUCKOSU2 [K39 : RE-TRANSMIT YOUR CURRENT STATUS]
14:48:27	Unit WEST671 [KC : UNIT CALLING]
14:48:50	Unit WEST671 [SITREP :] SO SMITH. ONE LPD. ONE HPD. AND AERIAL SET UP.
14:49:18	Unit WEST671 [COMCEN COM : MESSAGE] CAN YOU PROVIDE DIMENSIONS ON SIZE OF FIRE
14:49:18	(STAND BY)
14:50:21	Unit WEST671 [KC : UNIT CALLING]
14:50:49	Unit WEST671 [SITREP :] SIZE OF PROPERTY FIRE: APPROX 12M BY 6M.
14:51:54	Unit VSOWAITEM2 [K2 : IN ATTENDANCE AT INCIDENT]
14:58:13	Unit AUCK2018 [KC : UNIT CALLING]
14:58:38	Unit AUCK2018 [K44 : COMMAND OR CONTROL POINT ESTABLISHED - OIC AND LOCATION]
14:58:38	WHENUAPAI COMMAND
14:59:13	Unit AUCK2018 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] AAC BOOTH
14:59:19	Unit AUCK2018 [SITREP :] AAC BOOTH - FIRE IN CHIP BIN. BRIGADE GTWW AERIAL
14:59:19	APPLIANCE AND ONE LOW PRESSURE DELIVERY.
15:01:00	Unit AUCKOSU2 [K2 : IN ATTENDANCE AT INCIDENT]
15:03:19	Unit AUCK2018 [KC : UNIT CALLING]
15:04:04	Unit AUCK2018 [SITREP :] REQUEST T/O SUMMARY TO BE SENT OUT TO EMAIL ADDRESS
15:09:05	Unit WAITEMATA2 [K2 : IN ATTENDANCE AT INCIDENT]
15:24:29	Unit AUCK2018 [KC : UNIT CALLING]
15:25:48	Unit AUCK2018 [SITREP :] 1 FIRE IN KIL CHIPPER 1 GROUND MONITOR AND 1 AERIAL
15:25:48	APPLIANCE IN USE. GAINED ACCESS TO HOPPER. PROCEEDING TO DROWN WOODCHIPS IN
15:25:48	WATER
15:47:48	Unit HEND657 [K1 : PROCEEDING TO INCIDENT]
15:47:58	Unit HEND657 [K1 : PROCEEDING TO INCIDENT]
15:48:05	Unit HEND657 [K1 : PROCEEDING TO INCIDENT]
15:48:06	Unit HEND657 [K38 : ASSOCIATE THIS UNIT TO EVENT - EVENT ADDRESS]
15:48:09	Unit HEND657 [K39 : RE-TRANSMIT YOUR CURRENT STATUS]
15:48:10	Unit HEND657 [K1 : PROCEEDING TO INCIDENT]
15:48:33	Unit HEND657 [K1 : PROCEEDING TO INCIDENT]
15:49:46	Unit HEND657 [K2 : IN ATTENDANCE AT INCIDENT]
15:51:03	Unit AUCK2018 [KC : UNIT CALLING]
15:51:15	Unit AUCK2018 [KC : UNIT CALLING]
15:52:18	Unit AUCK2018 [SITREP :] CAN YOU COMMIT HEND657 TO THIS CALL

15:52:30 Unit AUCK2018 [KC : UNIT CALLING]

15:52:35 Unit AUCK2018 [COMCEN COM : MESSAGE] HEND657 ARE CURRENTLY SHOWING K2 AND HAVE BEEN FOR THE PAST 2 MINUTES

15:52:35

15:53:02 Unit AUCK2018 [SITREP :] REQUEST A 2ND AREA MANAGER TO BE COMMITTED TO THIS CALL

15:53:02

15:56:52 Unit AUCK2018 [KP : PRIORITY MESSAGE]

15:58:02 Unit AUCK2018 [KP : PRIORITY MESSAGE] TX 3RD ALARM FOR MANPOWER AND WATER - STAND DOWN SPECIALIST APPLIANCES ON 3RD ALARM.

15:58:02

15:58:29 INC INFO: BUILDING FIRE: 3RD ALARM - TOC: 1414 TOA: 1420

15:58:56 INC INFO: BUILDING FIRE: 3RD ALARM

15:59:06 ** Alarm level updated to 3

15:59:06 ** Recommended unit PARN255 for requirement AERIAL (>16.1 km)

15:59:06 ** Recommended unit ELLE274 for requirement AERIAL (>21.3 km)

15:59:06 ** Recommended unit AVON6015 for requirement BAT (>13.8 km)

15:59:06 ** Recommended unit AUCKOSU4 for requirement CANT (>25.7 km)

15:59:06 ** Recommended unit ALBA851 for requirement PUMP (>2.8 km)

15:59:06 ** Recommended unit TITI691 for requirement PUMP (>10.2 km)

15:59:16 ** Requirement PUMP added for alarm level 3

15:59:32 ** Recommended unit PARN255 for requirement AERIAL (>16.1 km)

15:59:32 ** Recommended unit ELLE274 for requirement AERIAL (>21.3 km)

15:59:32 ** Recommended unit AVON6015 for requirement BAT (>13.8 km)

15:59:32 ** Recommended unit AUCKOSU4 for requirement CANT (>25.7 km)

15:59:32 ** Recommended unit AVON607 for requirement ADHOC PUMP (>13.8 km)

15:59:38 Unit WAITEMATA3 [K1 : PROCEEDING TO INCIDENT]

15:59:55 Unit COUNTIES4 [K1 : PROCEEDING TO INCIDENT]

16:00:43 FIR2POL: FYI THIRD ALARM TRANSMITTED FOR MANPOWER

16:00:53 FIR2AMB: FYI THIRD ALARM TRANSMITTED FOR MANPOWER

16:01:37 Unit TITI691 [K1 : PROCEEDING TO INCIDENT]

16:01:37 Unit ALBA851 [K1 : PROCEEDING TO INCIDENT]

16:01:51 Unit AVON607 [K1 : PROCEEDING TO INCIDENT]

16:02:10 FIR2POL: CAN YOU RESPOND TO THIRD ALARM

16:02:17 Unit TITI691 [K1 : PROCEEDING TO INCIDENT]

16:02:57 Unit AUCK2018 [SITREP :] (PH) RESPOND CANTEEN UNIT PER 3RD ALARM PDA

16:03:01 ** Recommended unit AUCK205 for requirement AERIAL (>14.5 km)

16:03:01 ** Recommended unit PARN255 for requirement AERIAL (>16.1 km)

16:03:01 ** Recommended unit AVON6015 for requirement BAT (>13.8 km)

16:03:01 ** Recommended unit AUCKOSU4 for requirement CANT (>25.7 km)

16:03:40 Unit FIWAITEM2 [K1 : PROCEEDING TO INCIDENT]

16:05:27 Unit ALBA851 [K2 : IN ATTENDANCE AT INCIDENT]

16:05:49 COVERING UNIT HEND651 DISPATCHED TO STATION HENDERSON
16:05:49 D0710065
16:06:36 Unit AUCK2018 [COMCEN COM : MESSAGE] DO YOU REQUIRE A 3RD EXEC TO RESPOND TO
16:06:36 THIS INCIDENT?
16:06:43 Unit AUCK2018 [SITREP :] NEGATIVE
16:07:21 FOR COVER- ADVISE COVER REQUIRED - PAGE SENT
16:11:39 Unit WAITEMATA3 [K2 : IN ATTENDANCE AT INCIDENT]
16:11:47 Unit WAITEMATA3 [K2 : IN ATTENDANCE AT INCIDENT]
16:12:30 Unit WAITEMATA3 [K2 : IN ATTENDANCE AT INCIDENT]
16:16:48 Unit AVON607 [K2 : IN ATTENDANCE AT INCIDENT]
16:17:32 Unit AUCK2018 [KC : UNIT CALLING]
16:17:40 Unit AUCK2018 [KC : UNIT CALLING]
16:18:00 Unit AUCK2018 [SITREP :] MAKE TYPE 6 AERIAL APPLIANCES ONE
16:20:17 Unit AUCK2018 [COMCEN COM : MESSAGE] AUCK206 / PARN256 ARE K0 - WOULD YOU
16:20:17 PREFER
16:20:17 AUCK205 / PARN255?
16:20:32 Unit AUCK2018 [KC : UNIT CALLING]
16:20:41 Unit AUCK2018 [KC : UNIT CALLING]
16:22:01 Unit AUCK205 [K1 : PROCEEDING TO INCIDENT]
16:22:07 Unit AUCK2018 [COMCEN COM : MESSAGE] DO YOU REQUIRE AN AMB?
16:22:26 Unit AUCK2018 [SITREP :] NEGATIVE TO AMB. REQUEST FOR AN UPDATED LIST OF
16:22:26 APPLIANCES IN ATTENDANCE.
16:24:21 Unit FIWAITEM2 [K2 : IN ATTENDANCE AT INCIDENT]
16:27:02 GUYS AVAILABLE IN THE AREA SO IF THEY GOT A CALL THEY COULD RESPOND WITH CREW
16:27:02 OF
16:27:02 THREE. AT 1700 AN OFFICER WILL BE ON STATION
16:29:07 Unit AUCK2018 [KC : UNIT CALLING]
16:31:01 Unit AUCK2018 [SITREP :] K11 LIGHTING UNIT. REQUEST COUNCIL REP FOR WATER RUN
16:31:01 OFF AS CLASS A FOAM IS IN USE. 1 FIRE IN KILN WITH 250 CUBIC METRES OF WOODCHIP
16:31:01 POSSIBLE FIRE IN 2ND KILN WITH 125 CUBIC METRE OF WOODCHIP.
16:31:19 Unit AUCKOSU4 [K1 : PROCEEDING TO INCIDENT]
16:31:23 ** Requirement LIGHTING added for alarm level 3
16:38:38 Unit TITI691 [K2 : IN ATTENDANCE AT INCIDENT]
16:39:08 ENROUTE TO STATION NOW FOR THE LIGHTING PLANT
16:46:54 Unit AUCK2018 [KC : UNIT CALLING]
16:47:25 Unit AUCK2018 [SITREP :] ADDITIONAL FEEDERS ESTABLISHED. GTWW 2ND AERIAL.
16:47:47 Unit TEAT6619 [K1 : PROCEEDING TO INCIDENT]
16:48:02 Unit AUCK205 [K2 : IN ATTENDANCE AT INCIDENT]
16:54:39 Unit AUCKOSU4 [K2 : IN ATTENDANCE AT INCIDENT]
16:54:48 Unit AUCKOSU4 [K2 : IN ATTENDANCE AT INCIDENT]
16:55:42 COVERING UNIT TEAT662 DISPATCHED TO STATION TE ATATU AT

16:55:42	D0710065
17:11:32	Unit WAITEMATA3 [SITREP :] (PH) WORKSHOPS TO BRING FUEL TRAILER OUT FOR AERIAL
17:11:32	APPLIANCES
17:12:27	Unit WAITEMATA3 [SITREP :] PER PHONE - IS THE LIGHTING UNIT ENROUTE?
17:12:48	Unit WAITEMATA3 [COMCEN COM : MESSAGE] PER PHONE - AFFIRM - K1 FOR 24MINS NOW -
17:12:48	SHOULD BE NEARLY THERE
17:14:57	Unit TEAT6619 [K2 : IN ATTENDANCE AT INCIDENT]
17:16:03	Unit VSOWAITEM1 [K38 : ASSOCIATE THIS UNIT TO EVENT - EVENT ADDRESS]
17:17:20	Unit AVON607 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
17:19:36	Unit TITI691 [K2 : IN ATTENDANCE AT INCIDENT]
17:21:56	Unit ALBA851 [KC : UNIT CALLING]
17:22:13	Unit AUCK2018 [KC : UNIT CALLING]
17:22:15	Unit ALBA851 [K10 : RECOMMISSIONING]
17:22:30	Unit AUCK2018 [K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]
17:23:03	Unit VSOWAITEM1 [K1 : PROCEEDING TO INCIDENT]
17:23:53	RESPONDING FROM POKENO VIA OTAHUHU SO ETA IS APPROX 2 HOURS
17:25:52	Unit AUCK2018 [COMCEN COM : MESSAGE] FROM PRESTIGE RE FUEL REQUIRED: THEY'RE
17:25:52	RESPONDING FROM POKENO VIA OTAHUHU - ETA APPROXIMATELY 2 HOURS
17:29:51	Unit FIWAITEM2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
17:33:18	Unit KUME861 [K1 : PROCEEDING TO INCIDENT]
17:33:29	Unit AUCK2018 [KC : UNIT CALLING]
17:34:01	Unit AUCK2018 [SITREP :] CREWS ON FIREGROUND BEING MANAGED FOR CHANGEOVER AT
17:34:01	THE FIREGROUND
17:35:43	Unit AUCK2018 [COMCEN COM : MESSAGE] BE ADVISED KUME861 HAVE BEEN ATTACHED AND
17:35:43	ARE K1
17:41:36	Unit KUME861 [K2 : IN ATTENDANCE AT INCIDENT]
17:44:39	Unit AUCK2018 [COMCEN COM : MESSAGE] AUCKLAND COUNCIL ETA PASSED
17:49:11	Unit WEST672 [K1 : PROCEEDING TO INCIDENT]
17:49:35	Unit WEST672 [K1 : PROCEEDING TO INCIDENT] VERBAL
18:03:41	Unit TITI691 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
18:05:49	Unit TEAT662 [K1 : PROCEEDING TO INCIDENT]
18:10:53	Unit WAIT771 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
18:22:41	Unit VSOWAITEM1 [K2 : IN ATTENDANCE AT INCIDENT]
18:24:53	Unit TEAT662 [K2 : IN ATTENDANCE AT INCIDENT]
18:35:49	Unit AUCK2018 [COMCEN COM : MESSAGE] DO YOU STILL REQUIRE THE PRESTIGE
18:35:49	MECHANIC
18:35:49	WITH THE DIESEL TRAILER?
18:36:41	Unit AUCK2018 [SITREP :] AFFIRM DIESEL MINI TANKER STILL REQUIRED
18:41:15	Unit AUCK2018 [K26 : UNIT WILL BE ENGAGED AT INCIDENT - STATE TIME] 1
18:42:51	Unit TEAT6619 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

18:43:05	Unit KUME867 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
18:57:37	Unit AUCKOSU1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
18:59:03	Unit AUCKOSU3 [K1 : PROCEEDING TO INCIDENT]
18:59:37	Unit AUCKOSU3 [K1 : PROCEEDING TO INCIDENT]
18:59:46	Unit AUCKOSU3 [K2 : IN ATTENDANCE AT INCIDENT]
19:10:20	Unit TEAT662 [K7 : AT NORMAL STATION]
19:13:13	Unit WEST672 [K2 : IN ATTENDANCE AT INCIDENT]
19:23:40	COVERING UNIT TEAT662 DISPATCHED TO STATION TE ATATU AT
19:23:40	D0710063
19:25:22	SOMETIME AT INCIDENT
19:34:26	Unit AUCK2018 [SITREP :] CREWS ROTATED - ASSESSING FUTURE STANDBYS
19:34:32	FM TEAT FIRE 662 HAS A CREW ON STATION
19:35:35	Unit WAITEMATA3 [K6 : ON TELEPAGER]
19:38:03	Unit GLEN641 [K7 : AT NORMAL STATION]
20:18:16	Unit COUNTIES4 [K6 : ON TELEPAGER]
20:18:50	Unit VSOWAITEM2 [SITREP :] VIA CELLPHONE - REST OF TRUCKS WILL BE RELEASED IN
20:18:50	NEXT 30 MINS. WILL BE HERE ALL NIGHT & PROBABLY REST OF TOMORROW. WEST671 & 672
20:18:50	WILL REMAIN UNTIL 2200. STANDBYS CREWS AS FOLLOWS: GLEN641 TO BE HERE @ 2200,
20:18:50	ALBA851 @ 0130, HEND657 @ 0500. YELLOW WATCH WEST HARBOUR TO RETURN AT 0700.
20:19:58	CORRECTION: ABOVE SITREP FROM WAITEMATA2 - JOHN BOOTH
20:26:46	Unit AUCK2018 [KC : UNIT CALLING]
20:27:17	Unit AUCK2018 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SSO SOSICH
20:27:28	Unit AUCK2018 [K44 : COMMAND OR CONTROL POINT ESTABLISHED - OIC AND LOCATION]
20:27:28	HEND657
20:29:18	Unit VSOWAITEM2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
20:40:23	Unit WAITEMATA2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
20:42:25	Unit KUME861 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
20:45:48	Unit AUCKOSU4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
20:46:51	Unit AUCKOSU2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
20:49:02	Unit AUCKOSU3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
20:52:44	Unit AUCK2018 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
21:01:47	Unit VSOWAITEM1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
21:03:53	UNABLE TO CONTACT OSU 1
21:05:51	Unit HEND657 [SITREP :] VIA CELLPHONE OSU1 & 4 HAVE LEFT TELLY BOARDS HERE
21:05:51	THEY ARE WITH 657
21:17:04	Unit AUCK205 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
21:17:24	Unit HEND657 [KC : UNIT CALLING]
21:17:58	Unit HEND657 [SITREP :] BRIGADE BREAKING DOWN OPERATIONS - 2 UNMANNED LPD -
21:17:58	K45 [REDACTED] - WEST671
21:18:24	Unit HEND657 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] [REDACTED]

21:18:24	WEST671
21:22:44	Unit TEAT664 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
21:24:38	Unit WEST671 [KC : UNIT CALLING]
21:24:55	Unit WEST671 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] ██████████
21:28:37	Unit HEND657 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
21:34:11	Unit WEST672 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
21:37:40	Unit GLEN641 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
21:40:09	Unit GLEN641 [K1 : PROCEEDING TO INCIDENT]
21:40:10	Unit WEST671 [SITREP :] ██████████ - CREW STANDING DOWN WITH LDP AND 2 SILO
21:40:10	AND 1 EXTERNAL GROUND MONITOR STANDING BY - K26 1 - TIC CAMERA HAS BEEN USED FOR
21:40:10	CHECKING THERMAL DINAMICS IN SILO
21:40:40	Unit WEST671 [K26 : UNIT WILL BE ENGAGED AT INCIDENT - STATE TIME] 1
21:46:38	Unit WEST671 [SITREP :] CORRECTION ██████████ - CREW STANDING WITH LPD AND 2
21:46:38	SILO AND 1 EXTERNAL GROUND MONITOR STANDING BY - TIC CAMERA HAS BEEN USED FOR
21:46:38	CHECKING THERMAL DYNAMICS IN SILO
21:46:56	Unit WEST671 [K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]
21:58:04	Unit GLEN641 [K2 : IN ATTENDANCE AT INCIDENT]
23:02:44	Unit GLEN641 [KC : UNIT CALLING]
23:03:41	Unit GLEN641 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SO ARMSTRONG
23:59:17	Unit WEST671 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
23:59:46	Unit GLEN641 [KC : UNIT CALLING]
00:00:00	Unit GLEN641 [K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]
01:09:24	Unit GLEN641 [KC : UNIT CALLING]
01:09:29	Unit GLEN641 [KC : UNIT CALLING]
01:09:42	Unit GLEN641 [K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]
01:28:10	Unit ALBA851 [K1 : PROCEEDING TO INCIDENT]
01:28:24	Unit ALBA851 [K1 : PROCEEDING TO INCIDENT]
01:28:38	Unit ALBA851 [K2 : IN ATTENDANCE AT INCIDENT]
01:45:53	Unit ALBA851 [KC : UNIT CALLING]
01:46:36	Unit GLEN641 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
03:17:44	Unit ALBA851 [KC : UNIT CALLING]
03:17:58	Unit ALBA851 [K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]
04:22:34	Unit ALBA851 [KC : UNIT CALLING]
04:23:08	Unit ALBA851 [K26 : UNIT WILL BE ENGAGED AT INCIDENT - STATE TIME] 1
04:55:58	Unit HEND657 [K1 : PROCEEDING TO INCIDENT]
04:56:03	Unit HEND657 [K2 : IN ATTENDANCE AT INCIDENT]
04:58:49	Unit HEND657 [K2 : IN ATTENDANCE AT INCIDENT]
05:05:54	Unit ALBA851 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
06:48:33	WEST671 HEADING TO EVENT ABOUT 0700

07:13:07	Unit WEST671 [K38 : ASSOCIATE THIS UNIT TO EVENT - EVENT ADDRESS]
07:14:02	Unit WEST671 [K1 : PROCEEDING TO INCIDENT]
07:38:03	Unit WEST671 [K2 : IN ATTENDANCE AT INCIDENT]
07:38:11	Unit WEST671 [KC : UNIT CALLING]
07:39:46	Unit WEST671 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SO SMITH
07:42:01	Unit HEND657 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
07:58:37	Unit WEST671 [KC : UNIT CALLING]
07:59:29	Unit WEST671 [SITREP :] PLANT WORKERS COMMENCING WORK ON HOPPER, 1 COVERING
07:59:29	HPD
09:26:50	UNABLE TO CONTACT ALBA851 @ 0926 WILL KEEP TRYING
09:37:51	Unit WEST671 [KC : UNIT CALLING]
09:38:48	Unit WEST671 [SITREP :] SITE ENGINEER - ATTEMPTING TO START HOPPER AUGER - TO
09:38:48	ASSIST WITH EMPTYING HOPPER
10:15:49	Unit WEST671 [KC : UNIT CALLING]
10:16:14	Unit WEST671 [K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]
10:27:21	ADVISED
11:37:01	Unit WEST671 [KC : UNIT CALLING]
11:37:24	Unit WEST671 [K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]
12:11:31	Unit ALBA851 [K2 : IN ATTENDANCE AT INCIDENT]
12:49:32	Unit WEST671 [KC : UNIT CALLING]
12:50:12	Unit WEST671 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SO BUTTER ON
12:50:12	ALBA851
12:50:29	Unit WEST671 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
15:28:18	Unit ALBA851 [STOP : MESSAGE]
15:28:35	Unit ALBA851 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
15:30:04	Unit ALBA851 [STOP : MESSAGE] SO BUTTER - WEST671 TO COME WITH TIC AT 1730, AND
15:30:04	AGAIN IN THE MORNING. HOSES HAVE BEEN LEFT OUT AND WILL REMAIN SO OVERNIGHT
15:30:04	WITH
15:30:04	ONSITE SECURITY
16:53:00	BUSINESS RULE CHECKS CANCELLED AT 29/06/17 16:53:00
16:53:00	D0710066
16:54:20	Unit EVENTNCC1 [K2 : IN ATTENDANCE AT INCIDENT]
08:16:37	Unit WEST671 [K1 : PROCEEDING TO INCIDENT]
08:27:45	Unit WEST671 [K2 : IN ATTENDANCE AT INCIDENT]
09:14:14	Unit WEST671 [COMCEN COM : MESSAGE] NO ANSWER WHEN CALLED (X2) FOR AN UPDATED
09:14:14	SITREP
09:15:21	Unit WEST671 [KC : UNIT CALLING]
09:15:32	Unit WEST671 [COMCEN COM : MESSAGE] CAN WE HAVE AN UPDATED SITREP
09:16:10	Unit WEST671 [STOP : MESSAGE] SO SMITH. INCIDENT LEFT WITH PLANT MANAGEMENT
09:24:05	Unit WEST671 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

09:28:58	Unit EVENTNCC1 [SITREP :] WEST671 ADVISE THIS EVENT CAN NOW BE CLOSED
09:29:03	Unit EVENTNCC1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
09:40:08	UNIT EVENTNCC1 RESPONSE TIME [NULL] ADJUSTED TO
09:40:45	UNIT AUCKOSU1 ALERT TIME [NULL] ADJUSTED TO
09:40:45	UNIT AUCKOSU3 ALERT TIME [NULL] ADJUSTED TO
09:40:45	UNIT AUCKOSU2 ALERT TIME [NULL] ADJUSTED TO
09:40:45	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,
09:40:45	Qualifier 2:
09:40:46	UNIT EVENTNCC1 ALERT TIME [NULL] ADJUSTED TO
09:40:46	UNIT WEST672 ALERT TIME [NULL] ADJUSTED TO
09:40:46	UNIT TEAT662 ALERT TIME [NULL] ADJUSTED TO
09:40:46	UNIT HEND657 ALERT TIME [NULL] ADJUSTED TO
09:40:46	UNIT AUCKOSU3 ALERT TIME [NULL] ADJUSTED TO

Incident

CAD Number	F2333436
Incident Reporter	Dave Smith
Incident Controller	SO Dave Smith
Distance Travelled (km)	3
Delay In Receiving Call	Information not recorded

Property Details

Occupant	Auckland Pinepac Group Companies
Building Owner	Owner occupied
General Property Use	Industrial, Manufacturing
Special Property Use	Sawmill, Wood components, Tanalising mill, Frames, Prefabricated parts
Purpose Group	

Actions

Persons Reported Trapped	No
Evacuation Status	Evacuation in progress
Action Prior 1	Isolating power source
Action Prior 2	Information not recorded
Action Taken	Extinguishment only: Includes isolating fuel/power supply

Civilians

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0

Civilians Evacuated

Origin

Location Product storage, Tank, Bin, Agricultural storage, Hay barn, Hay stack
Level Ground level

Equipment Used

Quantity	Equipment
10	Vehicle Radio (LMR)
10	Handheld Radio (or Cellphone)
2	Hose reel, high pressure delivery
2	Low pressure delivery
1	Monitor (ground)
1	Monitor (aerial)
1	Hydraulic elevating platform (HEP), Snorkel, other Aerial
4	Foam - Class A 20L drum
2	Thermal Imaging Camera

Equipment Involved

Equipment Involved

Year

Make

Model

Fire

Arrival Condition Smoke only
Heat Source Unable to classify
Termination Stage Smoulder
First Object Ignited Dust, Lint, Fibre, Wood chips, Sawdust, Shavings, Bark
First Object Material Shavings, Sawdust, Chips
Second Object Ignited Dust, Lint, Fibre, Wood chips, Sawdust, Shavings, Bark
Second Object Material Shavings, Sawdust, Chips
Indicated Cause Undetermined
Certainty of Cause High
Age of Person Unknown
Ethnicity Unknown
Gender
FAIP Service Offered No

FAIP Service Accepted No

Released under the Official Information Act

Exposure Number 1

Incident Type 1102: Structure fire with no damage
Address 2-6 Airport Road Whenuapai
Distance Exposure Travelled 3
Surface Material of Exterior Wall Reconstituted wood products
Construction Material of Roof Steel, iron, coated tiles (includes decromastic tiles and metal shingles)
Method of Heat Transfer Conducted heat

Property Details

Occupant Pinepac Group Companies
Building Owner Owner occupied
General Property Use Industrial, Manufacturing
Special Property Use Sawmill, Wood components, Tanalising mill, Frames, Prefabricated parts
Purpose Group

Actions

Persons Reported Trapped No
Evacuation Status Evacuation in progress
Action Prior 1 Isolating power source
Action Prior 2 Unable to classify
Action Taken Extinguishment only: Includes isolating fuel/power supply

Civilians

Civilians Rescued 0
Civilians Extricated 0
Civilians Assisted 0
Civilians Evacuated

Origin

Location Product storage, Tank, Bin, Agricultural storage, Hay barn, Hay stack
Level Ground level

Equipment Used

Quantity	Equipment
1	Low pressure delivery

Equipment Involved

Equipment Involved
Year
Make
Model

Fire

Arrival Condition	Smoke only		
Heat Source	Unable to classify		
Termination Stage	Smoulder		
First Object Ignited	Dust, Lint, Fibre, Wood chips, Sawdust, Shavings, Bark		
First Object Material	Shavings, Sawdust, Chips		
Second Object Ignited	Dust, Lint, Fibre, Wood chips, Sawdust, Shavings, Bark		
Second Object Material	Shavings, Sawdust, Chips		
Indicated Cause	Undetermined		
Certainty of Cause	High		
Age of Person	Unknown		
Ethnicity	Unknown		
Gender			
FAIP Service Offered	No	FAIP Service Accepted	No

Released under the Official Information Act

Exposure Number 2

Incident Type 1102: Structure fire with no damage
Address 2-6 Airport Road Whenuapai
Distance Exposure Travelled 3
Surface Material of Exterior Wall Reconstituted wood products
Construction Material of Roof Steel, iron (roll formed steel and corrugated iron)
Method of Heat Transfer Conducted heat

Property Details

Occupant Pinepac Group Companies
Building Owner Owner occupied
General Property Use Industrial, Manufacturing
Special Property Use Sawmill, Wood components, Tanalising mill, Frames, Prefabricated parts
Purpose Group

Actions

Persons Reported Trapped No
Evacuation Status Evacuation in progress
Action Prior 1 Isolating power source
Action Prior 2 Unable to classify
Action Taken Extinguishment only: Includes isolating fuel/power supply

Civilians

Civilians Rescued 0
Civilians Extricated 0
Civilians Assisted 0
Civilians Evacuated

Origin

Location Duct: Air, Heating, Cable, Exhaust
Level Ground level

Equipment Used

Quantity	Equipment
1	Low pressure delivery

Equipment Involved

Equipment Involved
Year
Make
Model

Fire

Arrival Condition	Smoke only		
Heat Source	Exposure fire: Conducted heat		
Termination Stage	Smoulder		
First Object Ignited	Dust, Lint, Fibre, Wood chips, Sawdust, Shavings, Bark		
First Object Material	Shavings, Sawdust, Chips		
Second Object Ignited	Dust, Lint, Fibre, Wood chips, Sawdust, Shavings, Bark		
Second Object Material	Shavings, Sawdust, Chips		
Indicated Cause	Exposure fire		
Certainty of Cause	High		
Age of Person	Unknown		
Ethnicity	Unknown		
Gender			
FAIP Service Offered	No	FAIP Service Accepted	No

Comments

7/9/2017 11:03:20 AM

Reporter Comments

Fire in wood chips within hopper spread to secondary hopper and associated ducting.

Dave Smith