

SMS Incident Report

10/07/2017 13:12:04


Summary

CAD Number F2334700 **Status** Closed
Station West Harbour Station
Incident Started 30/06/2017 12:28:11 **Incident Ended** 30/06/2017 15:58:39
Incident Type 1102: Structure fire with no damage
Common Name KUMEU RUGBY CLUB
Address / 2 Alexandra Street Riverhead
Alarm Method 111 Telephone **Alarm Level** 2
PFA Number
Zone 148602
Map Grid E 1742079 **Map Grid N** 5930517
First Caller **First Caller Contact** ██████████
Incident Closed 30/06/2017 15:58:39
Report Completed 9:48, Sun 09 Jul 2017 by Dave Smith

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
WEST671	P1	12:29:01 30 Jun 2017	12:30:36 30 Jun 2017	12:39:02 30 Jun 2017	14:49:44 30 Jun 2017
KUME861	P1	12:38:16 30 Jun 2017	12:40:07 30 Jun 2017	12:47:03 30 Jun 2017	14:17:44 30 Jun 2017
WAIT771	P1	12:29:17 30 Jun 2017	12:35:26 30 Jun 2017	12:48:06 30 Jun 2017	13:13:33 30 Jun 2017
HELE891	P1	12:46:48 30 Jun 2017	12:47:11 30 Jun 2017	12:50:06 30 Jun 2017	13:13:48 30 Jun 2017
HEND657	PR	12:34:02 30 Jun 2017	12:34:31 30 Jun 2017	12:50:54 30 Jun 2017	13:29:47 30 Jun 2017
VSOWAITEM2	VSO	12:48:22 30 Jun 2017	12:48:26 30 Jun 2017	12:53:21 30 Jun 2017	13:15:58 30 Jun 2017
AUCKOSU2	SV	12:45:20 30 Jun 2017	12:52:41 30 Jun 2017	13:03:41 30 Jun 2017	13:07:39 30 Jun 2017
BETH7576	RWT	12:43:06 30 Jun 2017	12:51:13 30 Jun 2017	13:09:15 30 Jun 2017	14:56:12 30 Jun 2017
FIWAITEM3	FSO	13:20:27 30 Jun 2017	13:25:45 30 Jun 2017		13:26:58 30 Jun 2017
FIAKCITY4	FSO				13:10:17 30 Jun 2017
AUCKOSU1	SV	12:42:53 30 Jun 2017			13:11:06 30 Jun 2017
WAIT7772	RP	12:43:09 30 Jun 2017			13:06:49 30 Jun 2017
WAITEMATA2	OF	12:44:49 30 Jun 2017	12:48:29 30 Jun 2017		13:21:33 30 Jun 2017
FIAKCITY3	FSO	13:10:50 30 Jun 2017			13:21:14 30 Jun 2017

Start->Alert 7 min 10 min



Alert->1st Arrival

Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
WEST671	00:00:50	00:10:01	00:10:51	02:21:33
KUME861	00:10:05	00:08:47	00:18:52	01:49:33
WAIT771	00:01:06	00:18:49	00:19:55	00:45:22
HELE891	00:18:37	00:03:18	00:21:55	00:45:37
HEND657	00:05:51	00:16:52	00:22:43	01:01:36
VSOWAITEM2	00:20:11	00:04:59	00:25:10	00:47:47
AUCKOSU2	00:17:09	00:18:21	00:35:30	00:39:28
BETH7576	00:14:55	00:26:09	00:41:04	02:28:01
FIWAITEM3	00:52:16			00:58:47
FIAKCITY4				00:42:06
AUCKOSU1	00:14:42			00:42:55
WAIT7772	00:14:58			00:38:38
WAITEMATA2	00:16:38			00:53:22
FIAKCITY3	00:42:39			00:53:03

Notifications

Date	Time	Party Notified
30 Jun 2017	12:30:02	SELCAL FAILED WAIT771
30 Jun 2017	12:42:26	VECTOR
30 Jun 2017	12:43:20	AAC WAITEMATA
30 Jun 2017	12:43:35	AAC COUNTIES MANUKAU 4
30 Jun 2017	12:43:40	CFO/DCFO KUMEU
30 Jun 2017	12:43:46	OSU AUCKLAND
30 Jun 2017	12:47:13	ACC COUNTIES4 CHRIS DELFOS ACK PAGE - WILL MONITOR
30 Jun 2017	12:47:37	WAIT771 AND KUME861 BOTH SHORT CREWED
30 Jun 2017	13:14:28	VIA PHONE FROM JASON GOFFIN, HE ADV THIS IS NOT HIS AREA AND WE WOULD NEED
30 Jun 2017	13:18:28	FI AK CITY 4 CALLS CLAIMS THAT IN BUSINESS HRS A LOCAL AREA FI SHOUDL BE
30 Jun 2017	13:18:42	FI WAITEMATA1 (GARY BEER) / FI WAITEMATA3 (CHRISTINE MCGINTY) / FI
30 Jun 2017	13:21:56	FI UPTON CONTACTED COMMS, ADVISED FI WAITEMATA3 WILL NOW RESPOND. FI UPTON
30 Jun 2017	13:25:52	FIWAITEM3 PAGED STAND DOWN
30 Jun 2017	14:54:58	BTHELLS PAGED TO CONTACT COMMS

Caution: The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside the NZ Fire Service or the National Rural Fire Authority without prior approval

Message Log

Time	Message
12:28:45	INC INFO: SMOKE SHOWING
12:28:46	** LOI search completed at 30/06/17 12:28:46
12:28:54	** Recommended unit WEST671 for requirement PUMP (>6.7 km)
12:28:54	** Recommended unit WAIT771 for requirement PUMP (>10.7 km)
12:29:21	SMOKE COMING FROM SECOND FLOOR
12:29:48	FR NZFS
12:30:36	Unit WEST671 [K1 : PROCEEDING TO INCIDENT]
12:30:54	** Requirement PUMP added for alarm level 1
12:30:57	** Requirement PUMP removed for alarm level 1
12:32:52	Unit WEST671 [KC : UNIT CALLING]
12:33:34	Unit WEST671 [COMCEN COM : MESSAGE] ARE WAITAKERE LIKELY TO BE RESPONDING AND FULLY CREW
12:33:44	Unit WEST671 [SITREP :] ATTACH ANOTHER PUMP
12:33:47	** Requirement PUMP added for alarm level 1
12:33:49	** Recommended unit HEND657 for requirement ADHOC PUMP (>14.2 km)
12:34:31	Unit HEND657 [K1 : PROCEEDING TO INCIDENT]
12:34:33	** Requirement PUMP removed for alarm level 1
12:35:26	Unit WAIT771 [K1 : PROCEEDING TO INCIDENT]
12:35:27	Unit WEST671 [COMCEN COM : MESSAGE] ONE CALL - SMOKE SHOWING FROM THE SECOND FLOOR
12:36:01	Unit WAIT771 [KC : UNIT CALLING]
12:36:06	Unit WAIT771 [KC : UNIT CALLING]
12:36:20	Unit WAIT771 [KC : UNIT CALLING]
12:36:31	Unit WAIT771 [SITREP :] RESPONDING SHORT CREWED - OFFICER, DRIVER AND ONE
12:36:37	Unit WEST671 [SITREP :] COPIED
12:39:03	Unit WEST671 [K77 : NOTHING SHOWING]
12:39:07	Unit KUME861 [SITREP :] CREW OF 3 AVAILABLE (OFFICER AND 2)
12:40:06	Unit KUME861 [K39 : RE-TRANSMIT YOUR CURRENT STATUS]
12:40:07	Unit KUME861 [K1 : PROCEEDING TO INCIDENT]
12:41:30	Unit WEST671 [KP : PRIORITY MESSAGE]
12:41:57	Unit WEST671 [KP : PRIORITY MESSAGE] SO SMITH. SMOKE ON FLOOR. TRANSMIT SECOND ALARM
12:42:08	INC INFO: SECOND ALARM - SMOKE SHOWING
12:42:32	** Requirement PUMP added for alarm level 1
12:42:44	** Alarm level updated to 2
12:42:44	** Recommended unit WAIT7772 for requirement RPUMP (>10.7 km)

12:42:44	** Recommended unit AUCKOSU1 for requirement SUPPT (>29.8 km)
12:42:44	** Recommended unit BETH7576 for requirement TANKER (>15.0 km)
12:43:10	FIR2AMB FYI - 2ND ALARM BUILDING FIRE
12:43:26	AMBO EVENT 0431-1-2017/06/30-FIR LINKED AT 30/06/2017 12:43:26
12:43:35	FIR2POL FYI - 2ND ALARM BUILDING FIRE
12:47:04	Unit KUME861 [K2 : IN ATTENDANCE AT INCIDENT]
12:47:12	Unit HELE891 [K1 : PROCEEDING TO INCIDENT]
12:48:07	Unit WAIT771 [K2 : IN ATTENDANCE AT INCIDENT]
12:48:11	Unit WAIT771 [K2 : IN ATTENDANCE AT INCIDENT]
12:48:26	Unit VSOWAITEM2 [K1 : PROCEEDING TO INCIDENT]
12:48:30	Unit WAITEMATA2 [K1 : PROCEEDING TO INCIDENT]
12:48:42	Unit WAITEMATA2 [K1 : PROCEEDING TO INCIDENT]
12:48:48	Unit WAIT771 [K2 : IN ATTENDANCE AT INCIDENT]
12:49:16	Unit WAITEMATA2 [K1 : PROCEEDING TO INCIDENT]
12:50:08	Unit HELE891 [K2 : IN ATTENDANCE AT INCIDENT]
12:50:53	Unit WEST671 [SITREP :] SO SMITH. BUILDING 2 FLOORS APPROX 20 X 30. USED AS
12:50:53	RUGBY CLUB. SMOKE LOGGED FIRST FLOOR. 2 HPD.
12:50:55	Unit HEND657 [K2 : IN ATTENDANCE AT INCIDENT]
12:51:14	Unit BETH7576 [K1 : PROCEEDING TO INCIDENT] VERBAL
12:52:41	Unit AUCKOSU2 [K1 : PROCEEDING TO INCIDENT]
12:53:22	Unit VSOWAITEM2 [K2 : IN ATTENDANCE AT INCIDENT]
12:54:06	COVERING UNIT GLEN641 DISPATCHED TO STATION TE ATATU AT
12:54:06	D0710063
12:54:42	COVERING UNIT TITI691 DISPATCHED TO STATION GLEN EDEN AT
12:54:42	D0710063
13:03:41	Unit AUCKOSU2 [K2 : IN ATTENDANCE AT INCIDENT]
13:06:50	Unit WAIT7772 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] DID NOT RESPOND - HELE891
13:06:50	REDIRECTED FROM ANOTHER EVENT
13:07:15	Unit WEST671 [KC : UNIT CALLING]
13:07:37	Unit WEST671 [K11F : FIRE SAFETY REQUIRED]
13:07:41	Unit AUCKOSU2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
13:08:05	INC INFO: 2ND ALARM - SMOKE SHOWING TOC 1228 TOA 1239
13:08:52	Unit BETH7576 [KC : UNIT CALLING]
13:09:15	Unit BETH7576 [K2 : IN ATTENDANCE AT INCIDENT] ON SCENE AT KUMEU
13:10:18	Unit FIAKCITY4 [K6 : ON TELEPAGER]
13:11:07	Unit AUCKOSU1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
13:13:35	Unit WAIT771 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
13:13:50	Unit HELE891 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
13:14:28	TO CONTACT A FI FROM THE WAITEMATA AREA, THERE ARE NO FI ON THE ROSTER FOR
13:14:28	WAITEMATA

13:16:00	Unit VSOWAITEM2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
13:18:28	AVAILABLE. SM POINTED OUT THSI WAS NOT THE CASE IN SOPS. AGREED TO TRY ALL
13:18:28	WAITEMATA FI'S TO SEE IF OEN COULD GO
13:18:42	WAITEMATA4 (MICHAEL UPTON) PAGED TO RING FIRECOMS
13:20:17	Unit WEST671 [KC : UNIT CALLING]
13:20:55	Unit WEST671 [SITREP :] LOCATION AND ETA FOR FIRE SAFETY OFFICER
13:21:15	Unit FIAKCITY3 [K6 : ON TELEPAGER]
13:21:17	Unit WEST671 [COMCEN COM : MESSAGE] STANDBY. WE WILL ADVISE WHEN KNOWN
13:21:35	Unit WAITEMATA2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
13:21:53	Unit WEST671 [COMCEN COM : MESSAGE] FI WAITEMATA3 CHRISTINE MCGINTY IS
13:21:53	RESPONDING - WE DO NOT HAVE AN ETA AT THE MOMENT
13:21:56	IS ON CALL OVER NIGHT
13:24:12	Unit WEST671 [KC : UNIT CALLING]
13:24:50	Unit WEST671 [K28 : UNIT IS TO RETURN TO STATION] FIRE SAFETY
13:25:46	Unit FIWAITEM3 [K1 : PROCEEDING TO INCIDENT]
13:26:59	Unit FIWAITEM3 [K6 : ON TELEPAGER]
13:29:48	Unit HEND657 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
14:00:35	Unit KUME861 [K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]
14:17:46	Unit KUME861 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
14:48:20	Unit WEST671 [KC : UNIT CALLING]
14:49:04	Unit WEST671 [STOP : MESSAGE] DISH WASHER FIRE. POWER ISOLATED. DISH WAHSER
14:49:04	REMOVED FROM BUILDING. VENTILLATION. INCIDENT LEFT WITH RUGBY CLUB
14:49:45	MANAGEMENT
14:49:45	Unit WEST671 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
14:50:35	Unit BETH7576 [COMCEN COM : MESSAGE] NO ANSWER WHEN CALLED (X2)
14:51:35	BIT WEST671 CONFIRM BETHELLS HAVE LEFT THE FIREGROUND
14:53:18	Unit BETH7576 [COMCEN COM : MESSAGE] NO ANSWER TO STATION PHONE
14:56:13	Unit BETH7576 [K7 : AT NORMAL STATION]
15:58:39	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,
15:58:39	Qualifier 2:

Incident

CAD Number	F2334700
Incident Reporter	Dave Smith
Incident Controller	SO Dave Smith
Distance Travelled (km)	7
Delay In Receiving Call	Information not recorded

Property Details

Occupant	Kumeu Rugby Club
-----------------	------------------

Building Owner Unknown
General Property Use Sports club, Health club
Special Property Use Sports clubroom for: Athletics, Rugby, Golf, Boating, Sailing, Health clubs, YMCA etc
Purpose Group

Actions

Persons Reported Trapped No
Evacuation Status Not occupied at time of incident
Action Prior 1 Action prior - not classified above
Action Prior 2 Action prior - not classified above
Action Taken Ventilation only

Civilians

Civilians Rescued 0
Civilians Extricated 0
Civilians Assisted 0
Civilians Evacuated

Origin

Location Kitchen, Cooking area
Level 1st floor

Equipment Used

Quantity	Equipment
1	Vehicle Radio (LMR)
4	Handheld Radio (or Cellphone)
1	Thermal Imaging Camera

Equipment Involved

Equipment Involved
Year 2002
Make Starline
Model GA537

Fire

Arrival Condition Smoke only
Heat Source Arcing or overloaded electrical equipment - not classified above
Termination Stage Flame
First Object Ignited Electrical wire, Wiring insulation

First Object Material	PVC eg. Floor Tiles, Guttering/Pipes, Plastic Bags, Elec. Insulation		
Second Object Ignited	Electronic componentry		
Second Object Material	PVC eg. Floor Tiles, Guttering/Pipes, Plastic Bags, Elec. Insulation		
Indicated Cause	Other electrical failure		
Certainty of Cause	High		
Age of Person	Unknown		
Ethnicity	Unknown		
Gender			
FAIP Service Offered	No	FAIP Service Accepted	No

Alarms

Type of Alarm Initiating Call	Smoke Detector System (Monitored)
Performance of System	Alerted neighbour/passersby - detector in room of origin
Failure/Ineffectiveness of system	Unable to classify
Number of sprinkler heads operated	

Comments

7/9/2017 9:48:44 AM

Reporter Comments

Dishwasher fire out on arrival extinguished by dishwashers' own water supply.

Dave Smith

Released under the Official Information Act