SMS Incident Report

17/07/2017 14:22:48

Summary

CAD Number F2170003 Status Closed

Station Titirangi Station

Incident Started 17/10/2016 10:54:24 Incident Ended 17/10/2016 11:39:53

Incident Type 7106: False alarm: Undetermined alarm activation

Common Name

Address 16A GLENVAR ROAD TORBAY

Alarm Method 111 from Private Monitoring Alarm Level 1

Company

PFA Number

Zone 148385

 Map Grid E
 1756109
 Map Grid N
 5937781


First Caller ADT SECURITY LIMITED First Caller Contact

Incident Closed 17/10/2016 11:39:53

Report Completed 15:28, Mon 17 Oct 2016 by Dave Smith

Responses

| Call Sign | Туре | Station Alert | Enroute Time | Arrival Time | Departed |
|-----------|------|----------------------|----------------------|----------------------|----------------------|
| TITI691 | P1 | 10:55:04 17 Oct 2016 | 10:56:27 17 Oct 2016 | 11:10:43 17 Oct 2016 | 11:22:32 17 Oct 2016 |



Elapsed Times

| Call Sign | Start To Alert | Alert To Arrival | Start To Arrival | Start To Departed |
|-----------|----------------|------------------|------------------|-------------------|
| TITI691 | 00:00:40 | 00:15:39 | 00:16:19 | 00:28:08 |

Message Log

| Time | Message | |
|----------|--|--|
| 10:54:50 | INC INFO: ALARM ACTIVATION - RESIDENTIAL | |
| 10:54:57 | ** Recommended unit TITI691 for requirement PUMP (>7.7 km) | |
| 10:54:59 | OCCUPANTS NAME: | |
| 10:55:03 | ** LOI search completed at 17/10/16 10:55:03 | |
| 10:55:04 | CONTACT MADE WITH OWNER | |
| 10:55:08 | 1 HR AWAY | |
| 10:55:21 | WILL NOT BE RETURNING HOME | |
| 10:55:34 | REQ BRIGADE TO ATTEND | |
| 10:56:28 | Unit TITI691 [K1 : PROCEEDING TO INCIDENT] | |
| 11:01:56 | Unit TITI691 [COMCEN COM : MESSAGE] FURTHER DETAILS PASSED | |
| 11:10:44 | Unit TITI691 [K77 : NOTHING SHOWING] | |
| 11:11:59 | Unit TITI691 [KC : UNIT CALLING] | |
| 11:12:28 | Unit TITI691 [SITREP :] SO SMITH. INV RESIDENTIAL SMOKE ALARM ACTIVATION | |
| 11:20:03 | Unit TITI691 [KC : UNIT CALLING] | |
| 11:20:48 | Unit TITI691 [STOP : MESSAGE] UNDETERMINED ACTIVATION | |
| 11:22:33 | Unit TITI691 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] | |
| 11:39:53 | ** Assigned Result Code: MIN, Detailed Event Type: 7100, Qualifier 1: Q1, | |
| 11:39:53 | Qualifier 2: | |

Incident

| CAD Number | F2170003 |
|-------------------------|---------------|
| Incident Reporter | Dave Smith |
| Incident Controller | SO Dave Smith |
| Distance Travelled (km) | 8 |

Delay In Receiving Call Information not recorded

False Alarm

| Detector Type | Smoke alarm (mains powered) |
|-------------------|--------------------------------|
| False Alarm Cause | Equipment Unable to classify |
| Other Cause | Undetermined Alarm Activation |

Property Details

Occupant

Building Owner

General Property Use Single house
Special Property Use Single house

Purpose Group

SH - Sleeping Household

Comments

10/17/2016 3:27:10 PM

Reporter Comments

Repart of the official information and a selection of the control Key holder in attendance (friends of owner). I spoke with owner per telephone to discuss possible reason for activation. System had been in for 3 months with no issues up until todays activation.

Dave Smith