

SMS Incident Report

24/07/2017 14:16:39

Summary

CAD Number F2346906 **Status** Closed

Station Papatoetoe Station

Incident Started 20/07/2017 13:15:27 **Incident Ended** 20/07/2017 13:27:29

Incident Type 7104: False alarm: Accidental operation

Common Name RAINBOWS END FRONT ENTRY

Address 2 CLIST CRESCENT MANUKAU

Alarm Method Automatic PFA Call **Alarm Level** 1

PFA Number 117322

Zone 143403

Map Grid E 1767709 **Map Grid N** 5904181


First Caller **First Caller Contact**

Incident Closed 20/07/2017 14:19:27

Report Completed 8:31, Fri 21 Jul 2017 by Eddie Randall

Responses

| Call Sign | Type | Station Alert | Enroute Time | Arrival Time | Departed |
|-----------|------|----------------------|----------------------|----------------------|----------------------|
| PAPA344 | PM | 13:15:48 20 Jul 2017 | 13:16:49 20 Jul 2017 | 13:20:45 20 Jul 2017 | 13:28:15 20 Jul 2017 |
| MANU301 | P1 | 13:15:51 20 Jul 2017 | 13:17:32 20 Jul 2017 | 13:21:50 20 Jul 2017 | 13:22:50 20 Jul 2017 |
| PAPA347 | PR | 13:15:45 20 Jul 2017 | 13:17:27 20 Jul 2017 | 13:22:22 20 Jul 2017 | 13:23:05 20 Jul 2017 |



Elapsed Times

| Call Sign | Start To Alert | Alert To Arrival | Start To Arrival | Start To Departed |
|-----------|----------------|------------------|------------------|-------------------|
| PAPA344 | 00:00:21 | 00:04:57 | 00:05:18 | 00:12:48 |
| MANU301 | 00:00:24 | 00:05:59 | 00:06:23 | 00:07:23 |
| PAPA347 | 00:00:18 | 00:06:37 | 00:06:55 | 00:07:38 |

Message Log

| Time | Message |
|----------|---|
| 13:15:29 | AL: 117322 13:15:27 INITIAL - AL |
| 13:15:29 | AL: 117322 13:15:29 UPDATE - AL |
| 13:15:29 | PANEL: MAIN ENTRANCE DOOR |
| 13:15:30 | ** LOI search completed at 20/07/17 13:15:30 |
| 13:15:36 | ** Recommended unit PAPA344 for requirement AERIAL (>1.4 km) |
| 13:15:36 | ** Recommended unit PAPA347 for requirement PUMP (>1.4 km) |
| 13:15:36 | ** Recommended unit MANU301 for requirement PUMP (>3.7 km) |
| 13:16:49 | Unit PAPA344 [K1 : PROCEEDING TO INCIDENT] |
| 13:17:27 | Unit PAPA347 [K1 : PROCEEDING TO INCIDENT] |
| 13:17:32 | Unit MANU301 [K1 : PROCEEDING TO INCIDENT] |
| 13:20:46 | Unit PAPA344 [K77 : NOTHING SHOWING] |
| 13:21:51 | Unit MANU301 [K2 : IN ATTENDANCE AT INCIDENT] |
| 13:22:22 | Unit PAPA347 [K2 : IN ATTENDANCE AT INCIDENT] |
| 13:22:34 | Unit PAPA344 [KC : UNIT CALLING] |
| 13:22:51 | Unit MANU301 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA] |
| 13:23:06 | Unit PAPA347 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] |
| 13:26:54 | Unit PAPA344 [KC : UNIT CALLING] |
| 13:27:29 | Unit PAPA344 [K46-2 : STOP MESSAGE: FALSE ALARM ACCIDENTAL] SO RANDELL K46-2 |
| 13:27:29 | WORKMEN SANDING |
| 13:28:16 | Unit PAPA344 [K4 : ON RT INSIDE NORMAL TURNOUT AREA] |
| 14:19:27 | ** Assigned Result Code: STRU, Detailed Event Type: 7100, Qualifier 1: Q1, |
| 14:19:27 | Qualifier 2: |

Incident

CAD Number F2346906
Incident Reporter Eddie Randall
Incident Controller Eddie Randall
Distance Travelled (km)
Delay In Receiving Call

False Alarm

Detector Type Smoke detector
False Alarm Cause Human Intervention | Accidental alarm activation by (b) contractor (not the service agent)
Other Cause

Property Details

Occupant

Building Owner

General Property Use Recreational use, Theatre, Indoor sports, Pool, Park, Zoo, Aquarium

Special Property Use Playground, Park, Amusement park

Purpose Group CL - Crowd Large

Comments

7/21/2017 8:31:15 AM

Reporter Comments

Contractors sanding in room of detector activation.

Eddie Randall

Released under the Official Information Act