

SMS Incident Report


11/08/2017 08:50:02

Summary

CAD Number F2355610 **Status** Closed
Station East Coast Bays Station
Incident Started 02/08/2017 19:21:31 **Incident Ended** 02/08/2017 19:41:32
Incident Type 7103: False alarm: Defective
Common Name FREELING HOLT HOUSE
Address 9A MAWSON AVENUE TORBAY
Alarm Method 111 Telephone **Alarm Level** 1
PFA Number
Zone 14838501
Map Grid E 1755550 **Map Grid N** 5936202
First Caller FREELING HOLT TRUST **First Caller Contact** ██████████
Incident Closed 02/08/2017 19:51:59
Report Completed 23:33, Wed 02 Aug 2017 by Al Barr

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
EAST831	P1	19:22:15 02 Aug 2017	19:23:33 02 Aug 2017	19:29:43 02 Aug 2017	19:41:35 02 Aug 2017
TAKA807	PR	19:22:21 02 Aug 2017	19:23:24 02 Aug 2017	19:33:10 02 Aug 2017	19:33:53 02 Aug 2017
EAST832	P2	19:22:12 02 Aug 2017			19:33:51 02 Aug 2017
ALBA851	P1	19:22:18 02 Aug 2017	19:23:28 02 Aug 2017		19:34:42 02 Aug 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
EAST831	00:00:44	00:07:28	00:08:12	00:20:04
TAKA807	00:00:50	00:10:49	00:11:39	00:12:22
EAST832	00:00:41			00:12:20

ALBA851	00:00:47		00:13:11
---------	----------	--	----------

Message Log

Time	Message
19:21:53	INC INFO: ALARM ACTIVATION - COMMERCIAL
19:21:54	** LOI search completed at 02/08/17 19:21:54
19:22:02	** Recommended unit EAST831 for requirement PUMP (>2.2 km)
19:22:02	** Recommended unit EAST832 for requirement PUMP (>2.2 km)
19:22:02	** Recommended unit ALBA851 for requirement PUMP (>6.0 km)
19:22:02	** Recommended unit TAKA807 for requirement CANBACKUP (>7.7 km)
19:22:32	NO SIGN OF SMOKE OR FIRE BUT ALARM SOUNDING
19:23:25	Unit TAKA807 [K1 : PROCEEDING TO INCIDENT]
19:23:29	Unit ALBA851 [K1 : PROCEEDING TO INCIDENT]
19:23:33	Unit EAST831 [K1 : PROCEEDING TO INCIDENT]
19:29:44	Unit EAST831 [K77 : NOTHING SHOWING]
19:31:24	Unit EAST832 [KC : UNIT CALLING]
19:32:08	Unit EAST831 [KC : UNIT CALLING]
19:32:17	Unit EAST832 [KE : UNABLE TO PROCEED - STATE REASON] INSUFFICIENT CREW
19:32:46	Unit EAST831 [SITREP :] SO BURR IPS SMOKE DETECTOR ZONE 4
19:33:10	Unit TAKA807 [K2 : IN ATTENDANCE AT INCIDENT]
19:33:18	Unit EAST831 [KC : UNIT CALLING]
19:33:45	Unit EAST831 [K28-1 : RETURN OTHER RESPONDING UNITS]
19:33:52	Unit EAST832 [K7 : AT NORMAL STATION]
19:33:54	Unit TAKA807 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
19:34:43	Unit ALBA851 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
19:41:13	Unit EAST831 [KC : UNIT CALLING]
19:41:33	Unit EAST831 [K46-3 : STOP MESSAGE: FALSE ALARM DEFECTIVE APPARATUS]
19:41:37	Unit EAST831 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
19:51:58	** Assigned Result Code: STRU, Detailed Event Type: 7100, Qualifier 1: Q1,
19:51:58	Qualifier 2:

Incident

CAD Number	F2355610
Incident Reporter	Al Barr
Incident Controller	Al Barr
Distance Travelled (km)	5
Delay In Receiving Call	

False Alarm

Detector Type	Smoke alarm (mains powered)
False Alarm Cause	Other Unable to classify
Other Cause	none

Property Details

Occupant	
Building Owner	
General Property Use	Hospital, Hospice, Rest home, Rehabilitation centre
Special Property Use	Rest home: With nursing care
Purpose Group	SC - Sleeping Care

Released under the Official Information Act