SMS Incident Report

01/09/2017 08:22:54

Summary	
CAD Number	F2370907 Status Closed
Station	East Coast Bays Station
Incident Started	30/08/2017 09:01:32 Incident Ended 30/08/2017 09:31:34
Incident Type	4402: Arcing, shorted electrical equipment
Common Name	
Address	13A EASTWOOD RISE BROWNS BAY
Alarm Method	111 Telephone Alarm Level 1
PFA Number	
Zone	148385
Map Grid E	1754255 Map Grid N 5934496
First Caller	First Caller Contact
Incident Closed	30/08/2017 09:43:24
Report Completed	14:22, Wed 30 Aug 2017 by Nick Penfold
Responses	<u>S</u>

Responses

_

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
EAST831	P1	09:02:30 30 Aug 2017	09:03:59 30 Aug 2017	09:10:08 30 Aug 2017	09:33:55 30 Aug 2017
ALBA851	P1	09:02:33 30 Aug 2017	09:03:56 30 Aug 2017	09:11:53 30 Aug 2017	09:19:58 30 Aug 2017
Start->Alert	7 min	10 min			
	0				
in	20P		15 min		m
	Alert->1st A	Arrival			

Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
EAST831	00:00:58	00:07:38	00:08:36	00:32:23
ALBA851	00:01:01	00:09:20	00:10:21	00:18:26

Caution: The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside NZ Fire and Emergency without prior approval

Message Log	
Time	Message
09:02:04	INC INFO: POWER POINT SPARKING
09:02:05	** LOI search completed at 30/08/17 09:02:05
09:02:11	** Recommended unit EAST831 for requirement PUMP (>1.7 km)
09:02:11	** Recommended unit ALBA851 for requirement PUMP (>3.9 km)
09:02:38	CALLER TURNING POWER OFF AT THE MAINS
09:03:56	Unit ALBA851 [K1 : PROCEEDING TO INCIDENT]
09:03:59	Unit EAST831 [K1 : PROCEEDING TO INCIDENT]
09:10:09	Unit EAST831 [K77 : NOTHING SHOWING]
09:11:53	Unit ALBA851 [K2 : IN ATTENDANCE AT INCIDENT]
09:17:33	Unit EAST831 [KC : UNIT CALLING]
09:18:06	Unit EAST831 [SITREP :] SO PENFOLD WATER LEAKING IN WALL POWER ISOLATED
09:19:58	Unit ALBA851 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
09:31:17	Unit EAST831 [KC : UNIT CALLING]
09:31:35	Unit EAST831 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE]
09:33:56	Unit EAST831 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
09:41:08	BUSINESS RULE CHECKS CANCELLED AT 30/08/17 09:41:08
09:43:24	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,
09:43:24	Qualifier 2:

Incident	
CAD Number	F2370907
Incident Reporter	Nick Penfold
Incident Controller	N Penfold
Distance Travelled (km)	3
Delay In Receiving Call	
Property Details	
Occupant S	
Building Owner	
General Property Use	Flat, Apartment, Home unit
Special Property Use	Flats, Apartments, Units 1 to 2
Purpose Group	

Actions

Persons Reported Trapped	
Evacuation Status	
Action Prior 1	

Caution: The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside NZ Fire and Emergency without prior approval

3/3

Action Prior 2 Action Taken

Extinguishment only: Includes isolating fuel/power supply

Origin

Oligin		
Location	Dining area, Cafeteria, Canteen, Servery, Bar area	
Level	Ground level	

Equipment Used

Quantity	Equipment	
1	Dry powder extinguisher	
1	Hand tools - Crowbar, Saw, Hammer, Mop, Broom, Misc small gear	ALL OF THE OF TH

Equipment Involved

Equipment	Involved
-----------	----------

Year

Make

Model

Com

pment Involved	, C	00
ment Involved		> -
aments		
	8/30/2017 2:22:44 PM	Reporter Comments
water leaking inside wall caused plug socket to short circuit		
XO'		Nick Penfold
0		
2182580		
<u> </u>		
Y		