

SMS Incident Report


31/08/2017 16:32:14

Summary

CAD Number F2371445 **Status** Closed
Station Rotorua Station
Incident Started 31/08/2017 02:40:01 **Incident Ended** 31/08/2017 02:58:35
Incident Type 7103: False alarm: Defective
Common Name ROTORUA ENERGY EVENTS CENTRE
Address / Queens Drive Rotorua
Alarm Method 111 Telephone **Alarm Level** 1
PFA Number
Zone 188122
Map Grid E 1885718 **Map Grid N** 5774108
First Caller [REDACTED] **First Caller Contact** [REDACTED]
Incident Closed 31/08/2017 03:00:27
Report Completed 6:44, Thur 31 Aug 2017 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
ROTO811	P1	02:40:58 31 Aug 2017	02:42:40 31 Aug 2017	02:46:58 31 Aug 2017	03:00:11 31 Aug 2017
ROTO814	PM	02:40:58 31 Aug 2017	02:42:57 31 Aug 2017	02:48:52 31 Aug 2017	02:52:39 31 Aug 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
ROTO811	00:00:57	00:06:00	00:06:57	00:20:10
ROTO814	00:00:57	00:07:54	00:08:51	00:12:38

Message Log

Time	Message
02:40:39	INC INFO: ALARM SOUNDING
02:40:40	** LOI search completed at 31/08/17 02:40:40
02:40:52	** Recommended unit ROTO814 for requirement MONIT (>2.1 km)
02:40:52	** Recommended unit ROTO811 for requirement PUMP (>2.1 km)
02:41:06	CALLER ADV NSOF
02:42:41	Unit ROTO811 [K1 : PROCEEDING TO INCIDENT]
02:42:57	Unit ROTO814 [K1 : PROCEEDING TO INCIDENT]
02:46:59	Unit ROTO811 [K77 : NOTHING SHOWING]
02:48:52	Unit ROTO814 [K2 : IN ATTENDANCE AT INCIDENT]
02:48:59	Unit ROTO811 [KC : UNIT CALLING]
02:50:01	Unit ROTO811 [SITREP :] SO [REDACTED] PS FIRE & DEFECT ZONE 1 BELLS RINGING
02:50:01	CARETAKER IN ATT
02:52:39	Unit ROTO814 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
02:58:21	Unit ROTO811 [KC : UNIT CALLING]
02:58:35	Unit ROTO811 [K46-3 : STOP MESSAGE: FALSE ALARM DEFECTIVE APPARATUS]
03:00:11	Unit ROTO811 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
03:00:27	** Assigned Result Code: STRU, Detailed Event Type: 7100, Qualifier 1: Q1,
03:00:27	Qualifier 2:

Incident

CAD Number F2371445
Incident Reporter [REDACTED]
Incident Controller SSO [REDACTED]
Distance Travelled (km) 3
Delay In Receiving Call

False Alarm

Detector Type Smoke detector
False Alarm Cause Internal Environment | Flooding or water leaks
Other Cause

Property Details

Occupant
Building Owner
General Property Use Recreational use, Theatre, Indoor sports, Pool, Park, Zoo, Aquarium
Special Property Use Indoor sports centre

Purpose Group

CL - Crowd Large

Comments

8/31/2017 6:44:35 AM

Reporter Comments

Panel showing zone 1-4 Sportsdrome. Water found leaking through ceiling into smoke detector.



Released under the Official Information Act