

SMS Incident Report


26/09/2017 17:31:52

Summary

CAD Number F2377052 **Status** Closed
Station Sumner Volunteer Fire Brigade
Incident Started 10/09/2017 20:32:27 **Incident Ended** 10/09/2017 23:37:31
Incident Type 1101: Structure fire with damage
Common Name
Address 78 CLIFTON TERRACE CLIFTON
Alarm Method 111 Telephone **Alarm Level** 2
PFA Number
Zone 342801
Map Grid E 1580085 **Map Grid N** 5176059
First Caller **First Caller Contact** ██████████
Incident Closed 11/09/2017 01:44:27
Report Completed 12:54, Wed 13 Sep 2017 by Daryl Sayer

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
SUMN281	P1	20:33:27 10 Sep 2017	20:36:07 10 Sep 2017	20:40:10 10 Sep 2017	23:37:33 10 Sep 2017
WOOL241	P1	20:33:30 10 Sep 2017	20:35:05 10 Sep 2017	20:42:16 10 Sep 2017	22:43:44 10 Sep 2017
CHRI217	PR	20:37:58 10 Sep 2017	20:39:03 10 Sep 2017	20:54:02 10 Sep 2017	22:29:57 10 Sep 2017
LYTT291	P1	20:37:55 10 Sep 2017	20:41:29 10 Sep 2017	20:54:15 10 Sep 2017	22:11:59 10 Sep 2017
WAIN321	P1	20:54:21 10 Sep 2017	20:56:54 10 Sep 2017	21:08:48 10 Sep 2017	22:57:35 10 Sep 2017
CHRI214	PM	20:56:16 10 Sep 2017	20:56:58 10 Sep 2017	21:09:42 10 Sep 2017	21:30:19 10 Sep 2017
VSOCHR11	VSO	23:14:52 10 Sep 2017	23:14:53 10 Sep 2017	00:38:48 11 Sep 2017	00:57:58 11 Sep 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
SUMN281	00:01:00	00:06:43	00:07:43	03:05:06
WOOL241	00:01:03	00:08:46	00:09:49	02:11:17
CHRI217	00:05:31	00:16:04	00:21:35	01:57:30
LYTT291	00:05:28	00:16:20	00:21:48	01:39:32
WAIN321	00:21:54	00:14:27	00:36:21	02:25:08
CHRI214	00:23:49	00:13:26	00:37:15	00:57:52
VSOCHRI1	02:42:25	01:23:56	04:06:21	04:25:31


Notifications

Date	Time	Party Notified
10 Sep 2017	20:34:21	POWER
10 Sep 2017	20:38:29	FI CANTY PAGED RE 2ND ALARM
10 Sep 2017	20:38:56	PAGED AREA CHRISTCHURCH RE 2ND ALARM
10 Sep 2017	20:41:16	CHRISTCHURCH1 STACKHOUSE ACK PAGE KEEP UPDATED
10 Sep 2017	20:41:47	TUNNEL CONTROL
10 Sep 2017	20:42:24	PAGED CFO/DCFO SUMNER RE K99 2ND ALARM
10 Sep 2017	20:46:11	FI CHRISTCHURCH (MARK THOMAS) ACK PAGE
10 Sep 2017	20:48:53	REPAGED CFO/DCFO SUMNER RE 2ND ALARM K99
10 Sep 2017	20:49:05	VSO CANTY CHCH PAGED RE K99
10 Sep 2017	20:51:07	VSO CANTERBURY (ALAN HICKMAN) ACK PAGE
10 Sep 2017	20:53:11	PAGED AREA CHCH, CFO/DCOF SUMNER RE AMBULANCE REPORTS OF PATIENT
10 Sep 2017	20:55:31	CHCH1 STACKHOUSE ACK PAGE RE PATIENTS - DISCUSSED SITUATION RE COVERAGE
10 Sep 2017	20:58:14	DCFO SUMNER ACK PAGE ADVISES CFO IS ON SCENE
10 Sep 2017	21:06:05	FI CHRISTCHURCH PAGED RE INJURIES
10 Sep 2017	21:06:16	PAGED AREA CHCH, REGION 4 DUTY RE INJURIES
10 Sep 2017	21:08:02	FI CHCH ACK PAGE UPDATED WITH INJURIES
10 Sep 2017	21:08:23	CHCH1 STACKHOUSE ACK PAGE
10 Sep 2017	21:10:31	REGION 4 TUREK ACK PAGE GIVEN UPDATE
10 Sep 2017	22:07:28	PAGED AREA CHCH, REGION 4 DUTY RE PATIENTS TRANSPORTED
10 Sep 2017	22:10:28	REGION 4 TUREK ACK PAGE
10 Sep 2017	22:58:04	VSO CANTERBURY/CHRISTCHURCH PAGED
10 Sep 2017	23:00:05	VSO CANTERBURY/CHRISTCHURCH (ALAN HICKMAN) ACK PAGE AND PUT THROUGH TO


Message Log

Time	Message
20:33:08	INC INFO: HOUSE FIRE
20:33:09	** ELOI search completed at 10/09/17 20:33:09 - 1 result
20:33:11	** LOI search completed at 10/09/17 20:33:11
20:33:21	** Recommended unit SUMN281 for requirement PUMP (>0.6 km)
20:33:21	** Recommended unit WOOL241 for requirement PUMP (>4.8 km)
20:33:34	WHOLE HOUSE INVOLVED
20:34:21	INC INFO: HOUSE FIRE
20:34:21	Duplicate Event:Location = 78 CLIFTON TCE,CLIFTON,CHRISTCHURCH CITY, Type = STRU
20:34:21	- STRUCTURE FIRE, Caller Ph Number = [REDACTED], Call Source = 111Inc InfoHOUSE
20:34:21	FIRE, Event Source = Fire 111
20:34:21	End of Duplicate Event data
20:35:06	Unit WOOL241 [K1 : PROCEEDING TO INCIDENT]
20:35:19	**
20:35:42	HYDRANTS OUTSIDE 97 CLIFTON AND 68 CLIFTON TCE
20:35:44	**
20:36:07	Unit SUMN281 [K1 : PROCEEDING TO INCIDENT]
20:36:53	AL: PAGING ACK TIMED OUT FOR STATION: 3428 at 10/09/17 20:36:53
20:37:21	INC INFO: HOUSE FIRE
20:37:21	Duplicate Event:Location = 78 CLIFTON TCE,CLIFTON,CHRISTCHURCH CITY, Type = STRU
20:37:21	- STRUCTURE FIRE, Caller Name = [REDACTED], Caller Ph Number = [REDACTED],
20:37:21	Caller Address = TELECOM CELLULAR 027, TE PUKE, WESTERN BAY OF PLENTY DISTRICT,
20:37:21	Call Source = 111Inc InfoHOUSE FIRE , Event Source = Fire 111
20:37:21	End of Duplicate Event data
20:37:36	Unit SUMN281 [SITREP :] MAKE 2ND ALARM
20:37:48	** Alarm level updated to 2
20:37:48	** Recommended unit LYTT291 for requirement PUMP (>4.7 km)
20:37:48	** Recommended unit CHRI217 for requirement PUMP (>10.0 km)
20:37:51	POWER ADVISE ETA APPROX 15 MINS FROM NEW BRIGHTON
20:38:21	**
20:38:27	AMBO EVENT 0414-3-2017/09/10-FIR LINKED AT 10/09/2017 20:38:27
20:38:31	**
20:38:40	AL: PAGING ACK RECEIVED FROM STATION 3429 at 10/09/17 20:38:40
20:38:48	*
20:38:53	FIR2POL - 2ND ALARM HOUSE FIRE
20:38:58	*
20:39:04	Unit CHRI217 [K1 : PROCEEDING TO INCIDENT]
20:40:02	Duplicate Event:Location = CLIFTON TCE,CLIFTON,CHRISTCHURCH CITY, Type = STRU -
20:40:02	STRUCTURE FIRE, Caller Name = UNKNOWN OR DUPLICATE DETAILS, Caller Ph Number =

20:40:02 [REDACTED], Caller Address = CLIFTON TCE,CLIFTON,CHRISTCHURCH CITY, Call Source
20:40:02 = 111Inc InfoHOUSE FIRE, Event Source = Fire 111
20:40:03 INC INFO: HOUSE FIRE
20:40:03 MULTIPLE SUBSCRIBERS FOR CALLER NUMBER [REDACTED]. TESA LOOKUP RECOMMENDED.
20:40:04 AMBO update to 0414-3-2017/09/10-FIR:
20:40:04 Location = 78 Clifton Tce,CLIFTON,
20:40:04 Caller Name = ., Caller Phone = [REDACTED], Headline = HOUSE FIRE
20:40:04 End of Duplicate Event data
20:40:11 Unit SUMN281 [K99 : PROPERTY FIRE WELL INV]
20:40:23 CALLER STATES CAN ALSO ACCESS FROM 1 PANORAMA RD
20:40:55 *
20:41:06 .
20:41:17 *
20:41:20 AMB ... NOTIFICATION ONLY
20:41:30 Unit LYTT291 [K1 : PROCEEDING TO INCIDENT]
20:42:13 *
20:42:16 Unit WOOL241 [K2 : IN ATTENDANCE AT INCIDENT]
20:42:26 *
20:46:33 Unit SUMN281 [K99 : PROPERTY FIRE WELL INV]
20:46:38 Unit SUMN281 [KC : UNIT CALLING]
20:47:20 Unit SUMN281 [SITREP :] SO [REDACTED] 2 IN BA 3 DEL WAITING ARRIVAL OF OTHER
20:47:20 APPLIANCES
20:48:18 Duplicate Event:Location = CLIFTON TCE,CLIFTON,CHRISTCHURCH CITY, Type = STRU -
20:48:18 INC INFO: HOUSE FIRE SEEN FROM RICHMOND HILL
20:48:18 STRUCTURE FIRE, Caller Name = [REDACTED], Caller Ph Number =
20:48:18 [REDACTED], Caller Address = TELECOM CELLULAR 027, FOXTON, HOROWHENUA DISTRICT,
20:48:18 Call Source = 111Inc InfoHOUSE FIRE SEEN FROM RICHMOND HILL, Event Source = Fire
20:48:18 111
20:48:19 End of Duplicate Event data
20:48:38 *
20:48:54 *
20:51:33 **
20:51:34 **
20:51:35 AMB ADVISE THEY HAVE HAD A CALL STATING 6 PATIENTS 3 WITH [REDACTED] AND 3
20:51:35 PEOPLE WITH [REDACTED] [REDACTED]. AMB ADVICE 3
20:51:35 AMBULANCES
20:51:35 ARE HEADING TO SCENE AND A MANAGER.
20:51:36 **
20:51:37 **
20:51:48 Unit SUMN281 [KC : UNIT CALLING]



20:52:55 *
20:53:00 Unit SUMN281 [SITREP :] CAN YOU ADVISE POLICE THAT CLIFTON TERRACE IS CLOSED
20:53:00 WITH HOSE AND FIRE TRUCKS ACROSS THE ROAD
20:53:03 .
20:53:06 FIR2POL
20:53:12 *
20:53:26 UNIT SUMN281 [SITREP :] CAN YOU ADVISE POLICE THAT CLIFTON TERRACE IS CLOSED
20:53:33 WITH HOSE AND FIRE TRUCKS ACROSS THE ROAD
20:53:36 INC INFO: HOUSE FIRE
20:53:36 Duplicate Event:Location = 78 CLIFTON TCE,CLIFTON,CHRISTCHURCH CITY, Type = STRU
20:53:36 - STRUCTURE FIRE, Caller Ph Number = [REDACTED] Call Source = 111Inc InfoHOUSE
20:53:36 FIRE, Event Source = Fire 111
20:53:36 End of Duplicate Event data
20:54:02 Unit CHRI217 [K2 : IN ATTENDANCE AT INCIDENT]
20:54:16 Unit LYTT291 [K2 : IN ATTENDANCE AT INCIDENT]
20:54:59 *
20:55:08 Unit SUMN281 [KP : PRIORITY MESSAGE]
20:55:32 *
20:55:49 Unit SUMN281 [KP : PRIORITY MESSAGE] MAKE ADDITIONAL PUMP OFR MANPOWER TO
20:55:49 STANDBY AT CLIFTON/MAIN ROAD
20:55:58 ** Requirement PUMP added for alarm level 2
20:56:05 ** Requirement PUMP added for alarm level 2
20:56:09 ** Recommended unit CHRI214 for requirement ADHOC PUMP (>9.9 km)
20:56:55 Unit WAIN321 [K1 : PROCEEDING TO INCIDENT]
20:56:58 Unit CHRI214 [K1 : PROCEEDING TO INCIDENT]
20:57:52 COVERING UNIT SPRE221 DISPATCHED TO STATION
20:58:57 DCC ADVISED BY CH1A
21:04:07 Unit SUMN281 [KC : UNIT CALLING]
21:05:43 Unit SUMN281 [SITREP :] CFO SAYER 1 2 STOREY DWELLING TOTALLY INV 4 DEL 2 BA
21:05:43 IN PLACE WORKING IN OFFENSIVE/TACTICAL MODE AMB IN ATTEND ATTENDING TO 2
21:05:43 PATINETS WITH [REDACTED] AND 1 PATIENT WITH [REDACTED]
21:06:04 *
21:06:17 *
21:08:11 *
21:08:23 *
21:08:48 Unit WAIN321 [K2 : IN ATTENDANCE AT INCIDENT]
21:09:43 Unit CHRI214 [K2 : IN ATTENDANCE AT INCIDENT]
21:10:21 *
21:10:32 *
21:13:16 UNITS ASSISTING WITH TRAFFIC CONTROL.



21:21:26 ** Cross Referenced to Event # P030817359 at: 10/09/17 21:21:26

21:27:40 FIRE STILL TRYING TO CONTAIN FIRE.

21:29:38 Unit CHRI214 [KC : UNIT CALLING]

21:29:59 RRRR

21:30:16 Unit CHRI214 [SITREP :] 214 HAS BEEN RELEASED FROM THE FIREGROUND HEADING BACK

21:30:16 TO STATION

21:30:20 Unit CHRI214 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

21:31:16 Unit SUMN281 [KC : UNIT CALLING]

21:33:52 Unit SUMN281 [SITREP :] 3 LEVEL DWELLING 1 LEVEL TOTALLY INVOLVED MOSTLY

21:33:52 EXTINGUISHED 4 LPD 8 BA IN USE. ST JOHN HAS TRANSPORTED 6 PATIENTS 1 [REDACTED]

21:33:52 [REDACTED] AND 5 WITH [REDACTED] LEAVING 1 AMB IN ATTENDANCE. SAFETY OFFICER

21:33:52 APPOINTED SO WEST

21:40:12 CHS2A WILL GO TO SCENE WITH CAR SEATS FOR CHILDREN.

21:56:23 Unit SUMN281 [KC : UNIT CALLING]

21:57:34 Unit SUMN281 [SITREP :] DAMPENING DOWN AND RELEASING APPLIANCES HAS FI BEEN

21:57:34 ADVISED? IS HE/SHE RESPONDING OR CAN WE TALK TO THEM

21:58:57 **

21:59:04 FI CHCH PUT THROUGH TO SUMN281

21:59:07 **

22:07:29 *

22:10:29 *

22:12:00 Unit LYTT291 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

22:20:24 Duplicate Event:Location = 78 CLIFTON TCE CHRISTCHURCH CITY, Cross Street 1 =

22:20:24 ARANONI TRK, Cross Street 2 = SPINNAKER LA, Type = AMB2POL 1F AMBULANCE REQUEST

22:20:24 POLICE ASSIST ASSIST FIRE/AMBULANCE/TRAFFIC, Subtype = default 2, Caller Name =

22:20:24 ., Caller Ph Number = [REDACTED], Call Source = AMB, Alarm Level = 1, Headline

22:20:24 = RED - Burns (Scalds)/Explosions RED - BURNS (SCALDS)/EXPLOSIONS

22:20:25 End of Duplicate Event data

22:20:25 ** Cross Referenced to Event # P030817131 at: 10/09/17 21:21:26

22:20:25 [POL] amb crew request police to assist with taking a non injured persons to

22:29:34 Unit CHRI217 [KC : UNIT CALLING]

22:29:58 Unit CHRI217 [K10 : RECOMMISSIONING]

22:39:15 Unit SUMN281 [KC : UNIT CALLING]

22:41:13 Unit SUMN281 [SITREP :] EVENT NUMBER, TOC, TOA AND POLICE UNIT NUMBERS PLEASE


22:41:13 ... PASSED

22:43:45 Unit WOOL241 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

22:45:29 Unit WOOL241 [K10 : RECOMMISSIONING]

22:49:45 Unit SUMN281 [KC : UNIT CALLING]

22:51:45 Unit SUMN281 [SITREP :] ADVISE POLICE ROAD IS OPEN BELOW 78 CLIFTON ROAD



22:51:45	INCLUDING TUAWERA AND KINSEY FOR RESIDENTS. ABOVE THAT WILL BE CLOSED FOR APPROX
22:51:45	ANOTHER 30MINS
22:51:48	.
22:51:53	FIR2POL
22:52:00	UNIT SUMN281 [SITREP :] ADVISE POLICE ROAD IS OPEN BELOW 78 CLIFTON ROAD
22:52:06	INCLUDING TUAWERA AND KINSEY FOR RESIDENTS. ABOVE THAT WILL BE CLOSED FOR APPROX
22:52:13	ANOTHER 30MINS
22:52:17	*****
22:52:20	.
22:56:17	Unit WAIN321 [KC : UNIT CALLING]
22:56:41	CAN ONCALL VSO CONTACT SUMN281
22:57:36	Unit WAIN321 [K10 : RECOMMISSIONING]
23:00:05	SUMN281
23:14:30	Unit SUMN281 [KC : UNIT CALLING]
23:14:53	Unit VSOCHR11 [K1 : PROCEEDING TO INCIDENT]
23:37:15	Unit SUMN281 [KC : UNIT CALLING]
23:37:32	Unit SUMN281 [K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE]
23:37:34	Unit SUMN281 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
00:38:48	Unit VSOCHR11 [K2 : IN ATTENDANCE AT INCIDENT]
00:39:06	Unit VSOCHR11 [SITREP :] LEAVING SUMNER STATION NOW. HEADING HOME
00:57:59	Unit VSOCHR11 [K7 : AT NORMAL STATION]
01:44:26	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,
01:44:26	UNIT VSOCHR11 ALERT TIME [NULL] ADJUSTED TO
01:44:26	Qualifier 2:

Incident

CAD Number	F2377052
Incident Reporter	Daryl Sayer
Incident Controller	CFO D Sayer
Distance Travelled (km)	1
Delay In Receiving Call	

Property Details

Occupant	Overseas visitors
Building Owner	Rented property
General Property Use	Single house
Special Property Use	Single house
Purpose Group	

Actions

Persons Reported Trapped No
 Evacuation Status Fully evacuated
 Action Prior 1
 Action Prior 2
 Action Taken Extinguishment only: Includes isolating fuel/power supply

Civilians

Civilians Rescued 0
 Civilians Extricated 0
 Civilians Assisted 6
 Civilians Evacuated

Origin

Location Lounge, Common room, TV room, Sitting room, Music room
 Level 1st floor

Equipment Used

Quantity	Equipment
4	Low pressure delivery
8	BA set
1	Thermal Imaging Camera

Equipment Involved

Equipment Involved
 Year
 Make
 Model

Fire

Arrival Condition Totally involved fire
 Heat Source Wood or paper fuelled equipment: Spark, Ember, Flame, Chimney spark
 Termination Stage Flame
 First Object Ignited Furniture and utensils - not classified above
 First Object Material Unable to classify
 Second Object Ignited Interior wall covering
 Second Object Material Wood: sawn, finished timber
 Indicated Cause People playing with heat sources
 Certainty of Cause Medium

Age of Person Persons: 10 years or under
Ethnicity Asian / Indian
Gender Male
FAIP Service Offered No **FAIP Service Accepted** No

Alarms

Type of Alarm Initiating Call Domestic Smoke Alarms
 Performance of System Alerted occupants - detector in room of origin
 Failure/Ineffectiveness of system
 Number of sprinkler heads operated

Structure

Area of One Floor 60
Age of Building 1970 - 1991
Structural Frame Type Timber frame unprotected (normal housing)
Number of Floors 3
Number of Basements 0
Internal Wall Lining Timber, Sarking, Scrim, Pinex
Ceiling Lining Gypsum board (e.g. Gib board, Elephant board)
Material Generating Most Flame Processed wood, Paper
Material Generating Most Smoke Processed wood, Paper
Avenue of Flame Travel Combination of any of: ceiling, wall, floor finish
Avenue of Smoke Travel Combination of any of: ceiling, wall, floor finish
Extent of Flame Damage Confined to structure of origin
Area of Flame Damage 150
Extent of Smoke Damage No damage of this type
Area of Smoke Damage 0
Extent of Water Damage No damage of this type
Area of Water Damage 0
Extent of Fire Control Damage No damage of this type
Area of Fire Control Damage 0

Comments

9/12/2017 8:47:36 AM

Reporter Comments

6 occupants hospitalized. Media interest particularly as this was an AirBnB rental

Daryl Sayer

9/13/2017 12:50:02 PM

Reporter Comments

Please note that, at the present time (13Sep17), some aspects of this report are preliminary, and are subject to the input of Fire Investigator Mark Thomas. He will complete details regarding casualties in due course.

Daryl Sayer

9/18/2017 7:25:15 AM

Reporter Comments

A full mPad report will be completed by me

Mark Thomas

9/18/2017 7:27:23 AM

Reporter Comments

I attended and investigated this incident on Monday 11 September 2017.

Information recieved from the first caller indicated the fire was first seen in the dining/lounge area of the house. Further information received advised the free standing fireplace and the area in front of it were seen by occupants when they first became aware of the fire.

The area in front of the fireplace was excavated. The remains of a bag and clothing were located here. In this area the flooring was tiled and inspection revealed wide spread cracking and breaking of these tiles.

I travelled to Christchurch Hospital to interview the occupants. Two persons were seen. One of them, [redacted] was being treated for burns to his arms. He advised the fireplace had been going with the door shut when [redacted] went upstairs for prayer. The only member of the family not always present in the upstairs room was [redacted] [redacted] was running up and down the stairs.

Smoke and the sounding of smoke alarms caused the occupants to investigate. [redacted] saw fire in front of the fireplace. He ran to extinguish the fire attempting to smother it with a floor mat. He received moderate burns in doing so. He advised the door of the fireplace was open when he entered this room.

The most likely cause of fire in this event is [redacted] opening the fire box door and burning material falling out. However the possibility of the door not being completely secured before [redacted] went upstairs and being knocked open by the movement of burning content cannot be discounted. The fire cause is considered to be accidental.

Mark Thomas

Released under the Official Information Act 1982