

# SMS Incident Report


01/11/2017 08:49:01

## Summary

**CAD Number** F2399157 **Status** Closed  
**Station** Kawerau Station  
**Incident Started** 18/10/2017 09:23:24 **Incident Ended** 18/10/2017 10:39:26  
**Incident Type** 7103: False Alarm: Defective Apparatus K-46-3  
**Common Name** CARTER HOLT HARVEY SAWMILL KAWERAU  
**Address** UNKN0003 TARAWERA ROAD KAWERAU  
**Alarm Method** Sprinkler PFA Call **Alarm Level** 1  
**PFA Number** 230203  
**Zone** 189101  
**Map Grid E** 1926423 **Map Grid N** 5780076  
**First Caller** **First Caller Contact**  
**Incident Closed** 18/10/2017 10:39:26  
**Report Completed** 11:56, Wed 18 Oct 2017 by ██████████

## Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
KAWE917	PR	09:23:38 18 Oct 2017	09:25:22 18 Oct 2017	09:30:42 18 Oct 2017	09:36:05 18 Oct 2017
KAWE911	P1	09:23:36 18 Oct 2017	09:30:08 18 Oct 2017		09:35:15 18 Oct 2017



## Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
KAWE917	00:00:14	00:07:04	00:07:18	00:12:41
KAWE911	00:00:12			00:11:51

**Message Log**

Time	Message
09:23:25	AL: 230203 09:23:24 INITIAL - AL
09:23:25	** LOI search completed at 18/10/17 09:23:25
09:23:25	** ELOI search completed at 18/10/17 09:23:25 - 1 result
09:23:29	** Recommended unit KAWE917 for requirement PUMP (>1.9 km)
09:23:29	** Recommended unit KAWE911 for requirement PUMP (>1.9 km)
09:23:43	AL: 230203 09:23:43 UPDATE - AL
09:25:00	DIRECTIONS: DIRECTIONS OFF TAMARANGI DRIVE
09:25:05	ACCESS NO: -C
09:25:22	Unit KAWE917 [ K1 : PROCEEDING TO INCIDENT]
09:25:32	Unit KAWE917 [ K1 : PROCEEDING TO INCIDENT]
09:30:08	Unit KAWE911 [ K1 : PROCEEDING TO INCIDENT]
09:30:17	Unit KAWE911 [ K1 : PROCEEDING TO INCIDENT]
09:30:43	Unit KAWE917 [ K77 : NOTHING SHOWING]
09:32:08	Unit KAWE917 [ KC : UNIT CALLING]
09:32:53	Unit KAWE917 [ KC : UNIT CALLING]
09:32:54	Unit KAWE917 [ SITREP : ] PFA# REQUIRED (PASSED)
09:33:35	Unit KAWE917 [ KC : UNIT CALLING]
09:34:09	Unit KAWE917 [ STOP : MESSAGE] SO [REDACTED] - ALARM PANNEL SHOWING NORMAL.
09:34:09	SPRINKLER SYSTEM SHOWING NORMAL NABB
09:34:13	Unit KAWE917 [ K28-1 : RETURN OTHER RESPONDING UNITS]
09:35:17	Unit KAWE911 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
09:36:07	Unit KAWE917 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
10:39:26	** Assigned Result Code: SPRNKLR, Detailed Event Type: 7100, Qualifier 1: Q1,
10:39:26	Qualifier 2:

**Incident**

CAD Number F2399157  
 Incident Reporter [REDACTED]  
 Incident Controller SO [REDACTED]  
 Distance Travelled (km)  
 Delay In Receiving Call

**False Alarm**

Detector Type Sprinkler  
 False Alarm Cause Equipment | Defect system wiring  
 Other Cause

---

**Property Details**

---

**Occupant**

**Building Owner**

**General Property Use** Commercial - not classified above

**Special Property Use** Sawmill, Wood components, Tanalising, Prefab parts

**Purpose Group** WM - Working, Business or Storage Moderate Fire Hazard

**Comments**

10/18/2017 11:56:06 AM

Reporter Comments

---

Appears to be a fault in the wiring that is activating the alarms. No sprinkler activation has occurred and systems showing normal.



Released under the Official Information Act