

Version 2



Statement of Claim Checklist / Repair Strategy

Date: 7/1
 Author: J. Hutchinson

CLM/2010/088121
 MURRAY MCCARTHY
 7 PRESTONS ROAD
 REDWOOD
 CHRISTCHURCH 8051
 [Redacted]
 Estimator:

LA:

Room	Earthquake Damage	Walls	Ceiling	Floor	Repair Strategy
	Y/N	✓	✓	✓	
Lounge	N				
Dining Room	N				
Kitchen	Y		✓		Minor cracks ceiling rake stop paint
Family Room	N/A				
Bedroom 1	Y	✓			Minor cracks walls rake stop paint
Ensuite	N/A				
Bedroom 2	N				
Bedroom 3	N				

[Handwritten Signature]


Checked
[Handwritten Signature] 08.01.11

CIM/2010/088121

MURRAY MCCARTHY
 / PRESTONS ROAD
 REDWOOD
 CHRISTCHURCH 8051

Affix label here

SOC / Repair Strategy – Page 2



Room	Earthquake Damage	Walls	Ceiling	Floor	Repair Strategy
	Y/N	✓	✓	✓	
Bedroom 4	N/A				
Bathroom	Y	✓			door jamming ease & varnish
Toilet 1	N				
Toilet 2	N/A				
Office / Study	N/A				
Rumpus	N/A				
Entry / Hall(s)	Y	✓	✓		major cracks ceiling rake stop restipple edge door separated seal & paint frame only
Stairwell	N/A				
Laundry	N				
Garage	Y		✓		rafter snapped in ceiling strap new rafter to side 2hrs
Other					

CLM/2010/088121

MURRAY MCCARTHY
 7 PRESTONS ROAD
 REDWOOD
 CHRISTCHURCH 8051

Affix label here



Item		Event Damage	Repair Strategy
		Y / N	
Roof		N	
EXTERNAL WALLS	North	Y	minor brick mortar crack grind out re-mortar door out of square realign & paint this bulge this pane broken glass x 5 (0.8x0.8x4mm) remove & replace
	South	Y	minor brick mortar crack grind out re-mortar
	East	N	
	West	N	
Decks		N	
CHIMNEY	Base	N	
	Ceiling Cavity	N	
	Above Roof	N	
	Fireplace	N	

MURRAY MCCARTHY
7 PRESTONS ROAD
REDWOOD
CHRISTCHURCH 8051

Affix label here

SOC / Repair Strategy - Page 4





Item	Event Damage	Repair Strategy
	Y / N	
Foundations	Y	minor cracks ring foundation ground epoxy fill plaster
Piling	N	
Services	N	
Other Dwelling Items	N	
Outbuildings	N	
Land & Retaining Walls <i>(Discuss with Supervisor)</i>	N	

Supplementary Notes:

I confirm the rooms and areas listed above have been inspected by an EQC representative.

Damage caused by the event has been noted and to my knowledge there are no other areas of damage resulting from the event.

Signature of Claimant:  Dated: 7/1/11 

NOTE: THIS FORM IS TO BE COMPLETED IN THE CLAIMANT'S PRESENCE.


OFFICE USE ONLY - LOSS ADJUSTER TO COMPLETE

Date: 7/1/11


Claim Number: 2010/088121

Loss Adjuster: J. Hutchinson


Costing Estimate




Lounge




1/2 Kitchen




Dining




Family Room




Bed 1




Ensuite




Bed 2




Bed 3




Bed 4




Bathroom




Toilet 1




Toilet 2




Office/Study




Rumpus




Entry/Hall(s)



Stairwell



Laundry



Outbuildings/Garage

OFFICE USE ONLY - LOSS ADJUSTER TO COMPLETE

Date: 7/1/11

Claim Number: 2010/ 088121

Loss Adjuster: J. Hutchinson

Roof
\$

Foundations
\$ 750

Ex Walls/Windows
\$ 1200

\$

\$

\$

\$

\$

\$

Sub Totals:

\$ 450 ✓

\$ 2576 ✓

\$ 2384 ✓

Total Estimate: \$ 5410 ✓

Checked
[Signature]