

SMS Incident Report


17/09/2021 09:28:34

Summary

CAD Number F3308051 **Status** Closed
Station Silverdale Station
Incident Started 20/08/2021 05:40:01 **Incident Ended** 20/08/2021 08:16:46
Incident Type 1101: Structure fire with damage
Common Name
Address [REDACTED] Red Beach
Alarm Method 111 Telephone **Alarm Level** 1
PFA Number
Zone 149001
Map Grid E [REDACTED] **Map Grid N** [REDACTED]
First Caller [REDACTED] **First Caller Contact** [REDACTED]
Incident Closed 20/08/2021 08:16:46
Report Completed 16:42, Sat 21 Aug 2021 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
SILV907	PR	05:40:45 20 Aug 2021	05:45:25 20 Aug 2021	05:48:45 20 Aug 2021	07:34:16 20 Aug 2021
SILV901	P1	05:40:45 20 Aug 2021	05:44:58 20 Aug 2021	05:50:39 20 Aug 2021	08:12:33 20 Aug 2021
SILVOSU1	SV	06:06:47 20 Aug 2021	06:06:50 20 Aug 2021	06:08:38 20 Aug 2021	07:34:20 20 Aug 2021



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
SILV907	00:00:44	00:08:00	00:08:44	01:54:15
SILV901	00:00:44	00:09:54	00:10:38	02:32:32

SILVOSU1	00:26:46	00:01:51	00:28:37	01:54:19
----------	----------	----------	----------	----------

Message Log

Time	Message
05:40:31	https://web.pcl.govt.nz/?ecn=[REDACTED]
05:40:31	INC INFO: FIRE ALARM SOUNDING - WOOD PILE ON FIRE UNDER HOUSE
05:40:32	** LOI search completed at 20/08/21 05:40:32
05:40:39	** Recommended unit SILV901 for requirement SILVERDALESPECIALNIGHT (>1.5 km) **
05:40:39	Recommended unit SILV907 for requirement PUMP (>1.4 km)
05:40:41	PA Selcal used to Initiate Alerting. (SILV901 at 1490 SILVERDALE 182901)
05:40:41	PA Selcal used to Initiate Alerting. (SILV907 at 1490 SILVERDALE 182907)
05:40:45	ALERTING_COMPLETED SILV901
05:40:45	ALERTING_COMPLETED SILV907
05:44:58	Unit SILV901 [K1 : PROCEEDING TO INCIDENT]
05:45:26	Unit SILV907 [K1 : PROCEEDING TO INCIDENT]
05:47:08	Unit SILV901 [COMCEN COM : MESSAGE] ONE CALL FROM THE PREMISE ADVISING WOOD PILE
05:47:08	FIRE UNDER HOUSE - HYDRANT OUTSIDE [REDACTED] - THIS IS GONNA BE SECOND
05:47:08	HOUSE DOWN THE SHARED DRIVEWAY
05:47:17	Unit SILV901 [COMCEN COM : MESSAGE] NOW A SECOND CALL FOR THE HOUSE ON FIRE
05:47:27	Unit SILV901 [SITREP :] 907 BRING IN WATER
05:47:33	DECK IS NOW ON FIRE AND IS SPREADING TO THE HOUSE
05:47:33	Unit SILV907 [SITREP :] RECEIVED
05:48:45	Unit SILV907 [K2 : IN ATTENDANCE AT INCIDENT]
05:50:31	Unit SILV901 [COMCEN COM : MESSAGE] K2 RCVD FROM 907 - DO YOU HAVE AN ARRIVAL?
05:50:39	Unit SILV901 [K88 : PROPERTY FIRE APPARENTLY SMALL] VERBAL
05:50:39	VERBAL
05:52:35	Unit SILV901 [K88 : PROPERTY FIRE APPARENTLY SMALL]
05:56:51	Unit SILV901 [KC : UNIT CALLING]
05:58:11	Unit SILV901 [KC : UNIT CALLING]
05:58:15	Unit SILV901 [SITREP :] SO [REDACTED] - ONE TWO STOREY HOUSE APPROX 10M BY 8M FIR
05:58:15	E LOCATED IN WOOD SHED UNDERNEATH - 1HPD - EXTERIOR AGGRESSIVE CUT OFF
05:58:29	Unit SILV901 [COMCEN COM : MESSAGE] CONFIRM HOW LONG TRUCKS WILL BE COMMITTED FO
05:58:29	R RE COVER MOVES
05:58:53	Unit SILV901 [COMCEN COM : MESSAGE] WILL POWER BE NEEDED?

Incident Reporter [REDACTED]
Incident Controller
Distance Travelled (km)
Delay In Receiving Call

Property Details

Occupant [REDACTED]
Building Owner Owner occupied
General Property Use Single house
Special Property Use Single house
Purpose Group

Actions

Persons Reported Trapped
Evacuation Status Fully evacuated
Action Prior 1
Action Prior 2
Action Taken Extinguishment, salvage and ventilation

Civilians

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	3
Civilians Evacuated	0

Origin

Location Balcony, Porch, Veranda
Level Ground level

Equipment Used

Quantity	Equipment
1	Hose reel, high pressure delivery
1	Building/Site/Private Fire Equipment
1	Rescue saw
1	Medical/First Aid Equipment

Equipment Involved

Equipment Involved
Year

Make**Model****Fire**

Arrival Condition Small fire

Heat Source Cigarette, Cigar or Smoking materials

Termination Stage

First Object Ignited

First Object Material

Second Object Ignited

Second Object Material

Indicated Cause Careless disposal or use: cigarettes, ashes, embers

Certainty of Cause High

Age of Person Persons: [REDACTED]

Ethnicity [REDACTED]

Gender [REDACTED]

FAIP Service Offered Unknown

Alarms

Type of Alarm Domestic Smoke Alarms

Initiating Call

Performance of System Did not operate - detector in room of origin

Failure/Ineffectiveness of system Battery flat or removed

Number of sprinkler heads operated 0

Casualties**Casualty Number 1**

Gender [REDACTED]

Age [REDACTED]

Apparent Injury [REDACTED]

Ethnicity [REDACTED]

Severity of Injury [REDACTED]

Bleeding

Action by Fire Fighters Provided basic first aid

Condition Before Injury Awake, unimpaired

How Removed [REDACTED]

Location at Ignition Person in same building as fire origin

Factor Preventing Escape	Nothing
Activity When Injured	Firefighting/investigating fire
Cause of Injury	Fire Products
Victim Aware of Fire	Victim alerted by other than domestic smoke
Room Where Victim Found	Outside the structure/vehicle
Location Where Victim Found	
Familiarity With Property	Familiar with premises

Comments

8/21/2021 4:42:51 PM

Reporter Comments

Fire started by discarded cigarette. Ignited Wood pile against building. Alerted by smell as smoke alarm did not work, light smoke inside house. [REDACTED] received smoke inhalation while fighting the fire with garden hose. Garden hose make a big difference to the fire size

[REDACTED]

Released under the Official Information Act 1982