## **SMS** Incident Report

20/04/2023 11:51:34

Summary		
CAD Number	F3713922	Status Closed
Station	Kingswell Station	~`
Incident Started	08/04/2023 08:17:28	Incident Ended 08/04/2023 08:33:02
Incident Type	1101: Structure fire with damage	
Common Name	INVERCARGILL HOSPITAL	
Address	Kew Road Kew	
Alarm Method	111 Telephone	Alarm Level 1
PFA Number		
Zone	382202	
Map Grid E	1243300	Map Grid N 4846649
First Caller	SOUTHERN DISTRICT	First Caller Contact 9(2)a
Incident Closed	08/04/2023 08:33:02	
Report Completed	8:51, Sat 08 Apr 2023 by <mark>9(2)a</mark>	

## Responses

INVE211

Responses					
Call Sign	Туре	Station Aler	rt Enroute Tim	e Arrival Time	Departed
KING227	PR	08:18:44 08 A 2023	pr 08:19:29 08 Aj 2023	or 08:22:41 08 Apr 2023	08:28:27 08 Apr 2023
INVE211	P1	08:18 41 08 A 2023	pr 08:19:34 08 Aj 2023	or 08:24:24 08 Apr 2023	08:29:18 08 Apr 2023
INVE214	PM	08:18:41 08 A 2023	pr 08:19:58 08 Ap 2023	or 08:24:30 08 Apr 2023	08:28:42 08 Apr 2023
Start->Alert	7 min	10 min			
0 min			15 min		30 min
0	Aler Arriv	i->1st al			
Elapsed Times					
Call Sign	Sta	art To Alert	Alert To Arrival	Start To Arrival	Start To Departed
KING227		00:01:16	00:03:57	00:05:13	00:10:59

Caution: The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside Fire and Emergency NZ without prior approval

00:05:43

00:01:13

00:06:56

00:11:50

SMS Incident Report	F3713922	2/5		20/04/2023 11:51:3	4
INVE214	00:01:13	00:05:49	00:07:02	00:11:14	

## Notifications

Date	Time	Party Notified	
08 Apr 2023	08:19:39	POLICE VIA INTERCAD	

## Message Log

Time	Message
08:18:21	INC INFO 9(2)a
08:18:21	** ELOI search completed at 08/04/23 08:18:21 - 1 result
08:18:24	** LOI search completed at 08/04/23 08:18:24
08:18:33	FIRE IS NOW OUT
08:18:33	** Recommended unit INVE214 for requirement MONIT (>3.2 km) ** Recommended unit
08:18:33	KING227 for requirement PUMP (>1.4 km) ** Recommended unit INVE211 for require
08:18:33	ment PUMP (>3.2 km)
08:18:37	PA Selcal used to Initiate Alerting. (INVE214 at 3821 INVERCARGILL 196211)
08:18:37	PA Selcal used to Initiate Alerting. (KING227 at 3822 KINGSWELL 196221)
08:18:38	PA Selcal used to Initiate Alerting. (INVE211 at 3821 INVERCARGILL 196211)
08:18:41	ALERTING_COMPLETED INVE214
08:18:41	ALERTING_COMPLETED INVE211
08:18:44	ALERTING_COMPLETED KING227
08:18:45	9(2)a
08:18:59	POLICE REQUIRED 9(2)a
08:19:29	Unit KING227 [K1: PROCEEDING TO INCIDENT]
08:19:34	Unit INVE211 [K1 : PROCEEDING TO INCIDENT]
08:19:38	** Event P054240189 of NZP/IV copied from F3713922 of NZFS/SL at: 08/04/23 08:19
08:19:38	:38
08:19:45	Unit INVE211 [ K1 : PROCEEDING TO INCIDENT]
08:19:50	Unt KING227 [ K1 : PROCEEDING TO INCIDENT]
08:19:58	Unit INVE214 [ K1 : PROCEEDING TO INCIDENT]
08:20:14	FIR2POL 9(2)a
08:20:14	9(2)a
08:20:26	Unit INVE214 [ K1 : PROCEEDING TO INCIDENT]
08:21 18	Unit INVE214 [ KC : UNIT CALLING]
08:21:21	THEY CALLED BACK 9(2)a
08:22:41	Unit KING227 [ K77 : NOTHING SHOWING]

Caution: The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside Fire and Emergency NZ without prior approval

08:23:23	Unit KING227 [COMCEN COM : MESSAGE] 9(2)a
08:23:23	9(2)a
08:23:23	9(2)a
08:23:23	9(2)a
08:23:29	FIR2POL COPY THANKS
08:23:56	Unit KING227 [ KC : UNIT CALLING]
08:24:24	Unit INVE211 [ K2 : IN ATTENDANCE AT INCIDENT]
08:24:31	Unit INVE214 [ K2 : IN ATTENDANCE AT INCIDENT]
08:24:39	Unit KING227 [ SITREP : ] 9(2)a - LIAISING WITH STAFF AT THE MOMENT
08:27:40	Unit KING227 [ KC : UNIT CALLING]
08:28:27	Unit KING227 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
08:28:42	Unit INVE214 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
08:29:11	Unit KING227 [ STOP : MESSAGE] 1 TOILET ROLL ATTEMPTED TO BE LIT EXTGD WITH DRY
08:29:11	POWDER EXTINGUISHER BY STAFF LEFT IN THE HANDS 9(2)a (ARE PO
08:29:11	L STILL REQD?] AFFIRM TO ASSIST STAFF
08:29:18	Unit INVE211 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
08:29:52	FIR2POL UNIT KING227 [ STOP : MESSAGE] 1 TOILET ROLL ATTEMPTED TO BE LIT EXTGD W
08:29:52	ITH DRY POWDER EXTINGUISHER BY STAFF LEFT IN THE HANDS 3(2)a 9(2)a
08:29:52	[ARE POL STILL REQD?] AFFIRM TO ASSIST STAFF
08:33:02	** Assigned Result Code: STRU, Detailed Event Type: 1100

Incident CAD Number F3713922 Incident Reporter )(2)a Incident Controller Distance Travelled (km) Delay In Receiving Call **Property Details** Occupant 9(2) State owned Building Owner General Property Use Hospital, Hospice, Rest home, Rehab centre Special Property Use General hospital: Public and private Purpose Group

Caution: The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside Fire and Emergency NZ without prior approval

Persons Reported	1
Trapped Evacuation Status	Evacuation to a place of safety inside
Action Prior 1	
Action Prior 2	
Action Taken	Investigation only (Fire related)
Action Taken	
Civilians	
<b>Civilians Rescued</b>	
<b>Civilians Extricate</b>	ed Contraction of the second se
Civilians Assisted	
Civilians Evacuate	ed
Origin	
	Bedroom, Sleeping area, Cell: under 5 persons
	Ground level
Equipment Used	
Quantity	Equipment
Quantity 0	No equipment used
0	No equipment used
0 Equipment Inv	No equipment used
0 Equipment Involved	No equipment used
0 Equipment Involved Year	No equipment used
0 Equipment Involved Year Make	No equipment used
0 Equipment Involved Year	No equipment used
0 Equipment Involved Year Make	No equipment used
0 Equipment Involved Year Make	No equipment used
0 Equipment Involved Year Make Model	No equipment used
0 Equipment Involved Year Make Model Fire	No equipment used
0 Equipment Involved Year Make Model Fire Arrival Condition	No equipment used
0 Equipment Involved Year Make Model Fire Arrival Condition Heat Source	No equipment used
0 Equipment Involved Year Make Model Fire Arrival Condition Heat Source Termination Stage	No equipment used
0 Equipment Involved Year Make Model Fire Arrival Condition Heat Source Termination Stage First Object Ignite	No equipment used
0 Equipment Involved Year Make Model Fire Arrival Condition Heat Source Termination Stage First Object Ignite First Object Mater	No equipment used
0 Equipment Involved Year Make Model Fire Arrival Condition Heat Source Termination Stage First Object Ignite First Object Ignite Second Object Ign	No equipment used
0 Equipment Involved Year Make Model Fire Arrival Condition Heat Source Termination Stage First Object Ignite First Object Ignite Second Object Ign Second Object Ign	No equipment used
0 Equipment Involved Year Make Model Fire Arrival Condition Heat Source Termination Stage First Object Ignite First Object Ignite Second Object Ign	No equipment used

Caution: The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside Fire and Emergency NZ without prior approval

Q

5/5

	9(2)		
FAIP Service Offere	d Unknown		
			9
Alarms			
Type of Alarm Initiating Call	Heat detector, Thermal detecto	Ŋ	
Performance of System	Fire too small to activate detect	tor in room of origin	
Failure/Ineffectiven ess of system			
Number of sprinkler heads operated		÷.	
Comments		J.	
		4/8/2023 8:51:10 AM	<b>Reporter Comments</b>
	fer for PPV as there were no w	indows open and they had to	
9(2)a	1		9(2)a
		4/8/2023 8:51:19 AM	Reporter Comments
On arrival staff inforr	ned us that the fire was out		
9(2)a a toilet rol deployed a dry powd covered the room.	II on fire and there was smoke i ler extinguisher to put the fire o		
			9(2)a
	dertin		
sed	der extinguisher to put the fire o		