SMS Incident Report

29/06/2023 12:48:22

Summary

CAD Number F3756563 Status Closed

Station Manly Volunteer Fire Brigade

Incident Started 06/06/2023 14:38:40 Incident Ended 07/06/2023 11:44:46

Incident Type 1101: Structure fire with damage

Common Name

Address 50 Rawhiti Road Manly

Alarm Method 111 Telephone Alarm Level 2

PFA Number

Zone 149101

Map Grid E 1757557 Map Grid N 5944545

First Caller HIWAY STABLIZERS First Caller Contact


Incident Closed 07/06/2023 11:44:46

Report Completed 16:4, Mon 12 Jun 2023 by

Responses

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
MANL911	P1	14:39:39 06 Jun 2023	14:49:53 06 Jun 2023	14:51:46 06 Jun 2023	19:54:20 06 Jun 2023
SILV907	PR	14:39:42 06 Jun 2023	14:41:07 06 Jun 2023	14:53:27 06 Jun 2023	17:29:25 06 Jun 2023
SILV901	P1	14:39:42 06 Jun 2023	14:46:22 06 Jun 2023	15:03:17 06 Jun 2023	16:27:46 06 Jun 2023
EAST831		14:44:52 06 Jun 2023	14:45:07 06 Jun 2023	15:03:33 06 Jun 2023	15:23:30 06 Jun 2023
GMWAITE04	OF	14:53:43 06 Jun 2023	14:55:32 06 Jun 2023	15:07:06 06 Jun 2023	15:23:10 06 Jun 2023
ALBA851	P1	14:45:53 06 Jun 2023	14:47:12 06 Jun 2023	15:08:50 06 Jun 2023	15:22:42 06 Jun 2023
AUCK2018	CUHU	14:47:36 06 Jun 2023	14:49:05 06 Jun 2023	15:21:13 06 Jun 2023	16:32:30 06 Jun 2023
AUCKOSU1	SV	14:58:46 06 Jun 2023	14:58:52 06 Jun 2023	15:34:29 06 Jun 2023	16:46:33 06 Jun 2023
SILVOSU1	SV	14:45:52 06 Jun 2023	15:53:43 06 Jun 2023	16:07:09 06 Jun 2023	16:41:10 06 Jun 2023
VSOWAITE03	VSO	14:51:41 06 Jun 2023	14:51:42 06 Jun 2023	16:11:09 06 Jun 2023	17:22:00 06 Jun 2023
FIWAITE02	FSO	16:47:47 06 Jun 2023	16:50:54 06 Jun 2023	17:45:22 06 Jun 2023	11:35:21 07 Jun 2023

FIWAITE03	FSO	08:49:27 07 Jun 2023	08:50:24 07 Jun 2023	10:38:17 07 Jun 2023	11:36:41 07 Jun 2023
AUCKOSU	SV	14:52:50 06 Jun 2023			16:52:56 06 Jun 2023
VSOWAITE04	VSO	15:10:27 06 Jun 2023	15:10:50 06 Jun 2023		15:27:44 06 Jun 2023
FICOUMA05	FSO	16:29:14 06 Jun 2023			16:35:50 06 Jun 2023
FIAUCKL01	FSO	16:35:09 06 Jun 2023			16:47:52 06 Jun 2023



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
MANL911	00:00:59	00:12:07	00:13:06	05:15:40
SILV907	00:01:02	00:13:45	00:14:47	02:50:45
SILV901	00:01:02	00:23.35	00:24:37	01:49:06
EAST831	00:06:12	00:18:41	00:24:53	00:44:50
GMWAITE04	00:15:03	00:13:23	00:28:26	00:44:30
ALBA851	00:07:13	00:22:57	00:30:10	00:44:02
AUCK2018	00:08:56	00:33:37	00:42:33	01:53:50
AUCKOSU1	00:20:06	00:35:43	00:55:49	02:07:53
SILVOSU1	00:07:12	01:21:17	01:28:29	02:02:30
VSOWAITE03	00:13:01	01:19:28	01:32:29	02:43:20
FIWAITE02	02:09:07	00:57:35	03:06:42	20:56:41
FIWAITE03	18:10:47	01:48:50	19:59:37	20:58:01
AUCKOSU	00:14:10			02:14:16
VSOWAITE04	00:31:47			00:49:04
FICOUMA05	01:50:34			01:57:10
FIAUCKL01	01:56:29			02:09:12

Notifications

Date	Time	Party Notified
06 Jun 2023	14:42:10	VECTOR
06 Jun 2023	14:45:31	DCFO CONWAY - TX 2ND ALARM
06 Jun 2023	14:47:29	AMBULANCE VIA INTERCAD

06 Jun 2023	14:47:29	POLICE VIA INTERCAD
06 Jun 2023	14:47:39	GM WAITEMATA GROUP RE 2ND ALARM
06 Jun 2023	14:47:54	GMAUCKL01 RE 2ND ALARM
06 Jun 2023	14:48:04	GMCOUMA04 RE 2ND ALARM
06 Jun 2023	14:48:33	GMWAITE04 ACKNOWLEDGED VIA AMS
06 Jun 2023	14:48:37	CFO/DCFO SILVERDALE PAGED RE 2ND ALARM
06 Jun 2023	14:48:51	GMCOUMA03 RE 2ND ALARM
06 Jun 2023	14:49:12	GMCOUMA04 ACKNOWLEDGED VIA AMS
06 Jun 2023	14:51:11	CFO MANLY RE 2ND ALARM VIA ETXT
06 Jun 2023	14:51:26	GMWAITE01 ACK PAGE - ADVISED GMWAITE04 WILL MOST LIKELY GO
06 Jun 2023	14:52:01	GMWAITE02 ACK PAGE
06 Jun 2023	14:54:21	GMWAITE05 ACKNOWLEDGED VIA AMS
06 Jun 2023	15:03:49	GM WAITEMATA GROUP PAGED SITREP
06 Jun 2023	15:04:13	GMCOUMA03/GMCOUMA04/GMAUCKL01 PAGED SITREP
06 Jun 2023	15:06:01	GREATER ALARM ATTENDANCE SHEET EMAILED TO AUCK2018
06 Jun 2023	15:23:41	VECTOR FOR ETA - NO ETA AVAIL
06 Jun 2023	16:45:33	FIAUCKL01 (MIKE CANDY) REPAGED
06 Jun 2023	16:45:39	TRIED TO CALL FIAUCKL01, NO REPONSE
07 Jun 2023	10:15:33	FIWAITE03 MIKE DONOVAN PER CELLPHONE - NO ANSWER
07 Jun 2023	10:21:14	FIWAITE02 MICHAEL HOYNE - WENT TO VM
07 Jun 2023	10:39:07	FIWAITE02 MICHAEL HOYNE CONFIRMS FIWAITE03 IS IN ATTENDANCE

Message Log

Time	Message
14:39:26	https://web.pcl.govt.nz/?ecn=
14:39:26	INC INFO: HOUSE FIRE IN VICINITY
14:39:26	** LOI search completed at 06/06/23 14:39:26
14:39:34	** Recommended unit SILV907 for requirement SILVERDALESPECIALDAY (>7.0 km) ** R
14:39:34	ecommended unit MANL911 for requirement PUMP (>0.5 km) ** Recommended unit SILV
14:39:34	901 for requirement CANBACKUP (>7.0 km)
14:39:35	PA Selcal used to Initiate Alerting. (SILV907 at 1490 SILVERDALE 182907)
14:39:35	Station Selcal used to Initiate Alerting. (MANL911 at 1491 MANLY 182913)
14:39:36	PA Selcal used to Initiate Alerting. (SILV901 at 1490 SILVERDALE 182901)
14:39:39	ALERTING_COMPLETED MANL911
14:39:40	BEHIND THE SHOPS
14:39:42	ALERTING_COMPLETED SILV907
14:39:42	ALERTING_COMPLETED SILV901
14:39:52	UNKNOWN WHAT NUMBER ON BRIXTON RD

14:40:48	CALLER STATED THICK BLACK SMOKE
14:41:04	ABANDONED HOUSE ON FIRE AT 50 RAWHITI ROAD
14:41:07	Unit SILV907 [K1 : PROCEEDING TO INCIDENT]
14:41:20	Unit SILV907 [K1 : PROCEEDING TO INCIDENT]
14:41:49	** Event Location changed from "BRIXTON RD,MANLY,AUCKLAND" to "50 RAWHITI RD,MAN
14:41:49	LY,AUCKLAND" at: 06/06/23 14:41:49
14:41:50	** LOI search completed at 06/06/23 14:41:50
14:43:12	Unit SILV907 [COMCEN COM : MESSAGE] MULTIPLE CALLS TO ABANDONDED HOUSE ON FIRE A
14:43:12	T 50 RAWHITI ROAD, HYDRANTS OUTSIDE #50 AND #47A - FOUR ON SILV901 AMS, ZERO ON
14:43:12	MANL911
14:43:41	Unit SILV907 [K37-1 : UPDATED INFORMATION RECEIVED]
14:44:23	Unit SILV907 [KC : UNIT CALLING]
14:44:35	Unit SILV907 [SITREP :] ATTATCH EAST831
14:44:39	** Requirement PUMP added for alarm level 1
14:44:42	** Recommended unit EAST831 for requirement PUMP (>10.5 km)
14:44:44	MSU Selcal used to Initiate Alerting. (EAST831 D098D2)
14:44:52	ALERTING_COMPLETED EAST831
14:45:07	Unit EAST831 [K1 : PROCEEDING TO INCIDENT]
14:45:40	** Alarm level updated to 2
14:45:40	** Recommended unit ALBA851 for requirement PUMP (>11.3 km) ** Recommended unit
14:45:40	SILVOSU1 for requirement SUPPT (>7.0 km)
14:45:50	INC INFO: HOUSE FIRE TX 2ND ALARM
14:45:50	MSU Selcal used to Initiate Alerting. (ALBA851 D072F2)
14:45:50	Pager used to Initiate Alerting.
14:45:52	ALERTING_COMPLETED SILVOSU1
14:45:53	ALERTING_COMPLETED ALBA851
14:46:22	Unit SILV901 [K1 : PROCEEDING TO INCIDENT]
14:46:27	Unit ALBA851 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
14:46:35	Unit SILV901 [KC : UNIT CALLING]
14:46:38	** Requirement PUMP removed for alarm level 1
14:46.47	** Recommended unit ALBA851 for requirement PUMP (>14.4 km)
14:46:49	MSU Selcal used to Initiate Alerting. (ALBA851 D072F2)
14:46:49	Unit SILV901 [KC : UNIT CALLING]
14:46:52	ALERTING_COMPLETED ALBA851
14:46:56	Unit SILV907 [KC : UNIT CALLING]
14:47:12	Unit ALBA851 [K1 : PROCEEDING TO INCIDENT]
14:47:16	Unit SILV907 [SITREP :] CONFIRM CURRENT WIND DIRECTION

14:47:26	** Event A01121004 of AMBO/N copied from F3756563 of NZFS/AK at: 06/06/23 14:47:
14:47:26	26
14:47:27	** Event P054902420 of NZP/RE copied from F3756563 of NZFS/AK at: 06/06/23 14:47
14:47:27	Unit SILV901 [SITREP :] FULLY CREWED
14:47:27	FIR2AMB FYI 2ND ALARM
14:47:27	:27
14:47:29	** Requirement COMU added for alarm level 2
14:47:29	AMBO EVENT 0625-1-2023/06/06-FIR LINKED AT 06/06/2023 14:47:29
14:47:30	** Recommended unit AUCK2018 for requirement COMU (>24.9 km)
14:47:34	FIR2POL FYI 2ND ALARM
14:47:36	ALERTING_COMPLETED AUCK2018
14:48:41	DCFO MANLY AWARE
14:49:05	Unit AUCK2018 [K1 : PROCEEDING TO INCIDENT]
14:49:30	Unit MANL911 [KC : UNIT CALLING]
14:49:53	Unit MANL911 [K1 : PROCEEDING TO INCIDENT]
14:49:53	Unit MANL911 [SITREP :] RESPONDING SHORT CREWED, OFFICER AND TWO
14:50:04	Unit MANL911 [K1 : PROCEEDING TO INCIDENTI
14:50:04	FROM MANLY - TOP FLOOR WELL ALIGHT - IMPINGING ON NEIGHBOURING PROPERTIES
14:51:42	Unit VSOWAITE03 [K1 : PROCEEDING TO INCIDENT]
14:51:46	Unit MANL911 [K99 : PROPERTY FIRE WELL INVOLVED]
14:51:49	LARGE TWO STOREY HOUSE WELL INVOLVED
14:51:49	Unit MANL911 [K99 : PROPERTY FIRE WELL INVOLVED] LARGE TWO STOREY HOUSE WELL IN
14:51:49	VOLVED
14:52:16	VSOWAITE03 WILL PICK UP UNIFORM TRAILER ON HIS WAY
14:52:40	Unit SILVOSU1 [KE : UNABLE TO PROCEED (STATE REASON)] NO CREW
14:52:49	Pager used to Initiate Alerting.
14:52:50	ALERTING_COMPLETED AUCKOSU
14:53:27	Unit SILV907 [K2 : IN ATTENDANCE AT INCIDENT]
14:53:41	Pager used to Initiate Alerting.
14:53:43	ALERTING_COMPLETED GMWAITE04
14:53:43	ALERTING_COMPLETED GMWAITE04
14:55:32	Unit GMWAITE04 [K1 : PROCEEDING TO INCIDENT]
14:55:40	Unit AUCKOSU [K22-1 : APPLIANCE AVAILABLE FOR A FURTHER INCIDENT]
14:56:03	Unit AUCKOSU [SITREP :] BY PHONE - WILL RESPOND AUCKOSU01 SHORTLY
14:56:08	OWNER - REQUESTING ANY INFO - IS OVER AN HOUR AWAY.
14:56:46	Unit SILV907 [KC : UNIT CALLING]
14:56:51	COVERING UNIT BIRK821 DISPATCHED TO STATION EAST COAST BAYS AT 06/06/23 14:56:51
14:57:02	Unit SILV907 [KC : UNIT CALLING]

14:58:02	Unit SILV907 [K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SSO
14:58:11	Unit SILV907 [SITREP :] SSO THE THIS IS A TWO STOREY RESIDENTIAL DWELLING.
14:58:11	FULLY INVOLVED IN FIRE, APROX 10 X 14M. ONE LPD. ONE MONITOR BEING ESTABLISHED
14:58:11	AND A 2ND LPD. EXTERNAL FIRE ATTACK, DEFENSIVE MODE
14:58:35	Unit SILV907 [COMCEN COM : MESSAGE] SILVOSU1 NO CREW, - AUCKOSU1 SENDING CREW
14:58:45	Pager used to Initiate Alerting.
14:58:46	ALERTING_COMPLETED AUCKOSU1
14:58:52	Unit AUCKOSU1 [K1 : PROCEEDING TO INCIDENT]
15:00:44	Unit GMWAITE04 [COMCEN COM : MESSAGE] NO RESPONSE VIA R/T X2
15:03:17	Unit SILV901 [K2 : IN ATTENDANCE AT INCIDENT]
15:03:33	Unit EAST831 [K2 : IN ATTENDANCE AT INCIDENT]
15:07:07	Unit GMWAITE04 [K2 : IN ATTENDANCE AT INCIDENT]
15:07:23	Unit AUCK2018 [COMCEN COM : MESSAGE] YOU WERE RESPONDED FOR POST FIRE DECONTAMIN
15:07:23	ATION, WE HAVE ALSO EMAILED YOU THE GREATER ALARM ATTENDANCE SHEET
15:08:50	Unit ALBA851 [K2 : IN ATTENDANCE AT INCIDENT]
15:10:25	Pager used to Initiate Alerting.
15:10:27	ALERTING_COMPLETED VSOWAITE04
15:10:27	ALERTING_COMPLETED VSOWAITE04
15:10:50	Unit VSOWAITE04 [K1 : PROCEEDING TO INCIDENT]
15:17:42	Unit SILV907 [KC : UNIT CALLING]
15:18:29	Unit SILV907 [SITREP :] FIRE EXTINQUISHED, CREWS ENTERING PREMESIS TO CONDUCT
15:18:29	PRIMARY SEARCH ON GROUND FLOOR
15:21:13	Unit AUCK2018 [K2 : IN ATTENDANCE AT INCIDENT]
15:22:13	Unit SILV907 [KP : PRIORITY MESSAGE]
15:22:33	Unit SILV907 [K11E : ELECTRICAL AUTHORITY REQUIRED]
15:22:42	Unit ALBA851 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
15:22:42	Unit SILV907 [COMCEN COM : MESSAGE] WE"LL TRY GET AN ETA FOR YOU
15:23:10	Unit GMWAITE04 [K6 : ON PAGER (STATE LOCATION)]
15:23:31	Unit EAST831 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
15:26:53	BIRK821, WEST671 STOOD DOWN FROM COVER MOVES
15:27.44	Unit VSOWAITE04 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
15:28:26	Unit SILV907 [KC : UNIT CALLING]
15:28:40	Unit SILVOSU1 [K7 : AT NORMAL STATION]
15:28:50	Unit SILV907 [SITREP :] SEARCH CARRIED OUT, BRIGADE CONDUCTING OVERHAUL
15:34:29	Unit AUCKOSU1 [K2 : IN ATTENDANCE AT INCIDENT]
15:43:23	Unit SILV907 [SITREP :] PER PHONE - WHO CALLED THE SECOND ALARM AS NO ONE HERE
15:43:23	DID.

15:43:27	Alarm Timer Extended: 0
15:43:27	Alarm Timer Extended: 0
15:43:28	Alarm Timer Extended: 0
15:43:39	Unit SILV907 [COMCEN COM : MESSAGE] PER PHONE ACTING DCFO MANLY FIRE
15:50:41	Unit SILV907 [SITREP :] PER PHONE- POWER NOW ON SCENE
15:51:33	Pager used to Initiate Alerting.
15:51:34	ALERTING_COMPLETED SILVOSU1
15:51:39	Unit SILV907 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]
15:53:43	Unit SILVOSU1 [K1 : PROCEEDING TO INCIDENT]
16:05:00	Alarm Timer Extended: 0
16:05:29	Unit SILV907 [KC : UNIT CALLING]
16:05:51	Unit SILV907 [SITREP :] VECTOR NOW CONFIRM POWER NOW ISOLATED
16:07:09	Unit SILVOSU1 [K2 : IN ATTENDANCE AT INCIDENT]
16:11:09	Unit VSOWAITE03 [K2 : IN ATTENDANCE AT INCIDENT]
16:17:20	Alarm Timer Extended: 0
16:27:37	Unit SILV901 [KC : UNIT CALLING]
16:27:46	Unit SILV901 [K10 : RE-COMMISSIONING AFPLIANCE]
16:28:22	Unit SILV907 [KC : UNIT CALLING]
16:28:41	Unit SILV907 [K11P-1 : POLICE IN ATTENDANCE] THEY HAVE ADVSED THIS IS K12
16:28:49	Unit SILV907 [K11F : FIRE RISK MANAGEMENT REQUIRED] CONTACT 907 VIA CELLPHONE
16:29:01	INC INFO: HOUSE FIRE TX 2ND ALARM TOC 1438 TOA 1451
16:29:12	Pager used to Initiate Alerting.
16:29:14	ALERTING_COMPLETED FICOUMA05
16:29:14	ALERTING_COMPLETED FICOUMA05
16:32:30	Unit AUCK2018 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
16:34:41	Unit FICOUMA05 [SITREP :] VIA PHONE FIAUCKL01 ON CALL FOR WAITEMATA
16:35:07	Pager used to Initiate Alerting.
16:35:09	ALERTING_COMPLETED FIAUCKL01
16:35:09	ALERTING_COMPLETED FIAUCKL01
16:35:13	Unit MANL911 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
16:35:50	Unit FICOUMA05 [K6 : ON PAGER (STATE LOCATION)]
16:41:10	Unit SILVOSU1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
16:46:33	Unit AUCKOSU1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
16:47:34	Unit FIAUCKL01 [SITREP :] WAITEMATA HAVE ASKED WE GIVE THEIR JOBS TO THEM DURI
16:47:34	NG BUSINESS HOURS. ATTACH MICHAEL HOYNE INSTEAD
16:47:46	Pager used to Initiate Alerting.
16:47:47	ALERTING_COMPLETED FIWAITE02
16:47:47	ALERTING_COMPLETED FIWAITE02

16:47:52	Unit FIAUCKL01 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
16:48:56	AFFIRM
16:50:20	Unit FIWAITE02 [KC : UNIT CALLING]
16:50:49	Unit VSOWAITE03 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]
16:50:51	Unit VSOWAITE03 [K36 : CONTACT COMMUNICATIONS CENTRE BY PHONE]
16:50:54	Unit FIWAITE02 [K1 : PROCEEDING TO INCIDENT]
16:52:56	SILV901 HEADING BACK TO STATION AVAILABLE
16:52:56	Unit AUCKOSU [K6 : ON PAGER (STATE LOCATION)]
16:53:01	Alarm Timer Extended: 0
16:53:44	Unit SILV907 [COMCEN COM : MESSAGE] STANDBY FOR A PHONE CALL
16:57:42	Unit FIWAITE02 [SITREP :] VIA PHONE TRANSFERRED THROUGH TO S LV907
17:18:54	Phone used to Initiate Alerting.
17:18:55	ALERTING_COMPLETED MANL911
17:19:10	Unit MANL911 [K1 : PROCEEDING TO INCIDENT]
17:20:57	Unit SILV907 [KC : UNIT CALLING]
17:21:38	Unit SILV907 [SITREP :] MANL911 ARE RELIEVING SILV907 AT 1730 CAN YOU CONFIRM
17:21:38	THEY"RE LEAVING SHORTLY
17:21:46	Unit SILV907 [COMCEN COM : MESSAGE] THEY"RE K1
17:22:00	Unit VSOWAITE03 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
17:22:14	Unit MANL911 [K2 : IN ATTENDANCE AT INCIDENT]
17:28:55	Unit SILV907 [KC : UNIT CALLING]
17:29:21	Unit SILV907 [K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SO
17:29:21	NL911
17:29:25	Unit SILV907 [K10 : RE-COMMISSIONING APPLIANCE]
17:45:22	Unit FIWAITE02 [K2 : IN ATTENDANCE AT INCIDENT]
17:52:42	Unit MANL911 [KC : UNIT CALLING]
17:53:37	Unit MANL911 [SITREP :] SO 1 1 HPD ESTABLISHED A FEW HOTSPOTS FOUND AND DA
17:53:37	MPENING THEM DOWN
18:03:33	Alarm Timer Extended: 0
18:25:34	Alarm Timer Extended: 0
19:13:56	Unit FIWAITE02 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
19:14:15	Unit FIWAITE02 [SITREP :] (VIA PHONE) LEAVING SCENE WITH POL SCENE GUARD. SCEN
19:14:15	E IS LOCKED DOWN. WILL RETURN AT APPROX 0930
19:53:46	Unit MANL911 [KC : UNIT CALLING]
19:54:15	Unit MANL911 [STOP : MESSAGE] NO FURTHER NEED TO STAND BY CREWS SCENE LEFT IN H
19:54:15	ANDS OF POL
19:54:20	Unit MANL911 [K10 : RE-COMMISSIONING APPLIANCE]

19:55:02	UNIT 'VSOWAITE03' ALERT TIME '[NULL]' ADJUSTED TO '20230606145141NS' AT '06/06/2
19:55:02	** Assigned Result Code: STRU, Detailed Event Type: 1100
08:49:17	FIRE INVESTIGATION
08:49:19	** Event F3756563 has been reopened at: 07/06/23 08:49:19
08:49:20	** LOI search completed at 07/06/23 08:49:20
08:49:26	Pager used to Initiate Alerting.
08:49:26	Pager used to Initiate Alerting.
08:49:27	ALERTING_COMPLETED FIWAITE03
08:49:27	ALERTING_COMPLETED FIWAITE02
08:49:27	ALERTING_COMPLETED FIWAITE03
08:49:28	ALERTING_COMPLETED FIWAITE02
08:49:44	Unit FIWAITE02 [K1 : PROCEEDING TO INCIDENT]
08:50:24	Unit FIWAITE03 [K1 : PROCEEDING TO INCIDENT]
08:50:45	Unit FIWAITE02 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]
08:50:45	VIA PHONE - MYSELF AND FIWAITE03 - WELFARE CHECK AROUND 1200HRS
09:28:20	Unit FIWAITE02 [K2 : IN ATTENDANCE AT INCIDENT]
10:09:42	Alarm Timer Extended: 0
10:38:17	Unit FIWAITE03 [K2 : IN ATTENDANCE AT INCIDENT]
11:21:37	Alarm Timer Extended: 0
11:34:44	Unit FIWAITE02 [KC : UNIT CALLINC]
11:35:21	Unit FIWAITE02 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
11:35:23	Unit FIWAITE02 [SITREP ·] INVESTIGATION COMPLETED AND HANDED BACK TO OWNER
11:36:41	Unit FIWAITE03 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
11:44:46	UNIT 'VSOWAITE03' ALERT TIME '[NULL]' ADJUSTED TO '20230606145141NS' AT '07/06/2
11:44:46	** Assigned Result Code: STRU, Detailed Event Type: 1100

Incident

CAD Number F3756563

Incident Reporter

Incident Controller

Distance Travelled (km)

Delay In Receiving Call

Property Details

Occupant Vacant -

Building Owner Owner occupied
General Property Use Single house
Special Property Use Single house

Purpose Group

Actions

Persons Reported

Trapped

Evacuation Status Not occupied at time of incident

Action Prior 1
Action Prior 2

Action Taken Extinguishment only: Includes isolating fuel/power

Civilians

Civilians Rescued	× O	0
Civilians Extricated		0
Civilians Assisted		0
Civilians Evacuated		0

Origin

Location Living area - not classified above

Level 1st floor

Equipment Used

Quantity	Equipment
2	Low pressure delivery
1	Monitor
3	Thermal Imaging Camera (TIC)
22	Equipment Not Listed

Equipment Involved

Equipment Involved

Year

Make

Model

Fire

Arrival Condition Totally involved fire

Heat Source Lighters

Termination Stage

First Object Ignited

First Object Material

Second Object Ignited

Second Object Material

Indicated Cause Suspicious

Certainty of Cause High

Age of PersonUnknownEthnicityUnknown

Gender

FAIP Service Offered Unknown

Comments

6/12/2023 4:04:06 PM

Reporter Comments

There is a high probability that this was a deliberately lit fire. Power had not been A Relie as ed Under the Official Peleased Under the Offici used at the property for years and there is evidence available to NZ Police indicating two people entered the property and then left shortly before the fire was