# **SMS Incident Report**

12/06/2023 13:03:25

**Summary** 

CAD Number F3758620 Status Closed

Station Auckland City Station

Incident Started 09/06/2023 09:28:41 Incident Ended 09/06/2023 10:17:02

**Incident Type** 1102: Structure fire with no damage

Common Name CARLAW PARK COMMERCIAL PRECINCT

Address 8-20 Nicholls Lane Auckland Central

Alarm Method 111 Telephone Alarm Level 2

**PFA Number** 

**Zone** 142501

Map Grid E 1758273 Map Grid N 5919955

First Caller Contact


Incident Closed 09/06/2023 10:17:02

Report Completed 14:9, Sat 10 Jun 2023 by

#### Responses

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
AUCK207	PR	09:29:53 09 Jun 2023	09:30:03 09 Jun 2023	09:33:36 09 Jun 2023	10:15:05 09 Jun 2023
PARN251	P1	09:29:50 09 Jun 2023	09:31:19 09 Jun 2023	09:35:25 09 Jun 2023	10:05:28 09 Jun 2023
PARN255	HPNP	09:29:59 09 Jun 2023	09:31:43 09 Jun 2023	09:35:29 09 Jun 2023	10:00:28 09 Jun 2023
AUCK205	HP	09:37:43 09 Jun 2023	09:38:01 09 Jun 2023	09:38:21 09 Jun 2023	09:50:43 09 Jun 2023
REMU211	P1	09:29:56 09 Jun 2023	09:31:10 09 Jun 2023	09:39:55 09 Jun 2023	10:02:31 09 Jun 2023
AUCK2018	CUHU	09:36:33 09 Jun 2023	09:37:33 09 Jun 2023	09:43:13 09 Jun 2023	09:48:32 09 Jun 2023
GREY261	P1	09:36:40 09 Jun 2023	09:38:10 09 Jun 2023	09:44:25 09 Jun 2023	09:45:40 09 Jun 2023
GMCOUMA02	OF	09:38:41 09 Jun 2023	09:38:42 09 Jun 2023	09:55:15 09 Jun 2023	10:04:08 09 Jun 2023
AUCKOSU2	SV	09:42:32 09 Jun 2023	09:42:34 09 Jun 2023	09:58:03 09 Jun 2023	10:04:44 09 Jun 2023
AUCKOSU	SV	09:36:33 09 Jun 2023			10:04:51 09 Jun 2023

Start->Alert 7 min 10 min



## **Elapsed Times**

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
AUCK207	00:01:12	00:03:43	00:04:55	00:46:24
PARN251	00:01:09	00:05:35	00:06:44	00:36:47
PARN255	00:01:18	00:05:30	00:06:48	00:31:47
AUCK205	00:09:02	00:00:38	00:09:40	00:22:02
REMU211	00:01:15	00:09:59	00:11:14	00:33:50
AUCK2018	00:07:52	00:06:40	00:14:32	00:19:51
GREY261	00:07:59	00:07:45	00:15:44	00:16:59
GMCOUMA02	00:10:00	00:16:34	00:26:34	00:35:27
AUCKOSU2	00:13:51	00:15:31	00:29:22	00:36:03
AUCKOSU	00:07:52	. (		00:36:10

### **Notifications**

Date	Time	Party Notified
09 Jun 2023	09:36:12	POLICE VIA INTERCAD
09 Jun 2023	09:36:13	AMBULANCE VIA INTERCAD
09 Jun 2023	09:36:27	VECTOR
09 Jun 2023	09:40:04	PAGED DUTY GM RE SECOND ALARM
09 Jun 2023	09:40:27	GMAUCKL02 ACKNOWLEDGED VIA AMS
09 Jun 2023	09:42:51	GM WAITMATA 02 MONITORING
09 Jun 2023	10:08:09	GMCOUMA02 ACKNOWLEDGED VIA AMS

# Message Log

Time	Message	
09:29:19	INC INFO: SMELL OF BURNING ON LEVEL THREE	
09:29:20	** LOI search completed at 09/06/23 09:29:20	
09:29:29	** Requirement AERIAL added for alarm level 1	
09:29:42	** Recommended unit PARN251 for requirement PPARN25A (>1.2 km)  ** Recommended u	
09:29:42	nit AUCK207 for requirement PUMP (>1.1 km)  ** Recommended unit REMU211 for requ	
09:29:42	irement PUMP (>3.9 km) ** Recommended unit PARN255 for requirement AERIAL (>1.2	

09:29:42	km)
09:29:46	MSU Selcal used to Initiate Alerting. (PARN251 D0F982)
09:29:46	MSU Selcal used to Initiate Alerting. (AUCK207 D0F922)
09:29:46	MSU Selcal used to Initiate Alerting. (REMU211 D0FE02)
09:29:46	MSU Selcal used to Initiate Alerting. (PARN255 D0F412)
09:29:50	ALERTING_COMPLETED PARN251
09:29:53	ALERTING_COMPLETED AUCK207
09:29:56	ALERTING_COMPLETED REMU211
09:29:59	ALERTING_COMPLETED PARN255
09:30:03	Unit AUCK207 [ K1 : PROCEEDING TO INCIDENT]
09:31:04	Unit PARN255 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
09:31:10	Unit REMU211 [ K1 : PROCEEDING TO INCIDENT]
09:31:19	Unit PARN251 [ K1 : PROCEEDING TO INCIDENT]
09:31:36	Radio used to Initiate Alerting.
09:31:36	ALERTING_COMPLETED PARN255
09:31:43	Unit PARN255 [ K1 : PROCEEDING TO INCIDENT]
09:33:36	Unit AUCK207 [ K77 : NOTHING SHOWING]
09:35:25	Unit PARN251 [ K2 : IN ATTENDANCE AT INCIDENT]
09:35:29	Unit PARN255 [ K2 : IN ATTENDANCE AT INCIDENT]
09:35:32	Unit AUCK207 [ KP : PRIORITY MESSAGE]
09:35:54	Unit AUCK207 [ SITREP : ] TX 2ND ALARM
09:36:08	INC INFO: SMELL OF BURNING ON LEVEL THREE - TX 2ND ALARM
09:36:09	** Event A01121720 of AMBO/N copied from F3758620 of NZFS/AK at: 09/06/23 09:36:
09:36:09	09
09:36:10	** Event P054933798 of NZP/AC copied from F3758620 of NZFS/AK at: 09/06/23 09:36
09:36:10	AMBO EVENT 0307-1-2023/06/09-FIR LINKED AT 09/06/2023 09:36:10
09:36:10	:10
09:36:11	** Requirement AERIAL removed for alarm level 1
09:36:21	** Units excluded from recommendation: STHE241
09:36:24	Units restored to recommendation: STHE241
09:36:26	** Alarm level updated to 2
09:36:26	** Recommended unit AUCK2018 for requirement COMU (>3.7 km) ** Recommended unit
09:36:26	GREY261 for requirement PUMP (>3.5 km) ** Recommended unit STHE241 for require
09:36:26	ment PUMP (>7.3 km)  ** Recommended unit AUCKOSU for requirement SUPPT (>11.2 km
09:36:26	
09:36:29	MSU Selcal used to Initiate Alerting. (AUCK2018 D06F42)
09:36:30	PA Selcal used to Initiate Alerting. (GREY261 at 1426 GREY LYNN 182261)
09:36:30	Pager used to Initiate Alerting.

09:36:30	MSU Selcal used to Initiate Alerting. (AUCK205 D095D2)
09:36:31	FIR2AMB SMELL OF BURNING 2ND ALARM TXTD FOR INFO
09:36:33	ALERTING_COMPLETED AUCKOSU
09:36:33	ALERTING_COMPLETED AUCK2018
09:36:33	ALERTING_COMPLETED AUCKOSU
09:36:40	ALERTING_COMPLETED GREY261
09:36:44	FIR2POL SMELL OF BURNING 2ND ALARM TXTD FOR INFO
09:37:33	Unit AUCK2018 [ K1 : PROCEEDING TO INCIDENT]
09:37:36	MSU Selcal used to Initiate Alerting. (AUCK205 D095D2)
09:37:43	ALERTING_COMPLETED AUCK205
09:37:47	FIR2POL FYI ONLY AT THIS STAGE THANKS
09:38:01	Unit AUCK205 [ K1 : PROCEEDING TO INCIDENT]
09:38:10	Unit GREY261 [ K1 : PROCEEDING TO INCIDENT]
09:38:21	Unit AUCK205 [ K2 : IN ATTENDANCE AT INCIDENT]
09:38:42	Unit GMCOUMA02 [ K1 : PROCEEDING TO INCIDENT]
09:38:44	COVERING UNIT BALM611 DISPATCHED TO STATION AUCKLAND CITY AT 09/06/23 09:38:44 >
09:38:45	Unit AUCK207 [ KC : UNIT CALLING]
09:39:26	FIR2AMB AFFIRM FYI ONLY AT THIS STAGE
09:39:55	Unit REMU211 [ K2 : IN ATTENDANCE AT INCIDENT]
09:40:06	Unit AUCK207 [ SITREP : ] SSO - THIS IS A FOUR LEVEL BUILDING - 50M X 30M
09:40:06	- USED AS COMBINED OFFICE SPACE - REPORTS OF FIRE BETWEEN WALL ON LEVEL THREE I
09:40:06	N OFFICE AREA - CREWS INV AND AERIAL APPLIANCE SETTING UP FOR ACCESS
09:40:12	Unit GMCOUMA02 [ SITREP : ] COPIED
09:40:20	Unit AUCKOSU [ K22-1 : APPLIANCE AVAILABLE FOR A FURTHER INCIDENT]
09:42:15	Unit AUCK207 [ KC : UNIT CALLING]
09:42:31	Pager used to Initiate Alerting.
09:42:32	ALERTING_COMPLETED AUCKOSU2
09:42:34	Unit AUCKOSU2 [ K1 : PROCEEDING TO INCIDENT]
09:42:38	Unit AUCKOSU2 [ K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]
09:42:40	Unit AUCKOSU2 [ K39-1 : TRANSMIT K1]
09:43:06	Unit AUCK207 [ SITREP : ] FIRE LOCATED ON LEVEL THREE INVOLVING WIRING AND TRANS
09:43:06	FORMER - FIRE NOW ATB OUT - BRIG CHECKING FOR FIRE SPREAD
09:43:13	Unit AUCK2018 [ K2 : IN ATTENDANCE AT INCIDENT]
09:43:23	Unit AUCK207 [COMCEN COM : MESSAGE] BE ADV VECTOR AND OSU ARE ENROUTE
09:44:25	Unit GREY261 [ K2 : IN ATTENDANCE AT INCIDENT]
09:45:40	Unit GREY261 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
09:48:32	Unit AUCK2018 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
09:50:43	Unit AUCK205 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

09:55:15	Unit GMCOUMA02 [ K2 : IN ATTENDANCE AT INCIDENT]
09:55:40	Unit AUCK207 [ KC : UNIT CALLING]
09:56:26	Unit AUCK207 [ SITREP : ] CONFIRMATION OF NO FIRE SPREAD - LIAISING WITH ON SITE
09:56:26	BUILDING ELECTRICIAN
09:56:34	Unit AUCK207 [COMCEN COM : MESSAGE] ARE VECTOR STILL REQUIRED?
09:57:09	Unit AUCK207 [ SITREP : ] STANDBY
09:57:21	Unit AUCK207 [ KC : UNIT CALLING]
09:57:37	Unit AUCK207 [ SITREP : ] VECTOR NO LONGER REQUIRED
09:58:03	Unit AUCKOSU2 [ K2 : IN ATTENDANCE AT INCIDENT]
10:00:28	Unit PARN255 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
10:02:31	Unit REMU211 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
10:04:08	Unit GMCOUMA02 [ K6 : ON PAGER (STATE LOCATION)]
10:04:45	Unit AUCKOSU2 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
10:04:51	Unit AUCKOSU [ K7 : AT NORMAL STATION]
10:05:29	Unit PARN251 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
10:14:20	Unit AUCK207 [ KC : UNIT CALLING]
10:14:43	Unit AUCK207 [ STOP : MESSAGE] BUILDING LEFT WITH SITE FACILITY MANAGER
10:15:05	Unit AUCK207 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
10:17:01	UNIT 'GMCOUMA02' ALERT TIME '[NU'LL]' ADJUSTED TO '20230609093841NS' AT '09/06/20
10:17:01	** Assigned Result Code: STRU, Detailed Event Type: 1500

#### Incident

**CAD Number** F3758620

Incident Reporter

porter

**Incident Controller** 

**Distance Travelled (km)** 

**Delay In Receiving Call** 

#### **Property Details**

Occupant Nestle NZ

Building Owner Rented property

General Property Use Office, Bank, Embassy, Fire/Ambo/Police station

Special Property Use Office: General business

**Purpose Group** 

#### **Actions**

Persons Reported Trapped

Evacuation Status No evacuation

Action Prior 1
Action Prior 2

Action Taken Investigation only (Fire related)

#### **Civilians**

Civilians Rescued		0
Civilians Extricated		0
Civilians Assisted	20	0
Civilians Evacuated		0

#### Origin

**Location** Ceiling and roof assembly

Level 3rd or 4th floor

#### **Equipment Used**

Quantity	Equipment
1	Fire Extinguisher
1	Thermal Imaging Camera (TIC)
1	Aerial Ladder/Platform

#### **Equipment Involved**

**Equipment Involved** 

Year

Make

Model

#### **Fire**

Arrival Condition Out on arrival

Heat Source Short circuit arc: Unspecified

Termination Stage
First Object Ignited
First Object Material
Second Object Ignited

**Second Object Material** 

Indicated Cause Undetermined

Certainty of Cause Medium

Age of Person No person involved

**Ethnicity** 

Gender

**FAIP Service Offered** Unknown

#### **Alarms**

Type of Alarm Smoke Detector System (Monitored)

**Initiating Call** Performance of

Did not operate - detector not in room of origin

System

Failure/Ineffectiven Detector not in room of origin

ess of system

heads operated

Number of sprinkler

Comments

6/10/2023 2:09:39 PM **Reporter Comments** 

Small amount of electrical wiring arcing in ceiling space. initially thought to be a transformer however on arrival of electrician it appeared to be a loose wiring connector. No structural damage to building. Manager stated that they held smelt smoke for about two hours before calling FENZ. I advised them that any smell of smoke in the building they should call immediately. Released Under the