SMS Incident Report

14/09/2023 11:23:47

Summary

CAD Number F3812425 Status Closed

Station Invercargill Station

Incident Started 06/09/2023 00:59:57 Incident Ended 08/09/2023 14:08:14

Map Grid N 4849883

Incident Type 1101: Structure fire with damage

Common Name PALL MALL ARCADE

Address 104-106 Dee Street Invercargill

Alarm Method 111 Telephone Alarm Level 3

PFA Number

Zone 382101 **Map Grid E** 1242384

First Caller First Caller Contact


Incident Closed 08/09/2023 14:08:14

Report Completed 21:18, Wed 13 Sep 2023 by

Responses

Call Sign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
INVE211	P1	01:00:58 06 Sep 2023	01:02:30 06 Sep 2023	01:09:19 06 Sep 2023	11:24:06 06 Sep 2023
INVE214	PM	01:00:58 06 Sep 2023	01:02:48 06 Sep 2023	01:09:24 06 Sep 2023	01:10:48 07 Sep 2023
KING227	PR	01:05:28 06 Sep 2023	01:05:58 06 Sep 2023	01:13:52 06 Sep 2023	04:59:28 06 Sep 2023
INVE213	P3	01:05:25 06 Sep 2023	01:14:12 06 Sep 2023	01:18:25 06 Sep 2023	06:42:09 06 Sep 2023
GMSOUTH01	OF	01:19:20 06 Sep 2023	01:19:32 06 Sep 2023	01:21:02 06 Sep 2023	05:29:59 06 Sep 2023
INVE2120	LRV	01:05:25 06 Sep 2023	01:19:39 06 Sep 2023	01:21:31 06 Sep 2023	06:55:57 06 Sep 2023
WALL241	P1	01:07:38 06 Sep 2023	01:12:38 06 Sep 2023	01:21:45 06 Sep 2023	06:04:00 06 Sep 2023
FISOUTH02	FSO	01:22:55 06 Sep 2023	01:22:56 06 Sep 2023	01:29:51 06 Sep 2023	14:01:28 08 Sep 2023
DMSOUTH	OF	01:22:48 06 Sep 2023	01:22:49 06 Sep 2023	01:31:39 06 Sep 2023	03:28:34 06 Sep 2023
BLUF231	P1	01:07:40 06 Sep 2023	01:12:51 06 Sep 2023	01:32:11 06 Sep 2023	04:49:43 06 Sep 2023
INVE212	P2	01:05:31 06 Sep 2023	01:36:46 06 Sep 2023	01:42:33 06 Sep 2023	05:00:29 06 Sep 2023

INVE2118	CUHU	01:05:31 06 Sep 2023	01:48:08 06 Sep 2023	01:49:58 06 Sep 2023	05:26:37 06 Sep 2023
VSOSOUTH02	VSO	04:43:29 06 Sep 2023	04:43:30 06 Sep 2023	06:47:29 06 Sep 2023	07:35:34 06 Sep 2023
FISOUTH01	FSO	07:48:09 06 Sep 2023	07:48:10 06 Sep 2023	07:54:42 06 Sep 2023	13:21:11 08 Sep 2023
DUNE216	TL	10:49:33 06 Sep 2023	10:49:34 06 Sep 2023	14:02:15 06 Sep 2023	21:42:59 06 Sep 2023
DUNE2126	SU	10:59:57 06 Sep 2023	10:59:58 06 Sep 2023	14:17:32 06 Sep 2023	21:31:35 06 Sep 2023
EVENTSCC1	ОТ				06:34:02 08 Sep 2023



Elapsed Times

Elapseu Tillies				
Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
INVE211	00:01:01	00:08:21	00:09:22	10:24:09
INVE214	00:01:01	00:08:26	00:09:27	24:10:51
KING227	00:05:31	00:08:24	00:13:55	03:59:31
INVE213	00:05:28	00:13:00	00:18:28	05:42:12
GMSOUTH01	00:19:23	00:01:42	00:21:05	04:30:02
INVE2120	00:05:28	00:16:06	00:21:34	05:56:00
WALL241	00:07:41	00:14:07	00:21:48	05:04:03
FISOUTH02	00:22:58	00:06:56	00:29:54	61:01:31
DMSOUTH	00:22:51	00:08:51	00:31:42	02:28:37
BLUF231	00:07:43	00:24:31	00:32:14	03:49:46
INVE212	00:05:34	00:37:02	00:42:36	04:00:32
INVE2118	00:05:34	00:44:27	00:50:01	04:26:40
VSOSOUTH02	03:43:32	02:04:00	05:47:32	06:35:37
FISOUTH01	06:48:12	00:06:33	06:54:45	60:21:14
DUNE216	09:49:36	03:12:42	13:02:18	20:43:02
DUNE2126	10:00:00	03:17:35	13:17:35	20:31:38
EVENTSCC1				53:34:05

Notifications

Date	Time	Party Notified
06 Sep 2023	01:03:15	POWER (POWERNET)

06 Sep 2023	01:04:27	AMBULANCE VIA INTERCAD
06 Sep 2023	01:04:28	POLICE VIA INTERCAD
06 Sep 2023	01:05:40	TOC - WILL RESPOND CONTRACTORS TO ASSIST WITH TRAFFIC CONTROL
06 Sep 2023	01:06:26	INVERCARGILL WATER TOWER
06 Sep 2023	01:08:35	SOUTHLAND WAKATIPU BUILT PAGED RE 3RD ALARM
06 Sep 2023	01:09:01	FI TE KEI PAGED RE 3RD ALARM (NOTIFICATION ONLY)
06 Sep 2023	01:09:50	DMSOUTH ACKNOWLEDGED VIA AMS
06 Sep 2023	01:13:31	SOUTHLAND WAKATIPU BUILT (DM ACK PAGE - WILL RESPOND
06 Sep 2023	01:13:39	REGION TE KEI PAGED RE 3RD ALARM
06 Sep 2023	01:16:30	FISOUTH02 (CARREST OF ALARM - GOING TO ATTEND -
06 Sep 2023	01:19:58	DMSOUTH ACKNOWLEDGED VIA AMS
06 Sep 2023	02:36:49	INVERCARGILL CITY COUNCIL
06 Sep 2023	03:00:15	INVERCARGILL CITY COUNCIL RE BUILDING REP
06 Sep 2023	03:02:44	TOC - ASKING HOW LONG TRAFFIC CONTROL MAY BE REQUIRED - APPROX AT LEAST ANOT
06 Sep 2023	03:04:48	INVERCARGILL WATER TOWER - WILL CONTINUE FOR AT LEAST ANOTHER 2 HOURS - WANT
06 Sep 2023	03:19:46	INVERCARGILL WATER TOWER
06 Sep 2023	04:25:13	VSO TE KEI (DUTY)
06 Sep 2023	04:30:58	VSO ACK PAGE AND TRANSFERRED TO GM
06 Sep 2023	06:37:55	NATIONAL MEDIA SUPPORT RE TX 3RD ALARM
06 Sep 2023	08:48:00	INVERCARGILL STATION - THEY ARE CHECKING IF AVAILABILITY HAS BEEN STOOD DOWN
06 Sep 2023	09:03:34	ON CALL SOUTHLAND WAKATIPU PAGED TO CALL INTO SHIFT MGR
06 Sep 2023	09:07:24	DMSOUTH ACKNOWLEDGED VIA AMS
06 Sep 2023	10:31:55	DUNEDIN CITY FIRE SSO PHONED AND PATCHED THROUGH TO INVE214
06 Sep 2023	17:15:48	INVE214 TO FIND OUT WHAT THE STORY IS WITH DUNEDIN APPLIANCES - THEY WILL BE

Message Log

moodago Eog				
Time C	Message			
01:00:20	https://web.pcl.govt.nz/?ecn=			
01:00:20	INC INFO: BUILDING FIRE			
01;00:21	** LOI search completed at 06/09/23 01:00:21			
01:00:52	ARCADE BUILDING			
01:00:52	** Recommended unit INVE211 for requirement PUMP (>2.5 km) ** Recommended unit			
01:00:52	INVE214 for requirement PUMP (>2.5 km)			
01:00:54	PA Selcal used to Initiate Alerting. (INVE211 at 3821 INVERCARGILL 196211)			
01.00.04	177 Colour asset to minute 7 forting. (177 E211 at 3021 117 E160/10/10/E17)			
01:00:55	PA Selcal used to Initiate Alerting. (INVE214 at 3821 INVERCARGILL 196211)			

01:00:58	ALERTING_COMPLETED INVE211
01:00:58	ALERTING_COMPLETED INVE214
01:02:30	Unit INVE211 [K1 : PROCEEDING TO INCIDENT]
01:02:37	** Event Location changed from "DEE ST,/BAY RD,PRESTONVILLE,INVERCARGILL CITY" t
01:02:37	o "DEE ST,/SPEY ST,INVERCARGILL,INVERCARGILL CITY" at: 06/09/23 01:02:37
01:02:39	** LOI search completed at 06/09/23 01:02:39
01:02:49	Unit INVE214 [K1 : PROCEEDING TO INCIDENT]
01:03:08	Unit INVE214 [K1 : PROCEEDING TO INCIDENT]
01:03:56	*****
01:04:06	FIR2AMB FYI SH NOTIFICATION
01:04:12	FIR2POL FYI SH NOTIFICATION
01:04:14	*****
01:04:23	** Event A01145865 of AMBO/S copied from F3812425 of NZFS/SL at: 06/09/23 01:04:
01:04:23	23
01:04:24	AMBO EVENT 0014-3-2023/09/06-FIR LINKED AT 06/09/2023 01:04:24
01:04:25	Unit INVE211 [KP : PRIORITY MESSAGE]
01:04:25	** Event P055928115 of NZP/IV copied from F3812425 of NZFS/SL at: 06/09/23 01:04
01:04:25	:25
01:04:54	Unit INVE211 [SITREP :] K99 PROCEEDING, TX 2ND ALARM
01:05:05	** Event Location changed from "DEE ST,/SPEY ST,INVERCARGILL,INVERCARGILL CITY"
01:05:05	to "104-106 DEE ST,INVERCARGILL INVERCARGILL CITY: @PALL MALL ARCADE" at: 06/09/
01:05:05	23 01:05:05
01:05:07	** LOI search completed at 06/09/23 01:05:07
01:05:07	INC INFO: BUILDING FIRE - TX 2ND ALARM
01:05:15	** Alarm level updated to 2
01:05:15	** Recommended unit KING227 for requirement PUMP (>4.5 km) ** Recommended unit
01:05:15	INVE2118 for requirement COMU (>0.7 km) ** Recommended unit INVE2120 for requir
01:05:15	ement LRV (>0.7 km) ** Recommended unit INVE212 for requirement PUMP (>0.7 km)
01:05:15	** Recommended unit INVE213 for requirement PUMP (>0.7 km)
01:05:20	PA Selcal used to Initiate Alerting. (KING227 at 3822 KINGSWELL 196221)
01:05:20	PA Selcal used to Initiate Alerting. (INVE2118 at 3821 INVERCARGILL 196211)
01:05:21	Pager used to Initiate Alerting.
01:05:21	PA Selcal used to Initiate Alerting. (INVE212 at 3821 INVERCARGILL 196212)
01:05:22	Station Selcal used to Initiate Alerting. (INVE213 at 3821 INVERCARGILL 196212)
01:05:25	ALERTING_COMPLETED INVE213
01:05:25	ALERTING_COMPLETED INVE2120
01:05:28	ALERTING_COMPLETED KING227

01:05:31	ALERTING_COMPLETED INVE2118
01:05:31	ALERTING_COMPLETED INVE212
01:05:38	Unit INVE214 [KP : PRIORITY MESSAGE]
01:05:48	COVERING UNIT INVE21AMS2 DISPATCHED TO STATION INVERCARGILL AT 06/09/23 01:05:48
01:05:54	Unit INVE214 [KP : PRIORITY MESSAGE]
01:05:58	Unit KING227 [K1 : PROCEEDING TO INCIDENT]
01:05:58	COVERING UNIT INVE21AMS6 DISPATCHED TO STATION INVERCARGILL AT 06/09/23 01:05:57
01:06:26	Unit INVE214 [SITREP :] TX 3RD ALARM, BUILDING WELL INVOLVED, 2ND STORY, GTWW
01:06:26	LPD AND MONITORS
01:07:12	****
01:07:15	Unit INVE211 [KP : PRIORITY MESSAGE]
01:07:25	INC INFO: BUILDING FIRE - TX 3RD ALARM
01:07:28	FIR2POL FIRE IS WELL INVOLVED - CREWS SETTING UP ON SCENE. TOC SENDING CONTRACTO
01:07:28	RS FOR TRAFFIC CONTROL
01:07:31	** Alarm level updated to 3
01:07:31	** Recommended unit WALL241 for requirement PUMP (>10.0 km) ** Recommended unit
01:07:31	BLUF231 for requirement PUMP (>21.1 km)
01:07:36	Station Selcal used to Initiate Alerting. (WALL241 at 3824 WALLACETOWN 196241)
01:07:36	Station Selcal used to Initiate Alerting. (BLUF231 at 3823 BLUFF 196231)
01:07:39	ALERTING_COMPLETED WALL241
01:07:41	ALERTING_COMPLETED BLUF231
01:07:44	FIR2AMB FIRE CREWS ADVISING PERSONS REPORTED. CAN YOU RESPOND PLEASE
01:07:46	****
01:07:47	Unit INVE211 [K11A : AMBULANCE REQUIRED] PERSONS REPORTED
01:08:01	** Cross Referenced to Event # F3812426 at: 06/09/23 01:08:01
01:08:46	
01:09:05	
01:09:19	Unit INVE211 [K99 : PROPERTY FIRE WELL INVOLVED] ENTERED BY FIRECOM
01:09:19	ENTERED BY FIRECOM
01:09:24	ENTERED BY FIRECOM
01:09:25	Unit INVE214 [K2 : IN ATTENDANCE AT INCIDENT] ENTERED BY FIRECOM
01:09:36	Unit INVE211 [KP : PRIORITY MESSAGE]
01:10:09	Unit INVE211 [K11A : AMBULANCE REQUIRED] WE HAVE SOME PEOPLE THAT HAVE BEEN BUR
01:10:09	NT, JUST TRYING TO ASSESS THE BURNS AT THIS STAGE
01:11:00	AL: PAGING ACK TIMED OUT FOR STATION: 3824 at 06-09-23 01:11:00
01:12:38	Unit WALL241 [K1 : PROCEEDING TO INCIDENT]
01:12:51	Unit BLUF231 [K1 : PROCEEDING TO INCIDENT]

01:13:16	**
01:13:52	Unit KING227 [K2 : IN ATTENDANCE AT INCIDENT]
01:14:12	Unit INVE213 [K1 : PROCEEDING TO INCIDENT]
01:15:40	Unit INVE211 [KC : UNIT CALLING]
01:15:40	Unit BLUF231 [COMCEN COM : MESSAGE] FURTHER INFO PASSED
01:15:40	Unit INVE213 [COMCEN COM : MESSAGE] FURTHER INFO PASSED
01:15:41	Unit WALL241 [COMCEN COM: MESSAGE] FURTHER INFO PASSED
01:16:08	
01:16:30	K1 IN 10 MINS
01:16:33	
01:16:56	Unit INVE211 [SITREP :] SSO 1 1 LARGE BUILDING FIRE, BUILDING 2 STORY A
01:16:56	PPROX 10M BY 15M, 2 CREWS ON EXTERNAL ATTACK, ESTABLISHING THE BRONTO FOR WATER
01:16:56	PROTECTION,
01:16:56	
01:17:25	Unit INVE211 [COMCEN COM : MESSAGE] ARE THERE ANY FURTHER PEOPLE UNACCOUNTED FOR
01:17:25	? (AT THIS STAGE NEGATIVE, BUT TRYING TO ASSESS INFORMATION)
01:17:31	
01:18:01	FIR2AMB/FIR2POL -
01:18:01	
01:18:02	
01:18:05	Unit INVE211 [KC : UNIT CALLING]
01:18:25	Unit INVE213 [K2 : IN ATTENDANCE AT INCIDENT]
01:18:50	Unit INVE211 [SITREP :] COULD YOU ADVISE ALL FURTHER APPLIANCES, SFP NORTH OF
01:18:50	SPEY BELOW YARROW
01:19:09	Unit BLUF231 [SITREP :] ACK
01:19:10	Unit WALL241 [SITREP :] ACK
01:19:19	Pager used to Initiate Alerting.
01:19:20	ALERTING_COMPLETED GMSOUTH01
01:19:32	Unit GMSOUTH01 [K1 : PROCEEDING TO INCIDENT]
01:19:39	Unit INVE2120 [K1 : PROCEEDING TO INCIDENT]
01:19:50	Unit GMSOUTH01 [COMCEN COM : MESSAGE] SFP DEE ST NORTH OF SPEY ST SOUTH OF YARRO
01:19:50	W ST
01:20:14	Unit INVE2120 [COMCEN COM : MESSAGE] SFP DEE ST NORTH OF SPEY ST SOUTH OF YARROW
01:20:14	ST
01:21:02	Unit GMSOUTH01 [K2 : IN ATTENDANCE AT INCIDENT]
01:21:31	Unit INVE2120 [K2 : IN ATTENDANCE AT INCIDENT]

01:21:45	Unit WALL241 [K2 : IN ATTENDANCE AT INCIDENT]
01:22:49	Unit DMSOUTH [K1 : PROCEEDING TO INCIDENT]
01:22:56	Unit FISOUTH02 [K1 : PROCEEDING TO INCIDENT]
01:23:30	Unit DMSOUTH [COMCEN COM : MESSAGE] [VIA PHONE] WOULD YOU LIKE WINT377 DOWN FOR
01:23:30	COVER?
01:23:48	Unit DMSOUTH [SITREP :] [VIA PHONE] NOT AT THIS STAGE. WILL ASSESS WHEN ON SCE
01:23:48	NE NE
01:24:10	Unit FISOUTH02 [COMCEN COM : MESSAGE] SFP DEE ST NORTH OF SPEY ST SOUTH OF YARRO
01:24:10	w st
01:24:32	Unit DMSOUTH [COMCEN COM: MESSAGE] SFP DEE ST NORTH OF SPEY ST SOUTH OF YARROW
01:24:32	ST
01:28:36	Unit INVE211 [KC : UNIT CALLING]
01:29:30	Unit INVE211 [K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] ASSISTANT C
01:29:30	OMMANDER
01:29:51	Unit FISOUTH02 [K2 : IN ATTENDANCE AT INCIDENT]
01:31:07	Unit INVE211 [SITREP :] 3 STORY BUILDING, APPROX 30M BY 30M WELL INVOLVED ON T
01:31:07	HE 2ND AND 3RD FLOOR
01:31:07	
01:31:39	Unit DMSOUTH [K2 : IN ATTENDANCE AT INCIDENT]
01:32:11	Unit BLUF231 [K2 : IN ATTENDANCE AT INCIDENT]
01:35:16	FIR2POL -
01:36:46	Unit INVE212 [K1 : PROCEEDING TO INCIDENT]
01:37:04	Unit INVE212 COMCEN COM: MESSAGE] SFP DEE ST NORTH OF SPEY ST SOUTH OF YARROW
01:37:04	ST
01:41:19	Unit INVE211 [KC : UNIT CALLING]
01:42:33	Unit INVE212 [K2 : IN ATTENDANCE AT INCIDENT]
01:43:59	Unit INVE211 [SITREP :] CURRENTLY HAVE CREWS CONDUCTING AN INTERNAL OFFENSIVE
01:43:59	ATTACK USING 2 LPD, 2 GROUND MONITORS, 1 AERIAL APPLIANCE, CREWS ARE IN DEFENSIV
01:43:59	E MODE, CAN YOU CONFIRM IF INVE2118 IS K1 YET? (NEGATIVE, INVE212 IS. IS THE COM
01:43:59	MAND UNIT REQUIRED?) AFFIRM
01:48:08	Unit INVE2118 [K1 : PROCEEDING TO INCIDENT]
01:48:37	·
01:48:57	FIR2POL - KEYHOLDER WE HAVE LISTED FOR SNAP FITNESS IS RUTH STEVENSON
01:49:58	Unit INVE2118 [K2 : IN ATTENDANCE AT INCIDENT]

01:58:02	Alarm Timer Extended: 0
01:58:03	Alarm Timer Extended: 0
01:58:04	Alarm Timer Extended: 0
02:00:05	Alarm Timer Extended: 0
02:05:00	Unit INVE2118 [KC : UNIT CALLING]
02:05:24	Unit INVE2118 [K44 : COMMAND OR CONTROL POINT ESTABLISHED (STATE OIC AND LOCATI
02:05:24	ON)] DEE STREET COMMAND
02:05:48	Alarm Timer Extended: 0
02:05:49	Alarm Timer Extended: 0
02:05:50	Alarm Timer Extended: 0
02:08:08	Unit INVE2118 [KC : UNIT CALLING]
02:08:39	Unit INVE2118 [SITREP :] GM K25 WINT371 TO INVERCARGILL STATION
02:08:53	COVERING UNIT WINT371 DISPATCHED TO STATION INVERCARGILL AT 06/09/23 02:08:53 >>
02:10:02	Unit INVE2118 [KC : UNIT CALLING]
02:11:36	Unit INVE2118 [SITREP :] CREWS ON SECTOR 1 AND SECTOR 4 CONDUCTING INTERNAL SE
02:11:36	ARCHES OF ADJACENT BUILDINGS LOOKING FOR STRUCTURAL BREACHES AND FIRE SPREAD, CR
02:11:36	EWS ARE CONTINUING EXTERNAL ATTACK WITH LOW PRESSURE DELIVERIES AND GROUND MONIT
02:11:36	ORS
02:11:42	Alarm Timer Extended: 0
02:11:43	Alarm Timer Extended: 0
02:13:26	Alarm Timer Extended: 0
02:17:20	Unit INVE2118 [KC : UNIT CALLING]
02:17:51	Unit INVE2118 [SITREP :] NOTIFY US WHEN WINT371 ARE K9
02:23:41	Unit INVE2117 K99 : PROPERTY FIRE WELL INVOLVED]
02:28:55	Unit INVE2118 [KC : UNIT CALLING]
02:29:13	Alarm Timer Extended: 0
02:30:27	Unit INVE2118 [SITREP :] CREWS HAVE SEARCHED ALL SURROUNDING BUILDINGS, CONFIR
02:30:27	MED THAT THERE HAS BEEN NO FIRE SPREAD OUTSIDE ORIGINAL BUILDING, CREWS ARE NOW
02:30:27	CONDUCTING INTERNAL ATTACK OF BUILDINGS UPPER FLOORS FROM SECTORS 1 AND 4
02:30:30	Unit INVE2118 [K43 : ALL AVAILABLE PERSONNEL FULLY UTILISED]
02:34:59	Unit INVE2118 [KC : UNIT CALLING]
02:36:35	Unit INVE2118 [SITREP :] NOTIFY LOCAL COUNCIL THAT WE HAVE A POTENTIAL DANGERO
02:36:35	US BUILDING (DO YOU REQUIRE A BUILDING ENGINEER TONIGHT OR JUST A NOTIFICATION F
02:36:35	OR THE MORNING?) JUST A NOTIFICATION, WILL GET BACK TO YOU IF WE REQUIRE ANYTHIN
02:36:35	G URGENTLY

02:39:26	Unit INVE2118 [KC : UNIT CALLING]
02:41:26	Unit INVE2118 [SITREP :] CAN YOU CONFIRM LOCATION OF WINT371? (PASSING THROUGH
02:41:26	INTERSECTION OF DEE AND GUTHRIE, AVENAL) ACK
02:46:16	
02:46:22	WINT371 NOW K9 AT INVERCARGILL STATION
02:46:23	
02:55:37	Unit INVE2118 [KC : UNIT CALLING]
02:56:34	Unit INVE2118 [K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS] ASS
02:56:34	T CMDR CHALMERS.
02:56:59	Unit INVE2118 [KC : UNIT CALLING]
02:57:54	Unit INVE2118 [SITREP :] GM CAN YOU SEE IF THEY CAN PAGE THE BUILDIN
02:57:54	G INSPECTOR TO ARRIVE TONIGHT FROM THE COUNCIL IF POSSIBLE? (WILL TRY AND GET BA
02:57:54	CK TO YOU WITH UPDATE) ACK
03:00:17	***
03:00:51	INVERCARGILL CC REQUESTS WHEN WE ARE FINISHED USING LARGE AMOUNTS OF WATER TO LE
03:00:51	T THEM KNOW AS THEIR REP IS HAVING TO DO LOTS OF ACTIVE WATER PRESSURE BALANCING
03:00:51	
03:01:28	Unit INVE2118 [KC : UNIT CALLING]
03:01:38	INVERCAGILL CC IS GOING TO TRY GET A BUILDING REP TO THE SCENE NOW. HAVE GIVEN T
03:01:38	HEM COMCEN GENERAL NUMBER AND ADVISED OF SFP
03:01:39	***
03:02:44	HER 3 HOURS
03:02:47	
03:03:07	Unit INVE2118 [SITREP :] BOTH NORTHBOUND AND SOUTHBOUND SH6 WILL NEED TO BE CL.
03:03:07	OSED FOR AT LEAST 3 HOURS, SIGNIFICANT WATER USAGE WILL CONTINUE FOR AT LEAST 2
03:03:07	HOURS
03:03:29].
03:04:48	S A CALL 5-10 MINS BEFORE IT NEEDS TO BE CUT OFF SO TECH CAN CONTROL THE PRESSUR
03:04:48	E
03:04:49	·
03:05:11	Alarm Timer Extended: 0
03:18:15	Unit INVE2118 [KC : UNIT CALLING]
03:18:50	Unit INVE2118 [K42 : FIRE SUPRESSED, COMMENCING OVERHAUL]
03:19:09	Unit INVE2118 [SITREP :] CREWS ARE NOW COMMENCING OVERHAUL, NOTIFY COUNCIL THA
03:19:09	T WATER USAGE SHOULD DRAMATICALLY DECREASE FROM NOW ON

03:19:59	INVERCARGILL CC STILL HAVING TROUBLE GETTING HOLD OF THEIR BUILDING INSPECTOR. T	
03:19:59	HEY ARE STILL TRYING	
03:28:34	Unit DMSOUTH [K6 : ON PAGER (STATE LOCATION)]	
03:36:33		
03:36:52	GMSOUTH01 AVAILABLE TO SPEAK TO MEDIA UFN	
04:02:34	Unit INVE2118 [KC : UNIT CALLING]	
04:02:51	Unit INVE2118 [K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]	
04:24:08	Unit INVE2118 [KC : UNIT CALLING]	
04:24:43	Unit INVE2118 [SITREP :] COULD YOU HAVE THE ON CALL VSO CONTACT GM ON	
04:24:43	HIS MOBILE	
04:30:18		
04:34:13		
04:43:31	Unit VSOSOUTH02 [K1 : PROCEEDING TO INCIDENT]	
04:49:44	Unit BLUF231 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]	
04:59:13	Unit KING227 [KC : UNIT CALLING]	
04:59:28	Unit KING227 [K10 : RE-COMMISSIONING APPLIANCE]	
05:00:30	Unit INVE212 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
05:08:00	Unit INVE2118 [KC : UNIT CALLING]	
05:08:29	Unit INVE2118 [SITREP :] DEE STREET COMMAND SHUTTING DOWN	
05:08:36	Unit INVE2118 [K44 : COMMAND OR CONTROL POINT ESTABLISHED (STATE OIC AND LOCATI	
05:08:36	ON)] INVE211	
05:13:16	Unit FISOUTH02 [K6 : ON PAGER (STATE LOCATION)]	
05:13:55	Unit FISOUTH02 [SITREP :] CLEAR OF THE SCENE, WILL BE RETURNING LATER IN DAYLI	
05:13:55	GHT	
05:26:38	Unit INVE2118 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
05:29:36	Unit GMSOUTH01 [KC : UNIT CALLING]	
05:29:54	Unit GMSOUTH01 [K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)]	
05:29:54	ON	
05:30:00	Unit GMSOUTH01 [K6 : ON PAGER (STATE LOCATION)]	
05:43:53	Unit INVE213 [K22-1 : APPLIANCE AVAILABLE FOR A FURTHER INCIDENT]	
06:04:00	Unit WALL241 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
06:42:09	Unit INVE213 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]	
06:47:29	Unit VSOSOUTH02 [K2 : IN ATTENDANCE AT INCIDENT]	
06:55:23	ON CALL NATIONAL MEDIA SUPPORT SEDES CALLS IN TO ACKNOWLEDGE	
06:55:58	Unit INVE2120 [K7 : AT NORMAL STATION]	
07:16:20	Unit INVE211 [KC : UNIT CALLING]	
07:17:15	Unit INVE211 [SITREP :] SO CURRENTLY MONITORING FIRE CONDITIONS, NO CH	

07:17:15	ANGE FROM PREVIOUS UPDATES	
07:27:37	Alarm Timer Extended: 0	
07:33:15	Unit INVE211 [KC : UNIT CALLING]	
07:34:02	Unit INVE211 [SITREP :] K10 AND LEAVING IN HANDS OF INVE214	
07:34:06	Unit INVE211 [K10 : RE-COMMISSIONING APPLIANCE]	
07:35:34	Unit VSOSOUTH02 [K6 : ON PAGER (STATE LOCATION)]	
07:48:10	Unit FISOUTH01 [K1 : PROCEEDING TO INCIDENT]	
07:48:34	Unit FISOUTH02 [K1 : PROCEEDING TO INCIDENT]	
07:54:42	Unit FISOUTH01 [K2 : IN ATTENDANCE AT INCIDENT]	
07:55:14	Unit FISOUTH02 [K2 : IN ATTENDANCE AT INCIDENT]	
07:56:14	Unit FISOUTH01 [SITREP :] REQUEST FROM DM FOR DRONE SUPPORT TO ASSIST WITH FIR	
07:56:14	E INVESTIGATION - HAS TRIED CONTACTING INVERCARGILL POLICE AS THERE PHOTOGRAPHER	
07:56:14	S HAVE ACCESS BUT NO ANSWER SO PUTTING IN A FORMAL REQUEST	
08:00:12	Unit FISOUTH01 [SITREP :] FURTHER TO REQUEST FOR DRONE - NOT THROUGH USAR - RE	
08:00:12	QUEST FOR LOCAL INVERCARGIL POLICE PHOTOGRAPHY DRONE IF POSSIBLE	
08:00:36	Unit INVE214 [COMCEN COM : MESSAGE] HAD A REQUEST FROM INVERARGIL FIRE FOR YOU T	
08:00:36	O CONTACT ON HIS MOBILE (ACK)	
08:04:26	FIR2POL HAD A REQUEST FROM FIRE INVESTIGATORS ON SCENE FOR POSSIBLE DRONE ASSIST	
08:04:26	ANCE FROM THE INVERCARGILL POLICE PHOTOGRAPHY UNIT - ARE YOU ABLE TO ASSIST?	
08:09:30	FIR2POL FENZ POINT OF CONTACT FOR DRONE PHOTOS REQUEST -	
08:09:30		
08:24:31	Unit INVE214 [KC: UNIT CALLING]	
08:25:08	Unit INVE214 [K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SSO FREW	
08:27:19	POLICE PHOTOGRAPHY SPEAKING DIRECTLY WITH FISOUTH01	
08:34:48	Alarm Timer Extended: 0	
08:35:22	Alarm Timer Extended: 0	
08:48:00	, WILL CALL US BACK SHORTLY WITH UPDATE	
09:01:13	INJURY	
09:01:38	INVERCARGILL FIRE CALL IN TO ADVISE AVAILABILITY HAS BEEN STOOD DOWN	
09:20:39	Unit INVE211 [K2 : IN ATTENDANCE AT INCIDENT]	
09:20:49	Unit INVE211 [K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]	
09:57:28	Unit INVE211 [KC : UNIT CALLING]	
09:58:29	Unit INVE211 [SITREP :] SO CREWS ON ROOF REMOVING ROOFING IRON AND DA	
09:58:29	MPENING DOWN	
10:01:02	Alarm Timer Extended: 0	

10:29:20	Unit INVE214 [KC : UNIT CALLING]
10:30:02	Unit INVE214 [SITREP :] CAN WE HAVE ON DUTY SSO FOR DUNEDIN CITY TO CALL INVE2
10:30:02	14 CELL
10:49:07	SSO CALLS IN TO STATE DUNE216 AND DUNE2126 ARE RESPONDING TO ASSIS
10:49:07	T AT THIS INCIDENT. DUNE211 WILL BE KO UFN AND THEY WILL WORK TO BRING COVER IN
10:49:34	Unit DUNE216 [K1 : PROCEEDING TO INCIDENT]
10:59:58	Unit DUNE2126 [K1 : PROCEEDING TO INCIDENT]
11:24:07	Unit INVE211 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
11:42:06	Unit DUNE216 [K1 : PROCEEDING TO INCIDENT]
12:24:10	Unit DUNE216 [K1 : PROCEEDING TO INCIDENT]
13:31:39	Unit DUNE216 [K1 : PROCEEDING TO INCIDENT]
13:32:01	Unit DUNE216 [K1 : PROCEEDING TO INCIDENT]
14:02:16	Unit DUNE216 [K2 : IN ATTENDANCE AT INCIDENT]
14:17:32	Unit DUNE2126 [K2 : IN ATTENDANCE AT INCIDENT]
14:18:10	Unit FISOUTH01 [COMCEN COM : MESSAGE] CAN YOU CONFIRM IF DUNE2126 HAS ARRIVED? (
14:18:10	AFFIRM)
14:19:30	Unit DUNE2126 [K1 : PROCEEDING TO INCIDENT]
14:19:41	Unit DUNE2126 [K2 : IN ATTENDANCE AT INCIDENT]
14:43:21	Alarm Timer Extended: 0
15:00:19	Alarm Timer Extended: 0
15:10:54	Unit INVE214 [KC : UNIT CALLING]
15:11:34	Unit INVE214 [SITREP) SSO FREW - 216 IS IN USE REMOVING ROOFING AND RIDGELIN
15:11:34	E TO IDENTIFY AND DAMPEN DOWN HOTSPOTS
15:28:21	Unit INVE214 [KC : UNIT CALLING]
15:30:46	Unit INVE214 [SITREP :] 1 STRUCTURAL ENGINEER ONSITE DOING INSPECTION TO DETER
15:30:46	MIE STRUCTURAL INTEGRITY OF BUILDING, 1 CREW USING HPD ATTACKING MUILTIPLE HOTPO
15:30:46	TS INSIDE
16:23:02	Unit FISOUTH02 [KC : UNIT CALLING]
16:23:47	Unit FISOUTH02 [SITREP :] GOING CLEAR OF THE SCENE - LEAVE JOB OPEN FOR NEXT C
16:23:47	OUPLE OF DAYS AS WE WILL BE REQUIRED TO RETURN OVER BOTH DAYS
16:23:50	Unit FISOUTH01 [K6 : ON PAGER (STATE LOCATION)]
16:24:25	Unit FISOUTH02 [K6 : ON PAGER (STATE LOCATION)]
17:15:14	Unit INVE214 [COMCEN COM : MESSAGE] (VIA PHONE) WHAT"S HAPPENING WITH THE DUNEDI
17:15:14	N APPLIANCES TONIGHT?
17:15:44	Unit INVE214 [SITREP :] (VIA PHONE) THEY WILL BE RELEASED AROUND 1800HRS TO HE

17:15:44	AD BACK TO DUNEDIN, WILL NOT BE REQUIRED TO COME BACK AS THEY HAVE GOT AS MUCH O
17:15:44	F THE ROOF OFF AS THEY CAN. EXPECTING TO START MAKING UP SOON
17:15:48	RELEASED AROUND 1800HRS TO HEAD BACK TO DUNEDIN, WILL NOT BE REQUIRED TO COME B
17:15:48	ACK AS THEY HAVE GOT AS MUCH OF THE ROOF OFF AS THEY CAN. EXPECTING TO START MAK
17:15:48	ING UP SOON
17:33:48	FROM DUNE216 CALLS IN TO STATE ONCE THEY HAVE HAD A MEAL THEY WILL B
17:33:48	E HEADING BACK TO DUNEDIN, THEY WILL REMAIN ATTACHED TO THE EVENT AND WILL
17:33:48	HAVE THE SO PHONE ON FILE IF THEY ARE NEEDED BACK IN DUNEDIN
18:10:18	Unit INVE214 [KC : UNIT CALLING]
18:11:02	Unit INVE214 [SITREP :] SSO - K45 SSO - CREWS HAVE CHANGED TO GR
18:11:02	EEN WATCH NIGHT CREW
18:11:11	Unit INVE214 [K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SSO
18:11:14	*
18:24:24	Unit DUNE216 [KC : UNIT CALLING]
18:25:31	Unit DUNE216 [SITREP :] DUNE216 AND DUNE2126 ARE HEADING BACK TO DUNEDIN STATI
18:25:31	ON NOW, WE WILL STAY ATTACHED FOR NOW
18:28:12	* CO
18:57:45	Unit DUNE216 [K2 : IN ATTENDANCE AT INCIDENT]
18:58:13	Unit DUNE216 [K2 : IN ATTENDANCE AT INCIDENT]
19:23:35	Unit INVE214 [KC : UNIT CALLING]
19:24:23	Unit INVE214 [SITREP :] SSO - BUILDING STILL BEING OVERHAULED - MINOR H
19:24:23	OT SPOTS FOUND - WE WIL BE HERE FOR A BIT LONGER
19:33:51	* ~0
19:43:59	Alarm Timer Extended: 0
19:58:32	Unit DUNE216 [K2 : IN ATTENDANCE AT INCIDENT]
20:07:45	Unit INVE214 [KC : UNIT CALLING]
20:08:05	Unit INVE214 [K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SFF
20:43:59	Alarm Timer Extended: 0
20:53:13	Unit DUNE216 [K2 : IN ATTENDANCE AT INCIDENT]
21:31:26	Unit DUNE2126 [K2 : IN ATTENDANCE AT INCIDENT]
21:31:36	Unit DUNE2126 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
21:33:51	Alarm Timer Extended: 0
21:42:59	Unit DUNE216 [K7 : AT NORMAL STATION]
22:03:33	Unit INVE214 [KC : UNIT CALLING]
22:04:31	Unit INVE214 [SITREP :] NSOF OR SMOKE - MAKING SCENE SECURE AND RETURNING TO S

22:04:31	TATION - CREWS LIKELY TO DO VISITS OVER NIGHT - JOB TO BE LEFT OPEN FOR FI		
22:04:32	Unit INVE214 [K22-1 : APPLIANCE AVAILABLE FOR A FURTHER INCIDENT]		
22:12:56	Unit INVE214 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]		
22:43:35			
00:02:44	Unit INVE214 [K22-1 : APPLIANCE AVAILABLE FOR A FURTHER INCIDENT]		
00:04:59	Unit INVE214 [K1 : PROCEEDING TO INCIDENT]		
00:06:58	Unit INVE214 [K2 : IN ATTENDANCE AT INCIDENT]		
01:09:51	Unit INVE214 [KC : UNIT CALLING]		
01:10:47	Unit INVE214 [SITREP :] SSO - BUILDING CHECKED - NO HOTSPOTS FOUND WE		
01:10:47	MAY CALL BACK LATER IN THE MORNING TO CHECK		
01:10:48	Unit INVE214 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]		
12:45:31	Unit FISOUTH01 [K1 : PROCEEDING TO INCIDENT]		
12:50:46	Unit FISOUTH01 [K2 : IN ATTENDANCE AT INCIDENT]		
12:56:23	Unit FISOUTH02 [K1 : PROCEEDING TO INCIDENT]		
12:57:53	Unit FISOUTH02 [K2 : IN ATTENDANCE AT INCIDENT]		
14:09:03	Unit FISOUTH01 [KC : UNIT CALLING]		
14:09:51	Unit FISOUTH01 [KC : UNIT CALLING]		
14:10:18	Unit FISOUTH01 [K6 : ON PAGER (STATE LOCATION)]		
14:10:23	Unit FISOUTH01 [SITREP :] LEAVING THE SCENE RETURNING TOMORROW		
14:11:50	Unit FISOUTH02 [K6 : ON PAGER (STATE LOCATION)]		
16:22:30	Unit FISOUTH02 [SITREP :] MANUAL TIME ENTERED 07/09/23 16:22:13 VIA PHONE -		
16:22:30	KEEP EVENT OPEN PLEASE, LOOKING TO HEAD BACK IN THE MORNING		
06:34:03	Unit EVENTSCC1 [K7 :- AT NORMAL STATION]		
06:34:10	Unit FISOUTH02 [K1 : PROCEEDING TO INCIDENT]		
06:37:37	Unit FISOUTH02 [K2 : IN ATTENDANCE AT INCIDENT]		
06:43:02	Unit FISOUTH01 [K1 : PROCEEDING TO INCIDENT]		
06:43:11	Unit FISOUTH01 [K2 : IN ATTENDANCE AT INCIDENT]		
07:21:16	Alarm Timer Extended: 0		
07:27:25	Alarm Timer Extended: 0		
13:21:11	Unit FISOUTH01 [K6 : ON PAGER (STATE LOCATION)]		
14:00:51	Unit FISOUTH02 [KC : UNIT CALLING]		
14:01:26	Unit FISOUTH02 [STOP : MESSAGE] SCENE INVESTIGATION HAS BEEN COMPLETED, BUILDIN		
14:01:26	G NOW LEFT WITH INSURANCE COMPANY AND COUNCIL, THIS EVENT CAN NOW BE CLOSED		
14:01:28	Unit FISOUTH02 [K6 : ON PAGER (STATE LOCATION)]		
14:08:11	UNIT 'FISOUTH02' ALERT TIME '[NULL]' ADJUSTED TO '20230906012255NS' AT '08/09/20		
14:08:12	UNIT 'DUNE216' ALERT TIME '[NULL]' ADJUSTED TO '20230906104933NS' AT '08/09/2023		
14:08:12	UNIT 'VSOSOUTH02' ALERT TIME '[NULL]' ADJUSTED TO '20230906044329NS' AT '08/09/2		
14:08:12	UNIT 'DMSOUTH' ALERT TIME '[NULL]' ADJUSTED TO '20230906012248NS' AT '08/09/2023		

14:08:13	UNIT 'FISOUTH01' ALERT TIME '[NULL]' ADJUSTED TO '20230906074809NS' AT '08/09/20
14:08:13	UNIT 'DUNE2126' ALERT TIME '[NULL]' ADJUSTED TO '20230906105957NS' AT '08/09/202
14:08:14	** Assigned Result Code: STRU, Detailed Event Type: 1100

Incident

CAD Number F3812425
Incident Reporter
Incident Controller
Distance Travelled (km)
Delay In Receiving Call

Property Details

Occupant

Building Owner Rented property

General Property Use Shop, Mall, Supermarket, Gas station, Sales, Other

Special Property Use Shopping mall

Purpose Group

Actions

Persons Reported

Trapped

Evacuation Status Fully evacuated

Action Prior 1
Action Prior 2

Action Taken Extinguishment, salvage and ventilation

Civilians

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	6

Origin

Location Bedroom, Sleeping area, Cell: under 5 persons

Level 1st floor

Equipment Used

Quantity	Equipment
2	Low pressure delivery

Nothing

Factor Preventing Escape

Activity When Injured

Cause of Injury

Victim Aware of Fire

Room Where Victim Found

Location Where Victim Found

Familiarity With Property

Familiar with premises

Comments

9/13/2023 9:18:57 PM

Reporter Comments

Fire was well involved on arrival with flames showing from SE windows and heavy smoke coming from the North Side. Initial exterior cut off was carried out on SE side whilst persons were accounted for. The attacked was increased with ground. Released under the monitor and aerial monitor and third alarm had been transmitted and crews began working on the north side trying to access the fire. The fire could be seen through exterior windows but was hard to reach as was as later discovered in a false ceiling