

# SMS Incident Report

10/12/2024 08:51:16


## Summary

**CAD Number** F4052930 **Status** Closed  
**Station** Lincoln Volunteer Fire Brigade  
**Incident Started** 20/09/2024 23:10:23 **Incident Ended** 21/09/2024 07:29:37  
**Incident Type** 1101: Structure fire with damage  
**Common Name**  
**Address** 479 Old Tai Tapu Road Tai Tapu  
**Alarm Method** 111 Telephone **Alarm Level** 2  
**PFA Number**  
**Zone** 344108  
**Map Grid E** 1564620 **Map Grid N** 5168197  
**First Caller** 9(2)a **First Caller Contact** 9(2)a  
**Incident Closed** 23/09/2024 09:15:11  
**Report Completed** 20:39, Wed 02 Oct 2024 by Out of Scope

## Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
LINC417	PR	23:10:56 20 Sep 2024	23:15:08 20 Sep 2024	23:22:49 20 Sep 2024	06:03:12 21 Sep 2024
LINC411	P1	23:10:56 20 Sep 2024	23:16:53 20 Sep 2024	23:25:56 20 Sep 2024	02:38:56 21 Sep 2024
LINC4111	WT	23:10:56 20 Sep 2024	23:16:34 20 Sep 2024	23:25:59 20 Sep 2024	05:43:12 21 Sep 2024
WIGR257	PR	23:35:20 20 Sep 2024	23:37:02 20 Sep 2024	23:47:54 20 Sep 2024	01:55:50 21 Sep 2024
SPRE221	P1	23:35:24 20 Sep 2024	23:38:19 20 Sep 2024	23:52:27 20 Sep 2024	13:14:08 21 Sep 2024
LINCCFO	OF		23:39:06 20 Sep 2024	00:02:57 21 Sep 2024	03:15:06 21 Sep 2024
ROLL4211	WT	23:35:17 20 Sep 2024	23:44:11 20 Sep 2024	00:04:17 21 Sep 2024	01:04:04 21 Sep 2024
EVENTSCC1	OT				10:26:26 21 Sep 2024

Start->Alert 7 min 10 min



**Elapsed Times**

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
LINC417	00:00:33	00:11:53	00:12:26	06:52:49
LINC411	00:00:33	00:15:00	00:15:33	03:28:33
LINC4111	00:00:33	00:15:03	00:15:36	06:32:49
WIGR257	00:24:57	00:12:34	00:37:31	02:45:27
SPRE221	00:25:01	00:17:03	00:42:04	14:03:45
LINCCFO			00:52:34	04:04:43
ROLL4211	00:24:54	00:29:00	00:53:54	01:53:41
EVENTSCC1				11:16:03

**Notifications**

Date	Time	Party Notified
20 Sep 2024	23:35:28	POLICE VIA INTERCAD
20 Sep 2024	23:35:58	CANTERBURY BUILT PAGED RE 2ND ALARM
20 Sep 2024	23:36:08	GMCANTE03 (Out of Scope) ACKNOWLEDGED VIA AMS
20 Sep 2024	23:36:45	POWER (ORION)
20 Sep 2024	23:37:03	CFO'S PAGED
20 Sep 2024	23:39:10	VSO CANTERBURY PAGED RE 2ND ALARM/ UPGRADE FROM K88
20 Sep 2024	23:41:19	AMBULANCE VIA INTERCAD
21 Sep 2024	00:18:16	FI CANTY FICANTE05 PAGED
21 Sep 2024	00:20:24	FICANTE05 (Out of Scope) ACKNOWLEDGED VIA AMS
21 Sep 2024	00:50:37	VSOCANTE04 (Out of Scope) PAGE SENT
21 Sep 2024	05:28:37	CANTERBURY BUILT - LONG DURATION EVENT
21 Sep 2024	05:29:49	REGION TE IHU - LONG DURATION EVENT
21 Sep 2024	05:33:52	GMCANTE03 (Out of Scope) ACK - UPDATED
21 Sep 2024	05:34:52	DMMIDSC (Out of Scope) ACKNOWLEDGED VIA AMS

**Message Log**

Time	Message
23:10:43	<a href="https://web.pcl.govt.nz/?ecn=9(2)a">https://web.pcl.govt.nz/?ecn=9(2)a</a>
23:10:43	INC INFO: DECK ON FIRE
23:10:43	** ELOI search completed at 20/09/24 23:10:43 - 1 result

23:10:45 \*\* LOI search completed at 20/09/24 23:10:44

23:10:50 \*\* Recommended unit LINC4111 for requirement TANKER (>6.1 km)  
\*\* Recommended un

23:10:50 it LINC417 for requirement PUMP (>6.1 km)  
\*\* Recommended unit LINC411 for requi

23:10:50 rement PUMP (>6.0 km)

23:10:52 Station Selcal used to Initiate Alerting. (LINC4111 at 3441 LINCOLN 193411)

23:10:53 Station Selcal used to Initiate Alerting. (LINC417 at 3441 LINCOLN 193411)

23:10:53 Station Selcal used to Initiate Alerting. (LINC411 at 3441 LINCOLN 193411)

23:10:56 ALERTING\_COMPLETED LINC4111

23:10:56 ALERTING\_COMPLETED LINC417

23:10:57 ALERTING\_COMPLETED LINC411

23:11:00 \*\* ELOI button clicked

23:11:47 9(2)a

23:12:09 FIRE IS ON THE VERANDAH. ATTACHED TO THE HOUSE. OLD STYLE HOUSE

23:15:08 Unit LINC417 [ K1 : PROCEEDING TO INCIDENT]

23:15:59 Unit LINC417 [COMCEN COM : MESSAGE] 9(2)a - FIRE IS ON THE VE

23:15:59 RANDAH ATTACHED TO THE HOUSE - THIS IS AN OLD STYLE HOUSE

23:16:34 Unit LINC4111 [ K1 : PROCEEDING TO INCIDENT]

23:16:53 Unit LINC411 [ K1 : PROCEEDING TO INCIDENT]

23:19:43 SECOND CALL 9(2)a CAN JUST SEE A GLOW AT THE HOUSE

23:22:49 Unit LINC417 [ K88 : PROPERTY FIRE APPARENTLY SMALL]

23:25:10 Unit LINC417 [ KC : UNIT CALLING]

23:25:19 Unit LINC417 [ KC : UNIT CALLING]

23:25:27 Unit LINC417 [ KC : UNIT CALLING]

23:25:56 Unit LINC411 [ K2 : IN ATTENDANCE AT INCIDENT]

23:25:59 Unit LINC4111 [ K2 : IN ATTENDANCE AT INCIDENT]

23:26:18 Unit LINC417 [COMCEN COM : MESSAGE] NO RESPONSE ON RADIO X 3

23:27:23 Unit LINC417 [COMCEN COM : MESSAGE] NO RESPONSE ON APPLIANCE AND OIC PHONE X 2

23:28:38 Unit LINC411 [COMCEN COM : MESSAGE] LINC417 WAS CALLING US, I HAVE NOT HEARD A R

23:28:38 ESPONSE VIA RADIO OR PHONE (ACK WILL GET IN TOUCH WITH THEM)

23:29:08 Unit LINC411 [ KC : UNIT CALLING]

23:29:37 Unit LINC411 [ KC : UNIT CALLING]

23:31:22 Unit LINC411 [COMCEN COM : MESSAGE] NO RESPONSE ON RADIO X 3 - NO RESPONSE ON LI

23:31:22 NC411 APPLIANCE PHONE

23:34:52 Unit LINC411 [ SITREP : ] DCFO Out of Scope - 2 STOREY DWELLING APPROX 20M BY 15M,

23:34:52 DECK WAS FULLY INVOLVED AND FIRE GONE INTO ROOF SPACE, 4 IN BA ACCESSING INTERNA

23:34:52 LLY AND EXTERNALLY - MAKE 2ND ALARM

23:35:11 \*\* Alarm level updated to 2

23:35:11 \*\* Recommended unit ROLL4211 for requirement TANKER (>15.7 km)  
\*\* Recommended u

23:35:11 nit WIGR257 for requirement PUMP (>9.0 km)  
\*\* Recommended unit SPRE221 for requ

23:35:11 irement PUMP (>10.5 km)

23:35:13 Station Selcal used to Initiate Alerting. (ROLL4211 at 3442 ROLLESTON 193421)

23:35:14 PA Selcal used to Initiate Alerting. (WIGR257 at 3425 WIGRAM 193251)

23:35:14 PA Selcal used to Initiate Alerting. (SPRE221 at 3422 SPREYDON 192221)

23:35:18 ALERTING\_COMPLETED ROLL4211

23:35:21 ALERTING\_COMPLETED WIGR257

23:35:24 ALERTING\_COMPLETED SPRE221

23:35:26 \*\* Event P060033974 of NZP/CU copied from F4052930 of NZFS/CA at: 20/09/24 23:35

23:35:26 :26

23:35:29 FIR

23:35:46 FIR2POL 2ND ALARM HOUSE FIRE FYI

23:37:02 Unit WIGR257 [ K1 : PROCEEDING TO INCIDENT]

23:38:19 Unit SPRE221 [ K1 : PROCEEDING TO INCIDENT]

23:38:41 Unit LINC411 [ KC : UNIT CALLING]

23:39:06 Unit LINCCFO [ K1 : PROCEEDING TO INCIDENT]

23:39:43 Unit LINC411 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] DCFO  
Out of Scope

23:39:43 Out of Scope

23:41:02 Unit LINCCFO [ K11A : AMBULANCE REQUIRED] (VIA PHONE) AMB REQUIRED 9(2)a

23:41:02 9(2)a

23:41:14 Unit LINCCFO [COMCEN COM : MESSAGE] LATEST SITREP FROM DCFO IS A TWO STOREY DWEL

23:41:14 LING APPROX 20M BY 15M, DECK WAS FULLY INVOLVED AND FIRE GONE INTO ROOF SPACE, 4

23:41:14 IN BA ACCESSING INTERNALLY AND EXTERNALLY - APPLIANCES STILL RESPONDING ARE SPR

23:41:14 E221, WIGR257 AND ROLL4211 (ACK)

23:41:17 \*\* Event A01254087 of AMBO/S copied from F4052930 of NZFS/CA at: 20/09/24 23:41:

23:41:17 17

23:41:19 AMBO EVENT 0769-3-2024/09/20-FIR LINKED AT 20/09/2024 23:41:19

23:41:35 FIR2AMB UNIT LINCCFO [ K11A : AMBULANCE REQUIRED] (VIA PHONE) AMB REQUIRED 9(2)a

23:41:35 9(2)a

23:44:11 Unit ROLL4211 [ K1 : PROCEEDING TO INCIDENT]

23:44:40 VSOCANTE04 RICHIE PLATT ACK PAGE VIA PHONE

23:47:54 Unit WIGR257 [ K2 : IN ATTENDANCE AT INCIDENT]

23:52:27 Unit SPRE221 [ K2 : IN ATTENDANCE AT INCIDENT]

23:59:04 FIR2POL AFFIRM - LATEST SITREP FROM DCFO AT 23:41HRS: IS A TWO STOREY DWELLING A

23:59:04 PPROX 20M BY 15M, DECK WAS FULLY INVOLVED AND FIRE GONE INTO ROOF SPACE, 4 IN BA

23:59:04 ACCESSING INTERNALLY AND EXTERNALLY - AMBO RESPONDING 9(2)a

23:59:04 9(2)a

23:59:33 FIR2AMB COPY, THANKS

00:00:44 Unit LINC411 [ KC : UNIT CALLING]

00:01:19 Unit LINC411 [ SITREP : ] CONFIRM TANKER RESPONSE

00:01:45 Unit LINC411 [COMCEN COM : MESSAGE] ROLL4211 TRAVELLING UP OLD TAI TAPU RD NOW -

00:01:45 AMB FROM ROLLESTON AT 23:51HRS (ACK)

00:02:57 (VIA PHONE - NIL RADIO COMMS IN AREA)

00:02:57 Unit LINCCFO [ K2 : IN ATTENDANCE AT INCIDENT] (VIA PHONE - NIL RADIO COMMS IN A

00:02:57 REA)

00:03:30 Unit LINCCFO [ SITREP : ] CFO <sup>Out of Scope</sup> (VIA PHONE) NIL RADIO COMMS IN AREA. SAFETY OF

00:03:30 FICER APPOINTED. 6 IN BA. 2 HPD AND 1 LPD IN USE

00:03:52 Alarm Timer Extended: 0

00:04:18 Unit ROLL4211 [ K2 : IN ATTENDANCE AT INCIDENT]

00:06:03 Alarm Timer Extended: 0

00:06:04 Alarm Timer Extended: 0

00:17:35 Unit SPRE221 [ KC : UNIT CALLING]

00:17:46 Unit LINCCFO [ SITREP : ] [VIA PHONE] HAVE MADE SPRE221 AVAILABLE. AMB IN ATTEND

00:17:46 ANCE D9(2)a . STILL WORKING TO EXTINGUISH FIRE IN RO

00:17:46 OF. ON CALL FIRE INVESTIGATOR TO CONTACT ME ON 9(2)a

00:17:54 Unit SPRE221 [ K22-1 : APPLIANCE AVAILABLE FOR A FURTHER INCIDENT]

00:18:15 FIR2POL UPDATE: AMB IN ATTENDANCE 9(2)a

00:18:15 STILL WOR

00:18:15 KING TO EXTINGUISH FIRE IN ROOF

00:18:24 Unit ROLL4211 [ K2 : IN ATTENDANCE AT INCIDENT]

00:24:20 UNABLE TO PUT FICANTE05 THROUGH TO CFO VIA CELL. GOING STRAIGHT TO ANSWERPHONE

00:25:23 Unit LINCCFO [COMCEN COM : MESSAGE] EXTERNAL ALERT SENT

00:28:50 FICANTE05 PUT THROUGH TO LINCOLN CFO VIA CELL

00:28:55 Alarm Timer Extended: 0

00:36:44 Unit SPRE221 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

00:44:08 Alarm Timer Extended: 0

00:47:57 Unit LINC411 [ KC : UNIT CALLING]

00:48:54 Unit LINC411 [ K11V : VOLUNTEER SUPPORT OFFICER REQUIRED] REQUEST FROM DCFO - 7

00:48:54 BA CYLINDERS TO BE REPLACED AT LINCOLN STATION, REQUIRE THEM TONIGHT

00:51:49 Unit LINC411 [COMCEN COM : MESSAGE] EXTERNAL ALERT SENT

00:54:04 REQUEST FOR 7 BA CYLINDERS PASSED TO VSO **Out of Scope** VIA PHONE

01:00:57 Alarm Timer Extended: 0

01:04:04 Unit ROLL4211 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

01:47:07 Unit LINCCFO [ K42 : FIRE SUPRESSED, COMMENCING OVERHAUL]

01:55:28 Unit WIGR257 [ KC : UNIT CALLING]

01:55:50 Unit WIGR257 [ K10 : RE-COMMISSIONING APPLIANCE]

02:24:35 Unit LINCCFO [ KP : PRIORITY MESSAGE]

02:25:41 Unit LINCCFO [ SITREP : ] ACCIDENTAL KP - ILL BE ON SCENE FOR ANOTHER 15 MINS

02:25:51 Unit LINCCFO [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] DCFO  
**Out of Scope**

02:25:51 **Out of Scope**

02:38:56 Unit LINC411 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

03:15:06 Unit LINCCFO [ K6 : ON PAGER (STATE LOCATION)]

05:04:51 Unit LINC417 [ KC : UNIT CALLING]

05:05:25 Unit LINC417 [ SITREP : ] **9(2)a**

05:27:21 -

05:27:47 PA Selcal used to Initiate Alerting. (SPRE221 at 3422 SPREYDON 192221)

05:27:50 ALERTING\_COMPLETED SPRE221

05:28:09 (VIA PHONE) - CFO REQUESTING A CAREER TRUCK STAND BY AND ASSIST AT THIS FIRE - Q

05:28:09 UITE A DIFFICULT HOUSE TO GET THE LAST BIT EXTINGUISHED

05:28:25 SPRE221 REQUIRED TO RELIEVE LINCOLN CREWS

05:28:26 -

05:30:53 Unit SPRE221 [ K1 : PROCEEDING TO INCIDENT]

05:35:37 -

05:36:43 SPRE221 CREW TO RELIEVE LINCOLN CREW - SPREYDON OIC TO DECIDE WHETHER ANOTHER RE

05:36:43 LIEF CREW WILL BE REQUIRED DURING THE MORNING OR WHETHER THE SPREYDON BLUE WATCH

05:36:43 DAYSHIFT CREW COME AND RELIEVE THE NIGHT SHIFT CREW

05:36:53 -

05:37:18 Unit SPRE221 [ K37 : MOBILITY APP HAS UPDATED INFORMATION(USED BY COMCEN)]

05:38:02 Unit SPRE221 [ K37-1 : UPDATED INFORMATION RECEIVED]

05:42:57 Unit LINC4111 [ KC : UNIT CALLING]

05:43:13 Unit LINC4111 [ K10 : RE-COMMISSIONING APPLIANCE]

05:49:32 Unit SPRE221 [ K2 : IN ATTENDANCE AT INCIDENT]

06:01:17 Unit SPRE221 [ KC : UNIT CALLING]

06:01:55 Unit SPRE221 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SO  
**Out of Scope**

06:02:16 \*\* ELOI button clicked

06:02:47 Unit LINC417 [ KC : UNIT CALLING]

06:03:09 Unit LINC417 [ SITREP : ] HANDED OVER TO SPRE221

06:03:12	Unit LINC417 [ K10 : RE-COMMISSIONING APPLIANCE]
07:09:28	** ELOI button clicked
07:29:00	Unit SPRE221 [ KC : UNIT CALLING]
07:29:37	Unit SPRE221 [ K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM SITREP] BLUE WATCH WIL
07:29:37	L POP BACK LATER ON TO CHECK
07:29:38	Unit SPRE221 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
10:26:26	Unit EVENTSCC1 [ K7 : AT NORMAL STATION]
10:26:31	Unit SPRE221 [ K1 : PROCEEDING TO INCIDENT]
11:19:21	Unit SPRE221 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
11:39:07	Unit SPRE221 [ K7 : AT NORMAL STATION]
13:13:22	Unit SPRE221 [ K7 : AT NORMAL STATION]
13:13:51	Unit SPRE221 [ K7 : AT NORMAL STATION]
13:14:08	Unit SPRE221 [ K7 : AT NORMAL STATION]

## Incident

**CAD Number** F4052930

**Incident Reporter** Out of Scope

**Incident Controller**

**Distance Travelled (km)**

**Delay In Receiving Call**

## Property Details

**Occupant** Out of Scope

**Building Owner** Owner occupied

**General Property Use** Single house

**Special Property Use** Single house

**Purpose Group**

## Actions

**Persons Reported**

**Trapped**

**Evacuation Status** Fully evacuated

**Action Prior 1**

**Action Prior 2**

**Action Taken** Extinguishment only: Includes isolating fuel/power

## Civilians

**Civilians Rescued** 0

**Civilians Extricated** 0

Civilians Assisted 0  
Civilians Evacuated 0

### Origin

Location Patio, Court, Terrace, Gazebo  
Level Ground level

### Equipment Used

Quantity	Equipment
3	Hose reel, high pressure delivery
1	Low pressure delivery
2	Thermal Imaging Camera (TIC)

### Equipment Involved

Equipment Involved

Year

Make

Model

### Fire

Arrival Condition Large fire  
Heat Source Embers, Ashes  
Termination Stage  
First Object Ignited  
First Object Material  
Second Object Ignited  
Second Object Material  
Indicated Cause Careless disposal or use: cigarettes, ashes, embers  
Certainty of Cause High  
Age of Person Persons: 19 - 64 yrs  
Ethnicity 9(2)a  
Gender 9(2)a  
FAIP Service Offered Unknown

### Casualties

#### Casualty Number 1

Gender 9(2)a

Age 9(2)a



Apparent Injury	9(2)a
Ethnicity	9(2)a
Severity of Injury	9(2)a
Bleeding	
Action by Fire Fighters	9(2)a
Condition Before Injury	9(2)a
How Removed	9(2)a
Location at Ignition	9(2)a
Factor Preventing Escape	9(2)a
Activity When Injured	9(2)a
Cause of Injury	9(2)a
Victim Aware of Fire	9(2)a
Room Where Victim Found	9(2)a
Location Where Victim Found	
Familiarity With Property	9(2)a

**Comments**

10/2/2024 8:39:09 PM

Reporter Comments

9(2)a had put fireplace ashes in plastic bin on top of two wheely bins on a deck containing significant fire loading on the deck. The fire on the deck was fully involved on arrival and had gone into roof cavity which contained 3 upstairs bedrooms, bathroom and significant attic space. The house had a high loading of possessions all through the house. This was difficult to completely extinguish as the fire got under the roof capping which was unsafe to safety assess easily.

Out of Scope