

# SMS Incident Report

30/05/2017 08:47:17


## Summary

**CAD Number** F2308426 **Status** Closed  
**Station** Mount Roskill Station  
**Incident Started** 17/05/2017 02:04:27 **Incident Ended** 17/05/2017 18:19:36  
**Incident Type** 1101: Structure fire with damage  
**Common Name**  
**Address** 7 YEATS WAY MOUNT ROSKILL  
**Alarm Method** 111 Telephone **Alarm Level** 3  
**PFA Number**  
**Zone** 146236  
**Map Grid E** 1754265 **Map Grid N** 5911496  
**First Caller** **First Caller Contact** ██████████  
**Incident Closed** 17/05/2017 18:37:12  
**Report Completed** 20:5, Wed 24 May 2017 by Oswald Van Beerendonk

## Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
MTRO621	P1	02:05:34 17 May 2017	02:07:29 17 May 2017	02:10:39 17 May 2017	18:19:44 17 May 2017
ONEH221	P1	02:09:35 17 May 2017	02:11:13 17 May 2017	02:19:35 17 May 2017	17:07:42 17 May 2017
BALM611	P1	02:05:37 17 May 2017	02:07:15 17 May 2017	02:20:44 17 May 2017	14:30:55 17 May 2017
AVON607	PR	02:09:31 17 May 2017	02:11:50 17 May 2017	02:20:52 17 May 2017	04:55:47 17 May 2017
AUCK2018	CUHU	02:09:28 17 May 2017	02:15:17 17 May 2017	02:23:47 17 May 2017	05:00:49 17 May 2017
ELLE274	PM	02:14:26 17 May 2017	02:16:30 17 May 2017	02:31:07 17 May 2017	05:02:39 17 May 2017
AUCK207	PR	02:16:20 17 May 2017	02:18:15 17 May 2017	02:31:44 17 May 2017	04:34:51 17 May 2017
REMU211	P1	02:16:26 17 May 2017	02:18:31 17 May 2017	02:33:23 17 May 2017	04:54:25 17 May 2017
TEAT664	PM	02:16:14 17 May 2017	02:18:22 17 May 2017	02:34:02 17 May 2017	05:11:47 17 May 2017
GREY261	P1	02:16:23 17 May 2017	02:19:18 17 May 2017	02:34:13 17 May 2017	04:36:23 17 May 2017
PARN255	HPNP	02:16:10 17 May 2017	02:18:37 17 May 2017	02:34:36 17 May 2017	02:52:42 17 May 2017
AUCKOSU2	SV	02:17:49 17 May 2017	02:17:58 17 May 2017	02:38:01 17 May 2017	05:15:05 17 May 2017
AUCKCITY5	OF	02:19:03 17 May 2017	02:26:20 17 May 2017	02:38:54 17 May 2017	03:04:36 17 May 2017
GLEN641	P1	02:16:29 17 May 2017	02:18:06 17 May 2017	02:41:25 17 May 2017	04:53:28 17 May 2017
COUNTIES3	OF	02:17:32 17 May 2017	02:23:02 17 May 2017	02:41:32 17 May 2017	04:56:36 17 May 2017
AVON6015	BA	02:16:17 17 May 2017	02:30:06 17 May 2017	02:44:24 17 May 2017	04:55:46 17 May 2017

WAITEMATA3	OF	02:16:20 17 May 2017	02:17:02 17 May 2017	02:48:42 17 May 2017	03:06:32 17 May 2017
AUCKOSU4	CV	02:16:15 17 May 2017	02:46:27 17 May 2017	03:03:49 17 May 2017	05:08:11 17 May 2017
OTAH311	P1	02:43:35 17 May 2017	02:45:30 17 May 2017	03:05:36 17 May 2017	03:51:18 17 May 2017
OTAH3112	HL	02:43:35 17 May 2017	02:49:29 17 May 2017	03:05:39 17 May 2017	03:41:30 17 May 2017
FIACITY4	FSO	02:30:10 17 May 2017	02:38:48 17 May 2017	03:07:02 17 May 2017	13:07:44 17 May 2017
PARN251	P1	04:19:46 17 May 2017	04:21:45 17 May 2017	04:39:23 17 May 2017	07:46:22 17 May 2017
AUCK205	HPNP	02:09:28 17 May 2017	02:11:27 17 May 2017		02:19:36 17 May 2017
COUNTIES1	OF	02:17:32 17 May 2017			02:26:28 17 May 2017



**Elapsed Times**

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
MTRO621	00:01:07	00:05:05	00:06:12	16:15:17
ONEH221	00:05:08	00:10:00	00:15:08	15:03:15
BALM611	00:01:10	00:15:07	00:16:17	12:26:28
AVON607	00:05:04	00:11:21	00:16:25	02:51:20
AUCK2018	00:05:01	00:14:19	00:19:20	02:56:22
ELLE274	00:09:59	00:16:41	00:26:40	02:58:12
AUCK207	00:11:53	00:15:24	00:27:17	02:30:24
REMU211	00:11:59	00:16:57	00:28:56	02:49:58
TEAT664	00:11:47	00:17:48	00:29:35	03:07:20
GREY261	00:11:56	00:17:50	00:29:46	02:31:56
PARN255	00:11:43	00:18:26	00:30:09	00:48:15
AUCKOSU2	00:13:22	00:20:12	00:33:34	03:10:38
AUCKCITY5	00:14:36	00:19:51	00:34:27	01:00:09
GLEN641	00:12:02	00:24:56	00:36:58	02:49:01
COUNTIES3	00:13:05	00:24:00	00:37:05	02:52:09
AVON6015	00:11:50	00:28:07	00:39:57	02:51:19
WAITEMATA3	00:11:53	00:32:22	00:44:15	01:02:05
AUCKOSU4	00:11:48	00:47:34	00:59:22	03:03:44
OTAH311	00:39:08	00:22:01	01:01:09	01:46:51
OTAH3112	00:39:08	00:22:04	01:01:12	01:37:03
FIACITY4	00:25:43	00:36:52	01:02:35	11:03:17
PARN251	02:15:19	00:19:37	02:34:56	05:41:55
AUCK205	00:05:01			00:15:09

Caution: The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside the NZ Fire Service or the National Rural Fire Authority without prior approval

COUNTIES1	00:13:05			00:22:01
-----------	----------	--	--	----------

### Notifications

Date	Time	Party Notified
17 May 2017	02:08:25	AAC AUCKLAND CITY MULTIPLE CALLS
17 May 2017	02:08:32	VECTOR
17 May 2017	02:09:47	AAC AUCKLAND CITY
17 May 2017	02:09:50	AAC SHAW
17 May 2017	02:09:53	AAC MACKERETH
17 May 2017	02:09:55	OSU AUCKLAND
17 May 2017	02:10:20	POLICE
17 May 2017	02:10:21	AMBO
17 May 2017	02:11:49	AAC AUCKLAND CITY - K99
17 May 2017	02:11:56	OSU AUCKLAND - K99
17 May 2017	02:12:37	AAC SHAW ACK PAGE
17 May 2017	02:12:52	AAC MACKERETH ACK PAGE - WILL WAIT FOR SITREP
17 May 2017	02:14:49	AMB ADV BY PHONE
17 May 2017	02:16:05	AUCKLAND CITY AREA 3RD ALARM GROUP
17 May 2017	02:16:08	AAC SHAW
17 May 2017	02:16:12	AAC MACKERETH
17 May 2017	02:16:14	OSU AUCKLAND
17 May 2017	02:19:01	ROGER CALLISTER ACK PAGE WILL MONITOR
17 May 2017	02:21:12	COUNTIES1 ACK PAGE
17 May 2017	02:23:26	AC TWOMEY ACK PAGE
17 May 2017	02:26:41	██████████ (DOORS) - A/PH - MESSAGE LEFT
17 May 2017	02:27:09	██████████ AUCK OSU ADVISED OS4 ON THE ROAD WITHIN 20MINS
17 May 2017	02:30:44	GREATER ALARM RESPONSE LIST EMAILED TO 2018
17 May 2017	02:31:18	OPS MANAGER SMITH ACK PAGE
17 May 2017	02:32:45	FIKACITY4 WILL BE ON HIS WAY SHORTLY AS OF 02:32
17 May 2017	03:37:57	AUCK205 NOW FREE OF DOOR - WILL BE BACK ON THE RUN SHORTLY
17 May 2017	03:38:07	AUCK CITY APPLIANCE DOOR IS STUCK
17 May 2017	03:42:32	FI LEAVING SCENE, WILL BE BACK AT 0830 - 0900 (DAYLIGHT HOURS) TO MEET OWNER
17 May 2017	06:09:16	AVONDALE STATION THAT APPLIANCE IS READY FOR COLLECTION, THEY WILL PROCEED
17 May 2017	08:05:19	OSU AUCKLAND PAGED THAT EQUIPMENT READY FOR COLLECTION FM THIS EVENT
17 May 2017	08:08:08	VIA PHONE TO ██████████: ADV FI INTEND TO RETURN TO SCENE 0830 - 0900 THIS
17 May 2017	09:48:05	BALM611 ADVISED BY PHONE OF STAND BY AT 11:00
17 May 2017	16:23:11	ASKED MT ROSKILL IF THEY WILL BE ABLE TO SEND A STANDBY CREW TO THIS EVENT

17 May 2017	16:26:01	FM MTRO - AVON607
17 May 2017	16:29:33	MTRO WILL ARRANGE COVER AROUND 1700 HRS

**Message Log**

Time	Message
02:05:15	INC INFO: NEXT DOOR ON FIRE
02:05:15	** ELOI search completed at 17/05/17 02:05:15 - 2 results
02:05:16	** LOI search completed at 17/05/17 02:05:16
02:05:27	** Recommended unit MTRO621 for requirement PUMP (>1.6 km)
02:05:27	** Recommended unit BALM611 for requirement PUMP (>4.9 km)
02:05:38	HIEADS,
02:05:38	Duplicate Event:Location = 7 YEATS WAY,MOUNT ROSKILL,AUCKLAND, Type = STRU -
02:05:38	STRUCTURE FIRE, Caller Ph Number = [REDACTED] Call Source = 111Inc InfoHOUSE
02:05:38	INC INFO: HOUSE FIRE
02:05:38	FIRE, Event Source = Fire 111
02:05:38	End of Duplicate Event data
02:06:17	INC INFO: HOUSE FIRE
02:06:17	Duplicate Event:Location = 7 YEATS WAY,MOUNT ROSKILL,AUCKLAND, Type = STRU -
02:06:17	STRUCTURE FIRE, Call Source = 111Inc InfoHOUSE FIRE
02:06:17	End of Duplicate Event data
02:06:36	Duplicate Event:Location = 7 YEATS WAY,MOUNT ROSKILL,AUCKLAND, Type = STRU -
02:06:36	INC INFO: HOUSE FIRE
02:06:36	STRUCTURE FIRE, Caller Ph Number = [REDACTED] Call Source = 111Inc InfoHOUSE
02:06:36	FIRE, Event Source = Fire 111
02:06:36	End of Duplicate Event data
02:07:01	** Event Location changed from "2 YEATS WAY,MOUNT ROSKILL,AUCKLAND" to "7 YEATS
02:07:01	WAY,MOUNT ROSKILL,AUCKLAND" at: 17/05/17 02:07:01
02:07:02	** ELOI search completed at 17/05/17 02:07:02 - 2 results
02:07:03	** LOI search completed at 17/05/17 02:07:03
02:07:16	Unit BALM611 [ K1 : PROCEEDING TO INCIDENT]
02:07:29	Unit MTRO621 [ K1 : PROCEEDING TO INCIDENT]
02:07:58	INC INFO: HOUSE FIRE
02:07:58	Duplicate Event:Location = 7 YEATS WAY,MOUNT ROSKILL,AUCKLAND, Type = STRU -
02:07:58	STRUCTURE FIRE, Call Source = 111Inc InfoHOUSE FIRE
02:07:58	End of Duplicate Event data
02:08:37	INC INFO: HOUSE FIRE
02:08:44	Unit MTRO621 [ KP : PRIORITY MESSAGE]
02:09:02	Unit MTRO621 [ KP : PRIORITY MESSAGE] TRANSMIT 2ND ALARM
02:09:18	** Alarm level updated to 2

02:09:18 \*\* Recommended unit AUCK205 for requirement AERIAL (>8.5 km)

02:09:18 \*\* Recommended unit AUCK2018 for requirement COMU (>8.5 km)

02:09:18 \*\* Recommended unit AVON607 for requirement PUMP (>4.6 km)

02:09:18 \*\* Recommended unit ONEH221 for requirement PUMP (>4.9 km)

02:09:45 Duplicate Event:Location = 7 YEATS WAY,MOUNT ROSKILL,AUCKLAND, Type = STRU -  
02:09:45 BEHIND 481 HILLSBOROUGH RD  
02:09:45 INC INFO: HOUSE FIRE  
02:09:45 STRUCTURE FIRE, Caller Ph Number = [REDACTED], Call Source = 111Inc InfoHOUSE  
02:09:45 FIRE, Event Source = Fire 111  
02:09:45 End of Duplicate Event data  
02:09:48 Duplicate Event:Location = 7 YEATS WAY,MOUNT ROSKILL,AUCKLAND, Type = STRU -  
02:09:48 INC INFO: HOUSE FIRE  
02:09:48 MULTIPLE SUBSCRIBERS FOR CALLER NUMBER [REDACTED]. TESA LOOKUP RECOMMENDED.  
02:09:48 STRUCTURE FIRE, Caller Name = [REDACTED], Caller Ph Number =  
02:09:48 [REDACTED], Caller Address = [REDACTED], MOUNT ROSKILL, AUCKLAND CITY, Call  
02:09:48 Source = 111Inc InfoHOUSE FIRE, Event Source = Fire 111  
02:09:48 End of Duplicate Event data  
02:10:07 AMBO EVENT 0033-1-2017/05/17-FIR LINKED AT 17/05/2017 02:10:07  
02:10:12 POL AND AMB: FOR YOUR INFO - 2ND ALARM HOUSE FIRE  
02:10:17 Duplicate Event:Location = 7 YEATS WAY,MOUNT ROSKILL,AUCKLAND, Type = STRU -  
02:10:17 STRUCTURE FIRE, Caller Ph Number = [REDACTED], Call Source = 111Inc InfoHOUSE  
02:10:17 FIRE, Event Source = Fire 111  
02:10:18 INC INFO: HOUSE FIRE  
02:10:18 End of Duplicate Event data  
02:10:40 Unit MTRO621 [ K99 : PROPERTY FIRE WELL INV]  
02:10:42 INC INFO: HOUSE FIRE  
02:10:42 Duplicate Event:Location = 485A HILLSBOROUGH RD,MOUNT ROSKILL,AUCKLAND, Type =  
02:10:42 STRU - STRUCTURE FIRE, Caller Name = [REDACTED], Caller Ph Number =  
02:10:42 [REDACTED], Caller Address = 20 LNP FICT,, Call Source = 111Inc InfoHOUSE FIRE,  
02:10:42 Event Source = Fire 111  
02:10:42 End of Duplicate Event data  
02:10:43 \*CWS34 ADV  
02:10:46 [FIR] AMB>FIR RGR  
02:10:56 Duplicate Event:Location = YEATS WAY,MOUNT ROSKILL,AUCKLAND, Type = STRU -  
02:10:56 STRUCTURE FIRE, Caller Name = [REDACTED], Caller Ph Number = [REDACTED],  
02:10:56 Caller Address = [REDACTED], MOUNT ROSKILL, AUCKLAND CITY, Call Source = 111,  
02:10:56 Event Source = Fire 111  
02:10:57 INC INFO:  
02:10:57 End of Duplicate Event data  
02:11:14 Unit ONEH221 [ K1 : PROCEEDING TO INCIDENT]

02:11:28	Unit AUCK205 [ K1 : PROCEEDING TO INCIDENT]
02:11:31	Unit ONEH221 [ K1 : PROCEEDING TO INCIDENT]
02:11:38	FIR2POL - NO PERSONS REPORTED AT THIS STAGE
02:11:51	Unit AVON607 [ K1 : PROCEEDING TO INCIDENT]
02:12:00	Duplicate Event:Location = YEATS WAY,MOUNT ROSKILL,AUCKLAND, Type = STRU -
02:12:00	STRUCTURE FIRE, Call Source = 111Inc InfoHOUSE FIRE
02:12:01	INC INFO: HOUSE FIRE
02:12:01	End of Duplicate Event data
02:12:15	2 STOREY HOUSE = FIRE DOWNSTAIRS
02:12:50	Unit AUCK205 [ KC : UNIT CALLING]
02:12:51	FIR2POL: AFFIRM FOR INFO ONLY
02:13:17	Duplicate Event:Location = 7 YEATS WAY AUCKLAND, Cross Street 1 = RAMELTON RD,
02:13:17	Unit BALM611 [ KC : UNIT CALLING]
02:13:17	TD NOW
02:13:17	HEADLINE: INFMT SAYING HAS A FIRE AT THE ADDRESS
02:13:17	Type = 1F ASSIST FIRE/AMBULANCE/TRAFFIC, Subtype = 2, Caller Ph Number =
02:13:17	** LOI search completed at 17/05/17 02:11:29
02:13:17	RRRR
02:13:17	** Cross Referenced to Event # P029528509 at: 17/05/17 02:11:33
02:13:17	EVERYONE IS OUT OF THE HOUSE
02:13:17	RRRR
02:13:17	> CWS34 AWARE
02:13:17	*FIRE ARE ALREADY AWARE AND 10/2
02:13:17	** Event Type changed from 1F(2) to 1F(P1) at: 17/05/17 02:12:03
02:13:18	End of Duplicate Event data
02:13:22	Unit AUCK205 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
02:13:23	Unit AUCK205 [ SITREP : ] UNABLE TO RESPOND ISSUE WITH DOOR ON STATION
02:13:48	Unit MTRO621 [ SITREP : ] TRANSMIT 3RD ALARM
02:13:57	** Requirement AERIAL added for alarm level 2
02:14:09	** Recommended unit AUCK205 for requirement AERIAL (>8.5 km)
02:14:09	** Recommended unit ELLE274 for requirement ADHOC AERIAL (>7.3 km)
02:14:20	POL/AMB - NOW 3RD ALARM PLS RESPOND
02:14:23	Unit AUCK2018 [ KC : UNIT CALLING]
02:14:44	Duplicate Event:Location = YEATS WAY,MOUNT ROSKILL,AUCKLAND, Type = STRU -
02:14:44	INC INFO: HOUSE FIRE
02:14:44	STRUCTURE FIRE, Caller Ph Number = [REDACTED], Call Source = 111Inc InfoHOUSE
02:14:44	FIRE, Event Source = Fire 111
02:14:44	End of Duplicate Event data
02:15:18	Unit AUCK2018 [ K1 : PROCEEDING TO INCIDENT]
02:15:30	** Alarm level updated to 3

02:15:30 \*\* Recommended unit PARN255 for requirement AERIAL (>10.1 km)

02:15:30 \*\* Recommended unit TEAT664 for requirement AERIAL (>10.6 km)

02:15:30 \*\* Recommended unit AVON6015 for requirement BAT (>4.5 km)

02:15:30 \*\* Recommended unit AUCKOSU4 for requirement CANT (>9.8 km)

02:15:30 \*\* Recommended unit AUCK207 for requirement PUMP (>8.5 km)

02:15:30 \*\* Recommended unit GREY261 for requirement PUMP (>7.3 km)

02:15:30 \*\* Recommended unit REMU211 for requirement PUMP (>7.8 km)

02:16:30 Unit ELLE274 [ K1 : PROCEEDING TO INCIDENT]

02:16:53 Duplicate Event:Location = 7 YEATS WAY AUCKLANDCross Street 1RAMELTON RD, Type =

02:16:53 INC INFO: HOUSE FIRE

02:16:53 STRU STRUCTURE FIRE, Subtype = default, Caller Ph Number = [REDACTED], Call

02:16:53 \*\* LOI search completed at 17/05/17 02:05:36

02:16:53 Source = 111Alarm Level1Inc InfoHOUSE FIRE , Event Source = Fire 111

02:16:53 CALLER WOKE UP AND THERE IS FIRE DOWNSTAIRS

02:16:53 \*\* Event Location changed from "73 HILLSBOROUGH RD,HILLSBOROUGH,AUCKLAND" to "7

02:16:53 YEATS WAY,MOUNT ROSKILL,AUCKLAND" at: 17/05/17 02:06:42

02:16:53 \*\* ELOI search completed at 17/05/17 02:06:43 - 2 results

02:16:53 \*\* LOI search completed at 17/05/17 02:06:44

02:16:53 YISHANA

02:16:54 End of Duplicate Event data

02:16:54 \*\* Cross Referenced to Event # F2308427 at: 17/05/17 02:16:54

02:17:02 Unit WAITEMATA3 [ K1 : PROCEEDING TO INCIDENT]

02:17:05 Duplicate Event:Location = YEATS WAY,MOUNT ROSKILL,AUCKLAND, Type = STRU -

02:17:05 INC INFO: HOUSE FIRE

02:17:05 STRUCTURE FIRE, Caller Ph Number = [REDACTED], Call Source = 111Inc InfoHOUSE

02:17:05 FIRE, Event Source = Fire 111

02:17:05 End of Duplicate Event data

02:17:59 Unit AUCKOSU2 [ K1 : PROCEEDING TO INCIDENT]

02:18:03 HOUSE ON FIRE

02:18:03 Duplicate Event:Location = YEATS WAY,MOUNT ROSKILL,AUCKLAND, Type = STRU -

02:18:03 HILLSBOROUGH

02:18:03 STRUCTURE FIRE, Caller Ph Number = [REDACTED], Call Source = 111Inc InfoHOUSE

02:18:03 FIRE, Event Source = Fire 111

02:18:03 BEHIND 477 HILLSBOROUGH RD

02:18:03 INC INFO: HOUSE FIRE

02:18:03 End of Duplicate Event data

02:18:07 Unit GLEN641 [ K1 : PROCEEDING TO INCIDENT]

02:18:15 Unit AUCK207 [ K1 : PROCEEDING TO INCIDENT]

02:18:19 Unit WAITEMATA3 [ K1 : PROCEEDING TO INCIDENT]

02:18:22 Unit TEAT664 [ K1 : PROCEEDING TO INCIDENT]

02:18:33	Unit REMU211 [ K1 : PROCEEDING TO INCIDENT]
02:18:39	Unit PARN255 [ K1 : PROCEEDING TO INCIDENT]
02:19:18	Duplicate Event:Location = 7 YEATS WAY,MOUNT ROSKILL,AUCKLAND, Type = STRU -
02:19:18	STRUCTURE FIRE, Caller Ph Number = [REDACTED], Call Source = 111Inc InfoHOUSE
02:19:18	FIRE, Event Source = Fire 111
02:19:19	Unit GREY261 [ K1 : PROCEEDING TO INCIDENT]
02:19:19	INC INFO: HOUSE FIRE
02:19:19	End of Duplicate Event data
02:19:21	AUCK205 - GARAGE DOOR COME DOWN ON TOP OF TRUCK - K0
02:19:28	AL: PAGING ACK TIMED OUT FOR STATION: 1466 at 17/05/17 02:19:28
02:19:36	Unit ONEH221 [ K2 : IN ATTENDANCE AT INCIDENT]
02:19:37	Unit AUCK205 [ K0 : NOT AVAILABLE] DOOR DOWN ON TOP OF TRUCK
02:20:44	ONCALL EXEC TO CALL SSO'S PHONE AT AUCK CITY
02:20:45	Unit BALM611 [ K2 : IN ATTENDANCE AT INCIDENT]
02:20:53	Unit AVON607 [ K2 : IN ATTENDANCE AT INCIDENT]
02:22:28	INC INFO: HOUSE FIRE
02:22:28	Duplicate Event:Location = YEATS WAY,MOUNT ROSKILL,AUCKLAND, Type = STRU -
02:22:28	STRUCTURE FIRE, Caller Ph Number = [REDACTED], Call Source = 111Inc InfoHOUSE
02:22:28	FIRE, Event Source = Fire 111
02:22:28	End of Duplicate Event data
02:23:03	Unit COUNTIES3 [ K1 : PROCEEDING TO INCIDENT]
02:23:47	Unit AUCK2018 [ K2 : IN ATTENDANCE AT INCIDENT]
02:24:29	Unit MTRO621 [ K99 : PROPERTY FIRE WELL INV]
02:24:31	INC INFO: HOUSE FIRE
02:24:31	Duplicate Event:Location = YEATS WAY,MOUNT ROSKILL,AUCKLAND, Type = STRU -
02:24:31	STRUCTURE FIRE, Caller Name = [REDACTED], Caller Ph Number = [REDACTED],
02:24:31	Caller Address = 517E HILLSBOROUGH ROAD, MOUNT ROSKILL, AUCKLAND CITY, Call
02:24:31	Source = 111Inc InfoHOUSE FIRE, Event Source = Fire 111
02:24:31	End of Duplicate Event data
02:25:13	HOUSE FIRE
02:25:13	Duplicate Event:Location = YEATS WAY,MOUNT ROSKILL,AUCKLAND, Type = STRU -
02:25:13	STRUCTURE FIRE, Caller Name = [REDACTED], Caller Ph Number = [REDACTED],
02:25:13	INC INFO:
02:25:13	Caller Address = 30 GLENVEAGH DRIVE, MOUNT ROSKILL, AUCKLAND CITY, Call Source =
02:25:13	111, Event Source = Fire 111
02:25:13	End of Duplicate Event data
02:26:21	Unit AUCKCITY5 [ K1 : PROCEEDING TO INCIDENT]
02:26:29	Unit COUNTIES1 [ K6 : ON TELEPAGER]
02:26:57	Duplicate Event:Location = YEATS WAY,MOUNT ROSKILL,AUCKLAND, Type = MIN - MINOR,
02:26:57	INC INFO: SMELLING SMOKE IN THE AREA



02:26:57	Caller Name = [REDACTED], Caller Ph Number = [REDACTED], Caller Address = [REDACTED]
02:26:57	[REDACTED], LYNFIELD, AUCKLAND CITY, Call Source = 111Inc
02:26:57	InfoSMELLING SMOKE IN THE AREA, Event Source = Fire 111
02:26:57	End of Duplicate Event data
02:27:42	COVERING UNIT MANG351 DISPATCHED TO STATION ONEHUNGA
02:27:42	D0710067
02:28:23	COVERING UNIT HEND657 DISPATCHED TO STATION AVONDALE
02:28:23	D0710067
02:30:02	INC INFO: HOUSE FIRE TOC: 0205 TOA: 0210
02:30:07	Unit AVON6015 [ K1 : PROCEEDING TO INCIDENT]
02:30:30	Unit AUCK2018 [ KC : UNIT CALLING]
02:31:08	Unit ELLE274 [ K2 : IN ATTENDANCE AT INCIDENT]
02:31:24	Unit ELLE274 [ K2 : IN ATTENDANCE AT INCIDENT]
02:31:43	Unit AUCK2018 [ K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SSO RUSBRIDGE
02:31:43	LARGE 2 STOREY HOUSE WELL INV IN FIRE 3X LPDS AND BA IN USE
02:31:45	Unit AUCK207 [ K2 : IN ATTENDANCE AT INCIDENT]
02:32:02	COVERING UNIT BIRK821 DISPATCHED TO STATION GREY LYNN AT
02:32:02	D0710063
02:33:23	Unit REMU211 [ K2 : IN ATTENDANCE AT INCIDENT]
02:34:03	Unit TEAT664 [ K2 : IN ATTENDANCE AT INCIDENT]
02:34:13	Unit GREY261 [ K2 : IN ATTENDANCE AT INCIDENT]
02:34:37	Unit PARN255 [ K2 : IN ATTENDANCE AT INCIDENT]
02:38:02	Unit AUCKOSU2 [ K2 : IN ATTENDANCE AT INCIDENT]
02:38:48	Unit FIAKCITY4 [ K1 : PROCEEDING TO INCIDENT]
02:38:54	Unit AUCKCITY5 [ K2 : IN ATTENDANCE AT INCIDENT]
02:41:25	Unit GLEN641 [ K2 : IN ATTENDANCE AT INCIDENT]
02:41:32	Unit COUNTIES3 [ K2 : IN ATTENDANCE AT INCIDENT]
02:42:09	Unit AUCK2018 [ KC : UNIT CALLING]
02:42:41	Unit AUCK2018 [ SITREP : ] K11 HOSELAYER
02:44:24	Unit AVON6015 [ K2 : IN ATTENDANCE AT INCIDENT]
02:45:31	Unit OTAH311 [ K1 : PROCEEDING TO INCIDENT]
02:46:27	Unit AUCKOSU4 [ K1 : PROCEEDING TO INCIDENT]
02:47:44	Unit AUCK2018 [ KC : UNIT CALLING]
02:48:47	Unit WAITEMATA3 [ K2 : IN ATTENDANCE AT INCIDENT]
02:49:06	Unit AUCK2018 [ K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] AAM ROBERTS
02:49:06	YEATS COMMAND ALL PERSONS ACCOUNTED FOR AT PROP AND SURROUNDING PROPERTY'S DIRECT
02:49:06	HOSELAYER TO 487 HILLSBOROUGH RD WHERE 207 IS
02:49:29	Unit OTAH3112 [ K1 : PROCEEDING TO INCIDENT]
02:52:42	Unit PARN255 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

03:00:05	Unit AUCK2018 [ KC : UNIT CALLING]
03:00:46	Unit AUCK2018 [ K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] AAM SHAW FFS IN OFFENSIVE MODE
03:03:50	Unit AUCKOSU4 [ K2 : IN ATTENDANCE AT INCIDENT]
03:04:36	Unit AUCKCITY5 [ K6 : ON TELEPAGER]
03:05:37	Unit OTAH311 [ K2 : IN ATTENDANCE AT INCIDENT]
03:05:39	Unit OTAH3112 [ K2 : IN ATTENDANCE AT INCIDENT]
03:06:33	Unit WAITEMATA3 [ K6 : ON TELEPAGER]
03:07:03	Unit FIAKCITY4 [ K2 : IN ATTENDANCE AT INCIDENT]
03:41:31	Unit OTAH3112 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
03:44:31	Unit AUCK2018 [ KC : UNIT CALLING]
03:44:42	Unit FIAKCITY4 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
03:45:12	Unit AUCK2018 [ SITREP : ] FIRE UNDER CONTROL BRIGADE DAMPENING DOWN HOT SPOTS
03:51:19	Unit OTAH311 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
04:18:25	Unit AUCK2018 [ KC : UNIT CALLING]
04:19:27	Unit AUCK2018 [ SITREP : ] AAM SHAW RESP PARN251 AS RELIEF APPLLIANCE
04:21:46	Unit PARN251 [ K1 : PROCEEDING TO INCIDENT]
04:23:24	Unit BALM611 [ K2 : IN ATTENDANCE AT INCIDENT]
04:34:52	Unit AUCK207 [ K7 : AT NORMAL STATION]
04:36:00	Unit GREY261 [ KC : UNIT CALLING]
04:36:24	Unit GREY261 [ K10 : RECOMMISSIONING]
04:39:23	Unit PARN251 [ K2 : IN ATTENDANCE AT INCIDENT]
04:39:35	Unit PARN251 [ K2 : IN ATTENDANCE AT INCIDENT]
04:41:16	Duplicate Event:Location = 483 HILLSBOROUGH RD AUCKLANDCross Street 1CAPE HORN
04:41:16	GAS TANKS ON THE SIDE OF HER HOUSE
04:41:16	End of Duplicate Event data
04:41:16	INC INFO: EMBERS FLYING AROUND OUTSIDE
04:41:16	RDCross Street 2JAMES TYLER CR, Type = ADV ADVISED, Subtype = default, Caller
04:41:16	Name = [REDACTED], Caller Ph Number = [REDACTED], Call Source = 111Alarm Level1Inc
04:41:16	** LOI search completed at 17/05/17 02:40:40
04:41:16	InfoEMBERS FLYING AROUND OUTSIDE , Event Source = Fire 111
04:41:16	SMOKE COMING INTO THEIR HOUSE - HAVE CLOSED THEIR WINDOWS
04:41:16	** Requirement HOSE LAYER added for alarm level 1
04:41:17	** Cross Referenced to Event # F2308432 at: 17/05/17 04:41:17
04:47:34	Unit AUCK2018 [ KC : UNIT CALLING]
04:49:32	Unit AUCK2018 [ K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SO KERR 251 WILL BE STAYING ON SCENE IN 621 MTRO CREW RETURNING TO STATION IN 251 ALL OTHER APPLIANCES WILL GO K10 CAN YOU GET MTRO DAY CREW TO RELEIVE 151 CREW AT 0730
04:53:09	Unit GLEN641 [ KC : UNIT CALLING]
04:53:29	Unit GLEN641 [ K10 : RECOMMISSIONING]

04:54:06	Unit REMU211 [ KC : UNIT CALLING]
04:54:26	Unit REMU211 [ K10 : RECOMMISSIONING]
04:55:13	Unit AVON607 [ KC : UNIT CALLING]
04:55:47	Unit AVON6015 [ K10 : RECOMMISSIONING]
04:55:49	Unit AVON607 [ K10 : RECOMMISSIONING]
04:56:37	Unit COUNTIES3 [ K6 : ON TELEPAGER]
05:00:50	Unit AUCK2018 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
05:02:40	Unit ELLE274 [ K7 : AT NORMAL STATION]
05:04:29	Unit ONEH221 [ KC : UNIT CALLING]
05:04:47	Unit ONEH221 [ K10 : RECOMMISSIONING]
05:08:12	Unit AUCKOSU4 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
05:11:22	Unit BALM611 [ KC : UNIT CALLING]
05:11:48	Unit TEAT664 [ K7 : AT NORMAL STATION]
05:12:02	Unit BALM611 [ K10 : RECOMMISSIONING]
05:15:06	Unit AUCKOSU2 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
05:22:00	MTRO CREW ON PARN PUMP HAVE RETURNED TO MTRO STATION
05:22:54	Unit PARN251 [ K10 : RECOMMISSIONING]
05:24:37	PARN251 K10 - WILL GO K9-62 WHEN AVAIL (PROB AROUND 6)
06:08:04	Unit MTRO621 [ K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]
06:09:16	TO RETRIEVE BA TENDER
06:58:34	Unit MTRO621 [ KC : UNIT CALLING]
06:58:58	Unit MTRO621 [ K26 : UNIT WILL BE ENGAGED AT INCIDENT - STATE TIME] ONE
07:30:06	Unit PARN251 [ K38 : ASSOCIATE THIS UNIT TO EVENT - EVENT ADDRESS]
07:30:09	Unit PARN251 [ K1 : PROCEEDING TO INCIDENT]
07:30:11	Unit PARN251 [ K39 : RE-TRANSMIT YOUR CURRENT STATUS]
07:35:38	Unit PARN251 [ K2 : IN ATTENDANCE AT INCIDENT]
07:43:40	Unit MTRO621 [ KC : UNIT CALLING]
07:44:05	Unit MTRO621 [ K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SO GOODHUE
07:46:23	Unit PARN251 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
08:03:48	Unit MTRO621 [ SITREP : ] CAN YOU LET THE OP SUPPORT KNOW TO COME AND COLLECT
08:03:48	THEIR LIGHTING GEAR AND OTHER EQUIPMENT, AND CAN YOU FIND OUT WHO THE ON CALL
08:03:48	FIRE SAFETY OFFICER IS AND GET HIM TO GIVE ME A CALL [REDACTED]
08:08:08	MORNING, ADV IT IS RUSSELL DICKSON WHO IS ON TODAY. ADV OSU PAGED RE EQUIPMENT
08:08:08	READY TO COLLECT.
08:39:43	Unit FIAKCITY4 [ K1 : PROCEEDING TO INCIDENT]
09:06:33	Unit FIAKCITY4 [ K2 : IN ATTENDANCE AT INCIDENT]
09:08:50	Unit MTRO621 [ KC : UNIT CALLING]
09:09:27	Unit MTRO621 [ K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS] FIRE
09:09:27	SAFETY IN ATTENDANCE
09:22:20	*

09:23:03	FROM MTRO621.....NEED A RELIEF TRUCK FOR 11:00
10:52:40	Unit BALM611 [ K38 : ASSOCIATE THIS UNIT TO EVENT - EVENT ADDRESS]
10:52:48	Unit BALM611 [ K39 : RE-TRANSMIT YOUR CURRENT STATUS]
10:53:02	Unit BALM611 [ K1 : PROCEEDING TO INCIDENT]
10:53:11	Unit BALM611 [ K2 : IN ATTENDANCE AT INCIDENT]
11:24:04	Unit BALM611 [ KC : UNIT CALLING]
11:24:29	Unit BALM611 [ K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SO PIKE
11:50:38	Unit MTRO621 [ K7 : AT NORMAL STATION]
12:44:47	Unit BALM611 [ SITREP : ] VIA PHONE - SO PIKE - NEED RELIEVING AT 1400 - WILL
12:44:47	NEED TO BE A CLASS A FOAM TRUCK - EXCLU MTROS AND AVOND - POSSIBLY GLEN EDEN,
12:44:47	TITIRANGI, ONEHUNGA OR SHEL
12:49:23	SO MARTIN - CONFRIM CLASS A AND WILL RESPON STANDBY AT 1400
13:07:10	Unit FIAKCITY4 [ KC : UNIT CALLING]
13:07:44	Unit FIAKCITY4 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
13:07:46	Unit FIAKCITY4 [ STOP : MESSAGE] FI NOW COMPLETED
13:09:43	SO PIKE HAS SAID THE PREVIOUS WAS NOT A STOP MESSAGE
13:13:01	Unit BALM611 [ KC : UNIT CALLING]
13:14:51	Unit BALM611 [ SITREP : ] 2 FIXED HPD IN USE
13:56:37	Unit ONEH221 [ K2 : IN ATTENDANCE AT INCIDENT]
14:09:23	Unit ONEH221 [ KC : UNIT CALLING]
14:10:01	Unit ONEH221 [ K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SSO MARTIN
14:30:56	Unit BALM611 [ K7 : AT NORMAL STATION]
15:14:40	Unit ONEH221 [ KC : UNIT CALLING]
15:15:50	Unit ONEH221 [ K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]
16:03:22	Unit ONEH221 [ KC : UNIT CALLING]
16:03:41	Unit ONEH221 [ K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]
16:17:33	Unit ONEH221 [ KC : UNIT CALLING]
16:18:05	Unit ONEH221 [ SITREP : ] WILL REQUIRE ANOTHER APPLIANCE TO STAND BY AT 5PM,
16:18:05	STILL DAMPENING DOWN HOT SPOTS
16:23:11	AT 1700, THERE ARE SOME LOGISTICAL ISSUES, THEY SAID THAT ONE OF THEIR CREW IS
16:23:11	ON UNTIL 1800HRS, THEY ARE CALLING THIS PERSONS REPLACEMENT TO SEE IF THEY CAN
16:23:11	RESPOND TO THE SCENE AT 1800 AND THE FF CAN RETURN THEIR CAR TO THE
16:23:25	FIRESTATION.
16:23:25	APPARENTLY BALMORAL HAS SIMILAR ISSUES WAITING FOR CREW TO ARRIVE FROM OTHER
16:23:25	STATIONS.
16:27:28	MTRO SUGGESTS AVON607 AT 1700 FOR AN HOUR OR SO THEN POSSIBLY MTRO AFTER
16:27:28	THAT IF
16:27:28	REQUIRED
16:57:24	Unit MTRO621 [ K1 : PROCEEDING TO INCIDENT]
17:00:22	Unit MTRO621 [ K2 : IN ATTENDANCE AT INCIDENT]
17:07:51	Unit ONEH221 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

17:13:09	Unit MTRO621 [ KC : UNIT CALLING]
17:13:19	Unit MTRO621 [ KC : UNIT CALLING]
17:13:48	Unit MTRO621 [ KC : UNIT CALLING]
17:14:00	Unit MTRO621 [ K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SO GOODHUE
18:02:12	*****
18:19:06	Unit MTRO621 [ KC : UNIT CALLING]
18:19:36	Unit MTRO621 [ K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM INFORMATIVE] NO
18:19:36	FURTHER STANDBYS REQD
18:19:45	Unit MTRO621 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
18:37:12	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,
18:37:12	Qualifier 2:

**Incident**

<b>CAD Number</b>	F2308426
<b>Incident Reporter</b>	Oswald Van Beerendonk
<b>Incident Controller</b>	Beerendonk
<b>Distance Travelled (km)</b>	
<b>Delay In Receiving Call</b>	

**Property Details**

<b>Occupant</b>	unknown
<b>Building Owner</b>	Unknown
<b>General Property Use</b>	Single house
<b>Special Property Use</b>	Single house
<b>Purpose Group</b>	

**Actions**

<b>Persons Reported Trapped</b>	No
<b>Evacuation Status</b>	Fully evacuated
<b>Action Prior 1</b>	
<b>Action Prior 2</b>	
<b>Action Taken</b>	Extinguishment only: Includes isolating fuel/power supply

**Civilians**

<b>Civilians Rescued</b>	0
<b>Civilians Extricated</b>	0
<b>Civilians Assisted</b>	3
<b>Civilians Evacuated</b>	

**Origin**

**Location** Lounge, Common room, TV room, Sitting room, Music room  
**Level** 1st floor

**Equipment Used**

Quantity	Equipment
3	Low pressure delivery
1	Monitor (ground)

**Equipment Involved**

Equipment Involved

**Year**

**Make**

**Model**

**Fire**

**Arrival Condition** Totally involved fire

**Heat Source** Heat from electrical equipment: Defective or faulty

**Termination Stage** Flame

**First Object Ignited** Upholstered Furniture eg. Chairs, Sofas, Beds, Vehicle Seats

**First Object Material** Polyurethane eg. Furnishings, Upholstery, Mattresses

**Second Object Ignited**

**Second Object Material**

**Indicated Cause** Undetermined

**Certainty of Cause** Low

**Age of Person** No person involved

**Ethnicity** No person involved

**Gender**

**FAIP Service Offered** No **FAIP Service Accepted** No

**Alarms**

Type of Alarm Initiating Call Domestic Smoke Alarms

Performance of System Did not operate - detector not in room of origin

Failure/Ineffectiveness of system Unknown

Number of sprinkler heads operated 0

**Structure**

<b>Area of One Floor</b>		300
<b>Age of Building</b>	1970 - 1991	
<b>Structural Frame Type</b>	Timber frame unprotected (normal housing)	
<b>Number of Floors</b>		2
<b>Number of Basements</b>		0
<b>Internal Wall Lining</b>	Gypsum board (e.g. Gib board, Elephant board)	
<b>Ceiling Lining</b>	Gypsum board (e.g. Gib board, Elephant board)	
<b>Material Generating Most Flame</b>	Wood: Sawn, Finished timber	
<b>Material Generating Most Smoke</b>	Vinyl: Floor covering, Wallpaper	
<b>Avenue of Flame Travel</b>	Furniture, fixtures	
<b>Avenue of Smoke Travel</b>	Furniture, fixtures	
<b>Extent of Flame Damage</b>	Confined to structure of origin	
<b>Area of Flame Damage</b>		300
<b>Extent of Smoke Damage</b>	Confined to structure of origin	
<b>Area of Smoke Damage</b>		300
<b>Extent of Water Damage</b>	Confined to structure of origin	
<b>Area of Water Damage</b>		300
<b>Extent of Fire Control Damage</b>	Confined to structure of origin	
<b>Area of Fire Control Damage</b>		300

**Comments**

5/24/2017 8:05:09 PM

Reporter Comments

Total collapse of house meant that nobody had a chance to investigate/determine the cause of the fire. Having talked to the occupants, FRMO Dickson concluded that a dehumidifier in the lounge area was the only electrical appliance operating that night. Occupants were woken by the sound of breaking glass and evacuated to neighbouring property. Smoke alarms didn't sound, unable to discover the reason but suspect flat batteries.

Oswald Van Beerendonk