

SMS Incident Report

30/05/2017 08:05:22


Summary

CAD Number F2310793 **Status** Closed
Station Glen Eden Station
Incident Started 20/05/2017 21:27:45 **Incident Ended** 21/05/2017 17:15:02
Incident Type 1101: Structure fire with damage
Common Name
Address / 811 West Coast Road Oratia
Alarm Method 111 Telephone **Alarm Level** 3
PFA Number
Zone 147101
Map Grid E 1741947 **Map Grid N** 5911956
First Caller [REDACTED] **First Caller Contact** [REDACTED]
Incident Closed 21/05/2017 17:15:02
Report Completed 10:55, Sat 27 May 2017 by Hayden Robinson

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
GLEN641	P1	21:28:34 20 May 2017	21:29:44 20 May 2017	21:36:58 20 May 2017	09:00:12 21 May 2017
WAIA711	P1	21:28:31 20 May 2017	21:34:00 20 May 2017	21:38:11 20 May 2017	03:42:57 21 May 2017
HEND657	PR	21:28:37 20 May 2017	21:30:25 20 May 2017	21:39:08 20 May 2017	00:34:21 21 May 2017
HEND651	P1	21:29:35 20 May 2017	21:35:22 20 May 2017	21:46:16 20 May 2017	05:17:44 21 May 2017
AUCKOSU3	SV	21:33:57 20 May 2017	21:34:09 20 May 2017	21:49:59 20 May 2017	02:00:59 21 May 2017
TITI692	P2	21:41:50 20 May 2017	21:48:26 20 May 2017	21:57:53 20 May 2017	02:20:23 21 May 2017
TITI691	P1	21:41:53 20 May 2017	21:46:57 20 May 2017	22:07:10 20 May 2017	00:21:15 21 May 2017
WAITEMATA2	OF	21:42:11 20 May 2017	21:45:31 20 May 2017	22:36:10 20 May 2017	23:51:17 20 May 2017
TEAT664	PM	22:34:28 20 May 2017	22:35:02 20 May 2017	22:46:56 20 May 2017	00:00:32 21 May 2017
AVON607	PR	22:33:00 20 May 2017	22:35:53 20 May 2017	22:51:14 20 May 2017	00:18:14 21 May 2017
AVON6015	BA	22:32:59 20 May 2017	22:36:48 20 May 2017	22:53:38 20 May 2017	00:17:11 21 May 2017
TEAT6619	LU	22:17:02 20 May 2017	22:28:52 20 May 2017	22:53:45 20 May 2017	00:31:50 21 May 2017
PIHA761	P1	22:32:52 20 May 2017	22:38:16 20 May 2017	22:58:13 20 May 2017	23:32:22 20 May 2017
LAIN701	P1	22:32:55 20 May 2017	22:38:39 20 May 2017	22:58:25 20 May 2017	02:20:34 21 May 2017
FIWAITEM3	FSO	22:36:12 20 May 2017	22:44:21 20 May 2017	23:16:56 20 May 2017	16:33:15 21 May 2017
VSOWAITEM1	VSO	22:41:00 20 May 2017	22:47:47 20 May 2017	23:17:11 20 May 2017	00:08:40 21 May 2017

AUCKOSU4	CV	22:32:53 20 May 2017	23:09:20 20 May 2017	23:45:46 20 May 2017	00:36:03 21 May 2017
TITI6929	VN	01:55:44 21 May 2017	01:55:44 21 May 2017	01:55:44 21 May 2017	02:37:42 21 May 2017
FIWAITEM4	FSO	11:15:17 21 May 2017	11:15:24 21 May 2017	12:18:23 21 May 2017	14:45:47 21 May 2017
TEAT662	P2	22:33:03 20 May 2017			22:35:06 20 May 2017
FICOUNT4	FSO	11:14:29 21 May 2017			11:14:54 21 May 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
GLEN641	00:00:49	00:08:24	00:09:13	11:32:27
WAIA711	00:00:46	00:09:40	00:10:26	06:15:12
HEND657	00:00:52	00:10:31	00:11:23	03:06:36
HEND651	00:01:50	00:16:41	00:18:31	07:49:59
AUCKOSU3	00:06:12	00:16:02	00:22:14	04:33:14
TITI692	00:14:05	00:16:03	00:30:08	04:52:38
TITI691	00:14:08	00:25:17	00:39:25	02:53:30
WAITEMATA2	00:14:26	00:53:59	01:08:25	02:23:32
TEAT664	01:06:43	00:12:28	01:19:11	02:32:47
AVON607	01:05:15	00:18:14	01:23:29	02:50:29
AVON6015	01:05:14	00:20:39	01:25:53	02:49:26
TEAT6619	00:49:17	00:36:43	01:26:00	03:04:05
PIHA761	01:05:07	00:25:21	01:30:28	02:04:37
LAIN701	01:05:10	00:25:30	01:30:40	04:52:49
FIWAITEM3	01:08:27	00:40:44	01:49:11	19:05:30
VSOWAITEM1	01:13:15	00:36:11	01:49:26	02:40:55
AUCKOSU4	01:05:08	01:12:53	02:18:01	03:08:18
TITI6929	04:27:59	00:00:00	04:27:59	05:09:57
FIWAITEM4	13:47:32	01:03:06	14:50:38	17:18:02
TEAT662	01:05:18			01:07:21
FICOUNT4	13:46:44			13:47:09

Notifications

Date	Time	Party Notified
20 May 2017	21:29:39	OSU AUCKLAND VIA PAGER

20 May 2017	21:29:54	AAC WAITEMATA / AAC SHAW RE-PERSONS REPORTED..
20 May 2017	21:29:58	HEND651 TURNOUT AS EXTRA PUMP PER PERSONS REPORTED
20 May 2017	21:31:29	AAC MACKERETH ACK PAGER - MONITORING..
20 May 2017	21:33:04	AAC SHAW ACK PAGER - MONITORING..
20 May 2017	21:35:28	AAC BOOTH ACK PAGER - MONITORING..
20 May 2017	21:37:19	VECTOR - ON HOLD
20 May 2017	21:38:24	VECTOR - WILL CALL BACK WITH AN ETA
20 May 2017	21:42:44	AAC BOOTH PER PHONE - RESPONDING..
20 May 2017	21:43:09	VECTOR ADVSD OF 2ND ALARM - THEY ARE STILL TRYING TO ORGANISE FAULTMAN
20 May 2017	21:43:35	AAC MACKERETH (WAITEMATA3) ACK 2ND ALARM - NOT RESPONDING
20 May 2017	21:45:51	AAC SHAW ACK 2ND ALARM PAGER..
20 May 2017	21:56:13	VECTOR ETA WITHIN 20MINS @ 2156
20 May 2017	22:28:16	OSU AUCKLAND PER PAGER
20 May 2017	22:31:35	VECTOR RE 3RD ALARM
20 May 2017	22:31:55	POLICE ADVSD OF THIRD ALARM
20 May 2017	22:32:04	AMB ADVSD OF THIRD ALARM
20 May 2017	22:34:08	WAITEMATA AREA 3RD ALARM PER PAGER..
20 May 2017	22:34:45	AC PURCELL / AAC SHAW PER 3RD ALARM..
20 May 2017	22:35:49	TEAT662 PAGED TO STAND DOWN
20 May 2017	22:36:37	AAC MACKERETH ACK PAGER - SPOKE WITH AAC BOOTH - NOT REQUIRED..
20 May 2017	22:36:46	AVON607 COMMITTED TO X/MAN AVON6015
20 May 2017	22:37:57	AC PURCELL ACK PAGER..
20 May 2017	22:38:42	TEAT664 AND AUCK205 REMOVED (AS SPECIALIST APPLIANCES)
20 May 2017	22:38:45	COUNTIES3 (MIKE SHAW) HAVE SPOKEN TO JOHN BOOTH, MANPOWER ONLY NO FURTHER
20 May 2017	22:39:09	TEAT664 RECOMMITTED AS PUMP RESPONSE AND TEAT662 K28'D
20 May 2017	22:39:52	AUCK2018 REMOVED (AS SPECIALIST APPLIANCE)
20 May 2017	22:45:33	OPS MGR SMITH ACK PAGER..
21 May 2017	00:18:05	GLEN641 RE 6015 STATUS - LEAVING SCENE NOW
21 May 2017	00:19:50	ATOC/JTOC CALLED, ASKING IF WE REQUIRE THE ROAD TO BE CLOSED?
21 May 2017	00:24:11	GLEN641 EXTERNALLY ALERTED.
21 May 2017	01:08:48	HEND651 PAGED TO CONTACT SO ROBINSON (RE STANDBYS) SO ROBINSON WILL CALL
21 May 2017	01:51:49	WAIA711 PER PAGER RE-STANDBY REQUIRED..

Message Log

Time	Message
21:28:03	INC INFO: HOUSE FIRE - PERSONS REPORTED
21:28:03	MULTIPLE SUBSCRIBERS FOR CALLER NUMBER 98149493. TESA LOOKUP RECOMMENDED.
21:28:04	** LOI search completed at 20/05/17 21:28:04

21:28:09 NEIGHBOUR IS YELLING FOR HELP\
21:28:19 ** Recommended unit WAIA711 for requirement PUMP (>1.6 km)
21:28:19 ** Recommended unit GLEN641 for requirement PUMP (>5.6 km)
21:28:19 ** Recommended unit HEND657 for requirement PUMP (>5.9 km)
21:28:33 AMBO EVENT 0802-1-2017/05/20-FIR LINKED AT 20/05/2017 21:28:33
21:28:37 ** Requirement PUMP added for alarm level 1
21:28:41 ** Recommended unit HEND651 for requirement ADHOC PUMP (>5.9 km)
21:28:47 LOTS OFF YELLING AND SCREAMING IN BACKGROUND
21:29:45 Unit GLEN641 [K1 : PROCEEDING TO INCIDENT]
21:29:48 INC INFO: GARAGE FIRE
21:29:48 Duplicate Event:Location = 811 WEST COAST RD,ORATIA,AUCKLAND, Type = STRU -
21:29:48 INC INFO: GARAGE FIRE
21:29:48 STRUCTURE FIRE, Caller Name = [REDACTED], Caller Ph Number = [REDACTED],
21:29:48 Call Source = 111Inc InfoGARAGE FIRE , Event Source = Fire 111
21:29:48 End of Duplicate Event data
21:30:25 Unit HEND657 [K1 : PROCEEDING TO INCIDENT]
21:31:25 FIR2POL:NEG - ENROUTE
21:34:00 Unit WAIA711 [K1 : PROCEEDING TO INCIDENT]
21:34:09 Unit AUCKOSU3 [K1 : PROCEEDING TO INCIDENT]
21:34:10 Unit AUCKOSU3 [K38 : ASSOCIATE THIS UNIT TO EVENT - EVENT ADDRESS]
21:34:15 Duplicate Event:Location = 809 WEST COAST RD,ORATIA,AUCKLAND, Type = STRU -
21:34:15 INC INFO: HOUSE FIRE
21:34:15 MULTIPLE SUBSCRIBERS FOR CALLER NUMBER [REDACTED]. TESA LOOKUP RECOMMENDED.
21:34:15 STRUCTURE FIRE, Caller Name = [REDACTED] Caller Ph Number = [REDACTED],
21:34:15 Caller Address = [REDACTED] WEST COAST ROAD, ORATIA, AUCKLAND CITY, Call Source =
21:34:15 111Inc InfoHOUSE FIRE, Event Source = Fire 111
21:34:16 End of Duplicate Event data
21:35:23 Unit HEND651 [K1 : PROCEEDING TO INCIDENT]
21:35:29 Unit WAIA711 [COMCEN COM : MESSAGE] NEAREST HYDRANT ATB OUTSIDE 813 WEST COAST
21:35:29 RD
21:35:54 Duplicate Event:Location = 1 BENDALLS LA,ORATIA,AUCKLAND, Type = VEG -
21:35:54 INC INFO: LARGE BUSH FIRE
21:35:54 VEGETATION FIRE, Caller Name = TRUST POWER LTD, Caller Ph Number = [REDACTED]
21:35:54 Caller Address = [REDACTED] LANE, ORATIA, AUCKLAND CITY, Call Source = 111Inc
21:35:54 InfoLARGE BUSH FIRE, Event Source = Fire 111
21:35:54 End of Duplicate Event data
21:36:19 INC INFO: FIRE IN VICINITY
21:36:19 Duplicate Event:Location = WEST COAST RD,ORATIA,AUCKLAND, Type = MIN - MINOR,
21:36:19 Caller Name = [REDACTED], Caller Ph Number = [REDACTED], Caller
21:36:19 Address = [REDACTED] LANE, ORATIA, AUCKLAND CITY, Call Source = 111Inc InfoFIRE

21:36:19	IN VICINITY , Event Source = Fire 111
21:36:19	End of Duplicate Event data
21:36:24	Unit GLEN641 [SITREP :] COPY HYDRANT - ANY FURTHER INFO?
21:36:31	Unit GLEN641 [COMCEN COM : MESSAGE] DETAILS PASSED
21:36:45	Duplicate Event:Location = WEST COAST RD,ORATIA,AUCKLAND, Type = STRU -
21:36:45	INC INFO: HOUSE FIRE
21:36:45	STRUCTURE FIRE, Caller Name = [REDACTED], Caller Ph Number =
21:36:45	[REDACTED], Caller Address = TELECOM CELLULAR 027, WELLINGTON CENTRAL,
21:36:45	WELLINGTON CITY, Call Source = 111Inc InfoHOUSE FIRE, Event Source = Fire 111
21:36:45	End of Duplicate Event data
21:36:59	Unit GLEN641 [K99 : PROPERTY FIRE WELL INV]
21:38:11	Unit WAIA711 [K2 : IN ATTENDANCE AT INCIDENT]
21:38:25	LARGE FIRE REQUESTING ASSISTANCE FOR TRAFFIC CONTROL
21:39:08	Unit HEND657 [K2 : IN ATTENDANCE AT INCIDENT]
21:40:43	Unit GLEN641 [KC : UNIT CALLING]
21:40:55	NO ONE OUTSTANDING IN HOUSE
21:41:25	Unit GLEN641 [SITREP :] SO ROBINSON - WELL INVOLVE DHOUSE FIRE AND GARAGE FIRE
21:41:25	- GTWW 2LPDS AND BA - ALL PEROSNS ARE ACCOUNTED FOR - TX 2ND ALARM
21:41:35	INC INFO: HOUSE FIRE - TX 2ND ALARM
21:41:39	FIR2POL - ALL PERSONS ACCOUNTED FOR - 2ND ALARM TRANSMITTED
21:41:40	STARTED FROM GARAGE BUT WHOLE HOUSE FIRE
21:41:43	** Alarm level updated to 2
21:41:43	** Recommended unit TITI691 for requirement PUMP (>5.6 km)
21:41:43	** Recommended unit TITI692 for requirement PUMP (>5.6 km)
21:41:48	RRRR
21:41:56	FIR2AMB - ALL PERSONS ACCOUNTED FOR - 2ND ALARM TRANSMITTED
21:42:18	[FIR] amb copies - amb crew still enroute
21:45:32	Unit WAITEMATA2 [K1 : PROCEEDING TO INCIDENT]
21:46:17	Unit HEND651 [K2 : IN ATTENDANCE AT INCIDENT]
21:46:58	Unit TITI691 [K1 : PROCEEDING TO INCIDENT]
21:47:36	NLI2 FORESTHILL/WEST COAS
21:47:48	** LOI search completed at 20/05/17 21:47:48
21:47:53	TRAFFIC CONTROL
21:48:27	Unit TITI692 [K1 : PROCEEDING TO INCIDENT]
21:50:00	Unit AUCKOSU3 [K2 : IN ATTENDANCE AT INCIDENT]
21:55:02	**FIRE WELL INVOLVED
21:56:01	CAR IN GARAGE AND A CARAVAN ON THE PROPERTY .. WHICH ALSO BACKS ONTO BUSH
21:57:54	Unit TITI692 [K2 : IN ATTENDANCE AT INCIDENT]
22:00:53	**
22:01:17	SZI2 WILL BE REMAINING ON SCENE FOR SOME TIME

22:03:58 Unit GLEN641 [KC : UNIT CALLING]

22:04:28 Unit GLEN641 [SITREP :] 3LPD"S, 1HPD IN USE AND BA

22:07:11 Unit TITI691 [K2 : IN ATTENDANCE AT INCIDENT] ENTERED BY FCOMMS AS PER AVL

22:15:49 Unit GLEN641 [KC : UNIT CALLING]

22:16:23 Unit GLEN641 [SITREP :] MAKE LIGHTING PLANT ONE AND WE NOW HAVE 3 LPD"S AND

22:16:23 1HPD ESTABLISHED ON THE FIREGROUND

22:16:39 INC INFO: 2ND ALARM HOUSE FIRE: MAKE LIGHTING UNITS ONE

22:16:49 ** Requirement LIGHTING added for alarm level 2

22:16:52 ** Recommended unit TEAT6619 for requirement ADHOC LIGHTING (>9.0 km)

22:20:47 FOREST HILL/WEST COAST .. NLI2 DOING TRAFFIC CONTROL

22:21:28 >>

22:22:00 FIRE: DO YOU HAVE ANY STAFF AVAIL FOR TRAFFIC CONTROL .. AT FOREST HILL/WEST

22:22:00 COAST

22:22:49 10 FIRE APPLIANCES AT THE SCENE

22:26:03 Unit GLEN641 [COMCEN COM : MESSAGE] POLICE ARE ASKING IF YOU HAVE ANY CREWS

22:26:03 AVAILABLE THERE FOR TRAFFIC CONTROL ON FOREST HILL AND WEST COAST ROADS

22:26:07 Unit GLEN641 [KC : UNIT CALLING]

22:26:34 Unit GLEN641 [SITREP :] NEG TO SPARE PERSONELL FOR TRAFFIC CONTROL. MAKE OSU

22:27:02 FIR2POL : NEG TO SPARE PERSONEL. WE WILL PAGE FOR AND ADDITIONAL OP SUPPORT UNIT

22:28:53 Unit TEAT6619 [K1 : PROCEEDING TO INCIDENT]

22:29:38 Unit GLEN641 [KC : UNIT CALLING]

22:30:20 Unit GLEN641 [SITREP :] TRX 3RD ALARM FOR MANPOWER. K28-1 ALL SPEC APPLIANCES

22:30:20 EXCEPT THE BA TENDER.

22:30:46 Unit GLEN641 [COMCEN COM : MESSAGE] CAN YOU CONFIRM LU IS STILL REQUIRED AND

22:30:46 CONFIRM IF AAC BOOTH IS IN ATTENDANCE

22:30:59 Unit GLEN641 [SITREP :] BA TENDER AND LU REQUIRED. AAC BOOTH IS IN ATTENDANCE

22:31:09 RGR

22:31:21 INC INFO: 3RD ALARM FOR MANPOWER : HOUSE FIRE

22:31:28 FIR2POL: THIRD ALARM TRANSMITTED

22:31:43 FIR2AMB: THIRD ALARM TRANSMITTED

22:32:15 ** Alarm level updated to 3

22:32:15 ** Recommended unit AUCK2018 for requirement COMU (>14.7 km)

22:32:15 ** Recommended unit TEAT664 for requirement AERIAL (>9.0 km)

22:32:15 ** Recommended unit AUCK205 for requirement AERIAL (>10.2 km)

22:32:15 ** Recommended unit AVON6015 for requirement BAT (>10.2 km)

22:32:15 ** Recommended unit AUCKOSU4 for requirement CANT (>22.1 km)

22:32:15 ** Recommended unit PIHA761 for requirement PUMP (>11.0 km)

22:32:15 ** Recommended unit TEAT662 for requirement PUMP (>9.0 km)

22:32:15 ** Recommended unit LAIN701 for requirement PUMP (>5.0 km)

22:33:47	Unit GLEN641 [KC : UNIT CALLING]
22:35:03	Unit TEAT664 [K1 : PROCEEDING TO INCIDENT]
22:35:07	Unit TEAT662 [K7 : AT NORMAL STATION]
22:35:33	Unit GLEN641 [K11F : FIRE SAFETY REQUIRED]
22:35:44	INC INFO: 3RD ALARM HOUSE FIRE TOC: 2128 TOA:2136
22:35:50	Unit GLEN641 [SITREP :] K11 FIRE SAFETY. POLICE AND AMB IN ATTENDANCE
22:35:53	Unit AVON607 [K1 : PROCEEDING TO INCIDENT]
22:35:56	INC INFO: 3RD ALARM HOUSE FIRE TOC: 2128 TOA: 2136
22:36:11	Unit WAITEMATA2 [K2 : IN ATTENDANCE AT INCIDENT] ENTERED BY FCOMMS AS PER
22:36:11	GLEN641
22:36:16	AL: PAGING ACK TIMED OUT FOR STATION: 1466 at 20/05/17 22:36:16
22:36:37	Unit GLEN641 [KC : UNIT CALLING]
22:36:49	Unit AVON6015 [K1 : PROCEEDING TO INCIDENT]
22:37:02	Unit GLEN641 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SSO SWEENEY
22:37:38	AL: PAGING ACK TIMED OUT FOR STATION: 1466 at 20/05/17 22:37:38
22:38:16	Unit PIHA761 [K1 : PROCEEDING TO INCIDENT]
22:38:39	Unit LAIN701 [K1 : PROCEEDING TO INCIDENT]
22:38:45	EXECUTIVES REQUIRED.
22:40:04	COVERING UNIT MTRO621 DISPATCHED TO STATION HENDERSON
22:40:04	D0710063
22:41:04	Unit VSOWAITEM1 [K38 : ASSOCIATE THIS UNIT TO EVENT - EVENT ADDRESS]
22:41:17	Unit TITI691 [K2 : IN ATTENDANCE AT INCIDENT]
22:44:21	Unit FIWAITEM3 [K1 : PROCEEDING TO INCIDENT]
22:46:56	Unit TEAT664 [K2 : IN ATTENDANCE AT INCIDENT]
22:47:47	Unit VSOWAITEM1 [K1 : PROCEEDING TO INCIDENT]
22:51:15	Unit AVON607 [K2 : IN ATTENDANCE AT INCIDENT]
22:51:31	Unit GLEN641 [KC : UNIT CALLING]
22:51:53	Unit GLEN641 [SITREP :] FIRE HAS BEEN CONTAINED
22:53:39	Unit AVON6015 [K2 : IN ATTENDANCE AT INCIDENT]
22:53:46	Unit TEAT6619 [K2 : IN ATTENDANCE AT INCIDENT]
22:58:13	Unit PIHA761 [K2 : IN ATTENDANCE AT INCIDENT]
22:58:25	Unit LAIN701 [K2 : IN ATTENDANCE AT INCIDENT]
23:06:26	FIRPOL : WE HAVE HAD NOW FURTHER RESPONSE FROM OPS SUPPORT TO ASSIST WITH
23:06:26	TRAFFIC AT FOREST HILL AND WEST COAST ROADS
23:09:21	Unit AUCKOSU4 [K1 : PROCEEDING TO INCIDENT]
23:16:56	Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT]
23:17:11	Unit VSOWAITEM1 [K2 : IN ATTENDANCE AT INCIDENT]
23:19:25	Unit GLEN641 [KC : UNIT CALLING]
23:19:56	Unit GLEN641 [KC : UNIT CALLING]
23:20:05	Unit GLEN641 [SITREP :] GO AHEAD X 3

23:20:16 Unit GLEN641 [KC : UNIT CALLING]
23:20:34 Unit GLEN641 [SITREP :] SALVAGE
23:32:23 Unit PIHA761 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
23:32:41 Unit GLEN641 [KC : UNIT CALLING]
23:32:47 Unit GLEN641 [KC : UNIT CALLING]
23:33:09 Unit GLEN641 [SITREP :] FIRE SAFETY IN ATTENDANCE
23:36:10 ** Cancel Event:Event Canceled by InterCAD
23:36:10 Incident Closed. Reason: 805 Police / Fire Standby
23:45:47 Unit AUCKOSU4 [K2 : IN ATTENDANCE AT INCIDENT]
23:51:19 Unit WAITEMATA2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
23:54:12 Unit WAIA711 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
23:59:42 FIRE STILL FLARING UP .. APPEARS MIGHT HAVE STARTED IN THE ELECTRICAL BOARD
23:59:49 Unit TEAT664 [KC : UNIT CALLING]
23:59:54 Unit TEAT664 [KC : UNIT CALLING]
00:00:22 Unit TEAT664 [SITREP :] K10
00:00:34 Unit TEAT664 [K10 : RECOMMISSIONING]
00:00:52 AWC4 K8
00:08:42 Unit VSOWAITEM1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
00:10:17 ** FIRE ADVISE THAT THEY WILL HAVE TWO APPLIANCES THERE TILL 8-9 AM THEY HAVE
00:10:17 .NO TRAFFIC MANAGEMENT CONTROL
00:14:45 ** RIMU
00:14:49 AND KAURI LOOP
00:14:58 .
00:15:30 FIRE: ATOC ORGANISING ROADING CREWS FOR TRAFFIC MANAGEMENT
00:16:27 POL:FIRE: CONFIRM ROAD NEEDS TO BE CLOSED ENTIRELY? OFFICERS ON SCENE HAVE
BEEN
00:16:27 ADVISED THAT 2 FIRE CREWS WILL BE ONSCENE TILL 8-9 AM .. AND THEY HAVE NO
00:16:27 TRAFFIC MANAGEMENT IN PLACE
00:17:13 Unit AVON6015 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
00:18:15 Unit AVON607 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
00:18:41 Unit GLEN641 [K26-1 : APPLIANCE STILL ENGAGED, NO ADDITIONAL DEVELOPMENTS]
00:20:59 ..
00:21:05 SZI3 WILL BE SCENE GUARD
00:21:16 Unit TITI691 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
00:21:45 Unit GLEN641 [COMCEN COM : MESSAGE] PER PHONE - TRIED TO MAKE CONTACT TO ASK
00:21:45 ABOUT ROAD CLOSURE REQUIREMENTS. NO ANSWER.
00:23:37 LIASING WITH AWC4 . FIRE INVESTIGATOR WAS DUE TO HEAD OUT . UNKNOWN IF
00:23:37 SUSPICIOUS OR NOT . STARTED IN THE GARAGE
00:24:45 .
00:24:54 ETA FOR CONTRACTORS .. NIL ETA YET

00:26:01 Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
00:29:45 15 MINS .. FOR ONE OF THE CONTRACTORS
00:31:44 Unit TITI692 [KC : UNIT CALLING]
00:31:51 Unit TEAT6619 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
00:32:09 Unit TITI692 [K44 : COMMAND OR CONTROL POINT ESTABLISHED - OIC AND LOCATION]
00:32:09 LAIN701
00:32:23 Unit LAIN701 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] CFO BOOTH
00:34:22 Unit HEND657 [K7 : AT NORMAL STATION]
00:36:05 Unit AUCKOSU4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
00:44:11 Unit HEND651 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
01:08:48 FIRECOM WITH STANDBY PLAN WHEN CONFIRMED
01:13:18 >>
01:13:36 SZI2 . ADVISES TRAFFIC CONTROL HAVE NOT YET TURNED UP
01:19:21 CONTRACTORS ONSITE .. ARE PUTTING IN PLACE A STOP/GO
01:26:46 (TITI692 + LAIN701 UNTIL 0200) - (WAIA711 +HEND651 0200 - 0500) PAGE 711 CREW @
01:26:46 0150
01:29:06 0500 - 0800 GLEN641
01:42:18 Unit GLEN641 [K7 : AT NORMAL STATION]
01:54:22 Unit TITI692 [KC : UNIT CALLING]
01:54:38 Unit TITI692 [K42 : FIRE SUPPRESSED, COMMENCING OVERHAUL]
01:55:11 Unit TITI692 [COMCEN COM : MESSAGE] ON YOUR RETURN TO STN CAN YOU ADVISE IF
01:55:11 TITI6929 IS K7
01:55:20 Unit TITI692 [SITREP :] TITI6929 IS AT THIS INCIDENT
01:55:29 Unit TITI692 [COMCEN COM : MESSAGE] MSG RCVD, WE"LL RECOMMIT THEM
01:55:45 Unit TITI6929 [K2 : IN ATTENDANCE AT INCIDENT] ENTERED BY FCOMMS
01:57:41 Unit HEND651 [SITREP :] CAN YOU ATTACH US TO THE JOB ON WEST COAST RD
01:58:01 Unit HEND651 [K39 : RE-TRANSMIT YOUR CURRENT STATUS]
01:58:04 Unit HEND651 [K2 : IN ATTENDANCE AT INCIDENT]
02:00:58 Unit WAIA711 [K1 : PROCEEDING TO INCIDENT]
02:01:01 Unit AUCKOSU3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
02:11:38 Unit WAIA711 [K2 : IN ATTENDANCE AT INCIDENT]
02:18:03 Unit HEND651 [KC : UNIT CALLING]
02:18:29 Unit HEND651 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SO RUDD HEND651
02:20:24 Unit TITI692 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
02:20:35 Unit LAIN701 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
02:37:12 Unit TITI6929 [COMCEN COM : MESSAGE] CONFIRMING YOU"RE STILL IN ATTENDANCE
02:37:23 Unit TITI6929 [SITREP :] NEG, RETURNING TO TITITRANGI STN
02:37:26 Unit TITI6929 [K39 : RE-TRANSMIT YOUR CURRENT STATUS]
02:37:44 Unit TITI6929 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
03:42:59 Unit WAIA711 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

04:40:41	Unit GLEN641 [K38 : ASSOCIATE THIS UNIT TO EVENT - EVENT ADDRESS]
04:41:02	Unit GLEN641 [K39 : RE-TRANSMIT YOUR CURRENT STATUS]
04:41:34	Unit GLEN641 [K1 : PROCEEDING TO INCIDENT]
04:49:00	Unit GLEN641 [K2 : IN ATTENDANCE AT INCIDENT]
04:53:16	Unit GLEN641 [KC : UNIT CALLING]
04:53:47	Unit GLEN641 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SO ROBINSON 641
05:17:45	Unit HEND651 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
05:41:04	** FIRE IS OUT
05:41:30	NLI3 REMAINING ON SCENE .. TILL THE FIRE INVESTIGATOR ARRIVES AT 07:00
06:59:13	**SCQ1 - WILL TAKE OVER AS SCENE GUARD FOR EARLIES
07:28:05	Unit GLEN641 [SITREP :] [PHONE] - WE ARE RETURNING TO STATION TO SWAP WITH
07:28:05	BLUE WATCH. POLICE ARE STILL IN ATTENDANCE. GLEN641 BLUE WATCH WILL PUT IN THE
07:28:05	STOP MESSAGE
07:47:51	Unit FIWAITEM3 [K1 : PROCEEDING TO INCIDENT]
08:11:56	Unit GLEN641 [KC : UNIT CALLING]
08:12:43	Unit GLEN641 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SO RUTHERFORD
08:20:48	Unit FIWAITEM3 [K2 : IN ATTENDANCE AT INCIDENT]
08:57:58	Unit GLEN641 [KC : UNIT CALLING]
08:58:24	Unit GLEN641 [STOP : MESSAGE] FIRE INV AND CIB ON SCENE
09:00:14	Unit GLEN641 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
11:15:25	Unit FIWAITEM4 [K1 : PROCEEDING TO INCIDENT]
11:16:36	Unit FICOUNT4 [K6 : ON TELEPAGER]
12:18:24	Unit FIWAITEM4 [K2 : IN ATTENDANCE AT INCIDENT]
14:45:48	Unit FIWAITEM4 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
16:33:17	Unit FIWAITEM3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
17:14:56	UNIT TITI6929 RESPONSE TIME [NULL] ADJUSTED TO
17:15:01	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,
17:15:01	UNIT TITI6929 ALERT TIME [NULL] ADJUSTED TO
17:15:01	Qualifier 2:

Incident

CAD Number F2310793
Incident Reporter Hayden Robinson
Incident Controller SO Robinson
Distance Travelled (km)
Delay In Receiving Call

Property Details

Occupant [REDACTED]

Building Owner Owner occupied
General Property Use Single house
Special Property Use Single house
Purpose Group

Actions

Persons Reported Trapped No
Evacuation Status Fully evacuated
Action Prior 1 Portable extinguisher (all types)
Action Prior 2 Garden hose
Action Taken Extinguishment, salvage and ventilation

Civilians

Civilians Rescued 0
Civilians Extricated 0
Civilians Assisted 0
Civilians Evacuated

Origin

Location Garage, Carport, Vehicle storage, Storage Shed
Level Ground level

Equipment Used

Quantity	Equipment
3	Low pressure delivery
1	Hose reel, high pressure delivery
1	Thermal Imaging Camera
20	BA set
1	Hand tools - Crowbar, Saw, Hammer, Mop, Broom, Misc small gear

Equipment Involved

Equipment Involved
Year
Make
Model

Fire

Arrival Condition Large fire
Heat Source Information not recorded/Unknown

Termination Stage	Flame		
First Object Ignited	Framing, Structural member, Interior walls and doors		
First Object Material	Wood: sawn, finished timber		
Second Object Ignited	Upholstered Furniture eg. Chairs, Sofas, Beds, Vehicle Seats		
Second Object Material	Polyurethane eg. Furnishings, Upholstery, Mattresses		
Indicated Cause	Undetermined		
Certainty of Cause	Low		
Age of Person	Unknown		
Ethnicity	Unknown		
Gender			
FAIP Service Offered	No	FAIP Service Accepted	No

Structure

Area of One Floor		140
Age of Building	1946 - 1969	
Structural Frame Type	Timber frame unprotected (normal housing)	
Number of Floors		1
Number of Basements		0
Internal Wall Lining	Gypsum board (e.g. Gib board, Elephant board)	
Ceiling Lining	Gypsum board (e.g. Gib board, Elephant board)	
Material Generating Most Flame	Wood: Sawn, Finished timber	
Material Generating Most Smoke	Wood: Sawn, Finished timber	
Avenue of Flame Travel	Wind	
Avenue of Smoke Travel	Wind	
Extent of Flame Damage	Extended beyond structure of origin	
Area of Flame Damage		140
Extent of Smoke Damage	Confined to structure of origin	
Area of Smoke Damage		140
Extent of Water Damage	Confined to structure of origin	
Area of Water Damage		140
Extent of Fire Control Damage	Extended beyond structure of origin	
Area of Fire Control Damage		140

Mobile

Vehicle Type	Car, Taxi, Ambulance
Licence Plate	
Year	

Make	unkown
Model	unknown
Vehicle Type	Car, Taxi, Ambulance
Licence Plate	
Year	
Make	unknown
Model	unknown

Released under the Official Information Act

Exposure Number 1

Incident Type 1101: Structure fire with damage
Address 811 West Coast Road Oratia
Distance Exposure Travelled 10
Surface Material of Exterior Wall Wood, weatherboard
Construction Material of Roof Steel, iron (roll formed steel and corrugated iron)
Method of Heat Transfer Radiated heat

Property Details

Occupant [REDACTED]
Building Owner Owner occupied
General Property Use Single house
Special Property Use Single house
Purpose Group

Actions

Persons Reported Trapped No
Evacuation Status Fully evacuated
Action Prior 1 Portable extinguisher (all types)
Action Prior 2 Garden hose
Action Taken Extinguishment only: Includes isolating fuel/power supply

Civilians

Civilians Rescued 0
Civilians Extricated 0
Civilians Assisted 0
Civilians Evacuated

Origin

Location Wall surface (exterior)
Level Ground level

Equipment Used

Quantity	Equipment
1	Low pressure delivery
1	Thermal Imaging Camera

Equipment Involved

Equipment Involved
Year
Make

Model

Fire

Arrival Condition	Small fire		
Heat Source	Exposure fire: Radiated heat		
Termination Stage	Flame		
First Object Ignited	Exterior side wall covering surface, Cladding (included eaves)		
First Object Material	Wood: sawn, finished timber		
Second Object Ignited	Exterior side wall covering surface, Cladding (included eaves)		
Second Object Material	Wood: sawn, finished timber		
Indicated Cause	Exposure fire		
Certainty of Cause	High		
Age of Person	Unknown		
Ethnicity	Unknown		
Gender	Female		
FAIP Service Offered	No	FAIP Service Accepted	No

Structure

Area of One Floor		100
Age of Building	1992 - 2005	
Structural Frame Type	Timber frame unprotected (normal housing)	
Number of Floors		1
Number of Basements		0
Internal Wall Lining	Gypsum board (e.g. Gib board, Elephant board)	
Ceiling Lining	Gypsum board (e.g. Gib board, Elephant board)	
Material Generating Most Flame	Wood: Sawn, Finished timber	
Material Generating Most Smoke	Wood: Sawn, Finished timber	
Avenue of Flame Travel	No travel	
Avenue of Smoke Travel	No travel	
Extent of Flame Damage	Confined to object of origin	
Area of Flame Damage		20
Extent of Smoke Damage	Confined to object of origin	
Area of Smoke Damage		20
Extent of Water Damage	Confined to object of origin	
Area of Water Damage		20
Extent of Fire Control Damage	Confined to object of origin	
Area of Fire Control Damage		20

Comments

5/27/2017 10:55:42 AM

Reporter Comments

On Saturday the 20th of May we attended a House fire at 811 West Coast Road. Upon arrival, and first investigation I noticed the following

On the left of driveway

- Left house exterior had 9kg LPG cylinder on fire
- Left house exterior wall on fire

On the right side of driveway

- Car next to garage on fire
- Garage on fire
- House on fire (and spreading)

Questioning of occupants indicated fire started in garage area. Inside garage was a car, stand up freezer and other items. This area had power to it. The intensity, burning patterns and information from occupants points to this as the area of origin. The wind was pushing from the left side of driveway to the right, assisting with fire spread from garage to the house.

Also, radiant heat and LPG cylinder fire were factors in the house on left to have sustained damage to its exterior wall. Due to exposure protection, the fire damage was only to exterior wall and didn't spread to rest of this house.

Hayden Robinson

Released under the Official Information Act