

# SMS Incident Report


01/08/2017 13:03:55

## Summary

**CAD Number** F2354030 **Status** Closed  
**Station** Devonport Station  
**Incident Started** 31/07/2017 12:22:56 **Incident Ended** 31/07/2017 13:19:40  
**Incident Type** 4402: Arcing, shorted electrical equipment  
**Common Name**  
**Address** 1B NILE ROAD MILFORD  
**Alarm Method** 111 Telephone **Alarm Level** 1  
**PFA Number**  
**Zone** 148002  
**Map Grid E** 1756201 **Map Grid N** 5928218  
**First Caller** WAITEMATA DISTRICT HEALTHBOARD **First Caller Contact** ██████████  
**Incident Closed** 31/07/2017 13:19:40  
**Report Completed** 16:13, Mon 31 Jul 2017 by John Ellington

## Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
DEVO811	P1	12:24:55 31 Jul 2017	12:25:36 31 Jul 2017	12:28:17 31 Jul 2017	12:42:44 31 Jul 2017
TAKA807	PR	12:24:46 31 Jul 2017	12:26:06 31 Jul 2017	12:31:22 31 Jul 2017	12:38:21 31 Jul 2017



## Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
DEVO811	00:01:59	00:03:22	00:05:21	00:19:48
TAKA807	00:01:50	00:06:36	00:08:26	00:15:25

**Notifications**

Date	Time	Party Notified
31 Jul 2017	12:43:18	BIRK821 - K28

**Message Log**

Time	Message
12:24:09	INC INFO: SMOKE OF BURNING
12:24:10	** LOI search completed at 31/07/17 12:24:10
12:24:31	** Recommended unit TAKA807 for requirement PUMP (>2.3 km)
12:24:31	INC INFO: SMELL OF BURNING
12:24:31	** Recommended unit DEVO811 for requirement PUMP (>1.7 km)
12:25:37	Unit DEVO811 [ K1 : PROCEEDING TO INCIDENT]
12:26:06	Unit TAKA807 [ K1 : PROCEEDING TO INCIDENT]
12:28:18	Unit DEVO811 [ K77 : NOTHING SHOWING]
12:28:22	Unit DEVO811 [ K77 : NOTHING SHOWING]
12:30:39	Unit DEVO811 [ KC : UNIT CALLING]
12:30:44	Unit DEVO811 [ KC : UNIT CALLING]
12:31:00	Unit DEVO811 [ KC : UNIT CALLING]
12:31:23	Unit TAKA807 [ K2 : IN ATTENDANCE AT INCIDENT]
12:31:27	Unit DEVO811 [ SITREP : ] SO ELLINGTON. INV SMELL OF BURNING COMING FROM KITCHEN
12:33:44	COVERING UNIT BIRK821 DISPATCHED TO STATION TAKAPUNA AT
12:33:44	D0710063
12:38:22	Unit TAKA807 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]
12:41:47	Unit DEVO811 [ KC : UNIT CALLING]
12:42:07	Unit DEVO811 [ KC : UNIT CALLING]
12:42:13	Unit DEVO811 [ KC : UNIT CALLING]
12:42:45	Unit DEVO811 [ STOP : MESSAGE] STOP. OVERHEATED LIGHT FITTING
12:42:45	Unit DEVO811 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
13:19:40	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,
13:19:40	Qualifier 2:

**Incident**

<b>CAD Number</b>	F2354030
<b>Incident Reporter</b>	John Ellington
<b>Incident Controller</b>	john ellington
<b>Distance Travelled (km)</b>	1
<b>Delay In Receiving Call</b>	

**Property Details**

Occupant

Building Owner

General Property Use Doctors/Dentists emergency clinic, Medical centre

Special Property Use Doctors surgery, Dentist, Oral surgeon, Psychiatrists, combined medical centre

Purpose Group

**Actions**

Persons Reported Trapped

Evacuation Status

Action Prior 1

Action Prior 2

Action Taken Extinguishment only: Includes isolating fuel/power supply

**Origin**

Location Kitchen, Cooking area

Level Ground level

**Equipment Used**

Quantity	Equipment
1	Thermal Imaging Camera
2	Hand tools - Crowbar, Saw, Hammer, Mop, Broom, Misc small gear
1	Ladder

**Equipment Involved**

Equipment Involved

Year 1900

Make unknown

Model unknown

**Comments**

7/31/2017 4:13:02 PM

Reporter Comments

light ballast failed in flouro light, out of arrival, ventilated and isolate power to light fitting

John Ellington

Released under the Official Information Act