

SMS Incident Report


18/09/2017 08:47:40

Summary

CAD Number F2377136 **Status** Closed
Station East Coast Bays Station
Incident Started 11/09/2017 04:38:55 **Incident Ended** 11/09/2017 05:33:06
Incident Type 4402: Arcing, shorted electrical equipment
Common Name
Address 2 / 1006 Beach Road Torbay
Alarm Method 111 Telephone **Alarm Level** 1
PFA Number
Zone 148385
Map Grid E 1756554 **Map Grid N** 5937263
First Caller [REDACTED] **First Caller Contact** [REDACTED]
Incident Closed 11/09/2017 05:33:06
Report Completed 16:27, Fri 15 Sep 2017 by Nick Penfold

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
EAST831	P1	04:39:40 11 Sep 2017	04:40:46 11 Sep 2017	04:46:43 11 Sep 2017	05:31:00 11 Sep 2017
EAST832	P2	04:39:37 11 Sep 2017	04:47:02 11 Sep 2017		04:49:25 11 Sep 2017
ALBA851	P1	04:39:43 11 Sep 2017	04:44:01 11 Sep 2017		04:49:03 11 Sep 2017



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
EAST831	00:00:45	00:07:03	00:07:48	00:52:05
EAST832	00:00:42			00:10:30
ALBA851	00:00:48			00:10:08

Notifications

Date	Time	Party Notified
11 Sep 2017	04:39:46	VECTOR
11 Sep 2017	04:48:16	VECTOR ETA 20MINS @0448

Message Log

Time	Message
04:39:21	INC INFO: SWITCH BOARD ON FIRE
04:39:22	** LOI search completed at 11/09/17 04:39:22
04:39:29	** Recommended unit EAST831 for requirement PUMP (>3.3 km)
04:39:29	** Recommended unit EAST832 for requirement PUMP (>3.3 km)
04:39:29	** Recommended unit ALBA851 for requirement CANBACKUP (>7.5 km)
04:39:43	NTO VECTOR
04:40:46	Unit EAST831 [K1 : PROCEEDING TO INCIDENT]
04:44:01	Unit ALBA851 [K1 : PROCEEDING TO INCIDENT]
04:44:04	Unit ALBA851 [K39 : RE-TRANSMIT YOUR CURRENT STATUS]
04:46:44	Unit EAST831 [K77 : NOTHING SHOWING]
04:47:03	Unit EAST832 [K1 : PROCEEDING TO INCIDENT]
04:48:17	Unit EAST831 [KC : UNIT CALLING]
04:49:00	Unit EAST831 [SITREP :] SO PENFOLD SWITCH BOARD FIRE OOA K28-1
04:49:04	Unit ALBA851 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
04:49:23	Unit EAST831 [K28-1 : RETURN OTHER RESPONDING UNITS]
04:49:26	Unit EAST832 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
04:49:28	Unit EAST831 [K28 : UNIT IS TO RETURN TO STATION]
04:49:50	Unit EAST831 [COMCEN COM : MESSAGE] VECTOR ADVISED AT TIME OF CALL VECTOR ETA
04:49:50	20MINS
05:05:09	Unit EAST831 [KC : UNIT CALLING]
05:06:04	Unit EAST831 [SITREP :] VECTOR IN ATTENDANCE
05:29:25	Unit EAST831 [KC : UNIT CALLING]
05:30:19	Unit EAST831 [STOP : MESSAGE] 1 CO2 EXTENUISHER USED VETILATION USED INCIDENT
05:30:19	HANDED OVER TO VECTOR
05:31:01	Unit EAST831 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
05:33:05	** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,
05:33:05	Qualifier 2:

Incident

CAD Number	F2377136
Incident Reporter	Nick Penfold
Incident Controller	Nick Penfold

Distance Travelled (km) 4
Delay In Receiving Call

Property Details

Occupant
Building Owner
General Property Use Flat, Apartment, Home unit
Special Property Use Flats, Apartments, Units 1 to 2
Purpose Group

Actions

Persons Reported Trapped
Evacuation Status
Action Prior 1
Action Prior 2
Action Taken Extinguishment only: Includes isolating fuel/power supply

Origin

Location Lobby, Entrance way
Level Ground level

Equipment Used

Quantity	Equipment
1	CO2 extinguisher

Equipment Involved

Equipment Involved
Year
Make
Model

Comments

fire in main switch

9/15/2017 4:27:35 PM

Reporter Comments

Nick Penfold

Released under the Official Information Act