# Customer Request Management Enquiry CRM 65066/2019 - Routine Water CRMs

R	ece	ive	bs	Da	te

12/01/2019 03:00 PM

**Determination Details** 

20/05/2019 01:08 PM Complete (CRMC)

Reference Id

105078

**Contact Method** 

**TELEPHONE** 

Description

Investigate fowl water seepage outside 26 Isis Street

**Creation Officer** 

Judith Ann Jean Blair

**Last Modified By** 

Oscar Smit

Map

Click for interactive

#### Workflow

### **Workflow Summary**

Description

3Water Routine Water

Manager

Michael Goldingham

Responsible Officer Michael Goldingham

5 days

Target Time

**Service Standard** 

Workflow History

## **Create New Task**

New Task Type

Note 🗸

#### **Workflow Details**

Description	Status	Opened	Target	Due	Closed	Outcome	Action Officer	Role	Delegating Officer	Role	Notes	Checklist	Audi
Respond	Complete	12/01/19 03:00 PM		15/01/19	12/01/19 05:30 PM		Judith Blair	3Waters Routine CRM Contractor Group			12/1/19 Roading called water callout phone as they had received multiple calls of something toxic seeping from footpath. Found the same sort of water coming up thru footpath. Rang Warren to see what he wanted to do about. He would like area dug up on Monday and leak investigated (Judith Ann Jean Blair - 14/01/2019)		view
Resolve	Complete	АМ		17/01/19	РМ		Judith Blair	3Waters Routine CRM Contractor Group			WDC Roading department - Tom Reading has this in hand (Judith Ann Jean Blair - 18/01/2019)		<u>view</u>
Note	-	30/04/19 02:50 PM			30/04/19 02:51 PM	Complete	Michael Goldingham			1	has had a plumber		<u>view</u>

Description	Status	Opened	Target	Due	Closed	Outcome	Action Officer	Role	Delegating Officer	Role	Notes	Checklist	Audit
											to investigate the drainage problem outside his place at 26 Isis Street who has said that it is a Council problem and it is not coming from his property. He is wanting someone to ring him about this on (Barbara Sloan - 30/04/2019)		
Note	Complete	14/05/19 12:00 PM		20/05/19	20/05/19 01:09 PM	Complete	Michael Goldingham				Oscar has met with on site on 14th of May. Issue appears to be groundwater affecting the footpath and road, has been forwarded to Roading to address. (Oscar Smit - 20/05/2019)		view

**Customer Details** 

User

Anonymous NAR

**Business Phone** 

4330300

**Contact Method** 

Not required

**Property** 

Address

26 Isis Street Oamaru 9400

Title

Sec: 10 Blk: XC Twn: Oamaru

Parcel

<u>15609</u>

Assessment

104606

**Property Owners** 

**Owner Address** 

26 Isis Street Oamaru 9400

**Zoning** 

No zoning information available

# Water Supply Network (Required)

01 Oamaru

Leak (Required)

Leak

Water Asset Type (Required)

2 Service Line

Leak Info (Where does the water appear to be Coming from?) (Required)

Other

Subsequent Call (If yes put original CRM # in comments)

Comment	
Attachments Attachment Options Clicking 'Attachment Options' will launch an external program. Please be patient while the program loads.  Add No results found	
ENGINEER ONLY - Dayworks Approved (If yes put approved value in next Field)	
ENGINEER ONLY - Dayworks Approved Value	
ENGINEER ONLY - Extension to Resolution	

**ENGINEER ONLY - NFPM exclude from reporting** 

**ENGINEER ONLY - KPI exclude from reporting**