

# SMS Incident Report

15/11/2021 09:55:40


## Summary

**CAD Number** F3352885 **Status** Closed  
**Station** Ilam Station  
**Incident Started** 05/11/2021 03:34:03 **Incident Ended** 05/11/2021 15:30:27  
**Incident Type** 1101: Structure fire with damage  
**Common Name** ANTONIO HALL  
**Address** 265 Riccarton Road Upper Riccarton  
**Alarm Method** 111 Telephone **Alarm Level** 3  
**PFA Number**  
**Zone** 34263501  
**Map Grid E** 1566433 **Map Grid N** 5180050  
**First Caller** **First Caller Contact** [REDACTED]  
**Incident Closed**  
**Report Completed** 13:34, Mon 08 Nov 2021 by [REDACTED]

## Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
ILAM261	P1	03:34:59 05 Nov 2021	03:37:18 05 Nov 2021	03:41:31 05 Nov 2021	12:49:16 05 Nov 2021
SPRE221	P1	03:38:22 05 Nov 2021	03:39:27 05 Nov 2021	03:47:20 05 Nov 2021	14:15:50 05 Nov 2021
WIGR257	PR	03:41:10 05 Nov 2021	03:42:39 05 Nov 2021	03:51:53 05 Nov 2021	05:52:36 05 Nov 2021
CHRI216	TL	03:44:42 05 Nov 2021	03:47:39 05 Nov 2021	03:54:20 05 Nov 2021	14:14:36 05 Nov 2021
CHRI2518	CUHU	03:41:11 05 Nov 2021	03:45:28 05 Nov 2021	03:55:15 05 Nov 2021	06:24:02 05 Nov 2021
CHRI217	PR	03:41:14 05 Nov 2021	03:44:26 05 Nov 2021	03:55:32 05 Nov 2021	10:11:46 05 Nov 2021
CHRI214	PM	03:41:13 05 Nov 2021	03:45:22 05 Nov 2021	03:56:03 05 Nov 2021	15:30:31 05 Nov 2021
WOOL241	P1	03:53:13 05 Nov 2021	03:54:25 05 Nov 2021	04:06:48 05 Nov 2021	05:26:23 05 Nov 2021
REDW231	P1	03:53:10 05 Nov 2021	03:57:18 05 Nov 2021	04:12:11 05 Nov 2021	05:23:59 05 Nov 2021
GMCANTE01	OF	03:55:46 05 Nov 2021	03:55:47 05 Nov 2021	04:12:39 05 Nov 2021	15:30:52 05 Nov 2021
ANZA271	P1	03:56:13 05 Nov 2021	03:59:13 05 Nov 2021	04:13:55 05 Nov 2021	05:30:19 05 Nov 2021

LINC411	P1	03:55:56 05 Nov 2021	04:01:32 05 Nov 2021	04:18:04 05 Nov 2021	05:34:05 05 Nov 2021
REDW2312	HL	03:54:40 05 Nov 2021	04:00:37 05 Nov 2021	04:31:48 05 Nov 2021	08:28:02 05 Nov 2021
FICANTE01	FSO	05:58:33 05 Nov 2021	05:58:34 05 Nov 2021	06:47:31 05 Nov 2021	13:56:51 05 Nov 2021
DISTR7004	OT	07:20:59 05 Nov 2021	07:21:00 05 Nov 2021	07:49:25 05 Nov 2021	07:57:32 05 Nov 2021
FICANTE07	FSO	09:01:19 05 Nov 2021	09:01:20 05 Nov 2021	09:01:21 05 Nov 2021	13:56:04 05 Nov 2021
FICANTE06	FSO	13:28:43 05 Nov 2021	13:28:44 05 Nov 2021	13:28:45 05 Nov 2021	13:55:07 05 Nov 2021



### Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
ILAM261	00:00:56	00:06:32	00:07:28	09:15:13
SPRE221	00:04:19	00:08:58	00:13:17	10:41:47
WIGR257	00:07:07	00:10:43	00:17:50	02:18:33
CHRI216	00:10:39	00:09:38	00:20:17	10:40:33
CHRI2518	00:07:08	00:14:04	00:21:12	02:49:59
CHRI217	00:07:11	00:14:18	00:21:29	06:37:43
CHRI214	00:07:10	00:14:50	00:22:00	11:56:28
WOOL241	00:19:10	00:13:35	00:32:45	01:52:20
REDW231	00:19:07	00:19:01	00:38:08	01:49:56
GMCANTE01	00:21:43	00:16:53	00:38:36	11:56:49
ANZA271	00:22:10	00:17:42	00:39:52	01:56:16
LINC411	00:21:53	00:22:08	00:44:01	02:00:02
REDW2312	00:20:37	00:37:08	00:57:45	04:53:59
FICANTE01	02:24:30	00:48:58	03:13:28	10:22:48
DISTR7004	03:46:56	00:28:26	04:15:22	04:23:29
FICANTE07	05:27:16	00:00:02	05:27:18	10:22:01
FICANTE06	09:54:40	00:00:02	09:54:42	10:21:04

### Notifications

Date	Time	Party Notified
05 Nov 2021	03:40:54	POLICE VIA INTERCAD

05 Nov 2021	03:41:43	CANTERBURY BUILT PER 2ND ALARM
05 Nov 2021	03:42:36	ORION
05 Nov 2021	03:46:58	GMCANTE01 ( ) ACK PAGE AND ENROUTE SHORTLY
05 Nov 2021	03:52:05	AMBULANCE VIA INTERCAD
05 Nov 2021	03:52:08	ORION
05 Nov 2021	03:55:20	EQUIP/LOGISTICS ( ) PAGED
05 Nov 2021	03:55:32	FICANTE01 ( ) PAGED - PER 3RD ALARM
05 Nov 2021	03:56:16	VSO CANTERBURY PAGED - PER 3RD ALARM
05 Nov 2021	03:56:17	REGION TE IHU (THIRD ALARM)
05 Nov 2021	03:58:05	CANTERBURY CIVIL DEFENCE DUTY OFFICER - PER 3RD ALARM
05 Nov 2021	03:59:53	VSO ( ) ACK PAGE
05 Nov 2021	04:00:51	FI CANTE01 ( ) - 2ND PAGE AS NO RESPONSE
05 Nov 2021	04:01:31	REGION TE IHU ( ) ACK'D
05 Nov 2021	04:02:08	NATIONAL MEDIA
05 Nov 2021	04:02:29	FI CANTE01 ( ) ACK PAAGE
05 Nov 2021	04:05:26	( ) FROM NATION MEDIA TEAM ACK PAGE
05 Nov 2021	04:31:25	HPO

### Message Log

Time	Message
03:34:45	( )
03:34:48	** LOI search completed at 05/ 1/21 03:34:48
03:34:51	INC INFO: FIRE IN BACKYARD
03:34:53	** Recommended unit LAM261 for requirement PUMP (>1.2 km)
03:34:56	PA Selcal used to Initiate Alerting. (ILAM261 at 3426 ILAM 193261)
03:34:59	ALERTING COMPLETED ILAM261
03:35:58	** Event Location changed from "RICCARTON RD,UPPER RICCARTON,CHRISTCHURCH CITY"
03:35:58	to "( ) RICCARTON RD,UPPER RICCARTON,CHRISTCHURCH CITY" at: 05/11/21 03:35:58
03:36:00	** LOI search completed at 05/11/21 03:36:00
03:36:18	.
03:36:25	ENGLISH 2ND LANGUAGE
03:36:50	CALLER DESCRIBED AT TWO HOUSES DOWN FROM ( ) HOUSE, TOWARDS RICCARTON MALL DIREC
03:36:50	TION
03:37:01	DIFFICULT TO GET BETTER DESCRIPTION DUE TO LANGUAGE BARRIER
03:37:18	Unit ILAM261 [ K1 : PROCEEDING TO INCIDENT]
03:37:51	INC INFO: FIRE IN THE AREA
03:38:10	** Event Type changed from MIN to STRU at: 05/11/21 03:38:10

03:38:11 \*\* Event Priority changed from 2 to 1 at: 05/11/21 03:38:10

03:38:12 INC INFO: BUILDING FIRE

03:38:17 \*\* Recommended unit SPRE221 for requirement PUMP (>3.8 km)

03:38:19 PA Selcal used to Initiate Alerting. (SPRE221 at 3422 SPREYDON 192221)

03:38:22 ALERTING\_COMPLETED SPRE221

03:38:53 SAID IT WAS AN ABANDONDED BUILDING WITH A LOT OF TREES AROUND IT

03:39:12 INC INFO: BUSHES ON FIRE

03:39:26 INC INFO: FIRE IN THE AREA

03:39:27 Unit SPRE221 [ K1 : PROCEEDING TO INCIDENT]

03:39:57 INC INFO: BUILDING FIRE

03:40:26 Unit ILAM261 [COMCEN COM : MESSAGE] FURTHER INFO PASSED (COPY TX 2ND ALARM)

03:40:35 INC INFO: LARGE FIRE IN AREA

03:40:40 \*\* Event Location changed from [REDACTED] RICCARTON RD,UPPER RICCARTON,CHRISTCHURCH

03:40:40 CITY" to "265 RICCARTON RD,UPPER RICCARTON,CHRISTCHURCH CITY: @ANTONIO HALL" at:

03:40:40 05/11/21 03:40:40

03:40:41 .

03:40:43 INC INFO: BUILDING FIRE - TX 2ND ALARM

03:40:46 \*\* LOI search completed at 05/11/21 03:40:44

03:40:46 FIR2POL 2ND ALARM FIRE ANTONIO HALL

03:40:52 \*\* Event P048511970 of NZP/CR copied from F3352885 of NZFS/CA at: 05/11/21 03:40

03:40:52 :52

03:41:00 \*\* Alarm level updated to 2

03:41:00 \*\* Recommended unit WIGR257 for requirement PUMP (>5.3 km)

03:41:00 \*\* Recommended unit

03:41:00 CHRI2518 for requirement COMU (>5.4 km)

03:41:00 \*\* Recommended unit CHRI214 for require

03:41:00 ment PUMP (>5.2 km)

03:41:00 \*\* Recommended unit CHRI217 for requirement PUMP (>5.2 km)

03:41:00

03:41:05 PA Selcal used to Initiate Alerting. (WIGR257 at 3425 WIGRAM 193251)

03:41:06 PA Selcal used to Initiate Alerting. (CHRI2518 at 3425 WIGRAM 193251)

03:41:06 PA Selcal used to Initiate Alerting. (CHRI214 at 3421 CHRISTCHURCH 193211)

03:41:07 PA Selcal used to Initiate Alerting. (CHRI217 at 3421 CHRISTCHURCH 193211)

03:41:10 ALERTING\_COMPLETED WIGR257

03:41:11 ALERTING\_COMPLETED CHRI2518

03:41:14 ALERTING\_COMPLETED CHRI214

03:41:14 ALERTING\_COMPLETED CHRI217

03:41:31 VERBAL

03:41:31 Unit ILAM261 [ K99 : PROPERTY FIRE WELL INVOLVED] VERBAL

03:41:35 .

03:42:33 FIR2AMB JUST FYI AT THIS STAGE

03:42:39 Unit WIGR257 [ K1 : PROCEEDING TO INCIDENT]

03:43:16 INC INFO: BUILDING FIRE

03:43:56 Unit SPRE221 [ KP : PRIORITY MESSAGE]

03:44:18 Unit SPRE221 [ KP : PRIORITY MESSAGE] SSO [REDACTED] - MAKE AERIALS 1

03:44:26 Unit CHR1217 [ K1 : PROCEEDING TO INCIDENT]

03:44:29 INC INFO: BUILDING FIRE - TX 2ND ALARM - MK AERIALS X1

03:44:33 \*\* Requirement AERIAL added for alarm level 2

03:44:36 \*\* Recommended unit CHR1216 for requirement AERIAL (>3.7 km)

03:44:38 PA Selcal used to Initiate Alerting. (CHR1216 at 3422 SPREYDON 192221)

03:44:42 ALERTING\_COMPLETED CHR1216

03:44:57 .

03:45:22 Unit CHR1214 [ K1 : PROCEEDING TO INCIDENT]

03:45:25 .

03:45:28 Unit CHR12518 [ K1 : PROCEEDING TO INCIDENT]

03:45:55 INC INFO: BUILDING FIRE

03:46:08 INC INFO: BUILDING FIRE

03:46:20 Unit SPRE221 [ KP : PRIORITY MESSAGE]

03:46:39 .

03:46:47 Unit SPRE221 [ KP : PRIORITY MESSAGE] K11POLICE NEED TO CLOSE RICCARTON ROAD

03:46:54 Unit SPRE221 [ K11P : POLICE REQUIRED]

03:47:05 FIR2POL - POLICE REQ ON SCENE TO CLOSE RICCARTON ROAD

03:47:20 Unit SPRE221 [ K2 : IN ATTENDANCE AT INCIDENT]

03:47:23 \*

03:47:39 Unit CHR1216 [ K1 : PROCEEDING TO INCIDENT]

03:47:45 INC INFO:

03:48:05 Unit CHR12518 [ KC : UNIT CALLING]

03:48:18 POSSIBLY THREATENING UNITS [REDACTED] OF [REDACTED] WHARENUI ROAD

03:48:29 POSSIBLY THREATENING UNITS [REDACTED] OF [REDACTED] WHARENUI ROAD

03:49:14 Unit CHR12518 [ SITREP : ] SFP (WHARENUI ROAD RICCARTON ROAD)

03:49:28 INC INFO: BUILDING FIRE

03:49:42 INC INFO:

03:50:36 Unit ILAM261 [COMCEN COM : MESSAGE] CALL FROM NUMBER [REDACTED] WHARENUI ROAD STATING PO

03:50:36 SS THREATENING UNITS [REDACTED] )

03:50:37 Unit WIGR257 [ KP : PRIORITY MESSAGE]

03:51:34 Unit WIGR257 [ KP : PRIORITY MESSAGE] SSO [REDACTED] TX 3RD ALARM - HOSE LAYERS X1

03:51:43 INC INFO: BUILDING FIRE

03:51:47 INC INFO:

03:51:51 FIR2AMB-THIRD ALARM STRUCTURE FIRE  
03:51:53 Unit WIGR257 [ K2 : IN ATTENDANCE AT INCIDENT]  
03:51:58 INC INFO: BUILDING FIRE - TX 3RD ALARM - MK HL X1  
03:52:02 \*\* Event A00958176 of AMBO/S copied from F3352885 of NZFS/CA at: 05/11/21 03:52:  
03:52:02 02  
03:52:05 .  
03:52:06 [REDACTED] - AIRWAYS  
03:52:08 AMBO EVENT 0030-3-2021/11/05-FIR LINKED AT 05/11/2021 03:52:08  
03:52:22 FIR2AMB FIR2POL THIS IS NOW 3RD ALARM  
03:52:38 \*\* Alarm level updated to 3  
03:52:38 \*\* Recommended unit WOOL241 for requirement PUMP (>9.4 km)  
03:52:38 \*\* Recommended unit  
03:52:38 REDW231 for requirement PUMP (>7.3 km)  
03:52:38 \*\* No recommendation for requirement TTA  
03:52:38 BLE  
03:52:53 PA Selcal used to Initiate Alerting. (WOOL241 at 3424 WOOLSTON 193241)  
03:52:54 PA Selcal used to Initiate Alerting. (REDW231 at 3423 REDWOOD 193231)  
03:52:57 INC INFO: FIRE IN THE AREA  
03:53:07 Unit WOOL241 failed to contact via Selcal  
03:53:10 ALERTING\_COMPLETED REDW231  
03:53:13 ALERTING\_COMPLETED WOOL241  
03:53:21 INC INFO: FIRE IN THE AREA  
03:53:23 INC INFO: FIRE IN VICINITY  
03:53:44 INC INFO:  
03:54:08 Unit SPRE221 [ KC : UNIT CALLING]  
03:54:16 AIRWAYS CALLING IN TO CONFIRM WE ARE AWARE OF A FIRE. [REDACTED] WAS ON 13TH  
03:54:16 FLOOR OF A  
03:54:16 IRPORT LOOKING TOWARDS SUGARLOAF.  
03:54:18 \*\* Requirement HOSE LAYER added for alarm level 3  
03:54:20 Unit CHR1216 [ K2 : IN ATTENDANCE AT INCIDENT]  
03:54:25 \*\* Requirement HOSE LAYER removed for alarm level 3  
03:54:25 Unit WOOL241 [ K1 : PROCEEDING TO INCIDENT]  
03:54:34 \*\* PFA/CPN search completed  
03:54:37 PA Selcal used to Initiate Alerting. (REDW2312 at 3423 REDWOOD 193231)  
03:54:40 ALERTING\_COMPLETED REDW2312  
03:54:47 ADVISED THE RICCARTON FIRE WOULD BE IN THE LINE OF SIGHT TOWARDS  
03:55:12 SUGARLOAF  
03:55:12 \*\* Requirement AERIAL removed for alarm level 2  
03:55:15 Unit CHR12518 [ K2 : IN ATTENDANCE AT INCIDENT]  
03:55:19 .  
03:55:30 Unit WIGR257 [ SITREP : ] CHR1217 RESPONDING TO UNITS  
03:55:32 Unit CHR1217 [ K2 : IN ATTENDANCE AT INCIDENT]

03:55:34 FIR2AMB AFFIRM STILL FYI ONLY

03:55:39 \*\* Requirement PUMP added for alarm level 3

03:55:43 \*\* Requirement PUMP added for alarm level 3

03:55:45 Unit SPRE221 [ KC : UNIT CALLING]

03:55:47 Unit GMCANTE01 [ K1 : PROCEEDING TO INCIDENT]

03:55:50 \*\* Recommended unit ANZA271 for requirement PUMP (>10.3 km)  
\*\* Recommended unit

03:55:50 LINC411 for requirement PUMP (>14.4 km)

03:55:53 PA Selcal used to Initiate Alerting. (ANZA271 at 3427 ANZAC 193271)

03:55:53 Station Selcal used to Initiate Alerting. (LINC411 at 3441 LINCOLN 193411)

03:55:56 ALERTING\_COMPLETED LINC411

03:56:03 Unit CHRI214 [ K2 : IN ATTENDANCE AT INCIDENT]

03:56:08 .

03:56:10 Unit ANZA271 failed to contact via Selcal

03:56:12 Unit CHRI214 [ K2 : IN ATTENDANCE AT INCIDENT]

03:56:13 ALERTING\_COMPLETED ANZA271

03:56:53 .

03:57:18 Unit REDW231 [ K1 : PROCEEDING TO INCIDENT]

03:57:30 INC INFO: FIRE IN THE AREA - CALLING FROM PORT HILLS

03:57:47 Unit SPRE221 [ SITREP : ] SSO [REDACTED] - 1 TWO STOREY DWELLING WELL INVOLV - 1  
MON

03:57:47 ITOR IN USE - TACTICAL MODE EXPOSURE PROTECTION - K45 SSO [REDACTED]

03:57:49 REGN04EQUIP01 ( [REDACTED] ) AK PAGE

03:57:51 INC INFO: BUILDING FIRE

03:58:08 Unit CHRI214 [COMCEN COM : MESSAGE] YOU ARE NOW CONSIDERED AN AERIAL I  
HAVE ATTA

03:58:08 CHED ANOTHER PUMP (COPY)

03:58:57 Unit GMCANTE01 [ K1 : PROCEEDING TO INCIDENT]

03:59:07 Unit REDW231 [COMCEN COM : MESSAGE] DID YOU COPY MESSAGE TO UP LIFT HL  
(COPY)

03:59:11 INC INFO: FIRE IN THE AREA

03:59:14 Unit ANZA271 [ K1 : PROCEEDING TO INCIDENT]

03:59:29 .

03:59:37 Unit ANZA271 [ KC : UNIT CALLING]

03:59:47 .

04:00:35 .

04:00:37 Unit REDW2312 [ K1 : PROCEEDING TO INCIDENT]

04:00:43 INC INFO: BULIDING FIRE

04:00:48 Unit ANZA271 [ SITREP : ] DO YOU REQ US TO UPLIFT HL (NEG REDWOOD ARE)

04:01:19 COVERING UNIT LYTT291 DISPATCHED TO STATION CHRISTCHURCH AT 05/11/21  
04:01:18 >>

04:01:33 Unit LINC411 [ K1 : PROCEEDING TO INCIDENT]

04:02:13 .

04:02:31 .

04:05:15 .

04:06:48 Unit WOOL241 [ K2 : IN ATTENDANCE AT INCIDENT]

04:09:34 COVERING UNIT LYTT292 DISPATCHED TO STATION CHRISTCHURCH AT 05/11/21  
04:09:33 >>

04:12:11 Unit REDW231 [ K2 : IN ATTENDANCE AT INCIDENT]

04:12:39 Unit GMCANTE01 [ K2 : IN ATTENDANCE AT INCIDENT]

04:13:51 Unit LINC411 [ KC : UNIT CALLING]

04:13:55 Unit ANZA271 [ K2 : IN ATTENDANCE AT INCIDENT]

04:14:33 Unit LINC411 [ SITREP : ] SFP (WHARENUI ROAD AND RICCARTON ROAD)

04:18:04 Unit LINC411 [ K2 : IN ATTENDANCE AT INCIDENT]

04:18:21 \*

04:19:44 Unit CHRI2518 [ KC : UNIT CALLING]

04:20:30 Unit CHRI2518 [ K44 : COMMAND OR CONTROL POINT ESTABLISHED (STATE OIC AND  
LOCATI  
ON)] ANTONIO COMMAND SET UP ON RICCARTON ROAD

04:21:06 \*

04:21:20 Unit CHRI2518 [ KC : UNIT CALLING]

04:21:48 Unit CHRI2518 [ K32 : ON RADIO TEST - HOW DO YOU RECEIVE] K33-5

04:21:56 \*

04:22:50 Alarm Timer Extended: 0

04:24:33 Unit CHRI2518 [ KC : UNIT CALLING]

04:24:55 Unit CHRI2518 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] GM  
██████████

04:26:51 Unit CHRI2518 [ SITREP : ] 1 60 BY 20 VACANT BUILDING FULLY INVOLV IN FIRE - ATW

04:26:51 W 3 GROUND MONITORS 1 AERIAL CARRYING OUT EXTENSIVE EXTERNAL ATTACK  
AND EXPOSURE  
PROTECTION

04:26:51

04:29:04 Unit CHRI2518 [COMCEN COM : MESSAGE] IS THERE ANY ASBESTOS EXPOSURE (U/K  
AT THIS

04:29:04 STAGE BUT WILL TREAT AS IS AND UPDATE YOU WITH NOTIFICATIONS ON THE  
WAY)

04:29:07 \*

04:31:33 Alarm Timer Extended: 0

04:31:48 Unit REDW2312 [ K2 : IN ATTENDANCE AT INCIDENT]

04:33:42 Alarm Timer Extended: 0

04:35:11 Alarm Timer Extended: 0

04:36:20 Alarm Timer Extended: 0

04:36:21 Alarm Timer Extended: 0

04:48:00 Alarm Timer Extended: 0

04:54:10 Unit CHRI2518 [ SITREP : ] ADVISE WHAT COVER MOVES WE HAVE (LYTT292 ARE AT  
CITY

04:54:10 AND KAIA407 ARE AT WIGRAM - ANZAC VOLLYS HAVE NOT BEEN T/O YET) COPY



04:54:22 \*

05:00:21 Alarm Timer Extended: 0

05:00:22 Alarm Timer Extended: 0

05:00:23 Alarm Timer Extended: 0

05:00:24 Alarm Timer Extended: 0

05:01:47 Alarm Timer Extended: 0

05:14:00 Alarm Timer Extended: 0

05:21:58 FROM ANTONIO COMMAND - STARTING TO RELEASE UNIT FROM SCENE AS FOLLOWS:

05:22:18 REDW231 TO WIGRAM STATION (TO RELIEVE KAIAPOI)

05:22:34 WOOL241 TO CITY STATION (TO RELIEVE LYTTTELTON)

05:22:44 ANZA271 BACK TO ANZAC

05:22:46 .

05:23:16 Unit CHRI2518 [ KC : UNIT CALLING]

05:24:00 Unit REDW231 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

05:24:11 Unit CHRI2518 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SSO [REDACTED]

05:24:11 - OPERATIONS SCALLING DOWN - STILL DEFFENSIVE EXTERNAL ONLY - EVACUATED PROPERT

05:24:11 IES ALLOWED BACK IN

05:25:59 Unit WOOL241 [ KC : UNIT CALLING]

05:26:23 Unit WOOL241 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

05:26:24 Unit WOOL241 [ SITREP : ] RE DIRECTED TO COVER CITY STATION

05:30:14 Unit GMCANTE01 [ K6 : ON PAGER (STATE LOCATION)]

05:30:20 Unit ANZA271 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

05:34:05 Unit LINC411 [ K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]

05:51:56 Unit WIGR257 [ KC : UNIT CALLING]

05:52:27 Unit ILAM261 [ K2 : IN ATTENDANCE AT INCIDENT]

05:52:29 Unit WIGR257 [ SITREP : ] LEAVING SCENE K10

05:52:36 Unit WIGR257 [ K10 : RE-COMMISSIONING APPLIANCE]

05:58:31 Unit FICANTE01 [ K38 : ASSOCIATE THIS APPLIANCE TO EVENT (STATE EVENT ADDRESS)]

05:58:34 Unit FICANTE01 [ K1 : PROCEEDING TO INCIDENT]

06:07:48 Unit CHRI2518 [ KC : UNIT CALLING]

06:09:32 Unit CHRI2518 [ SITREP : ] ANTONIO COMMAND CLOSING DOWN SSO [REDACTED] STILL ION CHA

06:09:32 RGE OF OPERATIONS ALL COMMS THRU ILAM261

06:13:53 Unit CHRI214 [ KC : UNIT CALLING]

06:14:17 Unit CHRI214 [ K10 : RE-COMMISSIONING APPLIANCE]

06:24:03 Unit CHRI2518 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

06:26:48 Unit SPRE221 [ K2 : IN ATTENDANCE AT INCIDENT]

06:39:14 Alarm Timer Extended: 0

06:39:16 INC INFO: CALLER ADVISES [REDACTED] HAS ASHES IN [REDACTED] PROPERTY

06:39:53 \*\*

06:40:53 [REDACTED] CCC TRAAFC MANAGEMENT - [REDACTED] - LOOKING FOR THE PLAN FOR THE DAY

06:40:53 REGARDING TRAFFIC CLOSURES

06:40:55 \*\*

06:42:01 Unit ILAM261 [ KC : UNIT CALLING]

06:43:52 Unit ILAM261 [COMCEN COM : MESSAGE] CAN WE GET AN INDICATION OF THE ROAD CLOSURE

06:43:52 S AND HOW MUCH LONGER THEY WILL BE REQUIRED? (ST BY WILL CHECK)

06:47:32 Unit FICANTE01 [ K2 : IN ATTENDANCE AT INCIDENT]

06:53:43 Unit SPRE221 [ KC : UNIT CALLING]

06:55:21 Unit SPRE221 [ SITREP : ] SSO [REDACTED] WE ARE STILL DAMPENING DOWN THE ROAD WILL B

06:55:21 E OPEN IN APPROX 10 MINS HOWEVER WE MAY NEED TO CLOSE IT AGAIN IF WE NEED WATER

06:55:51 Unit SPRE221 [ KC : UNIT CALLING]

06:56:19 Unit SPRE221 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SO [REDACTED]

06:56:26 Unit SPRE221 [ K10 : RE-COMMISSIONING APPLIANCE]

07:21:00 Unit DISTR7004 [ K1 : PROCEEDING TO INCIDENT]

07:21:59 Unit DISTR7004 [ SITREP : ] RESPONDING WITH ABOLUTIONS TRAILER

07:22:36 Unit DISTR7004 [ K1 : PROCEEDING TO INCIDENT]

07:29:15 Unit ILAM261 [ K10 : RE-COMMISSIONING APPLIANCE]

07:41:31 Alarm Timer Extended: 0

07:49:25 Unit DISTR7004 [ K2 : IN ATTENDANCE AT INCIDENT]

07:57:32 Unit DISTR7004 [ K6 : ON PAGER (STATE LOCATION)]

08:27:58 Unit ILAM261 [ K2 : IN ATTENDANCE AT INCIDENT]

08:28:02 Unit REDW2312 [ K7 : AT NORMAL STATION]

09:01:21 Unit FICANTE07 [ K2 : IN ATTENDANCE AT INCIDENT]

09:31:16 Alarm Timer Extended: 0

09:49:25 Alarm Timer Extended: 0

10:11:24 Unit CHR|217 [ KC : UNIT CALLING]

10:11:46 Unit CHR|217 [ K10 : RE-COMMISSIONING APPLIANCE]

10:29:51 Unit ILAM261 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SSO [REDACTED]

10:31:40 Unit SPRE221 [ K2 : IN ATTENDANCE AT INCIDENT]

10:32:53 Unit ILAM261 [ SITREP : ] SSO [REDACTED] REPOSITIONING AERIAL APPLIANCE CONTINUING T

10:32:53 O DAMPEN DOWN HOTSPOTS

11:28:56 Alarm Timer Extended: 0

12:47:52 Unit ILAM261 [ KC : UNIT CALLING]

12:48:54 Unit ILAM261 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)] SO [REDACTED]

12:49:16 Unit ILAM261 [ K10 : RE-COMMISSIONING APPLIANCE]

13:28:41 Unit GMCANTE01 [ K2 : IN ATTENDANCE AT INCIDENT]

13:28:45 Unit FICANTE06 [ K2 : IN ATTENDANCE AT INCIDENT]

13:29:22 Unit FICANTE06 [ SITREP : ] HANDLING MEDIA FOR THIS INCIDENT

13:29:38 Unit GMCANTE01 [ SITREP : ] MAKE ANOTHER PUMP, ROAD SPEED

13:34:26 Unit GMCANTE01 [ SITREP : ] GTWW EXCAVATOR OPENING UP HOT SPOTS.  
AWAITING ARRIVA

13:34:26 L OF PUMP

13:36:56 PA Selcal used to Initiate Alerting. (CHR1214 at 3421 CHRISTCHURCH 193211)

13:36:59 ALERTING\_COMPLETED CHR1214

13:37:33 Unit CHR1214 [ K1 : PROCEEDING TO INCIDENT]

13:38:48 Unit FICANTE06 [ SITREP : ] CHR1214 TO ENTER OFF WESTERN END GATE, ILAM ROAD  
END

13:53:11 Unit GMCANTE01 [ SITREP : ] MANAGER OF THE SITE AND CCC BUILDING TEAM.  
MEETING O

13:53:11 N SITE IN 30 MINS.

13:55:08 Unit FICANTE06 [ K6 : ON PAGER (STATE LOCATION)]

13:56:05 Unit FICANTE07 [ K6 : ON PAGER (STATE LOCATION)]

13:56:22 Unit FICANTE01 [ KC : UNIT CALLING]

13:56:51 Unit FICANTE01 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

13:57:35 Unit FICANTE01 [ SITREP : ] SFI [REDACTED] INVESTIGATION COMPLETE CREWS  
DAMPENING DO

13:57:35 WN HOTSPOT

14:05:31 Unit CHR1214 [ K55 : SPECIAL SERVICE INCIDENT]

14:08:53 Alarm Timer Extended: 0

14:13:09 Unit GMCANTE01 [ K45 : COMMAND RESPONSIBILITY CHANGED TO (STATE NAME)]  
SSO [REDACTED]

14:13:09 [REDACTED]

14:14:37 Unit CHR1216 [ K7 AT NORMAL STATION]

14:15:51 Unit SPRE221 [ K7 AT NORMAL STATION]

14:18:35 \*\* Cross Referenced to Event # F3352888 at: 05/11/21 14:18:35

14:46:15 Alarm Timer Extended: 0

15:29:50 Unit CHR1214 [ KC : UNIT CALLING]

15:30:28 Unit CHR1214 [ K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM SITREP]

15:30:31 Unit CHR1214 [ K4 : ON RT INSIDE NORMAL TURNOUT AREA]

15:30:53 Unit GMCANTE01 [ K6 : ON PAGER (STATE LOCATION)]

15:33:12 FROM FI [REDACTED] .... IF YOU CAN GET THE NEAREST TRUCK TO RESPOND ANTONIO  
AHLL TO

15:33:12 UPLIFT APPROX 6 LENGTHS OF HOSE

15:33:18 .

15:33:26 CHR1214 ADV AND THEY WILL RETURN TO UPLIFT HOSE

15:33:27 .

15:35:18 \*\*

15:36:05 CHR1214 ADVISE THEY HAVE NOWHERE SAFE TO STOW 6 LENGTHS OF 90 HOSE SO  
WILL LIAIS

15:36:05	E WITH WIRGRAM STATION AND GET THEM TO UPLIFT THE HOSE IN THE VAN
15:36:06	**
17:17:16	UNIT FICANTE07 RESPONSE TIME [NULL] ADJUSTED TO 20211105090120ND AT 05/11/2021 1
17:17:16	UNIT FICANTE06 RESPONSE TIME [NULL] ADJUSTED TO 20211105132844ND AT 05/11/2021 1
17:17:22	UNIT 'GMCANTE01' ALERT TIME '[NULL]' ADJUSTED TO '20211105035546ND' AT '05/11/20
17:17:22	UNIT 'FICANTE01' ALERT TIME '[NULL]' ADJUSTED TO '20211105055833ND' AT '05/11/20
17:17:23	UNIT 'DISTR7004' ALERT TIME '[NULL]' ADJUSTED TO '20211105072059ND' AT '05/11/20
17:17:43	UNIT FICANTE07 RESPONSE TIME [NULL] ADJUSTED TO 20211105090120ND AT 05/11/2021 1
17:17:44	UNIT FICANTE06 RESPONSE TIME [NULL] ADJUSTED TO 20211105132844ND AT 05/11/2021 1
17:17:51	UNIT 'GMCANTE01' ALERT TIME '[NULL]' ADJUSTED TO '20211105035546ND' AT '05/11/20
17:17:51	UNIT 'FICANTE01' ALERT TIME '[NULL]' ADJUSTED TO '20211105055833ND' AT '05/11/20
17:17:52	UNIT 'DISTR7004' ALERT TIME '[NULL]' ADJUSTED TO '20211105072059ND' AT '05/11/20
17:17:52	UNIT 'FICANTE07' ALERT TIME '[NULL]' ADJUSTED TO '20211105090119ND' AT '05/11/20
17:17:53	UNIT 'FICANTE06' ALERT TIME '[NULL]' ADJUSTED TO '20211105132843ND' AT '05/11/20
17:17:53	** Assigned Result Code: STRU, Detailed Event Type: 1100

## Incident

**CAD Number** F3352885  
**Incident Reporter** [REDACTED]  
**Incident Controller**  
**Distance Travelled (km)**  
**Delay In Receiving Call**

## Property Details

**Occupant** [REDACTED]  
**Building Owner** Owner occupied  
**General Property Use** Boarding/Halfwayhouse, Dorm, Homestay/Backpacker  
**Special Property Use** Boarding, Half-way house, Dormitory - Other  
**Purpose Group**

## Actions

**Persons Reported Trapped**  
**Evacuation Status** Not occupied at time of incident  
**Action Prior 1**  
**Action Prior 2**

**Action Taken** Extinguishment only: Includes isolating fuel/power

### Civilians

<b>Civilians Rescued</b>	0
<b>Civilians Extricated</b>	0
<b>Civilians Assisted</b>	0
<b>Civilians Evacuated</b>	0

### Origin

**Location** Living area - not classified above  
**Level** Ground level

### Equipment Used

Quantity	Equipment
4	Low pressure delivery
2	Aerial Ladder/Platform

### Equipment Involved

Equipment Involved

**Year**

**Make**

**Model**

### Fire

**Arrival Condition** Totally involved fire  
**Heat Source** Cigarette, Cigar or Smoking materials  
**Termination Stage**  
**First Object Ignited**  
**First Object Material**  
**Second Object Ignited**  
**Second Object Material**  
**Indicated Cause** Suspicious  
**Certainty of Cause** High  
**Age of Person** Persons: [REDACTED]  
**Ethnicity** Unknown  
**Gender** [REDACTED]  
**FAIP Service Offered** Unknown

**Comments**

11/8/2021 1:34:30 PM

Reporter Comments

No internal examination was undertaken due to extent of damage to building.  
No power onto property.  
Fire works excluded due to time of day and water in guttering.

[REDACTED]  
Fire Observed at 3:15am on CCTV, [REDACTED]  
Fire classified as suspicious.

[REDACTED]

Released Under the Official Information Act