

3 July 2023

Frank

Via Email: fyi-request-23079-7bed71c5@requests.fyi.org.nz

Dear Frank

We respond to your request for Official Information received by Council by way of Transfer from Environment Canterbury on 22 June 2022 for information on this Council’s seismic building rating for buildings intended/likely to be used as the ECC or EOC following an event. In particular you requested the building/s current %nbs at IL4, the date of the last assessment and the type of the seismic assessment completed.

The information you have requested is as follows:

Currently the EOC following a seismic event for Selwyn is the Council Headquarters (SDC HQ) located at 2 Norman Kirk Drive, Rolleston. The building was originally built in 2006 and underwent seismic strengthening along with an executive pod addition in 2019. The table below details the %NBS for the various areas within the building following the building works carried out in 2019.

Building Name	Location	BC/CS Ref #'s	Occupancy Limit	Design IL	%NBS	Status / Information Source
SDC HQ	2 Norman Kirk Drive, Rolleston	BC061302 BC190951 R770264	525	IL4 - Executive pod (EOC support) IL4 – Council Chambers, Customer services area and generator room (EOC) IL2 – Offices/remainder of building	100% 70% 45%	SDC EOC IL and NBS details obtained from structural calculations submitted for strengthening works in 2019 ref. BC190951 and Beca engineering assessment dated 6 March 2018

Yours sincerely



Tim Harris

Interim CHIEF EXECUTIVE OFFICER