

SMS Incident Report


02/11/2023 14:51:48

Summary

CAD Number F3842372 **Status** Closed
Station Auckland City Station
Incident Started 22/10/2023 04:33:50 **Incident Ended** 22/10/2023 05:27:52
Incident Type 7199: False Alarm: Undetermined K-46-7
Common Name 16-18 BERESFORD SQUARE
Address 16-18 Beresford Square Auckland Central
Alarm Method Automatic PFA Call **Alarm Level** 1
PFA Number 117238
Zone 142011
Map Grid E 1756742 **Map Grid N** 5919541
First Caller **First Caller Contact**
Incident Closed 22/10/2023 05:27:52
Report Completed 14:46, Thur 02 Nov 2023 by [REDACTED]

Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
AUCK207	PR	04:34:10 22 Oct 2023	04:36:00 22 Oct 2023	04:37:44 22 Oct 2023	04:55:07 22 Oct 2023
AUCK205	HP	04:34:10 22 Oct 2023	04:35:56 22 Oct 2023	04:37:48 22 Oct 2023	04:47:12 22 Oct 2023
PARN251	P1	04:34:10 22 Oct 2023	04:36:24 22 Oct 2023	04:37:57 22 Oct 2023	04:51:30 22 Oct 2023
GREY261	P1	04:34:13 22 Oct 2023	04:36:09 22 Oct 2023	04:38:59 22 Oct 2023	04:48:05 22 Oct 2023



Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
AUCK207	00:00:20	00:03:34	00:03:54	00:21:17

AUCK205	00:00:20	00:03:38	00:03:58	00:13:22
PARN251	00:00:20	00:03:47	00:04:07	00:17:40
GREY261	00:00:23	00:04:46	00:05:09	00:14:15

Message Log

Time	Message
04:33:51	AL: 117238 04:33:50 INITIAL - ALARM
04:33:51	PANEL: DR FLOPPY COMPUTERS AT #16 BERESFORD SQUARE
04:33:51	** LOI search completed at 22/10/23 04:33:51
04:34:02	** Recommended unit AUCK205 for requirement AUCK205 (>0.1 km)
04:34:02	** Recommended un it AUCK207 for requirement PUMP (>0.1 km)
04:34:02	** Recommended unit PARN251 for requi rement PUMP (>0.1 km)
04:34:02	** Recommended unit GREY261 for requirement PUMP (>1.9 km)
04:34:05	PA Selcal used to Initiate Alerting. (AUCK205 at 1420 AUCKLAND CITY 182201)
04:34:05	PA Selcal used to Initiate Alerting. (AUCK207 at 1420 AUCKLAND CITY 182201)
04:34:06	PA Selcal used to Initiate Alerting. (PARN251 at 1420 AUCKLAND CITY 182201)
04:34:06	PA Selcal used to Initiate Alerting. (GREY261 at 1426 GREY LYNN 182261)
04:34:10	ALERTING_COMPLETED AUCK205
04:34:10	ALERTING_COMPLETED AUCK207
04:34:10	ALERTING_COMPLETED PARN251
04:34:13	ALERTING_COMPLETED GREY261
04:35:57	Unit AUCK205 [K1 : PROCEEDING TO INCIDENT]
04:36:00	Unit AUCK207 [K1 : PROCEEDING TO INCIDENT]
04:36:09	Unit GREY261 [K1 : PROCEEDING TO INCIDENT]
04:36:24	Unit PARN251 [K1 : PROCEEDING TO INCIDENT]
04:37:44	Unit AUCK207 [K77 : NOTHING SHOWING]
04:37:48	Unit AUCK205 [K2 : IN ATTENDANCE AT INCIDENT]
04:37:57	Unit PARN251 [K2 : IN ATTENDANCE AT INCIDENT]
04:38:59	Unit GREY261 [K2 : IN ATTENDANCE AT INCIDENT]
04:40:02	Unit AUCK207 [KC : UNIT CALLING]
04:40:54	Unit AUCK207 [COMCEN COM : MESSAGE] FIRECOM CALLS VIA RT X4 - NIL RESPONSE
04:42:12	Unit AUCK207 [SITREP :] SSO ████████ - PS FIRE LEVEL 1 MAZZANINE
04:47:12	Unit AUCK205 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
04:48:06	Unit GREY261 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
04:51:31	Unit PARN251 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
04:54:26	Unit AUCK207 [KC : UNIT CALLING]

04:55:07	Unit AUCK207 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
04:55:10	Unit AUCK207 [STOP : MESSAGE] SMOKE DETECTOR ACTIVATION IN GLORY HOLE ROOM
05:27:51	** Assigned Result Code: STRU, Detailed Event Type: 7100

Incident

CAD Number F3842372

Incident Reporter [REDACTED]

Incident Controller

Distance Travelled (km)

Delay In Receiving Call

False Alarm

False Alarm Type Smoke detector

Good Intent Type Other | Unable to classify

Additional comment Smoke detector activated in upstairs/ mezzanine room.

Property Details

Occupant

Building Owner

General Property Use Recreational, Assembly - not classified above

Special Property Use Recreation places: Variable use - Other

Purpose Group

Actions

Persons Reported

Trapped

Evacuation Status

Action Prior 1

Action Prior 2

Action Taken Investigation only (Fire related)

Civilians

Civilians Rescued 0

Civilians Extricated 0

Civilians Assisted 0

Civilians Evacuated 0

Origin

Location

Level

Equipment Used

Quantity	Equipment
0	No equipment used

Equipment Involved

Equipment Involved

Year

Make

Model

Comments

11/2/2023 2:46:21 PM

Reporter Comments

On arrival, all people evacuated from building. Approached by Building Warden who stated that alarm could have been caused by people using poppers. Unable to determine specific cause of activation.

