

Fire and Emergency New Zealand Incident Report

CADNumber F128045 **Start Date Time** 05 April 2008 16:03:43

Incident Details

Type: STRU **1st Caller:** SIGNATURE SECURITY SYSTEMS LTD (9(2)(a))

Method: 111

PFA:

Result: 1100: STRUCTURE FIRE (STRU)

Location: 30 DEVINE RD, TAMAHERE, WAIKATO DISTRICT **NZTM:** E 1807284
N 5810710


Common Name:

Zone: 164150 **Station:** 1641 HAMILTON

Incident Info: AT ICEPAK COOLSTORE PRIV MON

Incident History

		Elapsed Time (hh:mm:ss)
Created:	16:03:43 05 Apr 2008	
Confirmed:	16:04:16 05 Apr 2008	00:00:33
Alerted:	16:04:44 05 Apr 2008	00:01:01
1st Response:	16:05:47 05 Apr 2008	00:02:04
1st Arrival:	16:14:55 05 Apr 2008	00:11:12
2nd Arrival:	16:15:32 05 Apr 2008	00:11:49
3rd Arrival:	16:41:06 05 Apr 2008	00:37:23
Stop:		
Closed:	00:05:01 13 Apr 2008	17:01:18



Responses

Alarm Level	Call Sign	Dispatched		Response Time	Arrival Time	Departed	
		Day	Time			Day	Time
5	HAMI412	05	16:04:44	16:06:28	16:14:55	06	09:56:19
5	HAMI411	05	16:04:44	16:05:47	16:15:32	07	18:18:03
5	PUKE431	05	16:31:20	16:39:39	16:41:06	06	01:05:41
5	CHAR427	05	16:31:23	16:32:20	16:42:48	07	16:29:37
5	CAMB4411	05	16:31:17	16:35:50	16:46:51	10	05:51:55
5	HAMILTON1	05	16:36:58	16:37:51	16:46:58	05	20:38:02
5	BAYW3	05	16:39:17	16:58:20	16:58:32	06	01:12:33

The information contained in this report is subject to the provisions of the Official Information Act 1982 and Privacy Act 1993. Neither the information nor the report should be released to any person outside Fire and Emergency New Zealand without prior approval. Some message timestamps may differ to actual times in multi-agency incidents. Police/Ambulance messages may have been excluded for privacy. Communication Centres can supply these if essential.

5	HAMI4116	05	16:53:19	16:54:39	17:03:28	12	18:05:14
5	CHAR4226	05	16:33:32	16:54:08	17:08:25	10	18:15:28
5	HAMIFSO3	05	16:45:23	16:45:51	17:24:11	06	18:21:01
5	TEAW451	05	16:51:30	16:54:58	17:24:13	06	21:33:18
5	HAMI415	05	17:11:19	17:13:19	17:24:56	09	13:42:31
5	CAMB447	05	17:12:02	17:25:01	17:26:01	05	19:41:24
5	MORR3611	05	16:58:13	17:01:13	17:26:03	10	17:42:31
5	MORR361	05	17:10:46	17:13:16	17:33:00	06	22:52:10
5	HUNT3211	05	16:58:16	17:01:49	17:36:20	10	14:43:42
5	MORR367	05	17:12:05	17:16:31	17:37:15	05	23:21:37
5	MATA3811	05	16:58:47	17:03:06	17:37:30	06	22:34:36
5	ROTO8116	05	16:32:32	16:35:42	17:37:59	05	21:39:22
5	OTOR4611	05	16:58:22	17:06:05	17:41:18	10	17:33:22
5	TEAW4511	05	16:58:11	17:00:01	17:45:59	09	22:21:01
5	TEAR3711	05	17:05:09	17:10:53	17:50:59	06	04:41:34
5	HAMI4112	05	16:33:31	17:38:11	17:51:09	06	09:30:59
5	VSOWAIKATO	05	16:58:12	17:03:13	18:00:44	10	19:05:38
5	CAMB441	05	16:32:30	16:34:02	18:11:04	06	23:45:49
5	NORTHCOM2	05	17:31:57	17:32:57	18:19:12	05	21:02:43
5	HAMI6819	05	17:32:50	17:33:50	18:28:16	06	06:08:30
5	AUCKHSA1	05	17:07:22	17:11:16	18:36:01	06	16:05:33
5	VSOWESTBOP	05	18:07:06	18:29:48	18:42:22	08	21:09:36
5	PIRO5876	05	18:17:34	18:20:24	18:53:01	06	02:27:55
5	HAMILTON2	05	16:37:07	16:38:07	19:01:20	06	00:58:17
5	HAMI413	05	16:32:34	18:49:44	19:02:56	06	05:56:58
5	BAYW1	05	17:41:08	17:42:08	19:03:29	06	07:37:18
5	BAYW2	05	17:31:26	18:34:07	19:06:52	07	01:58:50
5	PAER5111	05	18:23:51	18:26:33	19:16:35	06	02:31:40
5	VSOSTHWAKO	05	18:56:59	18:24:16	19:25:44	06	01:12:13
5	GREE751	05	19:04:59	19:06:42	20:08:14	07	20:23:02
5	GREE752	05	19:04:59	19:13:01	20:16:52	06	00:47:46
5	AUCKFPOL8	05	18:19:04	18:35:29	20:25:06	06	02:02:14
5	GREE7510	05	19:04:59	19:15:38	20:38:54	06	02:28:14
5	AUCKFPOL5	05	19:35:33	19:36:33	21:35:08	06	01:03:16
5	AUCKFPOL6	05	20:13:54	19:43:46	21:39:56	06	01:39:15
5	TAUPO1	05	21:16:56	21:26:41	23:07:58	10	17:55:09
5	ROTORUA2	05	22:10:47	22:11:47	23:11:21	07	17:01:17
5	CENTAUCK1	05	22:28:05	22:29:05	23:33:26	06	08:33:35
5	HAMIFTO1	05	21:57:24	22:01:23	00:00:10	08	12:05:19
5	TAURANGA2	06	06:42:48	07:07:56	07:47:01	08	14:42:25
5	NGON822	06	07:01:26	07:02:26	08:02:07	06	18:50:48
5	ROTO8126	06	06:58:00	07:09:05	08:04:44	07	00:59:15
5	ROTO814	10	10:42:57	07:18:03	08:33:17	12	18:18:28
5	AUCK2015	06	07:40:19	07:54:01	09:36:21	06	22:24:02
5	OTOR4629	06	09:58:54	10:18:08	10:44:51	06	18:49:29
5	HAMIFSO1	06	13:43:19	13:43:23	13:47:23	07	00:11:08

The information contained in this report is subject to the provisions of the Official Information Act 1982 and Privacy Act 1993. Neither the information nor the report should be released to any person outside Fire and Emergency New Zealand without prior approval. Some message timestamps may differ to actual times in multi-agency incidents. Police/Ambulance messages may have been excluded for privacy. Communication Centres can supply these if essential.

5	ROTO8129	06	12:25:09	12:26:09	13:52:11	06	14:22:14
5	TAUPFSO1	06	17:13:49	15:32:57	17:18:27	07	07:32:01
5	TOKO8729	06	21:53:10	21:54:10	23:30:42	07	00:33:32
5	TAUP212	06	22:27:33	22:28:33	00:11:29	08	09:07:37
5	TAURANGA1	06	22:42:04	22:42:13	00:13:42	07	11:51:52
5	VSOTHAMVAL	07	05:45:20	05:46:00	09:49:08	08	08:26:26
5	VSOMATAPIA	07	08:22:08	08:22:16	09:55:20	09	17:40:35
5	BAYW412	07	08:08:52	08:09:41	10:11:01	07	17:33:03
5	BAYW410	07	17:32:36	17:32:41	17:32:52	08	07:41:05
5	HUNT3226	07	17:53:19	17:57:13	18:42:25	08	00:58:22
5	ROTO812	09	08:14:58	08:16:58	09:41:52	09	17:03:07
5	PAPA387	10	10:29:09	10:34:26	12:14:28	12	19:51:56
5	MANUKAU2	10	10:29:10	10:33:43	12:53:19	10	21:38:34
5	PAPA3811	10	10:29:10	10:33:35	13:20:23	12	19:59:21
5	TAURFSO1	10	08:11:23	08:54:16	17:55:53	12	18:11:13
5	GREE7520	10	09:54:43	09:55:43	17:56:04	10	18:56:59
5	ONEH221	10	19:05:35	19:06:25	21:46:14	12	12:24:08
5	PAPA3429	10	19:05:36	20:01:53	21:46:15	12	20:02:31
5	AUCKFSO1	12	06:45:31			12	06:50:25
5	MATA382	05	18:28:28	18:29:13		05	18:56:52
5	NGAR337	08	07:02:15			08	07:02:25
5	ROTO811	05	16:35:40	16:36:40		05	16:41:56

Cover Moves

Call Sign	Start Time	End Time
MATA381	05 18:25:48	
PUKE431	05 16:08:30	
TEAR371	05 18:25:22	

Notifications

Date	Party Notified
16:32:52	AMBOS
16:34:05	HAMILTON 2ND ALARM XTED PAGE SENT OUT
16:35:37	POLICE
16:35:58	RFO WAIKATO DC
16:36:07	AMB 9(2)(a) 2 AMB RESPONDING POSSIBLY MORE
16:36:30	AMB OF 9(2)(a)
16:37:17	CFO/DCFO Out of Scope RE 9(2)(a)
16:37:22	BAY WAIKATO MANAGEMENT
16:37:37	HAMILTON GREEN WATCH PAGES
16:41:20	HSO WAIKATO
16:42:55	FM Out of Scope ROTORUA 811 RETURNING TO STATION ROTO8116 TO CONTINUE AS COMMAND
16:43:08	AMBULANCE

16:44:05 AMBULANCE - 1 OFFICER ON SCENE, ON AIRPORT RD FOR 1ST VEHICLE
16:44:23 ROTORUA CO GREEN PAGED
16:45:02 Out of Scope ACKS PAGE IS EN ROUTE
16:45:59 CFO/DCFO Out of Scope RE 9(2)(a)
16:46:08 BAY WAIKATO MANAGEMENT GROUP UPDATE
16:48:36 VSO THAMES VALLEY ACK PAGER
16:49:34 POLICE
16:51:21 TE AWAMUTU SIREN PUT DOWN
16:51:41 DELAY IN ENETERING 3RD ALARM PAGE DUE TO INCOMING
16:51:43 WAIPA NETWORKS
16:55:10 BAYW1 ACKS PAGE BAD RECEPTION DETAILS PASSED
16:55:54 KEYHOLDER ETA WITHIN 20 MINS
16:56:30 WAIPA NETWORKS - HAVE HAD NO REPLY
16:57:51 VSO WAIKATO RESPONDING
16:57:55 HAMILTON CO BROWN
16:58:25 HAMILTON CO BLUE
17:05:05 HSA AUCKLAND
17:07:47 WAIPA NETWORKS
17:08:16 PROTECH THEY ARE RESPONDING
17:09:35 TXT 5TH ALARM
17:12:16 HAMILTON 3RD ALARM AND ABOVE FOR 5TH ALARM
17:12:28 NATIONAL COMMANDERS GROUP
17:13:14 WAIPA NETWORKS FAULTMAN RESPONDING ETA 20 MINS
17:17:12 Out of Scope NATIONAL COMMANDERS GROUP ACKS PAGE
17:27:59 SO Out of Scope ADVISES 2 PUMPS AT HOPUHOPU SOMEONE FROM HUNTLY CAN PICK 1 UP HES AT
17:28:04 CHARTWELL IF REQD
17:36:57 NATIONAL COMMANDERS HAS BEEN BRIEFED RE Out of Scope
17:42:12 Out of Scope ACK PAGE...CENTRAL COMM
17:46:14 NAT COMMANDERS GROUP WILL ADVISE REGARDING PRESS RELEASES
17:55:22 AUCKLAND CANTEEN EN ROUTE ETA 90 MINS
18:00:53 RCC REQUEST UPDATES WHEN NEEDED
18:01:58 PHONE NUMBER FOR COMMAND UNIT PH 9(2)(a)
18:04:58 SITREP PASSED TO NATIONAL COMMANDERS GROUP
18:07:14 PAGED VSO WESTERN BOP TO ATTEND
18:25:29 CONTACT FONTERA ON 07 8493969 WILL RING BACK WITH ETAS
18:25:34 FP AUCKLAND RESPONDING VERY SHORTLY
18:25:51 FP AUCKLAND OFFERED ABLUTIONS TRAILER ALSO
18:30:14 FP AUCKLAND PAGED RE ABLUTIONS TRAILER
18:37:23 OSH Out of Scope RESPONDING
18:46:03 9(2)(a) IS AVAILABEL FOR USE WITH SWIMMING POOL AND LARGE BORE THAT BE UTILISED
18:50:03 FROM DCFO HAMI413 TO BE COMMITTED TO TAMAHERE
18:54:44 FONTERA RESPONDING FROM TE RAPA AND WAITOA ETA FOR TE RAPA APPROX 30 MINS
19:05:37 PUBLIC MEMBER FROM 9(2)(a) HAS OFFERED THE WATER FROM SWIMMING POOL
19:07:56 FROM HAMILTON CONTACT THEM ON 9(2)(a) ABOUT FOOD
19:12:23 MAN POWER OFFERED FROM WHANGAMATA FIRE 9(2)(a)

19:13:51 HAMILTON TOWN AND COUNTRY MOTEL RANG TO OFFER THEIR BORE - THEY HAVE
19:25:33 HAMILTON CITY COUNCIL - RESPONDING NOW
19:25:54 9(2)(a) CENTRAL EXCAVATIONS HAS OFFERED ASSISTANCE
19:26:12 ABLE TO USE MYSTERY CREEK EVENT CENTRE HYDRANT FACILITIES 9(2)(a)
19:45:17 9(2)(a) LIONS RANG TO OFFER FOOD AND ASSISTANCE PH 9(2)(a)
20:07:55 Out of Scope STANDING BY AT NGAW STN - HVE FULL - THEIR OTHER OTHER TRUCK
20:25:58 RANG CAMBRIDGE LIONS - THEY ARE ON THEIR WAY WITH FOOD - ETA 20 MINS
21:18:52 9(2)(a) FONTERRA TE RAPA OFFERED TANKERS 9(2)(a) - TE AWAMUTU
21:49:38 WAIPA NETWORKS TO RECONNECT POWER
00:01:58 VSO WAIKATO Out of Scope REQUEST CFO TE KUITI PHONE HIM URGENTLY ON
791752 - CFO PAGED
00:32:16 SPILLTECH RANG - THEY HVE OPENED UP ANOTHER HYDRANT IN HOWELL
00:41:58 FROM CAMBRIDGE FIRE. CAN YOU ASK HAMI4116 IF THEY REQUIRE ANOTHER PUMP TO
ST.
06:00:58 CFO NGONGOTAHA PER PHONE RE STANDBY CREW REQUIREMENTS
06:01:28 NGONGOTAHA BRIGADE PAGED
06:01:34 ROTORUA FIRE - ARRANGING CREW TO BE ON ROAD @ 0700 IN ROTO814
06:46:54 ROTORUA STATION PUT THRU TO Out of Scope RE RESPONSE @0700
07:11:16 POLICE ADVISED REGARDING TRAFFIC BUILD UP WITH SPECTATORS AT THE SCENE
07:27:27 POLICE ADVISED RE SPECTATORS AT SCENE HAVE DISPATCHED 3 UNITS TO LIASE WITH
AND UNIT
07:32:44 FM FSO12 THE CRITICAL INCIDENT TEAM X 6 PERS ARE HEADING TO INCIDENT
07:43:03 HAMILTON FEQUESTS AK BA TENDER
08:19:11 CHAR4226 CALLED IN - 9(2)(a) - ASKING THEIR REQUIREMENTS - TOLD OP
08:51:36 Out of Scope REQUESTS VICTIM SUPPORT TO PHONE Out of Scope ON 9(2)(a)
08:51:44 DETAILS PASSED TO POLICE TO FOLLOW UP
08:57:03 CONTACTED MET SERVICE THEY WILL FAX THRU A COPY WITHIN NEXT 20 MINS
09:56:00 AUCKHSA1 PUT THRU TO HAMI4114
09:56:58 CFO OTOR - IS DOING IT
09:57:40 CFO OTOR - WILL BE LEAVING IN 25 MIN WITH CREW AND EQUIP
10:20:24 TAMIHERE COMMAND ADVISED VICTIM SUPPORT ARRANGED WITH POLICE VIA Out of Scope
OT AND CELL NUMBER PASSED
10:27:58 FSO 12 Out of Scope DCFO AUCKLAND Out of Scope AND Out of Scope HAS ARE ADY
IN HAMILTON WILL ATTACH TO EVENT
10:31:32 PAGED OIC FP NGARUAWAHIA TO CONTACT CHAR4226
10:36:57 POLICE VICTIM SUPPORT CONTACTED TO CONTACT Out of Scope ON 9(2)(a)
10:50:18 AFRC Out of Scope PAGED TO CONTACT COMMAND Out of Scope
12:06:30 Out of Scope FROM TAMAHERE COMMAND PUT THRU TO ROTORUA FIRE STATION
12:14:03 Out of Scope FROM TAMAHERE COMMAND PUT THRU TO ROTORUA FIRE STATION AGAIN
12:22:35 FROM MET SERVICE THEY WILL FAX ONE THRU IN 15 MINS
13:00:45 RE NATIONAL COMMANDERS INSTRUCTION ALL FRC AFRC AND PAID CFOS TO BE
ADVISED PAGE REGADRING UPDATE DETAILS OBTAINED VIA FIRENET.
13:01:51 MESSAGE READS: PLEASE REFER TO FIRENET FOR INFORMATION OF THE HAMILTON
STORE EXPLOSION. UPDATE WILL BE PROVIDED ON FIRENET AS MORE INFORMATION
MES AVAILABLE
13:09:55 CFO MORRINSVILLE PAGED TO Out of Scope LOGISTICS MANAGER @
13:14:32 PAGED ALL SOUTHERN PAID CHEIFS
13:14:50 PAID CFOS FOR CENTRAL AREA PAGED WITH UPDATES
13:29:52 Out of Scope PAGED TO CALL Out of Scope MORRINSVILLE

13:56:53 **Out of Scope** FM PONSONBY FIRE PUT THRU TO TAMAHERE COMMAND
15:00:27 POLICE
16:02:50 POLICE
16:08:49 **Out of Scope**
16:18:19 VSO WAIKATO **Out of Scope** CALLED IN - ATTACHED TO JOB
16:49:05 AFRC BOP **Out of Scope** PAGED TO CALL **Out of Scope** @RADIO LIVE
16:49:58 AFRC **Out of Scope** PAGED TO CONTACT **Out of Scope** PER CELL PHONE
17:13:04 TAMAHERE COMMAND ADVISES SHOULD WE BE ADVISED RE **9(2)(a)**
THEN WE TO CONTACT **9(2)(a)** EVENING NUMBER **9(2)(a)** OR DAYTIME
9(2)(a)
17:17:45 MET SERVICE WILL FAX THRU COPY OF WX IN THE NEXT 15 TO 20 MINS
19:47:26 ESS PHONES IN TO TOUCH BASE - GIVEN HIM AFRC **Out of Scope** NUMBER
19:47:36 ESS ALSO ADV TO RING BACK TOMORROW IF HE CAN'T GET HOLD OF **Out of Scope**
21:52:46 CFO TOKOROA ADVISES HE IS TAKING FOOD TRAILER TO THIS JOB
07:02:32 **Out of Scope** CALLED IN AND ASKED TO ME MADE K1 TO TAMAHERE.
07:03:41 **Out of Scope** FROM TAMAHERE COMMAND CALLED IN - PAGE **Out of Scope**
07:37:14 **Out of Scope** HAMIPTO1 CALLED IN - REATTACHED TO JOB
09:09:05 HAMILTON FIRE OPS MANAGER HAS OFFERED HAMI681 ROOF MONITOR 4000L WATER
TIBILITIES AND FOAM CAPIBILITES CALL **9(2)(a)** WHEN REQD
09:09:38 TAUPO1 **Out of Scope** OF ABOVE - HE WILL CALL WHEN REQD
09:20:12 HAMILTON AIRPORT THAT WE WILL LET THEM KNOW PER PHONE WHEN THEY ARE REQD
09:42:57 FROM TAMAHERE COMMAND. CFO **Out of Scope** REQUESTS THE ATTENDANCE
14:01:09 FRC BAY WAIKATO PAGED TO PHONE **Out of Scope** AS REQUEST BY TAMAHERE
19:28:20 MET WEATHER SERVICE
06:04:50 MET WEATHER SERVICE
09:07:15 TAUP212 RETURNING TO TAUPO STATION - GOING K0
13:51:21 TRANSIT
10:56:16 **Out of Scope** REQUESTS TAMAHERE COMMAND CONTACT HIM ON HIS CELLPHONE
11:00:35 ADHOC SELCAL HAMI4116 INTERNAL ALERT - NO RESPONSE
11:00:49 ADHOC SELCAL HAMI4116 EXTERNAL ALERT - NO RESPONSE
11:03:12 ADHOC SELCAL HAMI4116 EXTERNAL ALERT - NO RESPONSE
11:16:59 HAMI4114 021 CELL CONTACT MADE, TRANSFERRING TO **Out of Scope** RINGING,
NO ANSWER
11:18:25 CELLPHONE NUMBER **Out of Scope** PASSED TO HAMI4114
04:22:15 BAYWORKSHOPS1 PAGED
04:38:03 BAYWORKSHOPS1 ACK PAGER
11:19:43 ADVISED **Out of Scope** OIC PAPA381 THAT PAPA387 WILL BE AWAY OVERNIGHT
11:44:43 FP HAMILTON PAGED
14:15:53 MET SERVICE PHONED FOR WEATHER TO BE FAXED
16:25:51 UPDATED MET SERVICE WEATHER FAXED TO HAMI4116 **9(2)(a)** 1625HRS
16:35:23 WEATHER FAXED TO HAMILTON FIRE AS FAX ON 4116 NOT WORKING
17:49:32 AFRC **Out of Scope** ADVISED AK REGION TAKING OVER INCIDENT FROM THURSDAY
17:49:57 AND OVER THE WEEKEND. VEHICLE MOVEMENTS WILL BE ADVISED AS NECESSARY
18:56:15 CONTACT THROUGH PAPA387 CELL **9(2)(a)**
17:58:25 CFO/DCFO ACE PAGED RE RESPONSE OF ONEH221

Message Log

Time	Message
16:04:19	** Event F128045 was viewed at: 20080405160419ND
16:04:19	**
16:04:30	CUSTOMER NUMBER 250450
16:04:38	** Recommended unit HAMI411 for requirement PUMP (>7.31 km)
16:04:38	** Recommended unit HAMI412 for requirement PUMP (>7.31 km)
16:05:22	KEYHOLDER NOT ATTENDING NO GUARD BE SENT WILL RING BACK WITH
16:05:22	INSTRUCTIONS
16:05:47	Unit HAMI411 [K1 : PROCEEDING TO INCIDENT]
16:06:28	Unit HAMI412 [K1 : PROCEEDING TO INCIDENT]
16:07:44	FM SIGNATURE SECURITY FIRE HAVE PERMISSION TO ENTER IF REQUIRED
16:08:30	COVERING UNIT PUKE431 DISPATCHED TO STATION
16:08:30	HAMILTON AT 05/04/08 16:08:29
16:08:30	TERMINAL: D0191984
16:09:13	Unit HAMI412 [COMCEN COM : MESSAGE] DO YOU REQUIRE WATCH RECALL
16:09:28	Unit HAMI412 [SITREP :] NEG K25 PUKE431 INTO CITY
16:14:55	Unit HAMI412 [K2 : IN ATTENDANCE AT INCIDENT]
16:15:32	Unit HAMI411 [K77 : NOTHING SHOWING]
16:15:35	** LOI search completed at 05/04/08 16:15:35
16:15:40	Unit HAMI411 [K77 : NOTHING SHOWING]
16:20:30	Unit HAMI411 [KC : UNIT CALLING]
16:21:13	Unit HAMI411 [SITREP :] SO Out of Scope BRIG ATTEMPTING TO GAIN ACCESS TO BUILDING
16:21:13	APPEARS TO BE SMOKE COMING FROM BUILDING POSS LEAKING REFRIGERANT INV FURTHER
16:29:24	Unit HAMI411 [KC : UNIT CALLING]
16:29:47	Unit HAMI411 [SITREP :] ENTRY GAINED BRIG INV USING BA
16:30:29	Unit HAMI412 [KP : PRIORITY MESSAGE]
16:30:52	Unit HAMI412 [KP : PRIORITY MESSAGE] TX 2ND ALARM MAJOR EXP
16:31:07	** Alarm level updated to 2
16:31:10	** Recommended unit CAMB441 for requirement TANKER (>13.03 km)
16:31:10	** Recommended unit CHAR4226 for requirement SUPPT (>9.65 km)
16:31:10	** Recommended unit PUKE431 for requirement PUMP (>7.31 km)
16:31:10	** Recommended unit CHAR427 for requirement PUMP (>9.65 km)
16:31:36	Unit HAMI412 [KP : PRIORITY MESSAGE]
16:31:52	Unit HAMI412 [KP : PRIORITY MESSAGE] TX 3RD ALARM
16:32:12	** Alarm level updated to 3
16:32:15	** Recommended unit ROTO8116 for requirement COMU (>84.79 km)
16:32:15	** Recommended unit HAMI4112 for requirement HOSEL (>7.31 km)
16:32:15	** Recommended unit HAMI413 for requirement PUMP (>7.31 km)
16:32:15	** Recommended unit CAMB441 for requirement PUMP (>13.03 km)
16:32:20	Unit CHAR427 [K1 : PROCEEDING TO INCIDENT]
16:33:43	Unit HAMI412 [KP : PRIORITY MESSAGE]
16:33:46	Unit PUKE431 [KC : UNIT CALLING]
16:34:03	Unit CAMB441 [K1 : PROCEEDING TO INCIDENT]
16:34:09	Unit CAMB441 [K1 : PROCEEDING TO INCIDENT]
16:34:15	Unit HAMI412 [KP : PRIORITY MESSAGE] BE ADVISE 9(2)a

16:34:15 9(2)a
16:35:26 ** Cross Referenced to Event # P001010010 at: 05/04/08 16:35:26
16:35:26 **
16:35:42 Unit ROTO8116 [K1 : PROCEEDING TO INCIDENT]
16:35:47 Unit HAMI411 [KP : PRIORITY MESSAGE]
16:35:49 FM ROTO811 ATTACH 811 - TRANSMIT PAGERS FOR GREEN WATCH CALL BACKS
16:35:51 Unit CAMB4411 [K1 : PROCEEDING TO INCIDENT]
16:36:13 Unit HAMI411 [KP : PRIORITY MESSAGE] ACTIVATE GREEN WATCH CALL BACK CALL ON
16:36:13 DUTY EXEC
16:36:40 Unit ROTO811 [K1 : PROCEEDING TO INCIDENT]
16:36:58 HAMILTON 2 ON JOB
16:37:03 Unit ROTO811 [KC : UNIT CALLING]
16:37:25 NOT
16:37:51 Unit HAMILTON1 [K1 : PROCEEDING TO INCIDENT]
16:37:59 Unit HAMI412 [KC : UNIT CALLING]
16:38:07 Unit HAMILTON2 [K1 : PROCEEDING TO INCIDENT]
16:38:15 Unit ROTO811 [SITREP :] CAN YOU CONFIRM THAT THIS IS HAZMAT TURNOUT
16:38:26 AMBOS RESPONDING AND ADVANCED PARAMEDIC, 9(2)a
16:38:47 Unit HAMI412 [STOP : MESSAGE] 9(2)a
16:39:17 ** Cross Referenced to Event # F128068 at: 05/04/08 16:39:17
16:39:17 **
16:39:19 End of Duplicate Event data
16:39:19 ** Cross Referenced to Event # F128069 at: 05/04/08 16:39:19
16:39:19 **
16:39:21 End of Duplicate Event data
16:39:22 ** Cross Referenced to Event # F128070 at: 05/04/08 16:39:22
16:39:22 **
16:39:24 ** Cross Referenced to Event # F128071 at: 05/04/08 16:39:24
16:39:24 **
16:39:26 ** Cross Referenced to Event # F128077 at: 05/04/08 16:39:26
16:39:26 **
16:39:39 Unit PUKE431 [K1 : PROCEEDING TO INCIDENT]
16:40:49 Unit PUKE431 [K1 : PROCEEDING TO INCIDENT]
16:40:55 Unit PUKE431 [K1 : PROCEEDING TO INCIDENT]
16:41:01 Unit PUKE431 [K1 : PROCEEDING TO INCIDENT]
16:41:06 Unit PUKE431 [K2 : IN ATTENDANCE AT INCIDENT]
16:41:43 SITREP FROM 411 TWO INDUSTRIAL BUILDING WELL INVO, 9(2)a , ETA
OF
16:41:43 AMBO
16:41:55 Unit HAMILTON2 [COMCEN COM : MESSAGE] CALL COMCEN
16:41:56 Unit ROTO811 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
16:42:48 Unit CHAR427 [K2 : IN ATTENDANCE AT INCIDENT]
16:45:51 Unit HAMIFSO3 [K1 : PROCEEDING TO INCIDENT]
16:46:22 Unit CHAR427 [KC : UNIT CALLING]
16:46:28 ** Cross Referenced to Event # F128082 at: 05/04/08 16:46:28
16:46:28 **
16:46:51 Unit CAMB4411 [K2 : IN ATTENDANCE AT INCIDENT]

16:46:58 Unit HAMILTON1 [K2 : IN ATTENDANCE AT INCIDENT]
16:47:01 Unit CHAR427 [SITREP :] SO ^{Out of Scope} ON SCENE 9(2)a
16:47:01 9(2)a TAKING CARE OF FIRE ATTACK
16:47:04 Unit HAMILTON1 [K2 : IN ATTENDANCE AT INCIDENT]
16:47:14 Unit HAMILTON2 [KC : UNIT CALLING]
16:48:21 Unit HAMILTON2 [SITREP :] ADJACENT TO SH 1 CONSIDERABLE TRAFFIC CAUSING
16:48:21 CONGESTION HAVE POLICE ATTEND SH1
16:52:44 Unit CHAR427 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] CFO ^{Out of Scope}
16:54:03 ** Cross Referenced to Event # F128086 at: 05/04/08 16:54:03
16:54:03 **
16:54:08 Unit CHAR4226 [K1 : PROCEEDING TO INCIDENT]
16:54:17 ** Cross Referenced to Event # F128088 at: 05/04/08 16:54:17
16:54:17 **
16:54:39 Unit HAMI4116 [K1 : PROCEEDING TO INCIDENT]
16:54:58 Unit TEAW451 [K1 : PROCEEDING TO INCIDENT]
16:55:39 Unit CHAR427 [KP : PRIORITY MESSAGE]
16:56:02 Unit CHAR427 [KP : PRIORITY MESSAGE] MAKE WATER TANKERS 6
16:56:16 Unit HAMI4116 [KC : UNIT CALLING]
16:58:20 Unit BAYW3 [K1 : PROCEEDING TO INCIDENT]
16:58:32 Unit BAYW3 [K2 : IN ATTENDANCE AT INCIDENT]
17:00:01 Unit TEAW4511 [K1 : PROCEEDING TO INCIDENT]
17:00:33 Unit TEAW451 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
17:01:14 Unit MORR3611 [K1 : PROCEEDING TO INCIDENT]
17:01:37 Unit MORR3611 [K1 : PROCEEDING TO INCIDENT]
17:01:49 Unit HUNT3211 [K1 : PROCEEDING TO INCIDENT]
17:03:07 Unit MATA3811 [K1 : PROCEEDING TO INCIDENT]
17:03:13 Unit VSOWAIKATO [K1 : PROCEEDING TO INCIDENT]
17:03:28 Unit HAMI4116 [K2 : IN ATTENDANCE AT INCIDENT]
17:04:08 FM OTOROHONGA FIRE - WILL BE 5 MINS
17:04:51 ** Cross Referenced to Event # F128093 at: 05/04/08 17:04:51
17:04:51 **
17:05:05 Unit HAMI4116 [KC : UNIT CALLING]
17:06:05 Unit OTOR4611 [K1 : PROCEEDING TO INCIDENT]
17:06:19 Unit OTOR4611 [KC : UNIT CALLING]
17:06:35 Unit HAMI4116 [K44 : COMMAND OR CONTROL POINT ESTABLISHED - OIC AND LOCATION]
17:06:35 CAMBRIDGE COMMAND TILWORTH
17:08:00 Unit OTOR4611 [K1 : PROCEEDING TO INCIDENT]
17:08:25 Unit CHAR4226 [K2 : IN ATTENDANCE AT INCIDENT]
17:08:27 FM TEAR FIRE - K35 - DETAILS PASSED
17:08:32 Unit CAMB4411 [KP : PRIORITY MESSAGE]
17:09:24 Unit CAMB4411 [KP : PRIORITY MESSAGE] ETA OF NEXT AVAILABLE TANKER
17:09:40 Unit TEAW4511 [SITREP :] AT HAMILTON AIRPORT
17:10:36 ** Alarm level updated to 4
17:10:38 ** Recommended unit TEAW451 for requirement PUMP (>7.31 km)
17:10:38 ** Recommended unit MORR361 for requirement PUMP (>23.86 km)
17:10:53 Unit TEAR3711 [K1 : PROCEEDING TO INCIDENT]

17:11:15 H
17:11:16 Unit AUCKHSA1 [K1 : PROCEEDING TO INCIDENT]
17:11:48 Unit TEAW451 [K1 : PROCEEDING TO INCIDENT]
17:11:54 ** Alarm level updated to 5
17:11:55 ** Recommended unit CAMB447 for requirement PUMP (>13.03 km)
17:11:55 ** Recommended unit MORR367 for requirement PUMP (>23.86 km)
17:13:05 HAMILTON AIRP
17:13:16 Unit MORR361 [K1 : PROCEEDING TO INCIDENT]
17:13:19 Unit HAMI415 [K1 : PROCEEDING TO INCIDENT]
17:14:01 HAMILTON AIRPORT HAS TANKER WITH 6000 LTS - THEY ARE ON THE WAY
17:14:20 FM CAMB FIRE - K35
17:15:22 Unit AUCKHSA1 [KC : UNIT CALLING]
17:15:31 Unit CAMB447 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
17:16:31 Unit MORR367 [K1 : PROCEEDING TO INCIDENT]
17:17:15 Unit MORR367 [KC : UNIT CALLING]
17:18:33 Unit MORR367 [K35 : VERIFY ADDRESS OF EVENT]
17:24:11 Unit HAMIFSO3 [K2 : IN ATTENDANCE AT INCIDENT]
17:24:13 Unit TEAW451 [K2 : IN ATTENDANCE AT INCIDENT]
17:24:56 Unit HAMI415 [K2 : IN ATTENDANCE AT INCIDENT]
17:26:01 Unit CAMB447 [K2 : IN ATTENDANCE AT INCIDENT]
17:26:03 Unit MORR3611 [K2 : IN ATTENDANCE AT INCIDENT]
17:27:19 CU RANG IN ASKING FOR ALL ER AND AR UNITS - DETAILS PASSED
17:28:29 Unit TEAR3711 [KC : UNIT CALLING]
17:32:57 Unit NORTHCOM2 [K1 : PROCEEDING TO INCIDENT]
17:33:00 Unit MORR361 [K2 : IN ATTENDANCE AT INCIDENT]
17:33:42 Out of Scope FROM BLUE WATCH
17:33:50 Unit HAMI6819 [K1 : PROCEEDING TO INCIDENT]
17:33:59 FM HANI6819 - HAVE BEEN ASKED TO ATTEND
17:34:01 Unit VSOWAIKATO [K1 : PROCEEDING TO INCIDENT]
17:36:20 Unit HUNT3211 [K2 : IN ATTENDANCE AT INCIDENT]
17:37:15 Unit MORR367 [K2 : IN ATTENDANCE AT INCIDENT]
17:37:30 Unit MATA3811 [K2 : IN ATTENDANCE AT INCIDENT]
17:37:45 Unit HAMI4112 [KC : UNIT CALLING]
17:37:59 Unit ROTO8116 [K2 : IN ATTENDANCE AT INCIDENT]
17:38:11 Unit HAMI4112 [K1 : PROCEEDING TO INCIDENT]
17:38:40 FM HAMILTON FIRE - HAMI413 IS PUMP THAT'S AVAILABLE K7 AT HAMILTON STATION
17:38:54 Unit HAMI413 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
17:41:18 Unit OTOR4611 [K2 : IN ATTENDANCE AT INCIDENT]
17:45:12 Unit AUCKHSA1 [KC : UNIT CALLING]
17:45:59 Unit TEAW4511 [K2 : IN ATTENDANCE AT INCIDENT]
17:50:59 Unit TEAR3711 [K2 : IN ATTENDANCE AT INCIDENT]
17:51:09 Unit HAMI4112 [K2 : IN ATTENDANCE AT INCIDENT]
17:52:48 Unit BAYW2 [K6 : ON TELEPAGER]
17:53:36 Unit HAMI4116 [KC : UNIT CALLING]
17:54:00 ** Cross Referenced to Event # F128160 at: 05/04/08 17:54:00
17:54:00 **

17:57:01 Unit HAMI4116 [KC : UNIT CALLING]
17:57:52 HAMI4116 -9(2)a ?????
17:58:24 Unit HAMI4116 [COMCEN COM : MESSAGE] CAN NOT HEAR HAMI4116 OVER RADIO
18:00:44 Unit VSOWAIKATO [K2 : IN ATTENDANCE AT INCIDENT]
18:01:27 Unit HAMI4116 [SITREP :] RC ^{Out of Scope} STATUS REPORT FOR 9(2)a
18:01:27 9(2)a 3 80 X 30 SQ METRE MAJOR COOL STORE BUILDINGS 1
TOTALLY
18:01:27 INV SPREAD NOW TO SECOND BUILDING ATTEMPTING TO PROTECT 3RD BUILDING
HAMPERED BY
18:01:27 NON RETICULATED WATER SUPPLY USING TANKERS AND STATIC SUPPLIES USING
AIRPORT
18:01:27 FOAM TRUCKS TO REDUCE INTENSITY OF FIRE MULTIPLE MONITORS MULTIPLE MEDIUM
18:01:27 EXPLOSIONS STILL AND ENVIROMENT WAIKATO ADVISED LARGE AMOUNT OF RUN OFF.
18:02:17 ** Cross Referenced to Event # F128167 at: 05/04/08 18:02:17
18:02:17 **
18:02:58 ** Cross Referenced to Event # F128169 at: 05/04/08 18:02:58
18:02:58 **
18:03:40 Unit AUCKHSA1 [K1 : PROCEEDING TO INCIDENT]
18:06:34 Unit HAMI4116 [KC : UNIT CALLING]
18:06:56 Unit HAMI4116 [KC : UNIT CALLING]
18:07:47 Unit HAMI4116 [SITREP :] LOOK AT COVERS AT OTHER STATIONS. RE MORRINSVILLE
18:11:04 Unit CAMB441 [K2 : IN ATTENDANCE AT INCIDENT]
18:13:41 ** Situation found NOT
18:16:03 Unit HAMI4116 [KP : PRIORITY MESSAGE]
18:16:59 Unit HAMI4116 [SITREP :] LOCATION OF TWO TANKERS WHERE THEY ARE COMING FROM
18:16:59 TWO TANKERS FROM FONTERRA REQUIRED. ALSO MAYBE FROM PIRONGIA
18:19:12 Unit NORTHCOM2 [K2 : IN ATTENDANCE AT INCIDENT]
18:19:30 HAMILTON HAZMAT RESPONDING - NO RADIO LMR ON BOARD
18:20:24 Unit PIRO5876 [K1 : PROCEEDING TO INCIDENT]
18:21:20 Unit HAMI4116 [KC : UNIT CALLING]
18:24:16 Unit VSOSTHWAKO [K1 : PROCEEDING TO INCIDENT]
18:25:22 COVERING UNIT TEAR371 DISPATCHED TO STATION
18:25:22 MORRINSVILLE AT 05/04/08 18:25:21
18:25:24 NOPT FP AUCKLAND RESPONDING VERY SHORTLY
18:25:48 COVERING UNIT MATA381 DISPATCHED TO STATION
18:25:48 CAMBRIDGE AT 05/04/08 18:25:48
18:26:33 Unit PAER5111 [K1 : PROCEEDING TO INCIDENT]
18:28:16 Unit HAMI6819 [K2 : IN ATTENDANCE AT INCIDENT]
18:28:35 HAMI4116 - NOTIFY ENVIRONMENT WAIKATO & HEALTH DEPT
18:29:13 Unit MATA382 [K1 : PROCEEDING TO INCIDENT]
18:29:28 Unit MATA382 [K1 : PROCEEDING TO INCIDENT]
18:29:48 Unit VSOWESTBOP [K1 : PROCEEDING TO INCIDENT]
18:29:59 Unit HAMI4116 [KC : UNIT CALLING]
18:30:38 Unit HAMI4116 [SITREP :] RESPONSE OF THE CANTEEN UNIT AND ABULTIONS (K1)
18:31:59 Unit TEAW4511 [K2 : IN ATTENDANCE AT INCIDENT]
18:34:55 Unit VSOWESTBOP [KC : UNIT CALLING]
18:35:29 Unit AUCKFPOL8 [K1 : PROCEEDING TO INCIDENT]
18:36:02 Unit AUCKHSA1 [K2 : IN ATTENDANCE AT INCIDENT]

18:41:25 Unit HAMI4116 [KC : UNIT CALLING]
18:42:22 Unit VSOWESTBOP [K2 : IN ATTENDANCE AT INCIDENT]
18:42:29 Unit HAMI4116 [SITREP :] EVAC OF FUNCTION 9(2)a LEAKING
18:42:29 CHEMICALS INTO DRAINS BLOCKED OFF. ALL CREWS UTILISED. AWAITING FURTHER
TANKERS
18:46:22 Unit HAMI4116 [SITREP :] WONT BE REQUIRING THE BA TENDER
18:49:44 Unit HAMI413 [K1 : PROCEEDING TO INCIDENT]
18:53:01 Unit PIRO5876 [K2 : IN ATTENDANCE AT INCIDENT]
18:56:18 Unit MATA382 [KC : UNIT CALLING]
18:56:53 Unit MATA382 [K9 : OFF RT - STATE LOCATION]
18:58:00 Unit VSOSTHWAKO [K1 : PROCEEDING TO INCIDENT]
18:58:38 Unit HAMI413 [KC : UNIT CALLING]
18:59:46 POLICE ESCORT HAS BEEN ARRANGED FOR FONTERRA TANKERS
19:00:01 POLICE ESCORT TO MEET FONTERRA TANKERS AT BURGER KING CNR
19:00:09 TE RAPA STRAIGHT & AVALON DRIVE
19:01:20 Unit HAMILTON2 [K2 : IN ATTENDANCE AT INCIDENT] ENTERED BY FIRECOM
19:02:56 Unit HAMI413 [K2 : IN ATTENDANCE AT INCIDENT]
19:03:30 Unit BAYW1 [K2 : IN ATTENDANCE AT INCIDENT]
19:06:28 Unit BAYW2 [K6 : ON TELEPAGER]
19:06:42 Unit GREE751 [K1 : PROCEEDING TO INCIDENT]
19:06:50 Unit GREE751 [K1 : PROCEEDING TO INCIDENT]
19:06:52 Unit BAYW2 [K2 : IN ATTENDANCE AT INCIDENT]
19:06:57 Unit GREE751 [K1 : PROCEEDING TO INCIDENT]
19:07:46 Unit BAYW2 [SITREP :] REQUEST ENTIRE GREERTON BRIGADE TO MOBILISE
19:09:36 TUDOR MOTOR LODGE 9(2)a HAVE MADE 3 ROOMS AVAILABLE FOR FIRE CREWS
19:09:51 TO USE - ROOMS 21 / 25 & 28
19:10:17 LOCATED AT 24 THACKERAY ST HAMILTON - CONTACT 9(2)a
19:12:12 ROOMS ARE OPEN & ALL FACILITIES WITHIN ROOMS ARE AVAILABLE
19:13:01 Unit GREE752 [K1 : PROCEEDING TO INCIDENT]
19:14:10 THEIR OWN WATER SUPPLY: 9(2)a
19:15:38 Unit GREE7510 [K1 : PROCEEDING TO INCIDENT]
19:16:07 ** Event Type changed from STRU to STRU at: 05/04/08 19:16:07
19:16:07 ** Event Location changed from "CAMBRIDGE RD,TAMAHERE, WAIKATO DISTRICT" to "30
19:16:07 DEVINE RD,TAMAHERE, WAIKATO DISTRICT" at: 05/04/08 19:16:07
19:16:07 **
19:16:35 Unit PAER5111 [K2 : IN ATTENDANCE AT INCIDENT]
19:16:39 SIGNITURE SECURITY ADVISE CORRECT PHYSICAL ADDRESS FOR THIS PREMISES
19:16:41 Unit GREE7510 [K1 : PROCEEDING TO INCIDENT]
19:17:36 Unit GREE752 [KC : UNIT CALLING]
19:17:54 Unit GREE752 [SITREP :] RESPONDING SO AND 5
19:20:04 ** LOI search completed at 05/04/08 19:20:04
19:21:16 Unit HAMI4116 [KC : UNIT CALLING]
19:22:04 Unit HAMI4116 [SITREP :] CONTACT HAMILTON CC POLLUTION UNIT TO REPOSND HERE
19:22:04 WITH POLLUTION CONTROL EQUIPMENT TO ASSIST ENVIRTOMENTAL
19:22:17 Unit CHAR427 [K7 : AT NORMAL STATION]
19:25:44 Unit VSOSTHWAKO [K2 : IN ATTENDANCE AT INCIDENT]

19:36:33 Unit AUCKFPOL5 [K1 : PROCEEDING TO INCIDENT]
19:37:46 Unit AUCKFPOL8 [K1 : PROCEEDING TO INCIDENT]
19:37:59 Unit GREE752 [K1 : PROCEEDING TO INCIDENT]
19:40:33 Unit AUCKFPOL8 [KC : UNIT CALLING]
19:41:24 Unit CAMB447 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
19:42:00 Unit GREE751 [K1 : PROCEEDING TO INCIDENT]
19:43:46 Unit AUCKFPOL6 [K1 : PROCEEDING TO INCIDENT] RESPONDING WITH AUCKFPOL5
19:45:01 Unit VSOWESTBOP [KC : UNIT CALLING]
19:48:27 SSO **Out of Scope** AT TAURANGA FIRE REQ THAT ALL AVAILABLE GREERTON VOLUNTEERS
19:48:54 BE PAGED TO RESPOND TO GREERTON FIRE ASAP
19:49:16 IF THIS CANNOT BE ACHIEVED HE WILL ARRANGE FOR MT MAUNGANUI VOLUNTEERS
19:49:24 TO RESPOND TO GREERTON FOR COVER
20:01:30 GREE7510 HAVE NO RADIO COMS
20:06:02 **Out of Scope** PUT THRU TO COMMAND UNIT
20:08:05 CAN COVER AND HUNTLY AND NGAR IF RQD.
20:08:14 Unit GREE751 [K2 : IN ATTENDANCE AT INCIDENT]
20:10:24 Unit AUCKFPOL5 [K1 : PROCEEDING TO INCIDENT]
20:11:17 Unit HAMI4116 [KC : UNIT CALLING]
20:12:09 GREE752 COMING THRU CAMBRIDGE - ETA 5 MINS
20:13:07 Unit AUCKFPOL5 [KC : UNIT CALLING]
20:14:33 ** Event F128045 transferred from NZFS/WK to NZFS/ACOMM as F128045 at 05/04/08
20:14:33 20:14:33
20:15:44 ** Event F128045 was viewed at: 20080405201544ND
20:15:44 **
20:16:52 Unit GREE752 [K2 : IN ATTENDANCE AT INCIDENT]
20:20:03 HAMILTON CC DOING EVERYTHING POSSIBLE TO GET POLLUTION SQUAD TO SCENE
(8340303)
20:25:07 Unit AUCKFPOL8 [K2 : IN ATTENDANCE AT INCIDENT]
20:37:36 Unit HAMI4116 [KC : UNIT CALLING]
20:38:02 Unit HAMILTON1 [K6 : ON TELEPAGER]
20:38:15 Unit HAMI4116 [SITREP :] GREE752 HAVE NO RADIO COMS THEY ARE K-2
20:38:44 CORRECTION -UNIT HAMI4116 [SITREP :] GREE7510 HAVE NO RADIO COMS THEY ARE
K-2
20:38:54 Unit GREE7510 [K2 : IN ATTENDANCE AT INCIDENT]
20:53:19 Unit GREE7510 [K1 : PROCEEDING TO INCIDENT]
20:55:14 Unit GREE7510 [K1 : PROCEEDING TO INCIDENT]
20:55:43 Unit GREE7510 [K2 : IN ATTENDANCE AT INCIDENT]
21:02:43 Unit NORTHCOM2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
21:14:01 Unit HAMI4116 [KC : UNIT CALLING]
21:19:20 CAN ALSO GET ONE AND WAITRA
21:26:41 Unit TAUPO1 [K1 : PROCEEDING TO INCIDENT]
21:35:09 Unit AUCKFPOL5 [K2 : IN ATTENDANCE AT INCIDENT]
21:39:22 Unit ROTO8116 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
21:39:57 Unit AUCKFPOL6 [K2 : IN ATTENDANCE AT INCIDENT]
21:42:56 Unit CAMB441 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
21:45:09 Unit TAUPO1 [KC : UNIT CALLING]
21:46:29 Unit HAMI4116 [KC : UNIT CALLING]

21:47:01 Unit HAMI4116 [SITREP :] K-11 POWER TO RECONNECT
21:52:30 Unit AUCKFPOL5 [K2 : IN ATTENDANCE AT INCIDENT]
21:53:29 88 HANNON RD HAS A 56K LITRE SWIMMING POOL AVAILABLE IF FURTHER WATER
21:54:00 REQUIRED - PH 078232101 - CORK RESIDENCE
22:01:23 Unit HAMIFTO1 [K1 : PROCEEDING TO INCIDENT]
22:11:47 Unit ROTORUA2 [K1 : PROCEEDING TO INCIDENT]
22:29:05 Unit CENTAUCK1 [K1 : PROCEEDING TO INCIDENT]
23:07:58 Unit TAUPO1 [K2 : IN ATTENDANCE AT INCIDENT]
23:09:43 Unit HAMI4116 [KC : UNIT CALLING]
23:11:21 Unit ROTORUA2 [K2 : IN ATTENDANCE AT INCIDENT]
23:11:27 Unit ROTORUA2 [K2 : IN ATTENDANCE AT INCIDENT]
23:12:17 Unit HAMI4116 [SITREP :] AFRCO **Out of Scope** REASSESSING SITUATION TO POTENTIALLY
23:12:17 DOWNSIZE WITH MAIN FOCUS OF OPS NOW IS PROTECTING THE 3RD SHED ENVIRO
HAZNO &
23:12:17 HEALTH REPS ARE ALL ON SITE HAM CITY COUNCIL HAVE SET UP A HEALTH LINE FOR
ANY
23:12:17 LOCALS WITH ENVIRO CONCERNS
23:21:38 Unit MORR367 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
23:22:19 Unit AUCKFPOL8 [KC : UNIT CALLING]
23:22:59 Unit AUCKFPOL8 [SITREP :] HAVE HAMIL WORKSHOPS ATTEND PARKED BEHIND
COMMUNITY
23:22:59 CENTER. FLAT BATTERY
23:24:34 Unit AUCKFPOL8 [KC : UNIT CALLING]
23:33:07 Unit HAMI4116 [KC : UNIT CALLING]
23:33:26 Unit CENTAUCK1 [K2 : IN ATTENDANCE AT INCIDENT]
00:00:10 Unit HAMIFTO1 [K2 : IN ATTENDANCE AT INCIDENT] ENTERED BY FIRECOM
00:24:47 AS PER FRC **Out of Scope** REQUEST THROUGH OPS MGR **Out of Scope** .. ALL BAY WAIKATO
STATIONS
00:24:47 NOTIFIED PER PHONE BY SHIFT MANAGER OF NEWS
00:32:45 AVENUE, OFF RIVERLEA ROAD - CAN WE ADVISE FIRE PERSONNEL
00:33:19 Unit AUCKHSA1 [K2 : IN ATTENDANCE AT INCIDENT]
00:33:21 Unit TAUPO1 [K6 : ON TELEPAGER]
00:33:26 Unit AUCKHSA1 [K2 : IN ATTENDANCE AT INCIDENT]
00:33:33 Unit AUCKHSA1 [K2 : IN ATTENDANCE AT INCIDENT]
00:34:07 Unit AUCKHSA1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
00:34:35 Unit GREE751 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
00:47:41 Unit HAMI4116 [KC : UNIT CALLING]
00:47:47 Unit GREE752 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
00:48:30 Unit HAMI4116 [SITREP :] AN XTRA PUMP WOULD BE APPRECIATED
00:52:55 Unit CAMB441 [K1 : PROCEEDING TO INCIDENT]
00:58:14 Unit HAMILTON2 [K2 : IN ATTENDANCE AT INCIDENT]
00:58:18 Unit HAMILTON2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
01:03:01 Unit CAMB441 [K2 : IN ATTENDANCE AT INCIDENT]
01:03:17 Unit AUCKFPOL5 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
01:05:42 Unit PUKE431 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
01:12:14 Unit VSOSTHWAKO [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
01:12:33 Unit BAYW3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
01:12:57 Unit HAMI4116 [KC : UNIT CALLING]

01:13:11 Unit VSOWESTBOP [K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]
01:13:26 Unit HAMI4116 [SITREP :] GREE7510 IS NOW K3
01:20:49 Unit MORR361 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
01:39:16 Unit AUCKFPOL6 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
01:49:34 Unit HUNT3211 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
01:55:04 Unit HAMI4116 [KC : UNIT CALLING]
01:56:28 Unit HAMI4116 [SITREP :] AFRC **Out of Scope** LEFT FIRE GROUND 0102
01:57:50 Unit HAMIFTO1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
02:02:14 Unit AUCKFPOL8 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
02:06:19 Unit VSOWESTBOP [K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]
02:17:09 Unit HAMIFSO3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
02:21:08 ** Event F128045 transferred from NZFS/ACOMM to NZFS/WK as F128045 at 06/04/08
02:21:08 02:21:08
02:22:06 ** Event F128045 was viewed at: 20080406022206NS
02:22:06 **
02:27:56 Unit PIRO5876 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
02:27:59 Unit GREE7510 [K1 : PROCEEDING TO INCIDENT]
02:28:14 Unit GREE7510 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
02:31:40 Unit PAER5111 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
02:35:35 Unit VSOWESTBOP [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
02:35:53 Unit CAMB441 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
03:00:00 ##### Daylight Savings Time Changed one hour ago #####
03:09:22 Unit MORR3611 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
04:21:50 Unit TEAR3711 [KC : UNIT CALLING]
04:41:34 Unit TEAR3711 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
04:57:40 #####
04:58:40 AT 0600HRS - WAKE ROTORUA. ROTO814 TO PROCEED TO INCIDENT AT 0700HRS
04:59:33 AT 0600HRS - WAKE NGONGOTAHA CFO TO PROCEED 0700HRS (NGON822)
04:59:55 16 FIREFIGHTERS IN VANS RESPONDING FROM AUCKLAND
05:18:48 Unit TEAW451 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
05:39:07 Unit MATA3811 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
05:56:58 Unit HAMI413 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
06:08:30 Unit HAMI6819 [K7 : AT NORMAL STATION]
06:53:30 Unit TAUP01 [K1 : PROCEEDING TO INCIDENT]
06:53:47 Unit TAUP01 [K1 : PROCEEDING TO INCIDENT]
06:53:53 Unit TAUP01 [K1 : PROCEEDING TO INCIDENT]
06:55:40 Unit HAMI4116 [KC : UNIT CALLING]
06:56:30 Unit HAMI4116 [SITREP :] DC **Out of Scope** RESP ROTORUA OPERATIONAL SUPPORT FOR
CANTEEN
06:56:30 SUPPLIES
07:02:26 Unit NGON822 [K1 : PROCEEDING TO INCIDENT]
07:03:05 Unit TAUP01 [K2 : IN ATTENDANCE AT INCIDENT]
07:03:11 Unit TAUP01 [K2 : IN ATTENDANCE AT INCIDENT]
07:07:10 Unit NGON822 [SITREP :] CONTACTABLE CELL PHONE **9(2)a**
07:07:56 Unit TAURANGA2 [K1 : PROCEEDING TO INCIDENT]
07:09:05 Unit ROTO8126 [K1 : PROCEEDING TO INCIDENT]
07:18:03 Unit ROTO814 [K1 : PROCEEDING TO INCIDENT]

07:20:05 Unit HAMI4116 [COMCEN COM : MESSAGE] ROTO814 K1 AND PROCEEDING TO YOUR LOCATION

07:25:19 FM **Out of Scope** - VSO WAIKATO EAST - IS AVAILABLE TODAY IF NEEDED

07:30:40 Unit VSOWAIKATO [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

07:30:53 Unit HAMIFSO3 [K1 : PROCEEDING TO INCIDENT]

07:33:44 Unit HAMI4116 [COMCEN COM : MESSAGE] CRITICAL INCIDENT TEAM ENROUTE

07:35:48 NOT

07:37:18 Unit BAYW1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

07:37:18 Unit BAYW2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

07:41:37 Unit ROTO8126 [K1 : PROCEEDING TO INCIDENT]

07:47:01 Unit TAURANGA2 [K2 : IN ATTENDANCE AT INCIDENT]

07:51:16 Unit NGON822 [K1 : PROCEEDING TO INCIDENT]

07:54:02 Unit AUCK2015 [K1 : PROCEEDING TO INCIDENT]

08:01:18 Unit HAMIFSO3 [K2 : IN ATTENDANCE AT INCIDENT]

08:02:07 Unit NGON822 [K2 : IN ATTENDANCE AT INCIDENT]

08:04:44 Unit ROTO8126 [K2 : IN ATTENDANCE AT INCIDENT]

08:15:15 Unit CHAR4226 [K1 : PROCEEDING TO INCIDENT]

08:18:40 Unit HAMI4116 [KC : UNIT CALLING]

08:19:05 Unit HAMI4116 [K44 : COMMAND OR CONTROL POINT ESTABLISHED - OIC AND LOCATION]

08:19:05 DCFO **Out of Scope**

08:19:21 SUPPORT AND WILL GET MORE DETAILS ON SCENE

08:19:58 Unit HAMI4116 [KC : UNIT CALLING]

08:20:37 Unit HAMI4116 [SITREP :] ETA FOR ROTO814

08:21:25 Unit HAMI4116 [COMCEN COM : MESSAGE] ETA 15 MINS

08:21:50 Unit HAMI4116 [KC : UNIT CALLING]

08:25:11 Unit TEAW451 [K1 : PROCEEDING TO INCIDENT]

08:25:35 Unit TEAW451 [K2 : IN ATTENDANCE AT INCIDENT]

08:29:10 Unit CHAR4226 [K1 : PROCEEDING TO INCIDENT]

08:29:15 Unit CHAR4226 [K2 : IN ATTENDANCE AT INCIDENT]

08:32:52 FM **Out of Scope** - LEAVING HAMILTON NOW HEADING BACK TO AUCKLAND

08:33:17 Unit ROTO814 [K2 : IN ATTENDANCE AT INCIDENT]

08:33:24 Unit ROTO814 [K2 : IN ATTENDANCE AT INCIDENT]

08:33:35 Unit CENTAUCK1 [K6 : ON TELEPAGER]

08:35:33 Unit HAMI4116 [KC : UNIT CALLING]

08:48:11 Unit HAMI4116 [K44 : COMMAND OR CONTROL POINT ESTABLISHED - OIC AND LOCATION]

08:48:11 IC **Out of Scope**

08:49:20 Unit CAMB441 [K1 : PROCEEDING TO INCIDENT]

08:52:36 Unit HAMI4116 [KC : UNIT CALLING]

08:53:22 Unit HAMI4116 [SITREP :] FAX THRU LIST OF RESOURCES AT THIS INCIDENT AND A 24 HOUR WEATHER REPORT

09:00:19 Unit AUCKHSA1 [K1 : PROCEEDING TO INCIDENT]

09:00:30 Unit AUCKHSA1 [K2 : IN ATTENDANCE AT INCIDENT]

09:00:53 Unit CAMB441 [K2 : IN ATTENDANCE AT INCIDENT]

09:19:39 Unit AUCK2015 [K1 : PROCEEDING TO INCIDENT]

09:30:59 Unit HAMI4112 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

09:36:21 Unit AUCK2015 [K2 : IN ATTENDANCE AT INCIDENT]

09:40:26 FM ^{Out of Scope} ON AUCK2015 - CONTACT THEM ON ^{9(2)a}
09:40:41 Unit HAMI415 [K7 : AT NORMAL STATION]
09:54:31 CAN WE CONTACT CFO OTOR FOR RERLEIF DRIVER AND 1 EXTRA
09:56:01 Unit HAMI412 [KC : UNIT CALLING]
09:56:20 Unit HAMI412 [K7 : AT NORMAL STATION]
10:05:23 Unit OTOR4629 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
10:10:01 Unit HAMI4116 [KC : UNIT CALLING]
10:11:24 Unit HAMI4116 [SITREP :] FF OPERATIONS CEASED TO ALLOW ENVIRONMENT WAIKATO
TO
10:11:24 BUNDED AREAS TO CONTAIN RUN OFF
10:15:28 Unit HAMI4116 [KC : UNIT CALLING]
10:16:29 Unit HAMI4116 [SITREP :] K11 VICTIM SUPPORT HAVE THEM CONTACT TAMAHERE
COMMAND
10:18:08 Unit OTOR4629 [K1 : PROCEEDING TO INCIDENT]
10:19:41 Unit OTOR4629 [K1 : PROCEEDING TO INCIDENT]
10:44:51 Unit OTOR4629 [K2 : IN ATTENDANCE AT INCIDENT]
10:44:57 Unit OTOR4629 [K2 : IN ATTENDANCE AT INCIDENT]
10:45:11 Unit HAMI4116 [SITREP :] NATIONAL COMMANDER ^{Out of Scope} IS ON THE INCIDENT
10:45:11 GROUND
10:48:05 Unit HAMI4116 [KC : UNIT CALLING]
10:48:33 Unit HAMI4116 [KC : UNIT CALLING]
10:48:41 Unit HAMI4116 [SITREP :] CONTACT FIRE REG ^{Out of Scope} AND HAVE CONTACT THE
10:48:41 COMMAND POINT
10:49:28 Unit HAMI4116 [SITREP :] CONTACT AFRC ^{Out of Scope} TO CONTACT TAMAHERE COMMANI
10:53:09 Unit HAMI4116 [KC : UNIT CALLING]
10:53:51 Unit HAMI4116 [SITREP :] NATIONAL COMMANDER ^{Out of Scope} AND MINISTER INTERNAL
10:53:51 AFFAIRS ON THE FIRE GROUND
11:09:09 Unit OTOR4629 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
11:18:53 Unit HAMI4116 [KC : UNIT CALLING]
11:19:20 Unit AUCKHSA1 [KC : UNIT CALLING]
11:20:07 Unit HAMI4116 [SITREP :] CONTACT AUCKLAND HSA TO CONTANT TAMAHERE COMMAND
11:37:06 Unit CHAR4226 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
11:40:13 Unit HAMI4116 [KC : UNIT CALLING]
11:40:18 Unit ROTO814 [K2 : IN ATTENDANCE AT INCIDENT]
11:40:25 Unit ROTO814 [K2 : IN ATTENDANCE AT INCIDENT]
11:41:11 Unit HAMI4116 [SITREP :] LIAISING WITH HSA AND ENVIRONMENT WAIKATO ON TACTICS
11:44:14 Unit HAMI4116 [KC : UNIT CALLING]
11:44:39 Unit HAMI4116 [SITREP :] REFUELLING OFF TRUCKS COMMENCING
11:57:41 Unit HAMI4116 [KC : UNIT CALLING]
11:58:27 Unit HAMI4116 [SITREP :] INFORM ROTORUA BRIGADE TO BRING ALL FOAM STOCKS TO
11:58:27 TAMAHERE COMMAND
12:18:29 Unit HAMI4116 [KC : UNIT CALLING]
12:19:13 Unit HAMI4116 [SITREP :] UPDATED WEATHER REPORT AND FAX IT
12:26:10 Unit ROTO8129 [K1 : PROCEEDING TO INCIDENT]
12:29:10 FM ^{Out of Scope} @HAMILTON CC - HYDRANTS OUTSIDE 14 RIVERLEA RD HAVE BEEN LEFT
12:29:13 RUNNING
12:49:34 Unit ROTO814 [K2 : IN ATTENDANCE AT INCIDENT]

12:49:40 Unit ROTO814 [K2 : IN ATTENDANCE AT INCIDENT]
13:07:00 Unit HAMI4116 [KC : UNIT CALLING]
13:08:04 Unit HAMI4116 [SITREP :] PREPARING TO APPLY FOAM TO SOUTH WESTERN CORNER OF
13:08:04 INCIDENT AWAITING COMPLETION OF BUNDED AREA
13:10:01 TAMAHERE COMMAND ON 9(2)a
13:10:11 CORRECTION PAGED TO CALL Out of Scope
13:13:55 Unit HAMI4116 [KC : UNIT CALLING]
13:14:55 Unit HAMI4116 [SITREP :] ADV FM TAMAHERE SCHOOL, SCHOOL AND EARLY CHILDHOOD
13:14:55 CENTRE WILL BE CLOSED TOMORROW
13:43:23 Unit HAMIFSO1 [K1 : PROCEEDING TO INCIDENT]
13:43:30 Unit HAMIFSO1 [K1 : PROCEEDING TO INCIDENT]
13:46:45 -
13:47:23 Unit HAMIFSO1 [K2 : IN ATTENDANCE AT INCIDENT]
13:52:11 Unit ROTO8129 [K2 : IN ATTENDANCE AT INCIDENT]
14:02:53 Unit ROTO8129 [KC : UNIT CALLING]
14:22:15 Unit ROTO8129 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
14:30:11 Unit AUCK2015 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
14:38:43 Unit HAMI4116 [KC : UNIT CALLING]
14:39:54 Unit HAMI4116 [SITREP :] MATA TANKER REQUIRED SITREP TO FOLLOW BRIGADE
14:39:54 CARRYING OUT DIRECT FIRE ATTACK OF FOAM AND WATER DELIVERIES
14:42:02 FM MATA FIRE K35 - DETAILS PASSED
14:45:15 Unit MATA3811 [K1 : PROCEEDING TO INCIDENT]
14:55:53 Unit HAMIFTO1 [K1 : PROCEEDING TO INCIDENT]
14:58:40 Unit HAMI4116 [KC : UNIT CALLING]
14:59:19 Unit HAMI4116 [K11P : POLICE REQUIRED] SH 1 FIRE CAUSING CONGESTION
14:59:27 TRAFFIC CONTROL
15:00:21 ** Cross Referenced to Event # P001016640 at: 06/04/08 15:00:21
15:00:21 **
15:08:04 Unit HAMI4116 [KC : UNIT CALLING]
15:09:16 Unit HAMI4116 [SITREP :] CONTACT AUCKLAND CREWS THAT ARE COMING DOWN BRING
15:09:16 THE
15:09:16 BA TENDER
15:16:55 FM CITY STATION BA WILL BE RETURNING TO HAMILTON IN 30 MINS
15:19:48 Unit MATA3811 [K2 : IN ATTENDANCE AT INCIDENT]
15:28:40 Unit AUCK2015 [K1 : PROCEEDING TO INCIDENT]
15:30:17 Unit HAMIFTO1 [K2 : IN ATTENDANCE AT INCIDENT]
15:32:57 Unit TAUPFSO1 [K1 : PROCEEDING TO INCIDENT]
15:36:08 Unit HAMI4116 [KC : UNIT CALLING]
15:46:09 Unit HAMI4116 [SITREP :] HELOT STOOD DOWN EXTERNAL FIRE CHECK ONLY 5 LPD IN
15:55:56 BA
15:55:56 Unit MORR361 [K1 : PROCEEDING TO INCIDENT]
16:00:26 Unit HAMI4116 [KC : UNIT CALLING]
16:00:54 Unit HAMI4116 [K11P : POLICE REQUIRED] TO SORT OUT TRAFFIC URGENTLY ON SH 1
16:05:33 Unit AUCKHSA1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
16:08:38 TAMAHERE COMMAND ASKED Out of Scope TO RING Out of Scope ASAP
16:12:44 Unit HAMI4116 [COMCEN COM : MESSAGE] WHAT IS YOUR PHYSICAL LOCATION POLICE
16:12:44 WISH
16:12:44 TO LIAISE WITH THE COMMAND UNIT

16:12:57 Unit HAMI4116 [SITREP :] ADJACENT TO THE SCHOOL
16:14:04 Unit HAMI4116 [KC : UNIT CALLING]
16:14:26 Unit HAMI4116 [SITREP :] REQUIRE ETA BA TENDER
16:16:14 Unit HAMI4116 [COMCEN COM : MESSAGE] ETA APPROX 30 MINS JUST PASSED RANGIRIRI
16:17:31 Unit AUCK2015 [K1 : PROCEEDING TO INCIDENT]
16:18:09 Unit VSOWAIKATO [K1 : PROCEEDING TO INCIDENT]
16:25:21 Unit MORR361 [K2 : IN ATTENDANCE AT INCIDENT]
16:35:29 ** Situation found NOT
16:49:18 04 474 1098 RE MEDIA INTERVIEW TOMORROW @0700
16:52:32 Unit VSOWAIKATO [K2 : IN ATTENDANCE AT INCIDENT]
16:52:40 Unit AUCK2015 [K2 : IN ATTENDANCE AT INCIDENT]
17:14:49 Unit TAUPFSO1 [K1 : PROCEEDING TO INCIDENT]
17:14:51 Unit HAMI4116 [SITREP :] FAX THRU ANOTHER WEATHER UPDATE
17:18:27 Unit TAUPFSO1 [K2 : IN ATTENDANCE AT INCIDENT]
17:26:27 Unit NGON822 [K2 : IN ATTENDANCE AT INCIDENT]
17:33:49 Unit OTOR4629 [K1 : PROCEEDING TO INCIDENT]
18:00:58 Unit TAURANGA2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
18:09:12 Unit HAMI4116 [KC : UNIT CALLING]
18:10:27 Unit HAMI4116 [SITREP :] REQ UPDATE WEATHER FORECAST
18:21:01 Unit HAMIFSO3 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
18:28:42 Unit HAMI4116 [KC : UNIT CALLING]
18:29:50 Unit HAMI4116 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] AFRC
Out of Scope
18:35:07 Unit BAYW2 [K2 : IN ATTENDANCE AT INCIDENT]
18:49:22 Unit OTOR4629 [K2 : IN ATTENDANCE AT INCIDENT]
18:49:26 Unit HAMI4116 [KC : UNIT CALLING]
18:49:29 Unit OTOR4629 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
18:50:48 Unit NGON822 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
18:53:22 Unit HAMI4116 [SITREP :] AFRM **Out of Scope** CREWS CHANGED NEXT CHANGED TONIGHT
18:53:22 TRUCKS REFILLED DAMPENING DOWN HOTSPOTS TURNOVER OPERATIONS EXPECTED
TO COMMENCE
18:53:22 TOMORROW
19:10:04 Unit TAUPO1 [K6 : ON TELEPAGER]
20:10:13 Unit HAMIFTO1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
20:14:19 NEW CONTACT NUMBER @ FIREGROUND - 9(2)a - AFRC **Out of Scope**
20:28:45 Unit HAMI4116 [KC : UNIT CALLING]
20:29:50 Unit HAMI4116 [SITREP :] NO FURTHER DEVELOPMENTS AUCK2015 RETURNING TO
20:29:50 HAMILTON CITY STATION
21:33:18 Unit TEAW451 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
21:54:10 Unit TOKO8729 [K1 : PROCEEDING TO INCIDENT]
22:14:11 Unit HAMI4116 [KC : UNIT CALLING]
22:16:05 Unit HAMI4116 [SITREP :] TYPE 4 RELOCATION RUNOFF CONTAINED TO BUNDED AREA
22:16:05 SUPERVISED BY ENVIRONMENT WAIKATO CREW CHANGE OVER AT 2400
22:24:02 Unit AUCK2015 [K9 : OFF RT - STATE LOCATION]
22:28:33 Unit TAUP212 [K1 : PROCEEDING TO INCIDENT]
22:34:36 Unit MATA3811 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
22:42:13 Unit TAURANGA1 [K1 : PROCEEDING TO INCIDENT]

22:42:24 Unit TAURANGA1 [K1 : PROCEEDING TO INCIDENT]
22:52:10 Unit MORR361 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
23:24:16 Unit CAMB4411 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
23:30:20 Unit HAMI4116 [KC : UNIT CALLING]
23:30:42 Unit TOKO8729 [K2 : IN ATTENDANCE AT INCIDENT]
23:31:24 Unit HAMI4116 [SITREP :] RESPOND HUNT3211 TO THIS INCIDENT
23:36:11 Unit HUNT3211 [K1 : PROCEEDING TO INCIDENT]
23:37:44 Unit TAURANGA1 [K1 : PROCEEDING TO INCIDENT]
23:37:58 WIND CHANGE - SMOKE WILL PROBABLY START FLOATING ACROSS HAMILTON CITY
23:45:49 Unit CAMB441 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
00:10:42 Unit HUNT3211 [K2 : IN ATTENDANCE AT INCIDENT]
00:11:08 Unit HAMIFSO1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
00:11:29 Unit TAUP212 [K2 : IN ATTENDANCE AT INCIDENT]
00:13:43 Unit TAURANGA1 [K2 : IN ATTENDANCE AT INCIDENT]
00:19:12 Unit HAMI4116 [KC : UNIT CALLING]
00:21:13 Unit HAMI4116 [SITREP :] CREW CHANGEOVER UNDERWAY ROTO814 CREW RETURNING TO
00:21:13 STN ROTO814 NOW MANNED BY AUCKLAND CREW TAUPO CREW & HUNTLY TANKERT IN
00:21:13 ATTENDANCE BRIEFING IN PROGRESS FOR CHANGE OF COMMAND
00:27:30 Unit TEAW4511 [K7 : AT NORMAL STATION]
00:32:52 Unit HAMI4116 [KC : UNIT CALLING]
00:33:23 Unit HAMI4116 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] CFO Out of Scope
00:33:32 Unit TOKO8729 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
00:59:15 Unit ROTO8126 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
01:03:29 REQUEST RECEIVED FROM TAMAHERE COMMAND FOR A PRINTOUT
01:03:49 ICAD REPORTS NOT SHOWING DATA
01:07:20 Unit HAMI4116 [COMCEN COM : MESSAGE] AS PER CFO Out of Scope REQUEST WE ARE
UNABLE
01:07:20 TO ACCESS I-CAD PRINTOUT NOR VIA SMART STATUS. WE CAN PROVIDE A PRINTOUT OF
THE
01:07:20 CHRONOLOGY
01:07:40 Unit HAMI4116 [SITREP :] SEND THRU A PRINTED CHRONOLOGY
01:18:54 ** Cross Referenced to Event # F128994 at: 07/04/08 01:18:54
01:18:54 **
01:44:13 9(2)a CU FAX
01:45:01 SHIFT MANAGER PHONED HOTLINE SETUP FOR SMOKE CONCERNS... ADVISED OF WIND
CHANGE
01:45:01 AND INCREASED NUMBERS OF CALLS... THEY HAD NO KNOWLEDGE OF THIS PHONE
LINE AND
01:45:01 OF WHAT INFORMATION TO PASS TO CALLERS.... THEY ARE FOLLOWING THIS UP DUE TO
01:45:01 NOTIFICATION OF INCREASED CONCERNS AND WIND CHANGE
01:45:30 PROBLEMS WITH ICAD REPORTING DISCOVERED
01:45:43 UNABLE TO PRINT EVENT REPORT ON ICAD REPORTING
01:45:49 FAULTED WITH FIRE SERVICE HELP DESK
01:58:50 Unit BAYW2 [K6 : ON TELEPAGER]
02:18:32 Unit HAMI4116 [KC : UNIT CALLING]
02:19:05 Unit HAMI4116 [SITREP :] CFO Out of Scope RESPOND MORR3611
02:26:37 Unit MORR3611 [K35 : VERIFY ADDRESS OF EVENT]

02:26:47 Unit MORR3611 [COMCEN COM : MESSAGE] DETAILS PASSED
02:27:02 Unit MORR3611 [SITREP :] WILL BE DELAYED SLIGHTLY
02:27:39 Unit MORR3611 [K1 : PROCEEDING TO INCIDENT]
02:49:35 Unit MORR3611 [K2 : IN ATTENDANCE AT INCIDENT]
03:03:08 FRC [Out of Scope] PHONES IN... UPDATES PASSED
03:19:32 Unit HAMI4116 [KC : UNIT CALLING]
03:20:09 Unit HAMI4116 [K26 : UNIT WILL BE ENGAGED AT INCIDENT - STATE TIME] 1
05:46:01 Unit VSOTHAMVAL [K1 : PROCEEDING TO INCIDENT]
06:11:00 Unit HAMI4116 [KC : UNIT CALLING]
06:12:12 Unit HAMI4116 [SITREP :] GRD MONITORS 4 TANKERS IN USE ADV POLICE THERE COULD
06:12:12 BE USE ISSUES WITH SMOKE OVER SH 1
06:13:46 Unit HAMI4116 [SITREP :] FROM CFO [Out of Scope] REPOSITIONED AIREAL & GRD MONITORS
07:01:32 Unit TAUPO1 [K1 : PROCEEDING TO INCIDENT]
07:03:49 TO CALL CFO [Out of Scope] ON HIS CELLPHONE
07:26:31 Unit CAMB4411 [K1 : PROCEEDING TO INCIDENT]
07:27:30 Unit HAMI4116 [KC : UNIT CALLING]
07:28:14 Unit HAMI4116 [SITREP :] CFO [Out of Scope] RESPOND TEAW4511
07:32:02 Unit TAUPFSO1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
07:35:10 Unit TEAW4511 [SITREP :] WILL BE A DELAYED RESPONSE OF 20 MINS
07:37:30 Unit CAMB4411 [K2 : IN ATTENDANCE AT INCIDENT]
07:39:13 Unit HAMIFTO1 [K1 : PROCEEDING TO INCIDENT]
07:55:40 Unit TEAW4511 [K1 : PROCEEDING TO INCIDENT]
07:56:53 Unit HAMIFTO1 [K2 : IN ATTENDANCE AT INCIDENT]
08:09:02 Unit BAYW412 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
08:09:41 Unit BAYW412 [K1 : PROCEEDING TO INCIDENT]
08:19:42 Unit TEAW4511 [K2 : IN ATTENDANCE AT INCIDENT]
08:22:16 Unit VSOMATAPIA [K1 : PROCEEDING TO INCIDENT]
08:43:46 Unit VSOWAIKATO [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
08:52:34 Unit VSOMATAPIA [K1 : PROCEEDING TO INCIDENT]
08:52:41 Unit HAMI4116 [KC : UNIT CALLING]
08:53:36 Unit HAMI4116 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] DCFO [Out of Scope]
09:07:03 Unit TAUPO1 [K2 : IN ATTENDANCE AT INCIDENT]
09:13:40 Unit VSOMATAPIA [KP : PRIORITY MESSAGE]
09:13:48 Unit VSOMATAPIA [KP : PRIORITY MESSAGE]
09:13:56 Unit VSOMATAPIA [KP : PRIORITY MESSAGE]
09:14:12 Unit VSOMATAPIA [KP : PRIORITY MESSAGE]
09:25:04 Unit VSOMATAPIA [KC : UNIT CALLING]
09:28:37 Unit VSOMATAPIA [KC : UNIT CALLING]
09:43:06 OFF A SENIOR POLICE OFFICER FOR A STAKE HOLDERS MEETING
09:44:44 MEETING IS AT 10AM
09:49:08 Unit VSOTHAMVAL [K2 : IN ATTENDANCE AT INCIDENT]
09:55:20 Unit VSOMATAPIA [K2 : IN ATTENDANCE AT INCIDENT]
10:08:48 Unit TAUP212 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
10:11:01 Unit BAYW412 [K2 : IN ATTENDANCE AT INCIDENT]
10:53:45 Unit HAMI4116 [KC : UNIT CALLING]
10:54:23 Unit HAMI4116 [K26 : UNIT WILL BE ENGAGED AT INCIDENT - STATE TIME] K26-1

11:13:11 Unit HAMI4116 [KC : UNIT CALLING]
11:14:07 Unit HAMI4116 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] AFRC Out of Scope
11:14:07 Out of Scope
11:51:53 Unit TAURANGA1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
13:03:21 Unit HAMI4116 [KC : UNIT CALLING]
13:05:06 Unit HAMI4116 [SITREP :] STAKE HOLDER AND MEDIA LIAISON MEETING AT 1300 HOURS
13:05:06 WAITING FOR 2 DIGGERS TO BE USED IN CONJUNCTION WITH AERIAL APPLIANCES
14:01:12 COMMAND
14:45:13 Unit HAMI415 [K2 : IN ATTENDANCE AT INCIDENT]
15:24:31 Unit HAMI4116 [KC : UNIT CALLING]
15:25:18 Unit HAMI4116 [SITREP :] HAVE CHAR427 RESPOND WITH CHAINSAW
15:31:35 Unit CHAR427 [K1 : PROCEEDING TO INCIDENT]
15:41:00 Unit CHAR427 [K2 : IN ATTENDANCE AT INCIDENT]
16:11:00 Unit HAMI4116 [KC : UNIT CALLING]
16:11:32 Unit CHAR427 [K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]
16:18:20 Unit CHAR427 [K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]
16:22:30 Unit CHAR427 [K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]
16:29:37 Unit CHAR427 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
17:01:17 Unit ROTORUA2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
17:32:41 Unit BAYW410 [K1 : PROCEEDING TO INCIDENT]
17:32:52 Unit BAYW410 [K2 : IN ATTENDANCE AT INCIDENT]
17:33:04 Unit BAYW412 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
17:56:17 Unit HUNT3226 [KC : UNIT CALLING]
17:57:13 Unit HUNT3226 [K1 : PROCEEDING TO INCIDENT]
18:18:04 Unit HAMI411 [K7 : AT NORMAL STATION]
18:24:48 Unit HAMI4116 [KC : UNIT CALLING]
18:33:17 Unit HAMI4116 [SITREP :] ETA GREE751 - 1 HR
18:39:35 Unit GREE751 [K1 : PROCEEDING TO INCIDENT]
18:42:25 Unit HUNT3226 [K2 : IN ATTENDANCE AT INCIDENT]
18:42:54 Unit GREE751 [K1 : PROCEEDING TO INCIDENT]
18:48:12 Unit VSOTHAMVAL [KC : UNIT CALLING]
18:48:58 Unit GREE751 [KC : UNIT CALLING]
18:49:18 Unit VSOTHAMVAL [KC : UNIT CALLING]
19:04:54 Unit VSOWAIKATO [K1 : PROCEEDING TO INCIDENT]
19:18:23 Unit VSOMATAPIA [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
19:23:12 Unit VSOTHAMVAL [KC : UNIT CALLING]
19:24:09 Unit VSOTHAMVAL [SITREP :] ADVISE GREE751 TO PULL OVER - JUST GONE PAST THEM
19:26:05 Unit VSOWAIKATO [K2 : IN ATTENDANCE AT INCIDENT]
19:26:30 Unit HAMI4116 [KC : UNIT CALLING]
19:36:03 Unit HAMI4116 [KC : UNIT CALLING]
19:37:17 Unit GREE751 [K1 : PROCEEDING TO INCIDENT]
19:37:35 Unit HAMI4116 [SITREP :] 2 DIGGERS WORKING IN WESTERN CORNER REMOVING IRON
AND
19:37:35 CRATES INTO POADDOCK A14 WATER TOWER IS ON NORTH EASTERN CORNER 814
CREWS
19:37:35 WORKING IN BA 415 RELOCATED TO NORTH WESTERN CORNER
20:01:40 Unit HAMIFTO1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

20:07:00 Unit GREE751 [K1 : PROCEEDING TO INCIDENT]
20:22:53 Unit GREE751 [K2 : IN ATTENDANCE AT INCIDENT]
20:23:02 Unit GREE751 [K7 : AT NORMAL STATION]
20:28:14 Unit TAUPO1 [K6 : ON TELEPAGER]
20:33:20 Unit HAMI4116 [KC : UNIT CALLING]
20:33:51 Unit HAMI4116 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SSO [Out of Scope]
21:38:18 Unit VSOWAIKATO [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
22:20:42 Unit HAMI4116 [COMCEN COM : MESSAGE] CFO [Out of Scope] WANTS YOUR CELL - 9(2)a
22:31:59 Unit TAUP212 [K1 : PROCEEDING TO INCIDENT]
00:06:36 TAUPO212 IS COMING THROUGH KARAPIRO, STOPPING AT CAMBRIDGE FOR FUEL
00:50:14 Unit TAUP212 [K2 : IN ATTENDANCE AT INCIDENT]
00:52:30 Unit HAMI4116 [KC : UNIT CALLING]
00:53:17 Unit HAMI4116 [SITREP :] CELL PHONE COVERAGE DOWN CAN CONTACT ME ON [9(2)a]
00:58:23 Unit HUNT3226 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
01:10:57 Unit HAMI4116 [KC : UNIT CALLING]
01:11:45 Unit HAMI4116 [SITREP :] TAUP CREW ON SITE - ROTO CREW LEFT SITE CELL PHONE
01:11:45 BACK UP
01:25:50 Unit HAMI4116 [KC : UNIT CALLING]
01:26:32 Unit HAMI4116 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SO [Out of Scope]
02:08:02 Unit MORR3611 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
02:39:47 Unit OTOR4611 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
03:00:13 Unit HAMI4116 [KC : UNIT CALLING]
03:01:44 Unit HAMI4116 [SITREP :] UNABLE TO ACCRESS ALL SEATS OF FIRE - SNORKEL
03:01:44 RELOCATING TO EASTERN SIDE - 1 DIGGER- STILL WORKING ON NORTHERN FACE 814
HAS
03:01:44 BEEN STOODDOWN WITH 1 CREW MONITORING HOTSPOTS
04:12:06 Unit HAMI4116 [KC : UNIT CALLING]
04:13:30 Unit HAMI4116 [SITREP :] REMAINING FIRES DEEP SEATED UNABLE TO EXTING UNTIL
04:13:30 TURNOVER COMENCENCES ALONG W SCENE I NVEST GREE CREW LEAVING SIGHT 1
DIGGER
04:13:30 WORKING NORTH WEST CORNER CREWS CONTINUE TO MONOITOR SCENE
05:41:53 Unit VSOWESTBOP [K1 : PROCEEDING TO INCIDENT]
06:03:36 Unit HAMI4116 [KC : UNIT CALLING]
06:04:12 Unit HAMI4116 [SITREP :] ANOTHER WEATHER FORECAST REQUIRED FOR THIS AREA
06:06:25 ETA 30 MIN OF UPDATE
06:09:24 Unit VSOWESTBOP [K1 : PROCEEDING TO INCIDENT]
06:10:43 Unit MORR3611 [K1 : PROCEEDING TO INCIDENT]
06:17:40 Unit HAMI4116 [KC : UNIT CALLING]
06:18:13 Unit HAMI4116 [SITREP :] CREWS DAMPENING FURTHER HOT SPOTS NO FURTHER
06:18:13 DEVELOPMENTS
06:36:47 Unit MORR3611 [K2 : IN ATTENDANCE AT INCIDENT]
06:49:39 Unit TAURANGA2 [K1 : PROCEEDING TO INCIDENT]
06:52:31 Unit VSOWESTBOP [K2 : IN ATTENDANCE AT INCIDENT]
06:59:30 Unit OTOR4611 [K1 : PROCEEDING TO INCIDENT]
07:31:22 Unit TAURANGA2 [K1 : PROCEEDING TO INCIDENT]
07:41:05 Unit BAYW410 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
07:41:54 Unit OTOR4611 [K2 : IN ATTENDANCE AT INCIDENT]

07:50:45 Unit HAMIFTO1 [K1 : PROCEEDING TO INCIDENT]
07:57:29 Unit TAURANGA2 [K2 : IN ATTENDANCE AT INCIDENT]
08:15:00 Unit HAMIFTO1 [K2 : IN ATTENDANCE AT INCIDENT]
08:23:38 Unit HAMI4116 [KC : UNIT CALLING]
08:24:57 Unit HAMI4116 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] AFRC
Out of Scope
08:24:57 LIASING WITH ONSITE MANAGEMENT AT 0800 HOURS WILL UPDATE FURTHER AT
COMMENCEMENT
08:24:57 OF THAT MEETING
08:26:27 Unit VSOTHAMVAL [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
08:55:19 Unit VSOMATAPIA [K1 : PROCEEDING TO INCIDENT]
09:07:40 Unit TAUP212 [K0 : NOT AVAILABLE]
09:32:36 Unit VSOMATAPIA [K1 : PROCEEDING TO INCIDENT]
09:37:13 Unit CAMB4411 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
10:18:56 Unit VSOMATAPIA [K2 : IN ATTENDANCE AT INCIDENT]
11:35:57 Unit ROTO814 [KC : UNIT CALLING]
11:36:04 Unit ROTO814 [KC : UNIT CALLING]
11:37:25 Unit ROTO814 [K0 : NOT AVAILABLE]
12:05:19 Unit HAMIFTO1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
13:47:03 Unit HAMI4116 [SITREP :] CONTACT POLICE ABOUT THE NUMBER OF VEHICLES LEAVING
13:47:03 THE SITE AND THE ROUNDABOUT BY AIRPORT INTERCHANGE IS VERY SLIPPERY
13:48:10 Unit HAMI4116 [SITREP :] AFRC Out of Scope FIRE INV TEAM IS ON SITE AND
13:48:10 COMMENCING THEIR INVESTIGATION
13:58:12 Unit HAMI4116 [KC : UNIT CALLING]
14:15:20 Unit VSOMATAPIA [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
14:42:26 Unit TAURANGA2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
15:31:33 Unit MORR3611 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
15:53:21 Unit HAMI415 [K7 : AT NORMAL STATION]
16:28:34 Unit OTOR4611 [KC : UNIT CALLING]
16:29:43 Unit OTOR4611 [SITREP :] GOING K3 TO GET CLEANED UP THEN RETURNING TO STATION
16:39:14 Unit TEAW4511 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
16:45:59 Unit HAMI4116 [KP : PRIORITY MESSAGE]
16:46:33 Unit HAMI4116 [SITREP :] ONE CREW DAMPENING HOTSPOTS
17:18:49 Unit HAMI4116 [KC : UNIT CALLING]
17:54:51 Unit OTOR4611 [KC : UNIT CALLING]
18:23:01 Unit OTOR4611 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
18:46:10 Unit HAMI4116 [KC : UNIT CALLING]
18:46:38 Unit HAMI4116 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SSO Out of Scope
19:24:28 Unit HAMI4116 [KC : UNIT CALLING]
19:25:02 Unit HAMI4116 [SITREP :] ANY CONTACT FOR TAMAHERE 9(2)a
19:51:21 Unit VSOWESTBOP [K22-1 : UNIT AVAILABLE FOR A FURTHER EVENT]
21:09:37 Unit VSOWESTBOP [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
01:30:36 Unit HAMI4116 [KC : UNIT CALLING]
01:31:18 Unit HAMI4116 [SITREP :] DAMPENING DOWN HOT SPOTS 2 LPD
07:47:25 Unit VSOMATAPIA [K1 : PROCEEDING TO INCIDENT]
07:51:11 Unit VSOMATAPIA [K1 : PROCEEDING TO INCIDENT]
08:16:58 Unit ROTO812 [K1 : PROCEEDING TO INCIDENT]

08:31:23 Unit HAMI4116 [KC : UNIT CALLING]
08:32:03 Unit HAMI4116 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] CFO **Out of Scope**
08:42:29 Unit VSOMATAPIA [K2 : IN ATTENDANCE AT INCIDENT]
09:03:04 Unit ROTO812 [K1 : PROCEEDING TO INCIDENT]
09:03:10 Unit ROTO812 [K1 : PROCEEDING TO INCIDENT]
09:41:52 Unit ROTO812 [K2 : IN ATTENDANCE AT INCIDENT]
10:09:20 Unit HAMI4116 [KC : UNIT CALLING]
10:10:07 Unit HAMI4116 [SITREP :] CAN YOU PLEASE RESPOND HAMI415 TO TAMAHERE
COMMAND
10:10:07 ROAD SPEED
10:10:40 Unit HAMI415 [K2 : IN ATTENDANCE AT INCIDENT]
10:25:11 Unit TAUPO1 [K1 : PROCEEDING TO INCIDENT]
11:19:09 Unit HAMI4116 [KC : UNIT CALLING]
11:19:34 Unit HAMI4116 [SITREP :] PERMISSION TO SPEAK TO HAMI411
11:19:44 Unit HAMI4116 [COMCEN COM : MESSAGE] GRANTED
11:58:22 Unit TAUPO1 [K2 : IN ATTENDANCE AT INCIDENT]
11:58:28 Unit TAUPO1 [K2 : IN ATTENDANCE AT INCIDENT]
13:08:32 Unit HAMI4116 [KC : UNIT CALLING]
13:09:06 Unit HAMI4116 [SITREP :] MAKE TANKERS 1 - NORMAL TRAFFIC
13:13:17 Unit CAMB4411 [K35 : VERIFY ADDRESS OF EVENT]
13:13:28 Unit CAMB4411 [SITREP :] AWAITING DRIVER
13:19:36 Unit CAMB4411 [K1 : PROCEEDING TO INCIDENT]
13:41:29 Unit CAMB4411 [K2 : IN ATTENDANCE AT INCIDENT]
13:42:31 Unit HAMI415 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
15:04:50 Unit HAMI4116 [KC : UNIT CALLING]
15:05:13 Unit CAMB4411 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
15:05:22 Unit HAMI4116 [SITREP :] DEMO CONTRACTORS ARE COMMENCING WORK
17:03:08 Unit ROTO812 [K0 : NOT AVAILABLE]
17:40:35 Unit VSOMATAPIA [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
18:50:41 Unit HAMI4116 [KC : UNIT CALLING]
18:51:06 Unit HAMI4116 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SO **Out of Scope**
18:57:48 Unit TAUPO1 [K6 : ON TELEPAGER]
19:01:32 Unit HAMI4116 [KP : PRIORITY MESSAGE]
19:02:09 Unit HAMI4116 [KP : PRIORITY MESSAGE] MAKE TANKERS 1
19:04:10 Unit CAMB4411 [K35 : VERIFY ADDRESS OF EVENT] DETAILS PASSED
19:04:25 Unit CAMB4411 [SITREP :] WILL CONTACT VIA PHONE
19:06:18 Unit CAMB4411 [K7 : AT NORMAL STATION]
19:07:04 Unit TEAW4511 [K35 : VERIFY ADDRESS OF EVENT] DETAILS PASSED
19:08:03 Unit TEAW4511 [K1 : PROCEEDING TO INCIDENT]
19:26:02 Unit TEAW4511 [K2 : IN ATTENDANCE AT INCIDENT]
19:42:15 Unit HAMI4116 [KC : UNIT CALLING]
19:42:53 Unit HAMI4116 [SITREP :] HAMI411 IS KO, 411 CREW MANNING TAMEHERE COMMAND
22:14:46 Unit HAMI4116 [KC : UNIT CALLING]
22:21:01 Unit TEAW4511 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
23:57:19 Unit HAMI4116 [KC : UNIT CALLING]
23:58:31 Unit HAMI4116 [SITREP :] CONTRACTORS HAVE LEFT SITE RETURNING IN THE MORNING
00:07:34 Unit HAMI4116 [KC : UNIT CALLING]

00:08:11 Unit HAMI4116 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SO [Out of Scope]
04:06:59 Unit HAMI4116 [KC : UNIT CALLING]
04:07:32 Unit HAMI4116 [K26 : UNIT WILL BE ENGAGED AT INCIDENT - STATE TIME] ONE
04:18:40 Unit HAMI4116 [KC : UNIT CALLING]
04:19:45 Unit HAMI4116 [SITREP :] DISPATCH AN ADDITIONAL TANKER TO THIS SCENE AS
04:19:45 PORTABLE PUMP HAS BROKEN ON HUNTLYS TANKER, ALSO PAGE ON CALL MECHANICS
TO
04:19:45 CONTACT TAMAHERE COMMAND
04:23:08 Unit CAMB4411 [K35 : VERIFY ADDRESS OF EVENT] DETAILS PASSED
04:27:14 Unit CAMB4411 [K1 : PROCEEDING TO INCIDENT]
04:40:06 Unit HAMI4116 [KC : UNIT CALLING]
04:40:26 Unit HAMI4116 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SO [Out of Scope]
05:12:00 Unit CAMB4411 [K2 : IN ATTENDANCE AT INCIDENT]
05:37:00 Unit HAMI4116 [SITREP :] SO [Out of Scope] FIRE IN CENTRE OF RUBBISH TOO DANGEROUS FOR
05:37:00 LOW PRESSURE DELIVERIES UNABLE TO REACH WITH TRUCK MONITOR CAMB4411
RELEASED
05:37:00 FROM SCENE
05:51:56 Unit CAMB4411 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
07:05:56 Unit HAMI4116 [KC : UNIT CALLING]
07:07:12 Unit HAMI4116 [SITREP :] SO [Out of Scope] PERIMETER SEARCH CARRIED OUT STILL DEEP
07:07:12 SEATED FIRE UNABLE TO EXTINGUISH
07:27:57 Unit HAMI4116 [KC : UNIT CALLING]
07:28:34 Unit HAMI4116 [SITREP :] CONTRACTORS STARTING DEMOLITION AS WELL AS BUILDING
07:28:34 OWNER ON SITE
08:08:12 Unit VSOWAIKATO [K1 : PROCEEDING TO INCIDENT]
08:13:20 TAURFS01 HAS BEEN ON THIS JOB SINCE MONDAY
08:43:41 Unit HAMI4116 [KC : UNIT CALLING]
08:46:23 Unit HAMI4116 [KC : UNIT CALLING]
08:46:46 Unit HAMI4116 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] CFO [Out of Scope]
08:51:17 Unit VSOWAIKATO [K2 : IN ATTENDANCE AT INCIDENT]
08:54:16 Unit TAURFS01 [K1 : PROCEEDING TO INCIDENT]
09:55:43 Unit GREE7520 [K1 : PROCEEDING TO INCIDENT]
10:08:09 Unit ROTO814 [K1 : PROCEEDING TO INCIDENT]
10:21:54 Unit OTOR4611 [K1 : PROCEEDING TO INCIDENT]
10:33:35 Unit PAPA3811 [K1 : PROCEEDING TO INCIDENT]
10:33:44 Unit MANUKAU2 [K1 : PROCEEDING TO INCIDENT]
10:34:26 Unit PAPA387 [K1 : PROCEEDING TO INCIDENT]
10:41:46 Unit OTOR4611 [K1 : PROCEEDING TO INCIDENT]
10:43:57 Unit ROTO814 [K1 : PROCEEDING TO INCIDENT]
11:02:21 Unit OTOR4611 [K2 : IN ATTENDANCE AT INCIDENT]
11:23:09 Unit ROTO814 [K2 : IN ATTENDANCE AT INCIDENT]
11:41:14 Unit HAMI4116 [KC : UNIT CALLING]
11:41:53 Unit HAMI4116 [SITREP :] RESPOND OPERATIONAL SUPPORT WITH CREW OF 2 MIN
11:41:57 Unit HAMI4116 [KC : UNIT CALLING]
11:42:21 Unit HAMI4116 [SITREP :] 2 CREW WILL BE FINE NORMAL ROAD SPEED
11:44:48 .
11:49:13 Unit HAMI4116 [KC : UNIT CALLING]

11:49:41 Unit HAMI4116 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] SO Out of Scope
11:50:20 Unit CHAR4226 [KC : UNIT CALLING]
12:00:26 Unit CHAR4226 [K1 : PROCEEDING TO INCIDENT]
12:00:32 Unit CHAR4226 [K1 : PROCEEDING TO INCIDENT]
12:08:01 Unit CHAR4226 [KC : UNIT CALLING]
12:08:07 Unit CHAR4226 [KC : UNIT CALLING]
12:14:28 Unit PAPA387 [K2 : IN ATTENDANCE AT INCIDENT]
12:14:35 Unit PAPA387 [K2 : IN ATTENDANCE AT INCIDENT]
12:14:43 Unit PAPA387 [K2 : IN ATTENDANCE AT INCIDENT]
12:14:50 Unit PAPA387 [K2 : IN ATTENDANCE AT INCIDENT]
12:14:57 Unit PAPA387 [K2 : IN ATTENDANCE AT INCIDENT]
12:15:04 Unit PAPA387 [K2 : IN ATTENDANCE AT INCIDENT]
12:16:03 Unit CHAR4226 [KC : UNIT CALLING]
12:30:53 Unit CHAR4226 [KC : UNIT CALLING]
12:38:03 Unit PAPA387 [K2 : IN ATTENDANCE AT INCIDENT]
12:38:10 Unit PAPA387 [K2 : IN ATTENDANCE AT INCIDENT]
12:53:19 Unit MANUKAU2 [K2 : IN ATTENDANCE AT INCIDENT]
13:09:21 Unit MORR3611 [K1 : PROCEEDING TO INCIDENT]
13:09:31 Unit MORR3611 [K38 : ASSOCIATE THIS UNIT TO EVENT - EVENT ADDRESS]
13:18:26 Unit PAPA387 [K2 : IN ATTENDANCE AT INCIDENT]
13:20:23 Unit PAPA387 [K2 : IN ATTENDANCE AT INCIDENT]
13:34:08 Unit MORR3611 [K2 : IN ATTENDANCE AT INCIDENT]
13:41:23 Unit HAMI4116 [KC : UNIT CALLING]
13:42:06 Unit HAMI4116 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] DCFO Out of Scope
13:46:31 Unit CHAR4226 [K2 : IN ATTENDANCE AT INCIDENT]
14:13:49 Unit HAMI4116 [KC : UNIT CALLING]
14:14:29 Unit HAMI4116 [K45 : COMMAND RESPONSIBILITY CHANGED TO - NAME] DCFO Out of Scope
14:14:51 Unit HAMI4116 [SITREP :] CAN WE HAVE AN UPDATED WEATHER REPORT FAXED TO
14:14:51 COMMAND
14:43:42 Unit HUNT3211 [K7 : AT NORMAL STATION]
15:23:53 Unit HAMI4116 [KC : UNIT CALLING]
15:24:37 Unit HAMI4116 [SITREP :] DAMPENING DOWN CONTINUING WITH ASSISTANCE OF ARIEL
15:24:37 APPLIANCE
16:37:25 Unit HAMI4116 [COMCEN COM : MESSAGE] HAMILTON FIRE WILL ENSURE WEATHER
16:37:25 REPORT IS
16:37:25 DELIVERED TO YOU
16:37:59 Unit HAMI4116 [SITREP :] WE HAVE RCVD FAX HERE ON SITE
17:33:22 Unit OTOR4611 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
17:34:22 Unit HAMI4116 [KC : UNIT CALLING]
17:35:06 Unit HAMI4116 [SITREP :] DISASTABLISHING ALL MESSAGES THROUGH PAPA387 DCFO
17:35:06 Out of Scope
17:42:31 Unit MORR3611 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
17:55:09 Unit TAUPO1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
17:55:54 Unit TAURFSO1 [K2 : IN ATTENDANCE AT INCIDENT]
17:56:04 Unit GREE7520 [K2 : IN ATTENDANCE AT INCIDENT]
18:02:45 Unit TAURFSO1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
18:49:07 Unit CHAR4226 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]

18:56:59 Unit GREE7520 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
19:05:39 Unit VSOWAIKATO [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
19:06:26 Unit ONEH221 [K1 : PROCEEDING TO INCIDENT]
19:26:57 Unit PAPA387 [K2 : IN ATTENDANCE AT INCIDENT]
19:27:20 Unit PAPA387 [K2 : IN ATTENDANCE AT INCIDENT]
20:00:59 Unit PAPA3429 [K9 : OFF RT - STATE LOCATION]
20:01:53 Unit PAPA3429 [K1 : PROCEEDING TO INCIDENT]
20:07:56 Unit MANUKAU2 [K2 : IN ATTENDANCE AT INCIDENT]
20:08:04 Unit MANUKAU2 [K2 : IN ATTENDANCE AT INCIDENT]
21:07:13 Unit PAPA387 [KC : UNIT CALLING]
21:38:29 Unit MANUKAU2 [K2 : IN ATTENDANCE AT INCIDENT]
21:38:35 Unit MANUKAU2 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
21:46:15 Unit ONEH221 [K2 : IN ATTENDANCE AT INCIDENT]
21:46:15 Unit PAPA3429 [K2 : IN ATTENDANCE AT INCIDENT]
21:48:45 Unit PAPA3429 [K2 : IN ATTENDANCE AT INCIDENT]
22:43:52 Unit ONEH221 [K7 : AT NORMAL STATION]
22:47:13 Unit ONEH221 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
22:48:16 Unit ONEH221 [K2 : IN ATTENDANCE AT INCIDENT]
08:06:59 Unit PAPA387 [KC : UNIT CALLING]
08:08:08 Unit PAPA387 [SITREP :] IN BAY WAIKATO REGION RETURNING TO TAMAHERE
09:54:16 Unit ONEH221 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
14:42:44 Unit PAPA3429 [K2 : IN ATTENDANCE AT INCIDENT]
18:40:47 Unit ONEH221 [K1 : PROCEEDING TO INCIDENT]
20:12:55 Unit ONEH221 [K2 : IN ATTENDANCE AT INCIDENT]
20:14:24 Unit ONEH221 [K31 : REQUEST PERMISSION TO GO OFF RT] AVAILABLE ON CELLPHONE
20:14:24 9(2)a
20:14:24 9(2)a (Out of Scope)
20:47:29 Unit ONEH221 [K2 : IN ATTENDANCE AT INCIDENT]
10:32:47 Unit ONEH221 [K2 : IN ATTENDANCE AT INCIDENT]
12:24:08 Unit ONEH221 [K7 : AT NORMAL STATION]
18:00:41 STOP MESSAGE :HAM411 OPERATION SHUTTING DOWN INVESTIGATORS FINDINGS COMPLETE
18:00:55 COMMAND UNIT SHUTTING DOWN LEFT IN HANDS OF CONTRACTOR & OWNER
18:01:57 Unit HAMI4116 [STOP : MESSAGE] OPERATION SHUTTING DOWN INVESTIGATORS FINDINGS COMPLETE
18:01:57 COMPLETE COMMAND UNIT SHUTTING DOWN LEFT IN HANDS OF CONTRACTOR & OWNER
18:11:13 Unit TAURFSO1 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
18:18:29 Unit ROTO814 [K3 : ON RT OUTSIDE NORMAL TURNOUT AREA]
19:45:13 Unit PAPA387 [K2 : IN ATTENDANCE AT INCIDENT]
19:51:57 Unit PAPA387 [K7 : AT NORMAL STATION]
19:59:04 Unit PAPA3811 [K2 : IN ATTENDANCE AT INCIDENT]
19:59:21 Unit PAPA3811 [K7 : AT NORMAL STATION]
20:02:31 Unit PAPA3429 [K4 : ON RT INSIDE NORMAL TURNOUT AREA]
20:16:26 BUSINESS RULE CHECKS CANCELLED AT 12/04/08 20:16:26
23:59:40 UNIT BAYW2 RESPONSE TIME [NULL] ADJUSTED TO
23:59:40 20080405201336NS AT 12/04/08 23:59:33
23:59:41 UNIT BAYW2 RESPONSE TIME [NULL] ADJUSTED TO

23:59:41 UNIT CAMB447 RESPONSE TIME [NULL] ADJUSTED TO
23:59:41 20080405172501NS AT 12/04/08 23:59:34
23:59:41 20080405190552NS AT 12/04/08 23:59:33
23:59:41 20080406022012NS AT 12/04/08 23:59:34
23:59:41 20080406183407NS AT 12/04/08 23:59:34
00:02:18 UNIT AUCKFPOL5 ALERT TIME [NULL] ADJUSTED TO
00:02:18 20080405200924NS AT 13/04/08 00:02:11
00:02:18 20080405201354NS AT 13/04/08 00:02:11
00:02:19 UNIT AUCKFPOL5 ALERT TIME [NULL] ADJUSTED TO
00:02:19 UNIT AUCKFPOL6 ALERT TIME [NULL] ADJUSTED TO
00:02:19 UNIT BAYW1 ALERT TIME [NULL] ADJUSTED TO
00:02:19 UNIT CENTAUCK1 ALERT TIME [NULL] ADJUSTED TO
00:02:19 UNIT GREE7520 ALERT TIME [NULL] ADJUSTED TO
00:02:19 20080405174108NS AT 13/04/08 00:02:11
00:02:19 20080405193533NS AT 13/04/08 00:02:11
00:02:19 20080405194246NS AT 13/04/08 00:02:11
00:02:19 20080405201354NS AT 13/04/08 00:02:11
00:02:19 20080405222805NS AT 13/04/08 00:02:11
00:02:19 20080410095443NS AT 13/04/08 00:02:12
00:02:20 UNIT HAMI6819 ALERT TIME [NULL] ADJUSTED TO
00:02:20 UNIT HAMILTON2 ALERT TIME [NULL] ADJUSTED TO
00:02:20 UNIT MATA382 ALERT TIME [NULL] ADJUSTED TO
00:02:20 UNIT NGON822 ALERT TIME [NULL] ADJUSTED TO
00:02:20 20080405163707NS AT 13/04/08 00:02:12
00:02:20 20080405173250NS AT 13/04/08 00:02:12
00:02:20 20080405182813NS AT 13/04/08 00:02:12
00:02:20 20080405182828NS AT 13/04/08 00:02:12
00:02:20 20080406070126NS AT 13/04/08 00:02:13
00:02:21 UNIT NGON822 ALERT TIME [NULL] ADJUSTED TO
00:02:21 UNIT NORTHCOM2 ALERT TIME [NULL] ADJUSTED TO
00:02:21 UNIT ROTO811 ALERT TIME [NULL] ADJUSTED TO
00:02:21 UNIT ROTO812 ALERT TIME [NULL] ADJUSTED TO
00:02:21 20080405163540NS AT 13/04/08 00:02:13
00:02:21 20080405173157NS AT 13/04/08 00:02:13
00:02:21 20080406075016NS AT 13/04/08 00:02:13
00:02:21 20080409081458NS AT 13/04/08 00:02:13
00:02:21 20080409090204NS AT 13/04/08 00:02:13
00:02:21 20080409090209NS AT 13/04/08 00:02:13
00:02:22 UNIT ROTO8129 ALERT TIME [NULL] ADJUSTED TO
00:02:22 UNIT ROTO814 ALERT TIME [NULL] ADJUSTED TO
00:02:22 UNIT ROTORUA2 ALERT TIME [NULL] ADJUSTED TO
00:02:22 20080405221047NS AT 13/04/08 00:02:14
00:02:22 20080406071703NS AT 13/04/08 00:02:14
00:02:22 20080406122509NS AT 13/04/08 00:02:14
00:02:22 20080410100709NS AT 13/04/08 00:02:14
00:02:22 20080410104257NS AT 13/04/08 00:02:14

00:02:23 UNIT TAUP212 ALERT TIME [NULL] ADJUSTED TO
00:02:23 UNIT TAUPFSO1 ALERT TIME [NULL] ADJUSTED TO
00:02:23 UNIT TOKO8729 ALERT TIME [NULL] ADJUSTED TO
00:02:23 UNIT VSOSTHWAKO ALERT TIME [NULL] ADJUSTED TO
00:02:23 20080405182316NS AT 13/04/08 00:02:15
00:02:23 20080405185659NS AT 13/04/08 00:02:15
00:02:23 20080406153157NS AT 13/04/08 00:02:15
00:02:23 20080406171349NS AT 13/04/08 00:02:15
00:02:23 20080406215310NS AT 13/04/08 00:02:15
00:02:23 20080406222733NS AT 13/04/08 00:02:14
00:02:23 20080407223059NS AT 13/04/08 00:02:14
00:05:01 INCIDENT STOP TIME 20080405163847ND ADJUSTED TO
00:05:01 20080412180157NS AT 13/04/08 00:04:58
00:05:01 ** Assigned Result Code: STRU, Detailed Event Type: 1100, Qualifier 1: Q1,
00:05:01 Qualifier 2:
00:05:02 BUSINESS RULE CHECKS SUCCESSFULLY COMPLETED AT
00:05:02 D0191985
02:17:43 WAIU

Additional Calls Message Log

Time	Message
16:31:44	***** Privacy filter – refer to footer *****
16:31:44	***** Privacy filter – refer to footer *****
16:31:44	***** Privacy filter – refer to footer *****
16:31:44	***** Privacy filter – refer to footer *****
16:33:24	***** Privacy filter – refer to footer *****
16:33:24	***** Privacy filter – refer to footer *****
16:33:24	***** Privacy filter – refer to footer *****
16:33:24	***** Privacy filter – refer to footer *****
16:33:24	***** Privacy filter – refer to footer *****
16:33:36	***** Privacy filter – refer to footer *****
16:33:36	***** Privacy filter – refer to footer *****
16:33:36	***** Privacy filter – refer to footer *****
16:33:36	***** Privacy filter – refer to footer *****
16:33:37	***** Privacy filter – refer to footer *****
16:33:39	***** Privacy filter – refer to footer *****
16:33:39	***** Privacy filter – refer to footer *****
16:33:39	***** Privacy filter – refer to footer *****
16:33:39	***** Privacy filter – refer to footer *****
16:34:16	***** Privacy filter – refer to footer *****
16:34:16	***** Privacy filter – refer to footer *****
16:34:16	***** Privacy filter – refer to footer *****
16:34:16	***** Privacy filter – refer to footer *****
16:34:16	***** Privacy filter – refer to footer *****
16:34:16	***** Privacy filter – refer to footer *****
16:34:16	***** Privacy filter – refer to footer *****
16:34:16	***** Privacy filter – refer to footer *****
16:34:16	***** Privacy filter – refer to footer *****
16:35:43	***** Privacy filter – refer to footer *****
16:35:43	***** Privacy filter – refer to footer *****
16:35:43	***** Privacy filter – refer to footer *****
16:35:43	***** Privacy filter – refer to footer *****
16:39:15	***** Privacy filter – refer to footer *****
16:39:15	***** Privacy filter – refer to footer *****
16:39:15	***** Privacy filter – refer to footer *****
16:39:15	***** Privacy filter – refer to footer *****
16:39:16	***** Privacy filter – refer to footer *****
16:39:16	***** Privacy filter – refer to footer *****
16:39:18	***** Privacy filter – refer to footer *****
16:39:18	***** Privacy filter – refer to footer *****
16:39:18	***** Privacy filter – refer to footer *****
16:39:18	***** Privacy filter – refer to footer *****
16:39:18	***** Privacy filter – refer to footer *****
16:39:19	***** Privacy filter – refer to footer *****
16:39:19	***** Privacy filter – refer to footer *****
16:39:19	***** Privacy filter – refer to footer *****

16:45:15 ***** Privacy filter – refer to footer *****
16:45:15 ***** Privacy filter – refer to footer *****
16:46:26 ***** Privacy filter – refer to footer *****
16:46:26 ***** Privacy filter – refer to footer *****
16:46:26 ***** Privacy filter – refer to footer *****
16:46:27 ***** Privacy filter – refer to footer *****
16:48:29 ***** Privacy filter – refer to footer *****
16:48:29 ***** Privacy filter – refer to footer *****
16:48:29 ***** Privacy filter – refer to footer *****
16:48:29 ***** Privacy filter – refer to footer *****
16:48:29 ***** Privacy filter – refer to footer *****
16:54:02 ***** Privacy filter – refer to footer *****
16:54:02 ***** Privacy filter – refer to footer *****
16:54:02 ***** Privacy filter – refer to footer *****
16:54:02 ***** Privacy filter – refer to footer *****
16:54:03 ***** Privacy filter – refer to footer *****
16:54:16 ***** Privacy filter – refer to footer *****
16:54:16 ***** Privacy filter – refer to footer *****
16:54:16 ***** Privacy filter – refer to footer *****
16:54:16 ***** Privacy filter – refer to footer *****
16:54:16 ***** Privacy filter – refer to footer *****
16:54:16 ***** Privacy filter – refer to footer *****
16:54:16 ***** Privacy filter – refer to footer *****
16:54:16 ***** Privacy filter – refer to footer *****
16:54:16 ***** Privacy filter – refer to footer *****
16:54:16 ***** Privacy filter – refer to footer *****
16:54:16 ***** Privacy filter – refer to footer *****
16:54:16 ***** Privacy filter – refer to footer *****
16:54:16 ***** Privacy filter – refer to footer *****
16:54:16 ***** Privacy filter – refer to footer *****
16:54:16 ***** Privacy filter – refer to footer *****
16:54:17 ***** Privacy filter – refer to footer *****
16:54:26 ***** Privacy filter – refer to footer *****
16:54:26 ***** Privacy filter – refer to footer *****
16:54:26 ***** Privacy filter – refer to footer *****
16:54:26 ***** Privacy filter – refer to footer *****
17:04:50 ***** Privacy filter – refer to footer *****
17:04:50 ***** Privacy filter – refer to footer *****
17:04:50 ***** Privacy filter – refer to footer *****
17:04:50 ***** Privacy filter – refer to footer *****
17:04:51 ***** Privacy filter – refer to footer *****
17:53:58 ***** Privacy filter – refer to footer *****
17:53:58 ***** Privacy filter – refer to footer *****
17:53:58 ***** Privacy filter – refer to footer *****
17:53:58 ***** Privacy filter – refer to footer *****
17:53:58 ***** Privacy filter – refer to footer *****
17:53:59 ***** Privacy filter – refer to footer *****
17:53:59 ***** Privacy filter – refer to footer *****

The information contained in this report is subject to the provisions of the Official Information Act 1982 and Privacy Act 1993. Neither the information nor the report should be released to any person outside Fire and Emergency New Zealand without prior approval. Some message timestamps may differ to actual times in multi-agency incidents. Police/Ambulance messages may have been excluded for privacy. Communication Centres can supply these if essential.

18:02:16 ***** Privacy filter – refer to footer *****
18:02:16 ***** Privacy filter – refer to footer *****
18:02:16 ***** Privacy filter – refer to footer *****
18:02:16 ***** Privacy filter – refer to footer *****
18:02:17 ***** Privacy filter – refer to footer *****
18:02:17 ***** Privacy filter – refer to footer *****
18:02:17 ***** Privacy filter – refer to footer *****
18:02:17 ***** Privacy filter – refer to footer *****
18:02:56 ***** Privacy filter – refer to footer *****
18:02:56 ***** Privacy filter – refer to footer *****
18:02:56 ***** Privacy filter – refer to footer *****
18:02:56 ***** Privacy filter – refer to footer *****
18:02:56 ***** Privacy filter – refer to footer *****
18:02:57 ***** Privacy filter – refer to footer *****
18:02:57 ***** Privacy filter – refer to footer *****
18:14:11 ***** Privacy filter – refer to footer *****
18:14:11 ***** Privacy filter – refer to footer *****
18:14:11 ***** Privacy filter – refer to footer *****
18:14:11 ***** Privacy filter – refer to footer *****
18:14:11 ***** Privacy filter – refer to footer *****
01:18:51 ***** Privacy filter – refer to footer *****
01:18:51 ***** Privacy filter – refer to footer *****
01:18:51 ***** Privacy filter – refer to footer *****
01:18:51 ***** Privacy filter – refer to footer *****
01:18:53 ***** Privacy filter – refer to footer *****
01:18:53 ***** Privacy filter – refer to footer *****
01:18:53 ***** Privacy filter – refer to footer *****
01:18:53 ***** Privacy filter – refer to footer *****
01:18:53 ***** Privacy filter – refer to footer *****
01:18:53 ***** Privacy filter – refer to footer *****
01:18:53 ***** Privacy filter – refer to footer *****
01:18:53 ***** Privacy filter – refer to footer *****
01:18:53 ***** Privacy filter – refer to footer *****
01:18:53 ***** Privacy filter – refer to footer *****