

# SMS Incident Report


26/06/2024 13:56:48

## Summary

**CAD Number** F3996519 **Status** Closed  
**Station** Mapua Volunteer Fire Brigade  
**Incident Started** 17/06/2024 15:13:32 **Incident Ended** 17/06/2024 16:21:45  
**Incident Type** 1201: Mobile Property Fire  
**Common Name**  
**Address** / Waimea Inlet  
**Alarm Method** 111 Telephone **Alarm Level** 1  
**PFA Number**  
**Zone** 323130  
**Map Grid E** 1608627 **Map Grid N** 5432717  
**First Caller** 9(2)(a) **First Caller Contact** 9(2)(a)  
**Incident Closed** 17/06/2024 16:34:00  
**Report Completed** 10:48, Thur 20 Jun 2024 by Out of Scope

## Responses

Call Sign	Type	Station Alert	Enroute Time	Arrival Time	Departed
MAPU311	P1	15:14:15 17 Jun 2024	15:22:38 17 Jun 2024	15:27:27 17 Jun 2024	16:24:01 17 Jun 2024



## Elapsed Times

Call Sign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Departed
MAPU311	00:00:43	00:13:12	00:13:55	01:10:29

## Notifications

Date	Time	Party Notified
17 Jun 2024	15:17:01	POLICE VIA INTERCAD

Caution: The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside Fire and Emergency NZ without prior approval

17 Jun 2024	15:20:26	NELSON COASTGUARD WITH FYI
17 Jun 2024	15:23:31	TASMAN DISTRICT COUNCIL RE HARBOURMASTER
17 Jun 2024	15:31:30	DISTRICT NELSON MARLB PAGED

## Message Log

Time	Message
15:14:00	https://web.pcl.govt.nz/?ecn=9(2)(a)
15:14:00	INC INFO: BOAT FIRE
15:14:02	** LOI search completed at 17/06/24 15:14:02
15:14:10	** Recommended unit MAPU311 for requirement PUMP (>0.2 km)
15:14:12	Station Selcal used to Initiate Alerting. (MAPU311 at 3231 MAPUA 191311)
15:14:15	ALERTING_COMPLETED MAPU311
15:14:17	BOAT IS 30FT LONG
15:14:24	9(2)(a)
15:14:49	APPROX 30M AWAY FROM WHARF
15:15:02	LOOKS TO BE A SMALL FISHING BOAT
15:15:16	FRONT OF BOAT ON FIRE
15:15:31	9(2)(a)
15:16:59	** Event P059080525 of NZP/NS copied from F3996519 of NZFS/NL at: 17/06/24 15:16
15:16:59	:59
15:20:12	FIR2POL 9(2)(a)
15:20:12	9(2)(a)
15:20:12	9(2)(a) LOTS OF SMOKE SHOWING FROM FRONT OF BOAT
15:22:38	Unit MAPU311 [ K1 : PROCEEDING TO INCIDENT]
15:23:32	AMBO EVENT 0388-3-2024/06/17-POL LINKED AT 17/06/2024 15:23:32
15:24:01	Unit MAPU311 [ KP : PRIORITY MESSAGE]
15:24:39	Unit MAPU311 [ K1 : PROCEEDING TO INCIDENT]
15:24:40	Unit MAPU311 [ KP : PRIORITY MESSAGE] BOAT IS 50-100M OFF SHORE, WILL REQUIRE CO
15:24:40	ASTGUARD
15:27:26	HARBOURMASTER IS ENROUTE VIA BOAT, ETA 30 MINS
15:27:27	ENTERRED BY COMS
15:27:27	Unit MAPU311 [ K2 : IN ATTENDANCE AT INCIDENT] ENTERRED BY COMS
15:28:05	HARBOUR MASTER DOES NOT HAVE A CREW WITH HIM SO WOULD NEED FENZ TO BOARD HIS BOA
15:28:05	T TO ASSIST
15:28:57	Unit MAPU311 [ KC : UNIT CALLING]
15:29:52	Unit MAPU311 [ SITREP : ] SO Out of Scope - ONE 6M BOAT WELL INVOLVED AT REAR, LOOKI
15:29:52	NG AT GETTING FORESTRY INTO SMALL DINGHY TO FIGHT THE FIRE

15:30:12	Unit MAPU311 [COMCEN COM : MESSAGE] HARBOURMASTER ENROUTE IN BOAT, WILL REQUIRE
15:30:12	MANPOWER WHEN HE ARRIVES ETA 20MIN [ACK]
15:42:53	Unit MAPU311 [ K99 : PROPERTY FIRE WELL INVOLVED]
15:55:19	Unit MAPU311 [ KC : UNIT CALLING]
15:55:50	Unit MAPU311 [ SITREP : ] POLICE AND COASTGUARD ON SCENE, FIRE MOSTLY OUT, HARBO
15:55:50	URMASTER ARE GOING TO TOW BOAT ONTO SHORE
16:21:26	Unit MAPU311 [ KC : UNIT CALLING]
16:21:45	Unit MAPU311 [ K47 : STOP MESSAGE: MESSAGE UNCHANGED FROM SITREP]
16:23:27	Alarm Timer Extended: 0
16:24:01	Unit MAPU311 [ K7 : AT NORMAL STATION]
16:34:00	** Assigned Result Code: MIN, Detailed Event Type: 1100

## Incident

**CAD Number** F3996519

**Incident Reporter** **Out of Scope**

**Incident Controller**

**Distance Travelled (km)**

**Delay In Receiving Call**

## Property Details

**Occupant**

**Building Owner**

**General Property Use** Stormwater, Harbour, Lake, River, Beach/Waterfront

**Special Property Use** Harbour, Inlet

**Purpose Group**

## Actions

**Persons Reported Trapped**

**Evacuation Status**

**Action Prior 1**

**Action Prior 2**

**Action Taken** Investigation only (Fire related)

## Civilians

**Civilians Rescued** 0

**Civilians Extricated** 0

**Civilians Assisted** 1

Civilians Evacuated

0

**Origin****Location** Living area - not classified above**Level****Equipment Used**

Quantity	Equipment
1	Portable pump

**Equipment Involved**

Equipment Involved

**Year****Make****Model****Fire****Arrival Condition** Large fire**Heat Source** Embers, Ashes**Termination Stage****First Object Ignited****First Object Material****Second Object Ignited****Second Object Material****Indicated Cause** Carelessness with material ignited - other**Certainty of Cause** Medium**Age of Person** 9(2)(a)**Ethnicity** 9(2)(a)**Gender** 9(2)(a)**FAIP Service Offered** Unknown**Mobile****Vehicle Type** Yacht, Sail boat**Licence Plate****Year****Make****Model**

### Comments

6/20/2024 10:48:29 AM

Reporter Comments

2 LPG bottles

9(2)(a)

[REDACTED]

Out of Scope

RELEASED UNDER THE OFFICIAL INFORMATION ACT 1982